

Work Order 5

Equipment P-105. Bearing issue. Technician Rajesh Kumar. Linked to valve inspections.