

Work Order 6

Equipment P-106. Bearing issue. Technician Rajesh Kumar. Linked to valve inspections.