Generated using <u>SQL Data Dictionary</u> demo version.

•

Pbplastics

<u>Tables:</u>

dbo.customer_master (4 rows)	1
dbo.down_time_master (8 rows)	
dbo.family_master (3 rows)	1
dbo.fpa (1 row)	1
dbo.Login (4 rows)	2
dbo.machine_master (3 rows)	2
dbo.masterbatch_master (2 rows)	2
dbo.packaging_details_master (7 rows)	2
dbo.packaging_master (0 rows)	3
dbo.parts_master (4 rows)	3
dbo.post_operation_master (16 rows)	4
dbo.production (1 row)	4
dbo.production_tag_details_master (4 rows)	5
dbo.raw_material_master (5 rows)	5
dbo.rejection_master (0 rows)	5
dbo.shift_master (3 rows)	5
dbo.supplier_master (0 rows)	6
dbo.unit_of_measurement_master (3 rows)	6
dhe werker master (0 rows)	6

Tables:

<u>Table dbo.customer_master</u> (4 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	customer_name	varchar(250)			
	customer_address_one	varchar(250)		Χ	
	customer_address_two	varchar(250)		Χ	
	customer_contact	varchar(150)		Χ	
	customer_email	varchar(150)		Χ	
	customer_contact_person	varchar(150)		Χ	
	customer_gst_details	varchar(150)		X	

Indexes:

PK_customer_master (Primary Key) (Clustered)

id

Table dbo.down_time_master (8 rows)

	Column	Data Type	Identity	Nullable	Default
PK	Id	int	X		
	down_time_code	varchar(250)		Х	

Indexes:

PK_down_time_master (Primary Key) (Clustered)

Id

Table dbo.family_master (3 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	X		
	Family	varchar(150)		X	

Indexes:

PK_family_master (Primary Key) (Clustered)

id

Table dbo.fpa (1 row)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	worker_name	varchar(150)			
	part_name	varchar(150)			
	date	varchar(120)			
	operation_type	varchar(120)			
	total_qty	varchar(120)			
	no_of_parts	varchar(125)			
	total_time	varchar(125)			
	exp_qty	varchar(125)		Χ	
	rej_qty	varchar(125)		X	

wip_qty	varchar(125)	Х	
rej_code	varchar(125)		
prod_tag_details	varchar(125)		

PK_fpa (Primary Key) (Clustered)

id

Table dbo.Login (4 rows)

	Column	Data Type	Identity	Nullable	Default
PK	Id	int	Χ		
	username	varchar(50)			
	password	varchar(50)			
	role	varchar(50)		X	

Indexes:

PK__Login__3214EC07B720780F (Primary Key) (Clustered)

Id

<u>Table dbo.machine_master</u> (3 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	machine_no	varchar(50)			
	machine_name	varchar(50)		Χ	

Indexes:

PK_machine_master (Primary Key) (Clustered)

id

Table dbo.masterbatch_master (2 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	mb_name	varchar(150)			
	mb_grade	varchar(150)			
	mb_mfg	varchar(120)		X	
	mb_color	varchar(120)		X	
	mb_color_code	varchar(125)		Χ	

Indexes:

PK_masterbatch_master (Primary Key) (Clustered)

id

<u>Table dbo.packaging_details_master</u> (7 rows)

	Column	Data Type	Identity	Nullable	Default
PK	Id	int	Х		
	type	varchar(50)		X	

size	varchar(50)	X	
qty_per_package	varchar(50)	X	
photo	varchar(150)	X	
part_no	varchar(50)		
part_name	varchar(150)		

PK__packagin__3214EC078A53320D (Primary Key) (Clustered)

Id

<u>Table dbo.packaging_master</u> (0 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	packaging_type	varchar(150)			
	size	varchar(150)			

Indexes:

PK_packaging_master (Primary Key) (Clustered)

id

<u>Table dbo.parts_master</u> (4 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Х		
	part_no	varchar(50)			
	part_name	varchar(50)			
	customer_name	varchar(50)		Х	
	customer_part_no	int		Χ	
	product_category	varchar(50)			
	mold_name	varchar(50)		X	
	mold_mfg_year	varchar(50)		X	
	mold_life	varchar(50)		X	
	no_of_cavities	int			
	unit_of_measurement	varchar(50)		X	
	part_weight	int			
	shot_weight	int			
	cycle_time	int		X	
	jig_fixture_req	varchar(50)		Χ	
	production_in_pcs	varchar(50)			
	part_photo	varchar(50)		X	
	mold_spec_sheet	varchar(50)		X	
	raw_material	varchar(50)			
	rm_grade	varchar(50)			
	rm_make	varchar(50)			
	rm_color	varchar(50)			
	masterbatch	varchar(50)		X	
	alt_raw_material	varchar(50)		X	
	mb_name	varchar(50)		Χ	
	mb_grade	varchar(50)		Х	
	mb_mfg	varchar(50)		Х	
	mb_color	varchar(50)		Х	
	mb_color_code	varchar(50)		Х	
	alt_rm_name	varchar(50)		Х	

alt_rm_grade	varchar(50)	X	
alt_rm_make	varchar(50)	X	
alt_rm_color	varchar(50)	X	
alt_masterbatch	varchar(50)	X	
alt_mb_name	varchar(50)	X	
alt_mb_grade	varchar(50)	X	
alt_mb_mfg	varchar(50)	X	
alt_mb_color	varchar(50)	Χ	
alt_mb_color_code	varchar(50)	X	
post_operation_required	varchar(50)	X	
packaging_details_required	varchar(50)	X	
production_tag_details_required	varchar(50)	X	

PK_parts_master (Primary Key) (Clustered)

id

<u>Table dbo.post_operation_master</u> (16 rows)

	Column	Data Type	Identity	Nullable	Default
PK	Id	int	Χ		
	type	varchar(50)		X	
	target_quantity	varchar(50)		X	
	process_description	varchar(150)		Χ	
	photo	varchar(150)		Χ	
	part_no	varchar(50)			
	part_name	varchar(150)			

Indexes:

PK__tmp_ms_x__3214EC071B71A747 (Primary Key) (Clustered)

Id

Table dbo.production (1 row)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	X		
	part_name	varchar(150)			
	material_grade	varchar(150)			
	machine_no	varchar(120)			
	shift_details	varchar(120)			
	exp_qty	varchar(120)			
	no_of_shots	varchar(125)			
	rejection_pcs	varchar(125)			
	rejection_kgs	varchar(125)		Χ	
	act_qty	varchar(125)			
	downtime_hrs	varchar(125)		Χ	
	down_time_code	varchar(125)		Χ	
	efficiency	varchar(125)			
	date	varchar(125)		Χ	
	worker_name	varchar(150)		X	

Indexes:

id

<u>Table dbo.production_tag_details_master</u> (4 rows)

	Column	Data Type	Identity	Nullable	Default
PK	Id	int	Χ		
	emp_no	varchar(50)		Χ	
	date	varchar(50)		Χ	
	shift	varchar(50)		X	
	qty	varchar(50)		Χ	
	part_no	varchar(50)			
	part_name	varchar(150)			

Indexes:

PK__producti__3214EC07607ECBB7 (Primary Key) (Clustered)

Id

<u>Table dbo.raw_material_master</u> (5 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	material_name	varchar(50)			
	material_grade	varchar(50)		X	
	material_color	varchar(50)			
	material_make	varchar(50)		X	
	material_qty	varchar(50)		X	

Indexes:

PK_raw_material (Primary Key) (Clustered)

id

Table dbo.rejection_master (0 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	X		
	rejection_type	varchar(150)			
	rejection_code	varchar(150)			
	description	varchar(120)		Х	

Indexes:

PK_rejection_master (Primary Key) (Clustered)

id

Table dbo.shift_master (3 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	shift_time	varchar(150)			
	hours	int			

PK_shift_master (Primary Key) (Clustered)

id

<u>Table dbo.supplier_master</u> (0 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	Χ		
	supplier_name	varchar(150)			
	supplier_id	varchar(150)			
	user_id	varchar(150)			
	user_password	varchar(50)			
	rights	text			

Indexes:

PK_supplier_master (Primary Key) (Clustered)

id

<u>Table dbo.unit_of_measurement_master</u> (3 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	X		
	unit_of_measurement	varchar(150)		Χ	
	abbreviation	varchar(150)		Χ	

Indexes:

PK_unit_of_measurement_master (Primary Key) (Clustered)

id

<u>Table dbo.worker_master</u> (0 rows)

	Column	Data Type	Identity	Nullable	Default
PK	id	int	X		
	worker_name	varchar(150)			
	worker_id	varchar(150)			
	user_id	varchar(150)			
	user_password	varchar(50)			
	rights	text			

Indexes:

PK_worker_master (Primary Key) (Clustered)

id