



Lab Report: Analysis of 3-axis Piezo stage

Name: Sreekanth Reddy Suda

Email Address: s3srsuda@stud.eah-jena.de

Matrikel Number: 651709

Date of Report submission: 09- 02-2024

Ansys File Model name: 651709_FEM_Final_Project

List of Collaborators:

Name: Krishna Vamsi Chalamalasetti Matrikel Number: 651815

Name: Chakra Shree Harsha Aravilli Venkata Matrikel Number: 651503

Name: Nishkala Kambham Matrikel Number: 651422

Supervisor

Prof. Dr.-Ing. Frank Dienerowitz



Table of Contents

List of Figures	3
List of Tables	
1. Introduction	
1.1. Objective of the analysis:	5
1.2. Brief overview of the tool(s):	5
1.3. Material Parameters and Ambient Conditions applied to the analysis:	5
2. Description of the FEA model:	ε
3. Details of Mesh Convergence Study:	7
4. Figure of Final Mesh	8
5. Results	9
5.1. Stage Stiffness in X and Y Directions	9
5.1.1. Stiffness at Load point when Force Applied in X-Direction	<u>S</u>
5.1.2. Stiffness at Load point when Force Applied in Y-Direction	10
5.2. Workspace of Output Load Point	11
6. Verification by Hand Calculation	12
Declaration of Independence	15



List of Figures

igure 1: The design of 3- Axis Piezo stage	6
Figure 2: Detailed FEA Model of 3-Axis Piezo Stage	
Figure 3: Total Deformation at Output load point	7
igure 4: Plot of Mesh Convergence	
igure 5: Detailed Refined Mesh	8
Figure 6: Stiffness Plot in X-Direction	9
Figure 7: Stiffness Plot in Y-Direction	10
Figure 8: Workspace of the Output Load Point	



List of Tables

Table 1: Material Characteristics	5
Table 2: Geometric Dimensions of FEA Model in XY Plane	6
Table 3: Mesh Convergence Study at Output Load Point	7
Table 4: Nodes & Elements	8
Table 5: Directional Deformation towards X-direction for different Forces Applied	9
Table 6: Directional Deformation towards Y-Direction for different Forces Applied	10
Table 7: Stiffness in X and Y directions	10
Table 8: Deformations at Load Point in X & Y Directions for the given Temperature range	11



1. Introduction

1.1. Objective of the analysis:

The purpose of this report is to determine the evaluation on the design of an XY-stage of Piezo Actuators. The tasks which are to be accomplished are given below.

<u>Task 1</u>: Determine the stage stiffness in x- and y-direction regarding the output load point. Give your results in $\lceil N/mm \rceil$.

<u>Task 2</u>: Determine the workspace of the output load point if the actuators accept a voltage range of $-200V \dots +200V$

<u>Task 3</u>: Mesh convergence study based on the required results to prove correct mesh sizing and provide a hand calculation of the expected X and Y displacement for the output load point.

1.2.Brief overview of the tool(s):

The model assembly is designed using the software Ansys Workbench 2023 R2. The Ansys program use computer-based methods to find solutions and resolve challenging issues. The geometry and design are produced using the static structural design modeler feature. Engineering data like Young's modulus, Poisson's ratio, kind of material, and environmental circumstances are entered using the isotropic elasticity in the linear elastic design feature. To manually calculate the solution and insert the graphs for the mesh convergence, we used Microsoft Word for report preparation and MS Excel for the graph.

1.3. Material Parameters and Ambient Conditions applied to the analysis:

Material: Steel

Young's Modulus				Actuator's coefficient		
Actuator	Lever	Hinges	Frame	1 100000001 2 000 1110 10110		
E/MPa	E/MPa	E/MPa	E/MPa	d/ 1/V		
90000	16000	48000	240000	1,2E-04		

Table 1: Material Characteristics

Ambient Conditions: 20°C, 1bar atmospheric pressure, no harsh environment



2. Description of the FEA model:

The FEA Model consists of 3 Piezo Actuators connected with hinges to a Lever and Frame. These materials have their Isometric Elastic properties as mentioned in Table 1. The materials are connected to the frame and lever as shown in Figure 1. The results of the required analysis are carried out at Output Load point as shown in Figure 2.




Figure 1: The design of 3- Axis Piezo stage.

Key dimensions and Boundary conditions are shown in Figure 2 with assigned dimensions for the Analysis. The dimensions mentioned in Figure 2 are as per the below table.

A15 (°C)	A5 (°C)	L1 (mm)	L10 (mm)	L2 (mm)	L22 (mm)	L26 (mm)	V8 (mm)
113	40	3	15	6	4	15	13

Table 2: Geometric Dimensions of FEA Model in XY Plane



Figure 2: Detailed FEA Model of 3-Axis Piezo Stage



3. Details of Mesh Convergence Study:

A mesh convergence study in ANSYS is like finding the right level of detail for a picture. We want to make sure our results are accurate, so we check how changing the mesh affects them. We keep refining the mesh, making it more detailed, and see if the result changes a lot. We look at things like how much something moves or how stressful it gets to see if the results are stable as we refine the mesh. In short, a mesh convergence study helps us make sure our computer model gives us reliable answers by checking how various levels of detail affect our results.




Figure 3: Total Deformation at Output load point.

Figure 3 shows the Total deformation at the output load point with maximum and minimum deformations. The Total deformation at the load point is found at different element sizes and are tabulated in Table 3. The mesh is converged at the element size 0.6 mm. Figure 4 shows the graph plotted in between Mesh nodes and Total deformation at Output Load Point.

Mesh Element Size	Mesh Nodes	Mesh Elements	Total Deformation Maximum
mm			mm
1	11387	1792	0.146995199
0.9	13502	2140	0.14714566
0.7	24932	4344	0.148288997
0.6	35023	6370	0.148579009
0.5	53451	10208	0.148466503
0.45	73655	14559	0.148549119

Table 3: Mesh Convergence Study at Output Load Point




Figure 4: Plot of Mesh Convergence

4. Figure of Final Mesh

The below figure shows the Detailed figure of refined mesh with Element size 0.6 mm which consists of 41300 Nodes and 19463 Elements.

Element Size	0.6 mm
Nodes	41300
Elements	19463

Table 4: Nodes & Elements




Figure 5: Detailed Refined Mesh



5. Results

5.1. Stage Stiffness in X and Y Directions

Material stiffness refers to how resistant it is to bend or stretching under force, measured by Young's Modulus, with higher values indicating less deformation. It is calculated by the formula as shown below.

$$Stage\ Stiffness(k)\ = \frac{\text{Force Applied (F)}}{\text{Displacement (\Delta u)}}$$

For the given material the Stiffness is calculated in both X and Y directions by applying various values of force at the output load point.

5.1.1. Stiffness at Load point when Force Applied in X-Direction

The Directional deformation towards X direction is calculated by applying various forces in X direction as shown in Table 4 and the plot for this is show in Figure 5.

Force X Component (N)	Maximum Directional Deformation (mm)
100	9.387073517
90	8.448366165
80	7.509658813
70	6.570951462
60	5.63224411
50	4.693536758
40	3.754829407
30	2.816122055
20	1.877414703
10	0.938707352

Table 5: Directional Deformation towards X-direction for different Forces Applied




Figure 6: Stiffness Plot in X-Direction



5.1.2. Stiffness at Load point when Force Applied in Y-Direction

The Directional deformation towards Y direction is calculated by applying various forces in Y direction as shown in Table 5 and the plot for this is show in Figure 7.

Force Y Component (N)	Maximum Directional Deformation (mm)
100	40.6464653
90	36.58181763
80	32.51717377
70	28.45252609
60	24.38787842
50	20.32323265
40	16.25858688
30	12.19393921
20	8.129293442
10	4.064646721

Table 6: Directional Deformation towards Y-Direction for different Forces Applied




Figure 7: Stiffness Plot in Y-Direction

The Stiffness can be calculated from the plots by calculating the Slopes. These Slope values are provided in below Table 6.

Direction	Stiffness
X-axis	0.09387073
Y-axis	0.40646465

Table 7: Stiffness in X and Y directions



5.2. Workspace of Output Load Point

The workspace of the output load point depends on the voltages that actuators use, which goes from -200V to +200V. This voltage range decides how far the actuators can push the load point. By using this voltage range, the actuators can make the load point move in different directions, letting it go to different spots within its limits.

For Actuators varying in thermal conditions i.e., Temperature will increase the Resistance which increases Voltage. So here in this analysis we vary temperature in Actuators for varying Voltage. Table 7 shows the values of Deformation in both X and Y directions by providing different temperatures to three actuators.

Thermal Condition	Thermal Condition	Thermal Condition	Directional Deformation	Directional Deformation
Actuator 1 (C)	Actuator 2 (C)	Actuator 3 (C)	Maximum X-Axis (mm)	Maximum Y-Axis (mm)
200	200	200	0.024658507	-0.311635464
200	200	-200	0.113832586	0.090890728
200	-200	200	-0.00520959	0.091991469
200	-200	-200	0.101000778	0.511553943
-200	200	200	-0.075770088	-0.403194398
-200	200	-200	0.011641347	-0.002430869
-200	-200	200	-0.115716733	-0.009646027
-200	-200	-200	-0.009506362	0.409916431

Table 8: Deformations at Load Point in X & Y Directions for the given Temperature range

The below graph represents the workspace of the Output Load point when Temperature in Actuators are Varied.





Figure 8: Workspace of the Output Load Point



6. Verification by Hand Calculation

In our manual calculations we consider the Actuator 1 and Actuator 2 are Fixed and there is no temperature effect on it. As Actuator 3 deforms due to change in Temperature. It causes the entire lever shift in response. Consequently, we can simplify the problem by focusing on how various segments of the lever displace as it rotates around point O.

As the lever undergoes a specific angle of rotation, it creates two similar triangles, as illustrated in Figure below.



but here

$$D_{2}D_{1} = D_{2}D + DD_{1} + D_{1}D_{3} + D_{3}D_{1}$$
finding

(1) $D_{2}D$ from $\triangle ADD_{2}$

$$D_{2}D = AD \cos D_{2}DA = 15 \times \cos(20^{\circ})$$

$$D_{3}D \Rightarrow 14.0954 \text{ mm}$$

$$Aq + 90^{\circ} + D_{2}DA = 180^{\circ}$$

$$D_{2}D_{1} = 180 - 90 - 10^{\circ} \text{ (: }A_{1} = 10^{\circ}\text{)}$$

$$\Rightarrow 20^{\circ}$$
(2) DD_{1} from $\triangle EDD_{1}$

$$DEDD_{1} = DD_{2}$$

$$DD_{2} = DD_{3}DA = DD_{4}$$

$$DD_{3} = DD_{4} = DD_{5}COS DD_{4}$$

$$\Rightarrow DD_{4} = DD_{5}COS DD_{4}$$

$$\Rightarrow DD_{4} = DD_{5}COS DD_{4}$$

$$\Rightarrow DD_{4} = 0.3969 \text{ mm}$$

(3)
$$D_3D_4$$
 from $\triangle ED_3D_4$
 $D_4D_3 = D_3E \cdot \cos \angle ED_3D_4$
 $D_4D_3 = D_3E \cdot \cos \angle ED_3D_4$
 $D_3E = EF - FD_1 \Rightarrow (L_{16} + \frac{L_{23}}{2}) - L_{28}$
 $\Rightarrow 15 + \frac{10}{2} - 6 = 12mm$

(4) $D_1D_3 = \frac{FD_1}{\cos \angle ED_1D_3} = \frac{L_{28}}{\cos \angle 45} = \frac{8}{\cos \angle 45}$

$$D_1D_3 = \frac{FD_1}{\cos \angle ED_1D_3} = \frac{L_{28}}{\cos \angle 45} = \frac{8}{\cos \angle 45}$$

$$D_1D_3 = \frac{FD_1}{\cos \angle ED_1D_3} = \frac{L_{28}}{\cos \angle 45} = \frac{8}{\cos \angle 45}$$

$$D_2D_1 = D_2D + DD_4 + D_4D_3 + D_3D_1$$
 $= 14.0954 + 9.3969 + 8.4953 + 11.3137$

$$D_2D_1 = 43.2913 mm$$

$$D_2D_1 = 43.2913 mm$$

$$D_2D_2 = 43.2913 mm$$

$$D_2D_3 = 40.860 \angle AD_2$$

$$D_3D_4 = 40.860 \angle AD_2$$

$$D_3D_4 = 40.860 \angle AD_2$$

$$D_3D_4 = 40.860 \angle AD_2$$

$$D_3D_5 = 18.1303 mm$$

$$D_3D_5 = 18.1303 mm$$

$$D_3D_5 = 18.1303 mm$$



So, displacement at load point
$$d_2 = \frac{OD_1}{OD}d_1 = \frac{46.9345}{32.9649} \times 0.096 = 0.1962$$

$$d_2 = 0.1962 \text{ mm}$$

Vesification by finding Percentage Deviation:
$$\rightarrow \text{ANSYS simulation result}$$

$$d_{\text{simulation}} = 0.1486 \text{ mm}$$

$$\Rightarrow \text{Hand calculation result}$$

$$d_{\text{calculated}} = 0.1962 \text{ mm}$$

$$\therefore \text{Percentage deviation} = \frac{d_{\text{calculated}} - d_{\text{simulation}}}{d_{\text{calculated}}} \times 100\%$$

$$\Rightarrow \frac{0.1962 - 0.1486}{0.1962} \times 100\%$$

Deviation > 24.26%



Declaration of Independence

We declare on our honour that the work presented in this dissertation, entitled "Lab Report: Analysis of 3-axis piezo stage," is original and was carried out by Sreekanth Reddy Suda (651709), Krishna Vamsi Chalamalasetti (651815), Chakra Shree Harsha Aravilli Venkata (651503), and Nishkala Kambham (651422) under the supervision of Prof. Dr.-Ing. Frank Dienerowitz (Frank.Dienerowitz@eah-jena.de).

Date od Submission: 09th February 2024.

Signed,

K. Nishkala

Nishkala Kambham

Sreekanth Reddy Suda

Ch. Krishner Venni

W ree Harrish

Krishna Vamsi Chalamalasetti

Chakra Shree Harsha Aravilli Venkata