# ENPM 809T

UMCP, Mitchell, Summer 2019

# **GPIO**

- Uncommitted digital signal pin
- Acts as either input or output
  - · 3.3V on Raspberry Pi
- Controlled by user at run time
- Pulse-width modulation
- I2C
- Serial







# GPIO: Raspberry Pi

- Voltages
  - 2x 5V pins
  - 2x 3.3V pins
  - GND 0V pins
- Outputs
  - High (3.3V) or low (0V)
- Inputs
  - Read as high (3.3V) or low (0V)
- Type pinout in terminal window

\* Numbering is <u>not</u> in numerical order \*





# Solderless breadboards





### Solderless breadboards









# Ultrasonic Range Sensor


- Transmits high-frequency pulses of sound (pressure) via transducers
- Measure time from transmission to reception of scattered wave
- Typical range 2 400 cm (1 13 ft)



# Ultrasonic Range Sensor








# Ultrasonic Range Sensor



#### MAX3232

SLLS410N - JANUARY 2000-REVISED JUNE 2017

#### MAX3232 3-V to 5.5-V Multichannel RS-232 Line Driver/Receiver With ±15-kV ESD Protection







LM124-N, LM224-N LM2902-N, LM324-N

SNOSC16D - MARCH 2000 - REVISED JANUARY 2015


#### LMx24-N, LM2902-N Low-Power, Quad-Operational Amplifiers




# Timing



- From parts kit:
- 1. Raspberry Pi
- 2. Breadboard
- 3. Distance sensor
- 4. Three  $1k\Omega$  resistors
- 5. Jumper wires



• Plug sensor into end of breadboard




# Pin Allocations

Distance sensor


 We will track throughout the course






- Plug **red** male-female wire into pin 2
  - **5V** Vcc supply
- Plug **black** male-female wire into pin 14
  - · Ground

- Plug 5V into sensor Vcc
- Plug GND into breadboard ground rail





$$\frac{3.3}{5} = \frac{R2}{1000 + R2}$$

$$0.66 = \frac{R2}{1000 + R2}$$


$$0.66(1000 + R2) = R2$$


$$660 + 0.66R2 = R2$$

$$660 = 0.34R2$$

$$1941 = R2$$


• Create voltage divider using three  $1k\Omega$  resistors






- Plug blue male-female wire into pin 16
  - GPIO23
  - · Sensor Trig
- Plug **green** male-female wire into pin 18
  - GPIO24
  - · Sensor Echo


 Connect each wire on breadboard




 Plug black male-male wire between sensor GND and breadboard GND rail




\* Confirm circuit is properly wired before applying power to the RPi




- Create a new .py file: range01.py
- Import **RPIO** and **time** modules



• Define pins for trigger & echo



- Create distance() function
- Performs all required operations to measure range
- Returns single distance measurement




Setup board



• Assign GPIO pins as either input or output

```
pi@raspberrypi: ~
                                                        GNU nano 2.7.4
                          File: rangeOl.py
                                                     Modified
import RPi.GPIO as gpio
import time
 Define pin allocations
trig = 16
echo = 18
def distance():
        gpio.setmode(gpio.BOARD)
        gpio.setup(trig, gpio.OUT)
        gpio.setup(echo, gpio.IN)
  Get Help ^O Write Out^W Where Is ^K Cut Text ^J Justify
```

• Set trig pin low




ENPM 809T: Autonomous Robotics


# Timing

- Each range measurement requires:
- 1. Trigger HIGH for 10 microseconds
- 2. Sensor automatically transmits eight 40 kHz pulses
- 3. Received signal generates HIGH echo signal
- 4. Duration of echo HIGH output defines delta time

# Timing



• Generate trigger signal




```
pi@raspberrypi: ~
                                                       GNU nano 2.7.4
                          File: range01.py
                                                    Modified
import RPi.GPIO as gpio
import time
 Define pin allocations
trig = 16
echo = 18
def distance():
        gpio.setmode(gpio.BOARD)
        gpio.setup(trig, gpio.OUT)
        gpio.setup(echo, gpio.IN)
        # Ensure output has no value
        gpio.output(trig, False)
        time.sleep(0.01)
        # Generate trigger pulse
        gpio.output(trig, True)
        time.sleep(0.00001)
        gpio.output(trig, False)
G Get Help C Write Out Where Is K Cut Text J Justify
```

27

ENPM 809T: Autonomous Robotics

• Generate echo time signal



28

ENPM 809T: Autonomous Robotics

- Convert time measured to distance estimate
- At sea level, sound travels 343 m/sec = 34300 cm/sec

$$Speed = \frac{Distance}{Time}$$

$$34300 = \frac{Distance}{Time/2}$$

$$17150 = \frac{Distance}{Time}$$

 $17150 \times Time = Distance$ 

```
pi@raspberrypi: ~
                          File: rangeOl.py
  GNU nano 2.7.4
                                                     Modified
import RPi.GPIO as gpio
import time
 Define pin allocations
trig = 16
echo = 18
def distance():
        gpio.setmode(gpio.BOARD)
        gpio.setup(trig, gpio.OUT)
        gpio.setup(echo, gpio.IN)
        # Ensure output has no value
        gpio.output(trig, False)
        time.sleep(0.01)
        # Generate trigger pulse
        gpio.output(trig, True)
        time.sleep(0.00001)
        gpio.output(trig, False)
        # Generate echo time signal
        while gpio.input(echo) == 0:
                pulse start = time.time()
        while gpio.input(echo) == 1:
               pulse_end = time.time()
        pulse duration = pulse end - pulse start
        # Convert time to distance
        distance = pulse duration*17150
        distance = round(distance, 2)
   Get Help O Write Out W Where Is K Cut Text J Justify
```

- Cleanup GPIO pins
  - · Resets ports used in program as inputs
  - Prevents shorts/damage
- Return distance estimate from distance() function

```
pi@raspberrypi: ~
  GNU nano 2.7.4
                          File: range01.py
                                                     Modified
import RPi.GPIO as gpio
import time
 Define pin allocations
trig = 16
echo = 18
def distance():
        gpio.setmode(gpio.BOARD)
        gpio.setup(trig, gpio.OUT)
        gpio.setup(echo, gpio.IN)
        # Ensure output has no value
        gpio.output(trig, False)
        time.sleep(0.01)
        # Generate trigger pulse
        gpio.output(trig, True)
        time.sleep(0.00001)
        gpio.output(trig, False)
        # Generate echo time signal
        while gpio.input(echo) == 0:
                pulse start = time.time()
        while gpio.input(echo) == 1:
                pulse end = time.time()
        pulse duration = pulse end - pulse start
        # Convert time to distance
        distance = pulse duration*17150
        distance = round(distance, 2)
        # Cleanup gpio pins & return distance estimate
        gpio.cleanup()
        return distance
   Get Help O Write Out W Where Is K Cut Text J Justify
```

Print distance in terminal window

```
pi@raspberrypi: ~
                                                      GNU nano 2.7.4
                          File: range01.py
import RPi.GPIO as gpio
import time
 Define pin allocations
trig = 16
echo = 18
def distance():
        gpio.setmode(gpio.BOARD)
        gpio.setup(trig, gpio.OUT)
        gpio.setup(echo, gpio.IN)
        # Ensure output has no value
        gpio.output(trig, False)
        time.sleep(0.01)
        # Generate trigger pulse
        gpio.output(trig, True)
        time.sleep(0.00001)
        gpio.output(trig, False)
        # Generate echo time signal
        while gpio.input(echo) == 0:
               pulse start = time.time()
        while gpio.input(echo) == 1:
               pulse_end = time.time()
        pulse duration = pulse end - pulse start
        # Convert time to distance
        distance = pulse duration*17150
        distance = round(distance, 2)
        # Cleanup gpio pins & return distance estimate
        gpio.cleanup()
        return distance
print("Distance: ", distance(), " cm")
Get Help C Write Out Where Is K Cut Text Justify
```

ENPM 809T: Autonomous Robotics

• Run program to confirm proper operation

• Modify your code to measure and provide range estimates of 10 successive range measurements

### In-Class Exercise

- Place an object ~0.5 m from the Rpi
- Write a Python script to perform the following:
- 1. Record an image of the scene using raspistill
- 2. Record 10 successive distance measurements from the RPi to the object
- 3. Calculate & print the average of the 10 measurements onto the image using OpenCV

```
import numpy as np
import cv2
import imutils
import RPi.GPIO as gpio
import time
(import os
```

```
# Record image using Raspistill
name = "lecture4inclass.jpg"
os.system('raspistill -w 640 -h 480 -o ' + name)
```

### References

- Introduction to Autonomous Mobile Robots, Siegwart
  - Chapter 4
- Raspberry Pi GPIO Setup
  - https://learn.adafruit.com/adafruits-raspberry-pi-lesson-4-gpio-setup/overview
- HC-SR04 Ultrasonic Range Sensor on the Raspberry Pi
  - https://www.modmypi.com/blog/hc-sr04-ultrasonic-range-sensor-on-the-raspberry-pi
- Arduino lesson Ultrasonic Sensor HC-SR04
  - http://osoyoo.com/2017/07/23/arduino-lesson-ultrasonic-sensor-hc-sr04/