Stop a bad forging before it is machined into a brake bracket.

Giulia at receiving has a delivery note, a material certificate, the supplier's inspection report, and the shop's own measurement. The check is often late.

No measured number on this slide.

Release, quarantine, or hold. Then a person decides.

Code checks sizes, identities, and the gauge date. The model maps the supplier's feature names, and on a failure it quotes the contract and drafts the claim. The model cannot release the batch.

No measured number on this slide.

Four packets.

- P01, German supplier. Released.
- P06, bore 22.061 mm. Quarantined. Supplier. EUR 110.40.
- P09, fails the latest drawing, meets the revision on the order. Quarantined. Internal. No claim.
- P11, gauge expired. Held by code.

Source: docs/eval.md

Decision	Who
Feature names, on every packet	Model
Tolerances, identities, gauge date, release or quarantine, the euro amount	Code
Fault, the quoted clause, the report	Model, after code has failed the batch
Send the claim, or release under concession	A person

No measured number on this slide.

Incoming inspection already exists.

LineLock does not replace a quality system. The shop, the contracts, and the packets are written for this demo. Extraction in this build is local. The model is the local stand-in until it is pointed at AMD.

The four decisions: the revision on the purchase order, an expired gauge, a claim only when a sentence covers the defect, and a small-shop upload gate.

Source: linelock-plan.md section 11. No measured number.

12 of 12 labelled packets agreed.

- Packet 6 claim: EUR 110.40.
- Edited C4 of 22.080 mm became quarantine.
- Median case time 33 ms. Fastest 21 ms. Slowest 60 ms.

The hand-timed comparison is not measured.

12 of 12, EUR 110.40, and the edit: docs/eval.md. Times: docs/benchmark.md. Local stand-in, not an AMD card.

A quality engineer at a small receiving dock.

Offer shape: per receiving dock, per month. No price figure. Next step: one supplier at one shop in Imperia.

Assumption. Not a measured result. No euro price.

This run did not use an AMD card.

The stand-in returns a prepared answer. It does not generate tokens. There is no tokens-per-second number, and none belongs on the shop-floor screen.

When vLLM is connected, replace this slide with tokens per second, time to first token, and the median case time. Name the card.

Source: docs/benchmark.md

Rehearsal script · about 4 minutes · not yet timed

Say this. Two people still have to time it.

0:00 A wrong forging in a brake bracket is a safety problem. Giulia checks every batch's paperwork. This is a fictional shop.

0:30 Packet 1. The supplier calls this bore Bohrung A. Our drawing calls it characteristic 4. Code checked every tolerance. Released.

1:00 Packet 6. Bore out by four hundredths. Code quarantined it. The claim is EUR 110.40. A person approves it before anything is sent.

1:50 Packet 9. Also out of tolerance against the latest drawing. The purchase order named revision B, and the part meets B. No claim.

2:30 Packet 11. Our gauge expired. Code held the batch. The model only writes why.

3:00 Change the measurement and run it again.

3:20 Twelve of twelve labelled packets agreed. The hand comparison is not measured yet. The times are the local stand-in, not AMD.

3:45 Quality engineers at small shops. Per receiving dock, per month. We are not replacing a quality system.

Words from linelock-plan.md section 9, with the AMD and Evolus sentences left out until those endpoints are connected.