

Avasthi & Associates, Inc.

Worldwide Petroleum Consulting

800 Rockmead Drive, Suite 212, Kingwood, TX 77339, U.S.A.

P.O. Box 60497, Houston, TX 77205-0497, U.S.A.

Phone: +1-281-359-2674 • E-mail: avasthi@att.net • Fax: +1-281-754-4969

Customized Software Development Services

April 20, 2006

PROPHET Model Read Me First File

- (1) Copy ‘Prophet’ folder from CD to your desktop
- (2) Open ‘Prophet’ folder
- (3) On top of ‘Prophet’ folder window, click on Tools > Folder Options > View > and make sure that ‘Hide extensions for known file types’ is UNCHECKED. This is to ensure that file extensions are visible (such as Prophet.exe, CO2.exe, etc.); NO file should have double extensions.
- (4) Now double click on Prophet.exe; a small black Prophet/ DOS window should open.
- (5) Now RIGHT click on top blue strip of that small black Prophet/ DOS window > Defaults > and make sure that under Edit Options, QuickEdit Mode is UNCHECKED. If you had to UNCHECK it, then it is a good idea to restart the computer before running prophet.
- (6) Now click on File (on top of that small black Prophet/ DOS window) > Read > Open one of the .SAV files (such as May51245.SAV) > click on ‘Do It’ at bottom of that small black Prophet/ DOS window to run CO2.exe > check output in four (output, labelout, indata, and digitout) files in the Prophet folder.
- (7) Now click on File (on top of that small black Prophet/ DOS window) again > Read > Open one of the .SAV files (such as May51245.SAV) > modify that file as necessary (and put the new file name in the Project Title under Options) > SAVE the modified file (with the new file name) > Open the new modified and saved file, and click on ‘DO It’ to run CO2.exe > check output in four (output, labelout, indata, and digitout) files in the Prophet folder.
- (8) Repeat step (7) to investigate different scenarios.
