

INVOICE

Charlie Melnarik
159 Kendra Way, Hamilton, MT 59840
(406) 360-6324

Invoice #: 2025000009
Date: December 24, 2025
Date In: August 20, 2025

BILL TO

Judy Banks

JOB DETAILS

Vehicle: 2007 Volvo XC90
Rate/Hour: \$65.00
Total Hours: 3.5 hrs

Labor

Description	Time	Line Total
Leak detection	2.5 hrs	\$162.50
Leak correction	1 hrs	\$65.00

Parts

Part	Price
NA	

NOTES

Passenger side floor water leak found and corrected.
Leak was from A/C accumulator condensation in blower motor housing.
Drain in housing was plugged with gunk.
Blower motor housing would fill with water and eventually spill over into the cabin air filter housing above the passenger side floor.
This is why there wasn't water pooling on floor until driven for a couple hours with A/C running.
Condensation now drains as it should to the outside of the vehicle.

SUMMARY

Parts: \$0.00
Labor: \$227.50
Supplies: \$15.00

Total: \$242.50
Paid: \$242.50

AMOUNT DUE: \$0.00