

INVOICE

Charlie Melnarik
159 Kendra Way, Hamilton, MT 59840
(406) 360-6324

Invoice #: 2025000014
Date: December 24, 2025
Date In: November 19, 2025

BILL TO

Ryley Conner

JOB DETAILS

Vehicle: 2013 Toyota Tacoma V6
Rate/Hour: \$75.00
Total Hours: 26.5 hrs

Labor

Description	Time	Line Total
Blown Engine Removed and Replaced With Power Engines Reman Engine	16 hrs	\$1,200.00
New Engine Removed. Timing cover Removed and Resealed.	10 hrs	\$750.00
Engine Reinstalled		
Checked and Topped off Vehicle Fluids	0.5 hrs	\$37.50

Parts

Part	Price
Napa Gold Oil Filter	\$10.18
5w-30 Oil	\$32.48
Felpro Gasket 35767 (2)	\$6.58
Murray K070834 Serpentine Belt	\$38.99
Denso 3381 Spark Plug (6)	\$47.94
Duralast 1741 Knock Sensor Pigtail	\$36.99
Felpro MS96671 Intake Manifold Gasket	\$43.99
Felpro 35781 Water Pump Gasket	\$23.99
Felpro MS96913 Exhaust Manifold Gasket	\$13.19
Peak OET Asian Antifreeze 1 Gal (3)	\$59.97
STP Sa9683 Engine Air Filter	\$21.99
75w-90 Differential Fluid	\$18.99

NOTES

Engine swapped with Power Engines reman engine
Passenger side valve cover swapped (different style)
Repaired knock sensor wiring harness chewed up from mice
Timing cover coolant leaks detected after install
Removal of engine to repair timing cover leaks necessary to repair leak correctly

SUMMARY

Parts:	\$355.28
Labor:	\$1,987.50
Supplies:	\$0.00
Total:	\$2,342.78
Paid:	\$2,342.78

AMOUNT DUE: \$0.00

Thank you for your business.