





FIXTURE	PART NUMBER	DESCRIPTION	вом
COLORADOPXLCURVE12	PTH030100004238	LED PCB LJB130 (BOM#1)	1
COLORADOPXLCURVE12	PTH030100004236	LED PCB LJB130 (BOM#2)	2
COLORADOPXLCURVE12	PTH030100004235	LED PCB LJB130 (BOM#3)	3
COLORADOPXLCURVE12	PTH030100004234	LED PCB LJB130 (BOM#4)	4
COLORADOPXLCURVE12	PTH030100004233	LED PCB LJB129 (BOM#5)	5
COLORADOPXLCURVE12	PTH030100004232	LED PCB LJB129 (BOM#6)	6
COLORADOPXLCURVE12	PTH030100004231	LED PCB LJB129 (BOM#7)	7
COLORADOPXLCURVE12	PTH030100004230	LED PCB LJB129 (BOM#8)	8
COLORADOPXLCURVE12	PTH030100004229	LED PCB LJB128 (BOM#9)	9
COLORADOPXLCURVE12	PTH030100004228	LED PCB LJB128 (BOM#10)	10
COLORADOPXLCURVE12	PTH030100004227	LED PCB LJB128 (BOM#11)	11
COLORADOPXLCURVE12	PTH030100004226	LED PCB LJB128 (BOM#12)	12
COLORADOPXLCURVE12	PTH010504000268	arm connection blockD08 (BOM#13)	13
COLORADOPXLCURVE12	PTH070100011513	arm wiring coverC03 (BOM#14)	14
COLORADOPXLCURVE12	PTH010101012640	arm press boardA07 (BOM#15)	15
COLORADOPXLCURVE12	PTH070100004823	arm cover gasketC06 (BOM#16)	16
COLORADOPXLCURVE12	PTH010101012736	wire press boardA13 (BOM#17)	17
COLORADOPXLCURVE12	PTH010101012730	switch blockerA08 (BOM#18)	18
COLORADOPXLCURVE12	PTH070100004821	arm gasketC05 (BOM#19)	19
COLORADOPXLCURVE12	PTH070100004821	arm bracket 1D06 (BOM#20)	20
	PTH010304000239		21
COLORADOPXLCURVE12		arm bracket 2D07 (BOM#21)	22
COLORADOPXI CURVE12	PTH010504000230	front coverD05 (BOM#22)	23
COLORADOPXLCURVE12	PTH070200011913	head gasket (BOM#23)	
COLORADOPXLCURVE12	PTH010101012499	glass board (BOM#24)	24 25
COLORADOPXLCURVE12	PTH050102011678	lens SD02-80*69H32 (BOM#25)	
COLORADOPXLCURVE12	PTH010102015234	light shieldA12 (BOM#26)	26
COLORADOPXLCURVE12	PTH010201000175	focus press ring IW-1220BAR-B13 (BOM#27)	27
COLORADOPXLCURVE12	PTH010201010525	focus holderB01 (BOM#28)	28
COLORADOPXLCURVE12	PTH010203005839	slider coverB02 (BOM#29)	29
COLORADOPXLCURVE12	PTH010201010480	tilt bushing 2BZ04 (BOM#30)	30
COLORADOPXLCURVE12	PTH070200011796	yoke oil seal TC 27*35*5 (BOM#31)	31
COLORADOPXLCURVE12	PTH010203005833	tilt axis 2BZ03 (BOM#32)	32
COLORADOPXLCURVE12	PTH070200011892	O ring D28*2MM (BOM#33)	33
COLORADOPXLCURVE12	PTH120102000107	M3*14 Screw	33
COLORADOPXLCURVE12	PTH070200011821	O ring D50*2.0MM (BOM#34)	34
COLORADOPXLCURVE12	PTH110100000007	bearing 6804ZZ (BOM#35)	35
COLORADOPXLCURVE12	PTH120305010767	axis circlip 19*1 (BOM#36)	36
COLORADOPXLCURVE12	PTH010201010499	bearing press ringB03 (BOM#37)	37
COLORADOPXLCURVE12	PTH010203005842	sliderB06 (BOM#38)	38
COLORADOPXLCURVE12	PTH210200013887	light guide assembly CD-FA-02-A-05 (BOM#39)	39
COLORADOPXLCURVE12	PTH010201010478	head front coverD01 (BOM#40)	40
COLORADOPXLCURVE12	PTH210200013981	tilt motor (BOM#41)	41
COLORADOPXLCURVE12	PTH070100004816	back cover gasketC01 (BOM#42)	42
COLORADOPXLCURVE12	PTH010504000229	motor coverD02 (BOM#43)	43
COLORADOPXLCURVE12	PTH010101012735	optocoupler bracketA14 (BOM#44)	44
COLORADOPXLCURVE12	PTH030100003661	optocoupler sensor GD009 (BOM#45)	45
COLORADOPXLCURVE12	PTH120600000001	dial 0.5mm (BOM#46)	46
COLORADOPXLCURVE12	PTH010203006227	gear DL-316-06 (BOM#47)	47
COLORADOPXLCURVE12	PTH010203005957	PCB postB07 (BOM#48)	48
COLORADOPXLCURVE12	PTH010302000040	standoff H5*7+6 (BOM#49)	49
COLORADOPXLCURVE12	PTH010101012494	focus motor bracketA05 (BOM#50)	50

201 00 10 00 11 01 10 15 10	DT.104000040000	. (2014)54)	1
COLORADOPXLCURVE12	PTH210200013982	zoom motor (BOM#51)	51
COLORADOPXLCURVE12	PTH110100004337	bearing 6903ZZ (BOM#52)	52
COLORADOPXLCURVE12	PTH070200011893	yoke oil seal TC 22*28*4 (BOM#53)	53
COLORADOPXLCURVE12	PTH010201010479	tilt bushing 1BZ02 (BOM#54)	54
COLORADOPXLCURVE12	PTH010203005835	tilt axis 1BZ01 (BOM#55)	55
COLORADOPXLCURVE12	PTH070200000024	O ring D44*2.4MM (BOM#56)	56
COLORADOPXLCURVE12	PTH090200004202	belt 3M-222-5mm (BOM#57)	57
COLORADOPXLCURVE12	PTH120305010765	barrier ring 30*1.2 (BOM#58)	58
COLORADOPXLCURVE12	PTH010203005826	gear DL-342-01 (BOM#59)	59
COLORADOPXLCURVE12	PTH150200000002	wire clip B1251 (BOM#60)	60
COLORADOPXLCURVE12	PTH010101012743	lens fix boardA04 (BOM#61)	61
COLORADOPXLCURVE12	PTH010201010498	lens front covrD03 (BOM#62)	62
COLORADOPXLCURVE12	PTH050101004292	glass 111*76*3 (BOM#63)	63
COLORADOPXLCURVE12	PTH080400000014	connector J5F2C-W-B-LY (BOM#64)	64
COLORADOPXLCURVE12	PTH080400000015	connector SE8FDYH-31-B (BOM#65)	65
COLORADOPXLCURVE12	PTH080500000016	connector CNAC-MPX-LY (BOM#66)	66
COLORADOPXLCURVE12	PTH010201010184	PSU base 1 (BOM#67)	67
COLORADOPXLCURVE12	PTH010102000409	Ethernet connector pad IP-2W-A01-18 (BOM#68)	68
COLORADOPXLCURVE12	PTH070200011859	PSU base gasket SW-3WBAR-C12 (BOM#69)	69
COLORADOPXLCURVE12	PTH010203006152	lock sliderB11 (BOM#70)	70
COLORADOPXLCURVE12	PTH010504000271	lock sliding blockD11 (BOM#71)	71
COLORADOPXLCURVE12	PTH120105000006	set screw M5*6 (BOM#72)	72
COLORADOPXLCURVE12	PTH010203006222	axisB10 (BOM#73)	73
COLORADOPXLCURVE12	PTH120202000007	nut M15*1*5*19 (BOM#74)	74
COLORADOPXLCURVE12	PTH010504000263	handleD09 (BOM#75)	75
COLORADOPXLCURVE12	PTH070200000012	fuse cap IP-2W-C18 (BOM#76)	76
COLORADOPXLCURVE12	PTH080500000013	connector SAC3MPX-LY (BOM#77)	77
COLORADOPXLCURVE12	PTH210200013526	fuse holder FH15-22A (BOM#78)	78
COLORADOPXLCURVE12	PTH021000010961	fuse F12A (BOM#79)	79
COLORADOPXLCURVE12	PTH010101012738	safety buckleA09 (BOM#80)	80
COLORADOPXLCURVE12	PTH080500000014	connector SAC3FPX-LY (BOM#81)	81
COLORADOPXLCURVE12	PTH080500000027	USB-C connector SCCMCDF-01 (BOM#82)	82
COLORADOPXLCURVE12	PTH070200011814	valve VV-P465-00-KS1 (BOM#83)	83
COLORADOPXLCURVE12	PTH080500000017	connector CNAC-FPX-LY (BOM#84)	84
COLORADOPXLCURVE12	PTH010102012834	USB press board IP-1W-A01-05 (BOM#85)	85
COLORADOPXLCURVE12	PTH010201010185	PSU base 2-800BAR-B19 (BOM#86)	86
COLORADOPXLCURVE12	PTH080400000013	lordash	87
COLORADOPXLCURVE12	PTH010504000264	side cover boardD10 (BOM#88)	88
COLORADOPXLCURVE12	PTH070100004820	side cover gasketC04 (BOM#89)	89
COLORADOPXLCURVE12	PTH010201010505	base aluminum coverB09 (BOM#90)	90
COLORADOPXLCURVE12	PTH010102015478	switch board fix bracketA15 (BOM#91)	91
COLORADOPXLCURVE12	PTH030100000282	switch PCB ZJ050 (BOM#92)	92
COLORADOPXLCURVE12	PTH030100004369	switch PCB ZJ077 (BOM#93)	93
COLORADOPXLCURVE12	PTH010101011120	base fan bracket-800BAR-A03 (BOM#94)	94
COLORADOPXLCURVE12	PTH210200014078	fan (BOM#95)	95
COLORADOPXLCURVE12	PTH150600000003	fan mesh 6*6 (BOM#96)	96
COLORADOPXLCURVE12	PTH040301010870	PSU H24-UP500S+32 (BOM#97)	97
COLORADOPXLCURVE12	PTH010102016694	blockerA17 (BOM#98)	98
COLORADOPXLCURVE12	PTH210200014079	fan (BOM#99)	99
COLORADOPXLCURVE12	PTH030100004370	switch PCB ZJ077 (BOM#100)	100
COLORADOPXLCURVE12	PTH010102015476	switch board fix bracketA16 (BOM#101)	101
COLORADOPXLCURVE12	PTH021800000002	battery 14430, wire length 17cm (BOM#102)	102
COLONADOI ALCONVLIZ	111021000000002	Dates y 17730, with length 17th (BOIVI#102)	102

COLORADOPXLCURVE12	PTH010101000235	battery press plate IB-5R-A01-07 (BOM#103)	103
COLORADOPXLCURVE12	PTH010504000184	quick lock IP cover IP-1W-B12 (BOM#104)	104
COLORADOPXLCURVE12	PTH120500000017	nut M22 (BOM#105)	105
COLORADOPXLCURVE12	PTH070200011846	quick lock gasket IP-1W-C09 (BOM#106)	106
COLORADOPXLCURVE12	PTH070200000040	machine foot φ15*8 (BOM#107)	107
COLORADOPXLCURVE12	PTH010203004764	mat cover IP-1W-B13 (BOM#108)	108
COLORADOPXLCURVE12	PTH070200011751	O ring 6*1.5 (BOM#109)	109
COLORADOPXLCURVE12	PTH210200012120	Omega Hanging bracket CD-D08 (BOM#110)	110
COLORADOPXLCURVE12	PTH030100004372	display PCB board C-1250 LED BAR (BOM#111)	111
COLORADOPXLCURVE12	PTH010101011195	display press board IP-1W-A01-02 (BOM#112)	112
COLORADOPXLCURVE12	PTH070100004389	display cover board-800BAR-C11 (BOM#113)	113
COLORADOPXLCURVE12	PTH070200011643	display gasket SW-3WBAR-C08 (BOM#114)	114
COLORADOPXLCURVE12	PTH070200011856	front cover gasket SW-3WBAR-C05 (BOM#115)	115
COLORADOPXLCURVE12	PTH010201010171	display front cover-800BAR-B06 (BOM#116)	116
COLORADOPXLCURVE12	PTH021300005381	magnetic filter A2 FYP 16*16*8-MB (BOM#117)	117
COLORADOPXLCURVE12	PTH210200014576	Complete Head Assembly 1 with glass and screws	
COLORADOPXLCURVE12	PTH210200014577	Complete Head Assembly 2 with glass and screws	
COLORADOPXLCURVE12	PTH210200014578	Complete Head Assembly 3 with glass and screws	
COLORADOPXLCURVE12	PTH210200014579	Complete Head Assembly 4 with glass and screws	
COLORADOPXLCURVE12	PTH210200014580	Complete Head Assembly 5 with glass and screws	
COLORADOPXLCURVE12	PTH210200014581	Complete Head Assembly 6 with glass and screws	
COLORADOPXLCURVE12	PTH210200014582	Complete Head Assembly 7 with glass and screws	
COLORADOPXLCURVE12	PTH210200014583	Complete Head Assembly 8 with glass and screws	
COLORADOPXLCURVE12	PTH210200014584	Complete Head Assembly 9 with glass and screws	
COLORADOPXLCURVE12	PTH210200014585	Complete Head Assembly 10 with glass and screws	
COLORADOPXLCURVE12	PTH210200014586	Complete Head Assembly 11 with glass and screws	
COLORADOPXLCURVE12	PTH210200014587	Complete Head Assembly 12 with glass and screws	
COLORADOPXLCURVE12	PTH210200014591	Complete Head + Arm Assembly 1	
COLORADOPXLCURVE12	PTH210200014592	Complete Head + Arm Assembly 2	
COLORADOPXLCURVE12	PTH210200014593	Complete Head + Arm Assembly 3	
COLORADOPXLCURVE12	PTH210200014594	Complete Head + Arm Assembly 4	
COLORADOPXLCURVE12	PTH210200014595	Complete Head + Arm Assembly 5	
COLORADOPXLCURVE12	PTH210200014596	Complete Head + Arm Assembly 6	
COLORADOPXLCURVE12	PTH210200014597	Complete Head + Arm Assembly 7	
COLORADOPXLCURVE12	PTH210200014598	Complete Head + Arm Assembly 8	
COLORADOPXLCURVE12	PTH210200014599	Complete Head + Arm Assembly 9	
COLORADOPXLCURVE12	PTH210200014600	Complete Head + Arm Assembly 10	
COLORADOPXLCURVE12	PTH210200014601	Complete Head + Arm Assembly 11	
COLORADOPXLCURVE12	PTH210200014602	Complete Head + Arm Assembly 12	