

Figure 1: Raw Signal Data

- 1 Data
- 2 PCA
- 2.1 Truncated Transient, Waves as Samples
- 3 Factor Analysis
- 3.1 Truncated Transient, Waves as Samples
- 4 References




Figure 2: Truncated Raw Signal Data (aligned at red points)





Figure 3: Signal Mean (black) from samples (blue)






Figure 4: Centered Signals




Figure 5:




Figure 6: Principal Modes 1,2,3 (rows) for two datasets (columns)




Figure 7: Explained Variance Ratio




Figure 8: Factor Analysis time-dependent noise variance (red and green) by




Figure 9: Factor Analysis procures Bounds by determined time-dependent noise variance (red and green) by