
SID(VECTOR) EDMONTON INTL THREE DEP (CYEG 3.)



DEPARTURE ROUTE DESCRIPTION

Rwys 02, 20, & 30: 1. Climb rwy hdg for vectors to assigned route or depicted fix.

2. Maintain 7000' ASL or flight planned altitude, whichever is lower.

Rwy 12: 1. Climb on track 118° via "LEDUC" NDB for vectors.

2. Maintain 7000' ASL or flight planned altitude, whichever is lower.

3. TURBO-JET/TURBO-FAN aircraft no right turns before passing "LEDUC" NDB.

NOTE: Refer to Noise Abatement Procedures for additional requirements.

COMMUNICATION FAILURE

On recognition of failure 10 minutes or less after take-off and in IFR weather conditions, proceed as follows:

- 1. Transponder 7600;
- 2. Upon reaching last assigned altitude proceed directly on course:
- 3. Maintain last assigned altitude for 10 minutes after take-off; then,
- 4. Climb to flight planned altitude.

NOTE: If communication failure occurs more than 10 minutes after take-off, comply with the appropriate procedure for communication failure enroute.

NOISE ABATEMENT PROCEDURES

TURBO JET/TURBO FAN

DEPARTURE PROCEDURES

RWY	VNAP
ALL RWYS	A or B

Rwy 12 - Turbo-jet/Turbo-fan aircraft. No right turns west of the "LEDUC" NDB.

ARRIVAL PROCEDURES - VFR AND VISUAL APPROACH

- 1. Avoid flying over the town of Leduc below 5000' ASL.
- 2. Runway 30 right hand circuits.

Source of Canadian Civil Aeronautical Data : © 2008 NAV CANADA All rights reserved