
JEPPESEN

JeppView 3.5.2.0



CHANGES: New chart.


© JEPPESEN SANDERSON, INC., 2007. ALL RIGHTS RESERVED.

Licensed to Elefant air. Printed on 15 Jun 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 05-2008

JEPPES EN


JeppView 3.5.2.0



LA PALMA, CANARY IS **%**JEPPESEN GCLA/SPC LA PALMA (10-3) Eff 7 Jul 1 JUL 05 Apt Elev Trans level: By ATC Trans alt: 6000' 107' 10,000' BIMBO ONE TANGO (BIMBO 1T) [BIMB1T] BIMBO ONE UNIFORM (BIMBO 1U) [BIMB1U] 8500' GRAN CANARIA ONE TANGO (LPC 1T) MSA BX NDB GRAN CANARIA ONE UNIFORM (LPC 1U) RWYS 01, 19 DEPARTURES ▲ N31 25.3 W016 02.0 KASAS N29 59.2 △ W015 46.1 N28 49.6 W017 26.4 BIMBO 1T LPC 1T **ARTEM** N28 24.5 W016 02.0 TENERIFE-- NORTH -GRAN CANARIA **BIMBO 1U** 117.7 TFN 112.9 GDV N28 04.6 W015 25.7 389 BX GRAN CANARIA N28 36.1 W017 45.4 P115.0 LPC NOT TO SCALE Initial ATC clearance: Maintain FL90 and await further clearance. ROUTING SID RWY BIMBO 1T 01 Turn RIGHT visually in accordance with aerodrome traffic circuit, intercept 058° bearing from BX, intercept TFN R-293 inbound to TFN, TFN R-023 to KASAS, turn LEFT, intercept GDV R-357 to BIMBO. BIMBO 1U 19 058° bearing from BX, intercept TFN R-293 inbound to TFN, TFN R-023 to KASAS, turn LEFT, intercept GDV R-357 to BIMBO LPC 1T Turn RIGHT visually in accordance with aerodrome traffic circuit, intercept 058° bearing from BX, intercept TFN R-293 inbound to TFN, TFN R-128 via ARTEM to GDV, GDV R-187 to LPC. LPC 1U Turn LEFT visually in accordance with aerodrome traffic circuit, intercept 058° bearing from BX, intercept TFN R-293 inbound to TFN, TFN R-128 via

Licensed to Elefant air. Printed on 15 Jun 2008.
NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 05-2008

JEPPESEN *JeppView 3.5.2.0* 



ARTEM to GDV, GDV R-187 to LPC.

JEPPESEN JeppView 3.5.2.0

LA PALMA, CANARY IS **M**JEPPESEN GCLA/SPC LA PALMA 1 JUL 05 (10-3B) Eff 7 Jul Apt Elev Trans level: By ATC Trans alt: 6000' 107' ORION ONE TANGO (ORION 1T) [ORIO17] ORION ONE UNIFORM (ORION 1U)[ORIO1U] SAMAR TWO TANGO (SAMAR 2T) [SAMA2T] SAMAR TWO UNIFORM (SAMAR 2U)/SAMA2U] RWYS 01, 19 DEPARTURES **KASAS** W015 46.1 49.6 26.4 N28 V017 ORION 1T SAMAR 2T SAMAR 2T ORION SAMAR

© JEPPESEN SANDERSON, INC., 2002,

CHANGES: La Palma NDB ident

JEPPESEN Licensed to Elefant air. Printed on 15 Jun 2008. JeppView 3.5.2.0 NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 05-2008

**∏**JEPPESEN LA PALMA, CANARY IS GCLA/SPC 1 JUL 05 (10-3C) Eff 7 Jul LA PALMA Apt Elev Trans level: By ATC Trans alt: 6000 107' 10,000' TENERIFE NORTH ONE TANGO (TFN 1T) TENERIFE NORTH ONE UNIFORM (TFN 1U) TENERIFE SOUTH ONE TANGO (TFS 1T) BX NDB TENERIFE SOUTH ONE UNIFORM (TFS 1U) RWYS 01, 19 DEPARTURES TFN 1T TENERIFE-NORTH— 117.7 TFN LA PALMA N28 32.2 W016 16. 389 BX N28 36.1 W017 45.4 At or above FL80 TENERIFE -- SOUTH -D 116.4 TFS N28 00.1 W016 41.3 NOT TO SCALE Initial ATC clearance: Maintain FL90 and await further clearance SID RWY ROUTING TFN 1T Turn RIGHT visually in accordance with aerodrome traffic circuit, intercept 058° bearing from BX, intercept TFN R-293 inbound to TFN Turn LEFT visually in accordance with aerodrome traffic circuit, intercept TFN 1U 058° bearing from BX, intercept TFN R-293 inbound to TFN TFS 1T Turn RIGHT visually in accordance with aerodrome traffic circuit, intercept TFS 1U

CHANGES: La Palma NDB ident.

TFS R-310 inbound to TFS.

© JEPPESEN SANDERSON, INC., 2002, 2005. ALL RIGHTS RESERVED.

Turn LEFT visually in accordance with aerodrome traffic circuit, intercept

Licensed to Elefant air. Printed on 15 Jun 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 05-2008

JEPPIES EN

JeppView 3.5.2.0

LA PALMA, CANARY IS **%**JEPPESEN GCLA/SPC LA PALMA 7 APR 06 (10-3D) Eff 13 Apr Apt Elev Trans level: By ATC Trans alt: 6000' 107 VASTO ONE TANGO (VASTO 1T)/VASTIT/ VASTO ONE UNIFORM (VASTO 1U)/VAST1U] ,000 RWYS 01, 19 DEPARTURES **VASTO**N30 30.6 W013 34.4 **SARAY** 45.5 W014 09.4 fic circuit, intercept TEN, TEN R-082 to VASTO. and await further ATC clearance: Maintain Turn RIGHT v 058° bearing t LARYS, turn L Turn LEFT vis 058° bearing t LARYS, turn L /ASTO 1T 389 BX 36.1 W017 SID VASTO

© JEPPESEN SANDERSON, INC., 2006. ALL RIGHTS RESERVED.

CHANGES: New procedures at this airport

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 05-2008

Licensed to Elefant air. Printed on 15 Jun 2008.

JEPPESEN

JeppView 3.5.2.0

GCLA/SPC Apt Elev 107' MJEPPESEN LA PALMA, CANARY IS 25 NOV 05 (10-9) LA PALMA N28 37.6 W017 45.3 LA PALMA Ground \*Tower 121.8 118.9 17-45.4 17-45.2 17-46 17-45 28-37.4 - 28-38 AIS WET CAUTION: Due to reduced dimensions of the apron, all operations on this area 2 must be executed with the minimum power TMNL 18 engine rating possible. If acft requires to increase significantly power/trust while parking at positions 1 and 5, captain must coordinate with ATC. LEGEND All jet acft must accomplish back-track Northeast 2200m by turning right at the end of the runway. Southeast Aviation Once cleared to taxi, the acft will have to start taxiing in less than 60 seconds, otherwise the authorization will be 17-44 cancelled. Area of magnetic abnormality. Birds. AIS + MET Rwy 01 right-hand circuit. PARKING POSITIONS COORDINATES - 28-37 N28 37.2 W017 45.2 28-37 1 thru 3 103' • N28 37.3 W017 45.2 N28 37.4 W017 45.2 17-46 17-45 17-44 ADDITIONAL RUNWAY INFORMATION
USABLE LENGTHS
LANDING BEYOND RWY Threshold Glide Slope TAKE-OFF WIDTH HIRL (50m) CL (15m) ALS REIL PAPI (3.0°) 19 HIRL (50m) CL (15m) REIL PAPI (3.0°) PREFERENTIAL RUNWAY SYSTEM: Whenever tail wind component does not exceed 10 KT and/or cross wind 25 KT, use rwy 01. JAR-OPS TAKE-OFF All Rwys LVP must be in Force RCLM (DAY only) RCLM (DAY only) RL & CL or RL (DAY only) 200m 250m 400m 500m 250m 300m ■ Operators applying U.S. Ops Specs: CL required below 300m.

JEPPESEN
JeppView 3.5.2.0

GCLA/SPC

# MJEPPESEN LA PALMA, CANARY IS

25 NOV 05 (10-9A) LA PALMA

## LOW VISIBILITY PROCEDURES (LVP)

### **GENERAL**

LVP for ground will be applied when the following meteorological minimum established as follows:

- RVR to Rwy 01/19
- general VIS in the movement area is 500m or below.

TWR will inform pilots about application of LVP.

#### **GROUND MOVEMENT**

Pilots will proceed to verify at every moment the aircraft position, checking that taxiing is being executed under total safety conditions. In case of being disoriented or in doubt, pilots will stop aircraft and immediately notify TWR.

### **ARRIVALS**

Aircraft, that have already landed, will notify:

- Rwy vacated and
- Twy used.

At the apron entry, they must wait for the arrival of a "FOLLOW ME" vehicle, in order to be guided to the assigned stand.

## **DEPARTURES**

Pilots will avoid requesting clearance for starting-up, push-back or taxiing when the RVR values or the meteorological visibility are below their operational minimum. When the RVR/VIS is lower than 500m, the movement of only one aircraft at the same time will be authorized in the manoeuvring area.

### MINIMUM RUNWAY OCCUPANCY TIME

Aircraft shall be able to initiate the take-off immediately after alignment with the corresponding runway centre line. Pilots unable to comply shall notify ATC before entering the runway to taxi.

## WIND PHENOMENA

Hillside wind generates strong turbulence in an area of up to 10 NM, within altitudes of 1000' to 1500'. It is produced for rwy 01 by wind direction btn 210° and 310°, with an intensity of 15 kts or more and QNH less than 1008 hPa. Additionally hillside wind can be found with QNH of 1000-1003 hPa with intensities less than 15 kts.

A strong windshear effect can be produced in short final position (of up to 50') with variations of direction and intensity of 10 kts and 10° btn the airport's anemometers. Under such circumstances, when wind direction is close to 330°, the effects of windshear and turbulence can appear to be combined. When the hillside wind has a direction of 210°-310° and an intensity higher

than 15 kts, an approach is not recommended. It is recommended that aircrews have a basic level of recent experience in the airport.

CHANGES: None.

© JEPPESEN SANDERSON, INC., 2004, 2005. ALL RIGHTS RESERVED.

Licensed to Elefant air. Printed on 15 Jun 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 05-2008

JEPPESEN JeppView 3.5.2.0

