
#### Effective 0901Z 20 NOVEMBER 2008 to 0901Z 15 JANUARY 2009 STAR (RNAV) FUNDY SIX ARR (CETTY, FUNDY 6) 236.6 275.8 225.2 229.1 118.4 121.9 119.2 W63 18.10 V44 47.14 HALIFAX TWR HALIFAX GND (FACF) VOKIL 3400 N45 01.48 W63 22.18 LEROS (FACF) ATIS 3100 ARR



W63 46.06 N44 55.00

> VV. .00

N44 46.79 W63 45.27 HOROW

MODIR

112°. (13.8)

If RNAV STAR includes a DTW, the following procedures apply. If approach clearance is NOT RECEIVED prior to DTW ALL ALTITUDES WILL BE ISSUED BY ATC 0.17) (0.17) If approach clearance RECEIVED prior to DTW - Fly RNAV STAR via DTW, then Fly the STRAIGHT-IN approach W64 05.48 N44 55.56 Expect radar vectors to final CETTY - Via FACF then

HALIFAX NS HALIFAX/STANFIELD INTL

Chart not to scale


Source of Canadian Civil Aeronautical Data: © 2008 NAV CANADA All rights reserved

STAR (RNAV)
LISCOM SIX ARR (IGTAS. LISCM 6) HALIFAX NS If RNAV STAR includes a DTW, the following procedures apply. 236.6 275.8 225.2 229.1 If approach clearance is NOT RECEIVED prior to DTW ALL ALTITUDES WILL BE ISSUED BY ATC 118.4 121.9 119.2 If approach clearance RECEIVED prior to DTW HALIFAX TWR HALIFAX GND 145 04.84 W62 59.61 IGTAS Fly the STRAIGHT-IN approach - Fly RNAV STAR via DTW, then - Fly depicted heading •••  $\bot$ Expect radar vectors to final ARR 6: - Via FACF, then (16.4) (\$. N44 51.22 W63 14.04 GABAP V63 18.10 V44 47.14 (FACF) VOKIL 3400 145 01.48 W63 22.18 LEROŚ **RWY 23** 3100 N44 47.02 W63 25.30 GOLKE 278°. (6.9) Max 200 kt W63 33.78 N44 41.06 (S) OBNOM (DTW) 4400 00/2/2 N45 00.05 W63 31.67 TIDON 4200 Max 200 kt 145 03.19 W63 37.99 GVOP (MLQ) Chart not to scale N44 43.93 W63 39.52 (FACF) ODKAŚ 3400 N44 59.09 W63 42.03 (FACF) TETAR 3200

LISCOM SIX ARR (IGTAS. LISCM 6)

HALIFAX NS HALIFAX/STANFIELD INTL

Source of Canadian Civil Aeronautical Data: © 2008 NAV CANADA All rights reserved



### HALIFAX/STANFIFLD INTL HALIFAX NS

LOC or NDB RWY 05 (GNSS)

ATIS TWR GND DEP 477 **ELEV** 121.0 119.2 121.9 118.4 119.2 TDZE 05 462 229.1 225.2 236.6 275.8 225.2 CYHZ LOC ONLY **URMIN BLUENOSE** N45 00.13 NO GLIDE PATH 385 ZNS 🚃 🖫 R-307 W63 47.11 5.7 DME Ch 28 Common LOC frequency Rwys 05 & 23. Verify LOC ident for this approach N. W. 2200 RW05 . 24°° N44 52.12 My HALIFAX W63 31.46 115.1 YHZ .... DME Ch 98 SPLIT CROW LOCALIZER 109.9 6.3 DME IGX ≝... Ch 28 **DME 109.1** IHZ ... Ch 28 **XOMRO** No PT N44 42.93 1700 W63 40.38 IF ODKAS 11.5 DME Ch 28 N44 43.93 MSA ZHZ 25NA W63 39.52 CYR SURFACE TO 1500 2200 1800 OCSL BY NOTAM ENROUTE FACILITIES SAFE ALT 100 NM 2800 MISSED APPROACH TDZL Rwy 23 "ZHZ" NDB Climb to 2200 on track of 054° to "ZNS" NDB. Rwy 32 down 0.55% 6.3 DME Ch 28 234 RW06 2200 1.5 DME 1700 Procedure turn RIGHT within 10 NM of "ZHZ" NDB CATEGORY Α LOC 740 (278)LOC/DME 960 (498)1 1/2 NDB 980 1080 054° 4.9 NM 980 CIRCLING (503)1 1/2 From "ZHZ" NDB (503)(603)"ZHZ" NDB to MAP 4.9 NM Knots 90 Min:Sec 4:12 3:16 2:40 2:16 1:58 LOC or NDB RWY 05 (GNSS) HALIFAX NS

EFF 30 AUG 07

CHANGE: A/D name


445251N 633031W

VAR 19°W

HALIFAX/STANFIELD INTL

NAD83 ◆

Source of Canadian Civil Aeronautical Data : © 2008 NAV CANADA All rights reserved



EFF 30 AUG 07

LOC(BC) RWY 32

CHANGE: A/D name

445251N 633031W

VAR 19°W

Knots

Min:Sec


3:31 2:44 2:14 1:54 1:38 HALIFAX NS HALIFAX/STANFIELD INTL

FAF to MAP 4.1 NM

90 110 130 150

### HALIFAX/STANFIFLD INTL

HALIFAX NS



EFF 30 AUG 07

CHANGE: A/D name

ILS/DMF or LOC RWY 14

445251N 633031W

VAR 19°W


Min:Sec

HALIFAX NS HALIFAX/STANFIELD INTL

3:56 3:04 2:30 2:07 1:50

Source of Canadian Civil Aeronautical Data: © 2008 NAV CANADA All rights reserved

### HALIFAX/STANFIELD INTL



EFF 30 AUG 07

CHANGE: A/D name


445251N 633031W

VAR 19°W

HALIFAX/STANFIELD INTL

NAD83 ◆

## HALIFAX/STANFIELD INTL



EFF 30 AUG 07

CHANGE: A/D name

445251N 633031W

VAR 19°W

HALIFAX/STANFIELD INTL

HALIFAX NS

**ATIS** 

121.0

229.1

POINT IN SPACE APPROACH.

Airport center 274° 7 NM from KEPTA. Proceed VFR to landing as directed by TWR.

COPTER VOR/DME 305°

ARR

119.2

225.2

274

**TWR** 

118.4

236.6

**HALIFAX** 115.1 YHZ -DME Ch 98

KEPTA

GND

121.9

275.8

**ROMRI** 

7 DME

N44 53.68

W63 14.56

MEKPI IF

10 DME

N44 52.95

W63 10.47


DEP

119.2

225.2

**ELEV** 

CYHZ



CHANGE: A/D name

Min:Sec

HALIFAX NS


ALTERNATE

"YHZ" VOR

CATEGORY

VOR/DME

SID(VECTOR) **HALIFAX THREE DEP** (CYHZ 3)



#### DEPARTURE ROUTE DESCRIPTION

ALL RUNWAYS:

- 1. Climb runway heading or as assigned for radar vectors.
- 2. Maintain 5000 ASL or as assigned.

COMMUNICATION FAILURE - TRANSPONDER MODE A/3 CODE 7600

On recognition of communication failure 10 minutes or less after take-off and in IFR weather conditions proceed as follows:


- 1. Upon reaching last assigned altitude proceed directly on course;
- 2. Maintain last assigned altitude for 10 minutes after take-off; then
- 3. Climb to flight planned altitude.

Note: If communication failure occurs more than 10 minutes after take-off, comply with the appropriate procedure for communication failure enroute.

### **CANADA AIR PILOT**


Effective 0901Z 20 NOVEMBER 2008 to 0901Z 15 JANUARY 2009

# HALIFAX/STANFIELD INTL



### **CANADA AIR PILOT**

Effective 0901Z 20 NOVEMBER 2008 to 0901Z 15 JANUARY 2009



HALIFAX/STANFIELD INTL

NAD83