Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

JEPPESEN

JeppView 3.5.2.0

MADEIRA, MADEIRA IS **¼** JEPPESEN LPMA/FNC 30 MAR 07 (10-1R) RADAR MINIMUM ALTITUDES MADEIRA Apt Elev Alt Set: hPa Trans level: By ATC Trans alt: 5000 192' 60NM 34-00 4000 2000 CONTOUR - 33-30 20NM - PORTO SANTO-3000 SNT VOR DME -PORTO SANTO PORTO SANTO-RADAR PST NDB - 33-00 Porto Santo - FUNCHAL-±6) 10' FUN VOR DME MAD NDB Madeira 8200 32-30 - 32-00 20 SANTA MARIA OCEANIC CTA (A)/LPPO FIR (G) CASABLANCA GMMM FIR (G) LISBON LPPC FIR (G) /CTA (C) UIR (G) /UTA (C) CANARIES GCCC FIR (A/E/G) /UIR (A/G)

CHANGES: Reissue.

© JEPPESEN SANDERSON, INC., 2007. ALL RIGHTS RESERVED.

Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

JEPPESEN JeppView 3.5.2.0

MADEIRA, MADEIRA IS # JEPPESEN LPMA/FNC 20 JUL 07 (10-2) MADEIŔA Apt Elev Alt Set: hPa 124.4 192' Trans level: By ATC Trans alt: 5000' BIMBO 3A [BIMB3A], MADAT 3A [MADA3A] 8200' 3500 NIKAV 3A [NIKA3A], SANTO 3A (SNT 3A) RWYS 05, 23 ARRIVALS MSA FUN VOR FOR SPECIAL PROCEDURES AND OPERATING LIMITATIONS SEE CHARTS 10-6 TO 10-6B Clearance limit is ABUSU at 3000'. N33 20.9 W016 52.4 PORTO SANTO D 114.9 SNT N33 05.4 W016 21.0 **D9 SNT** N33 10.0 W016 30.3 ZMMOD TZOL
ZMMOD TZOL
ZMMOD TZOL ALTERNATE HOLDING To be used in case of communication failure. N33 03.0 W017 08.6 **D9 SNT** N33 03.2 FL100_ LOST COMMS LOST COMMS LOST COMMS **ABUSU** N32 52.0 W016 38.1 - FUNCHAL -[□]112.2 FUN N32 44.8 W016 42.3 FUSUL N32 36.1 W016 39.7 NOT TO SCALE △ MADAT **BIMBO** N31 25.3 W016 02.0

JEPPESEN Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 JeppView 3.5.2.0

MADEIRA, MADEIRA IS M JEPPESEN LPMA/FNC 20 JUL 07 (10-2A) RNAV STAR MADEIŔA Apt Elev Alt Set: hPa 124.4 192' Trans level: By ATC Trans alt: 5000 LIDRO 2A [LIDR2A] 8200' 3500 NIDUL 2A [NIDU2A] RWYS 05, 23 RNAV ARRIVALS MSA FUN VOR FOR SPECIAL PROCEDURES AND OPERATING LIMITATIONS SEE CHARTS 10-6 TO 10-6B **LIDRO** N33 40.1 W015 57.0 Clearance limit is ABUSU at 3000' IRSAN D9 SNT N33 10.0 W016 30.3 LOST COMMS LOST COMMS LOST COMMS ALTERNATE HOLDING To be used in case of communication failure. PORTO SANTO LOST COMMS LOST COMMS LOST COMMS 114.9 SNT N33 05.4 W016 21.0 ABÚSU N32 52.0 W016 38.1 FUNCHAL -112.2 FUN N32 44.8 W016 42.3 **NIDUL** W017 21.2 FL100 NIDUL 2A **XERON** N32 22.9 W016 56.6 NOT TO SCALE STAR ROUTING LIDRO 2A LIDRO - IRSAN - ABUSU NIDUL 2A NIDUL - XERON - FUN - ABUSU

CHANGES: XINGA INS coords. © JEPPESEN SANDERSON, INC., 2003, 2007. ALL RIGHTS RESERVED. Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

Apt Elev

192'

IRKID 3S 23

CHANGES: Procedure notes.

JEPPESEN JeppView 3.5.2.0

MADEIRA, MADEIRA IS

🖁 JEPPESEN LPMA/FNC з ост оз (10-3) MADEIRA

MADEIRA Approach Trans level: By ATC Trans alt: 5000' 1. Contact MADEIRA Approach immediately after take-off. 119.2 2. Pilots are advised to select full power on take-off in 119.6 the presence of turbulence or downdraft reports. 3. Take-off must be made in a minimum visibility of 2800m.


Required take-off alternate. 4. Each operator must prepare its own engine failure

procedures.



IRKID 3N [IRKI3N], IRKID 3S [IRKI3S] RWYS 05, 23 DEPARTURES

FOR SPECIAL PROCEDURES AND OPERATING LIMITATIONS SEE CHARTS 10-6 TO 10-6C



IRKID, do not overshoot FUN R-322 to the south.

339° track keeping FUN LEFT hand, above 3000' intercept FUN R-323 to

1500' turn LEFT.

Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 **JEPPESEN** JeppView 3.5.2.0

MADEIRA, MADEIRA IS # JEPPESEN LPMA/FNC 3 OCT 03 (10-3A) MADEIRA

MADEIRA Approach Trans level: By ATC Trans alt: 5000' 119.2 119.6

Apt Elev

192'

1. Contact MADEIRA Approach immediately after take-off. 2. Pilots are advised to select full power on take-off in

the presence of turbulence or downdraft reports. 3. Take-off must be made in a minimum visibility of 2800m.

Required take-off alternate. 4. Each operator must prepare its own engine failure procedures.



OUTSIDE THIS AREA


D11 FUN


N32 35.0 W016 48.2 After D11 FUN

or above 3500'

MADAT 3N [MADA3N], MADAT 3S [MADA3S] RWYS 05, 23 DEPARTURES

FOR SPECIAL PROCEDURES AND OPERATING LIMITATIONS SEE CHARTS 10-6 TO 10-6C





Immediately after take-off and at 100' minimum (50' when using QFE for threshold runway 23 or 250' using QNH) or at runway end, whichever comes first, turn LEFT. Keep to the LEFT of the coastline.

MADAT \triangle

N32 09.7 W017 05.1

Rwy 23: With westerly winds, tailwind shears may be expected. Anemometer readings reported by Tower at the end of the runway and at Rosario may indicate this possibility.

INITIAL CLIMB CLEARANCE FL60					
SID	RWY	ROUTING			
MADAT 3N	05	Intercept FUN R-214, after D11 FUN or above 3500' turn RIGHT, intercept FUN R-216 to MADAT.			
MADAT 3S	23	179° track, intercept FUN R-214, after D11 FUN or above 3500' intercept			

CHANGES: Procedure notes.

© JEPPESEN SANDERSON, INC., 2003. ALL RIGHTS RESERVED.

Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 JEPPESEN JeppView 3.5.2.0

LPMA/FNC MADEIRA

Apt Elev

192'

JEPPESEN 8 JUN 07 (10-3B)

MADEIRA, MADEIRA IS

Trans level: By ATC Trans alt: 5000' MADEIRA Approach 119.2


1. Contact MADEIRA Approach immediately after take-off. 2. Pilots are advised to select full power on take-off in the presence of turbulence or downdraft reports.

3. Take-off must be made in a minimum visibility of 2800m. Required take-off alternate.

4. Each operator must prepare its own engine failure procedures.



SANTO 3E (SNT 3E), SANTO 3F (SNT 3F) SANTO 3N (SNT 3N), SANTO 3S (SNT 3S)



Immediately after take-off and at 100' minimum (50' when using QFE for threshold runway 23 or 250' using QNH) or at runway end, whichever comes first, turn LEFT. Keep to the LEFT of the coastline

shears may be expected. Anemometer readings reported by Tower at the end of the runway and at Rosario may indicate this possibility.

Initial climb clearance FL60

SID	RWY	ROUTING
SNT 3E	05	088° track, after passing FUN R-179 (abeam FUN) and crossing FUN 4 DME and above 1500' intercept 039° bearing towards PST, intercept FUN R-081, intercept SNT R-183 inbound to SNT.
SNT 3F	23	078° track, after passing FUN R-169 (abeam FUN) or 1500′ intercept 039° bearing towards PST, keep beyond FUN 3 DME, intercept FUN R-083, intercept SNT R-183 inbound to SNT.
SNT 3N	05	088° track, after passing FUN R-179 (abeam FUN) and crossing FUN 4 DME and not below 1500′ intercept 039° bearing to PST, then to SNT.
SNT 3S	23	078° track, after passing FUN R-169 (abeam FUN) or 1500′ intercept 039° bearing to PST, keep beyond FUN 3 DME, then to SNT.

To be used pending traffic conditions and for traffic landing at LPPS. 2 Alternate for SNT 3S. To be used for landing at LPPS runway 36.

Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 **JEPPESEN** JeppView 3.5.2.0

MADEIRA, MADEIRA IS JEPPESEN LPMA/FNC 8 JUN 07 (10-3C) MADEIRA

MADEIRA Approach 119.2

Apt Elev

192'


Trans level: By ATC Trans alt: 5000'

- 1. Contact MADEIRA Approach immediately after take-off. 2. Pilots are advised to select full power on take-off in
- the presence of turbulence or downdraft reports. 3. Take-off must be made in a minimum visibility of 2800m. Required take-off alternate.
- 4. Each operator must prepare its own engine failure



TABOM 3N [TABO3N], TABOM 3S [TABO3S] RWYS 05, 23 DEPARTURES FOR SPECIAL PROCEDURES AND OPERATING LIMITATIONS SEE CHARTS 10-6 TO 10-6B

Immediately after take-off and at 100' minimum (150' when using QFE for threshold runway 05 or 300' using QNH) or at runway end, whichever comes first, turn RIGHT to avoid high ground on the LEFT side.



Rwy 23: With westerly winds, tailwind shears may be expected. Anemometer readings reported by

may indicate this possibility.

Tower at the end of the runway and at Rosario

Initial alimb algerance ELGO

Initial climb clearance FL60					
SID	RWY	ROUTING			
TABOM 3N	05	Intercept FUN R-164 to TABOM.			
TABOM 3S	23	148° track, intercept FUN R-164 to TABOM.			

CHANGES: None.

© JEPPESEN SANDERSON, INC., 2003. ALL RIGHTS RESERVED.

TABOMN32 13.5 W016 27.5 △

Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 JEPPESEN JeppView 3.5.2.0

LPMA/FNC MADEIŔA

Apt Elev

192'

IEPPESEN 8 JUN 07 (10-3D)

MADEIRA, MADEIRA IS RNAV SID

MADEIRA Approach 119.2


Trans level: By ATC Trans alt: 5000'

- 1. Contact MADEIRA Approach immediately after take-off. 2. Pilots are advised to select full power on take-off in the presence of turbulence or downdraft reports.
- 3. Take-off must be made in a minimum visibility of 2800m. Required take-off alternate.
- 4. Each operator must prepare its own engine failure



DEGUN 1N [DEGU1N], DEGUN 1S [DEGU1S] RWYS 05, 23 RNAV DEPARTURES

FOR SPECIAL PROCEDURES AND OPERATING LIMITATIONS SEE CHARTS 10-6 TO 10-6B



ROUTING

MABUT - POBAR - DEGUN

JEPPESEN Licensed to Elefant air. Printed on 06 Sep 2008. JeppView 3.5.2.0 NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

MADEIRA, MADEIRA IS M JEPPESEN LPMA/FNC (10-3E)8 JUN 07 RNAV SID MADEIŔA

MADEIRA Approach 119.2

Immediately after take-off and at

for threshold runway 23 or 250'

whichever comes first, turn LEFT.

Keep to the LEFT of the coastline

--274°

using QNH) or at runway end,

Apt Elev

192'

Trans level: By ATC Trans alt: 5000'


- 1. Contact MADEIRA Approach immediately after take-off. 2. Pilots are advised to select full power on take-off in the presence of turbulence or downdraft reports.
- 3. Take-off must be made in a minimum visibility of 2800m. Required take-off alternate.
- 4. Each operator must prepare its own engine failure



NIDUL 1N/NIDU1N], NIDUL 1S/NIDU1S]

RWYS 05, 23 RNAV DEPARTURES FOR SPECIAL PROCEDURES AND OPERATING LIMITATIONS SEE CHARTS 10-6 TO 10-6B

Immediately after take-off and at 100' minimum (150' when using QFE for threshold runway 05 or 300' using QNH) or at runway end, whichever comes first, turn RIGHT to avoid high ground on the LEFT side.



Rwy 23: With westerly winds, tailwind shears may be expected. Anemometer readings reported by Tower at the end of the runway and at Rosario may indicate this possibility.

Initial climb clearance FL100					
SID	RWY	ROUTING			
NIDUL 1N	05	Intercept FUN R-213, after D11 FUN or above 3500' turn RIGHT, intercept FUN R-215 to XERON, at XERON or at FL100, whichever is earlier, turn RIGHT to NIDUL.			
NIDUL 1S	23	178° track, intercept FUN R-213, after D11 FUN or above 3500' turn RIGHT, intercept FUN R-215 to XERON, at XERON or at FL100, whichever is earlier, turn RIGHT to NIDUL.			

CHANGES: Bearings.

NIDUL N32 21.9 W017 21.2

© JEPPESEN SANDERSON, INC., 2003, 2007. ALL RIGHTS RESERVED.

Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 JEPPESEN JeppView 3.5.2.0

MADEIRA

MADEIRA, MADEIRA IS

10-6 **AIRPORT BRIEFING**

" JEPPESEN

SPECIAL PROCEDURES AND OPERATING LIMITATIONS

11 JUL 03

OPERATING AT MADEIRA AIRPORT

- a) The airport is located on a plateau on the East coast of Madeira Island. Except for the seaside ground raises rapidly very closed to it. This fact generates, very often, wind variation and turbulence. Also severe low altitude wind shear conditions and/or microburst are likely to be encountered.
- b) STRAIGHT-IN APPROACHES NOT AUTHORIZED FROM FUNCHAL VOR TO RWY 23.

1. APPLICABILITY

LPMA/FNC

- a) The following items 2 thru 5 are mandatory to scheduled and non-scheduled revenue flights involving aircraft with a capacity in excess of 10 passengers.
- b) Pilots are informed that, at any time, they may be required to show evidence to Madeira airport authorities of compliance with referred items.

2. CREW REQUIREMENTS

a) Initial experience

To operate at Madeira airport, the Pilot-in-Command must have a minimum of 200 flying hours as captain on the concerned type of aircraft, before completing the initial training.

b) Recent experience

To operate at Madeira airport, the Pilot-in-Command must have performed there, on the last 6 months:

- one landing and take-off or,
- a flight simulator training comprising a landing and take-off on each runway, on a simulated adverse weather condition or,
- a line training flight to Madeira airport, comprising a landing and take-off, assisted by a qualified instructor occupying the right-hand seat.

3. MINIMUM TRAINING REQUIREMENTS

In order to operate at Madeira airport, the operator must establish and accomplish beforehand a training program concerning the type of aircraft to be used. This training, if performed on local flights, must include at least, landings and take-offs by day and night in both directions, emphasizing:

- the take-off flight path to runway 23;
- the take-off flight path to runway 05;
- the balked landing (go-around initiated in landing configuration from very low height) on both directions;
- the let-down and approach to both runways:
- the operational effect on runway slope and dimensions and associated safety

If the training is to be performed in a flight simulator, the following procedures must be included in the training program, for each runway:

- a) Take-off with engine failure after V1;
- b) Relight after engine failure;
- c) VOR approach;
- d) Balked landing and go-around;
- e) Visual approach;
- f) Landing:
- g) Weather conditions: Winds the maximums as indicated in Operating Procedures and Limitations paragraph 1.b. & 1.c. (see 10-6A & 10-6B), severe turbulence. Windshear and up and downdrafts must be included in the different approaches;
- h) One landing at night must be executed for each runway.

cont'd

CHANGES: See other side © JEPPESEN SANDERSON, INC., 2001, 2003. ALL RIGHTS RESERVED. Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

JEPPES E N

JeppView 3.5.2.0

LPMA/FNC S JEPPESEN MADEIRA, MADEIRA IS MADEIRA

OPERATING AT MADEIRA AIRPORT (cont'd)

4. LINE TRAINING

No line training is required if the flight simulator used is level D. If level C flight simulator is used, line training must be performed with one landing and take-off at Madeira airport, with an instructor occupying the right-hand seat.

5. AIRCRAFT TYPE CHANGE

A captain qualified at Madeira airport in one type of aircraft, changing to another type, must do the flight simulator training program mentioned in paragraph 3 or, instead, will land and take-off in both runways without passengers on board and no line training will be required on both cases.

6. TRAINING PROGRAM

The training program referred in paragraph 3 will have to be approved by INAC (Portuguese Civil Aviation Authority).

7. DEVIATIONS OR UNCONFORMITIES

Any deviations or unconformities stated from requirements stated in paragraph 2 thru 5 will be dealt in a case by case basis.

RESPONSIBILITY

Compliance with operating limitations is mandatory. Any deviation must be reported to INAC by Tower.

OPERATING PROCEDURES AND LIMITATIONS

WIND/TURBULENCE

a. Wind Information

On downwind and final approach to rwy 05 the Control Tower will provide two minutes mean wind values at Rosario and touch down. Instantaneous wind read out will be provided at pilot's request.

b. Wind Limitations

When landing

Maximum of two minutes mean wind speed values indicated by the touchdown anemometer:

- In the sector 300° to 010° MAG (clockwise) 15 KT with a maximum wind gust of 25 KT.
- In the sector 020° to 040° MAG (clockwise) 20 KT with a maximum wind gust of 30 KT.
- In the sector 120° to 190° MAG (clockwise) and if rwy in use is 05 20 KT, with a maximum wind gust of 30 KT, and if runway in use is 23 - 15 KT subject also to a maximum wind gust of 25 KT as indicated by MID anemometer.

Maximum of two minutes mean wind speed values, including gust indicated by the MID or Rosario anemometer:

- In the sector 200° to 230° MAG (clockwise) - 25 KT.

cont'd

CHANGES: Wind Limitations. © JEPPESEN SANDERSON, INC., 2001, 2003. ALL RIGHTS RESERVED.

Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

11 JUL 03

JEPPESEN JeppView 3.5.2.0

1 03 (10-6B)

" JEPPESEN

MADEIRA, MADEIRA IS MADEIRA

OPERATING PROCEDURES AND LIMITATIONS (cont'd)

b. Wind Limitations (cont'd)

When taking-off

LPMA/FNC

Maximum of two minutes mean wind speed values indicated by the MID anemometer:

- In the sector 300° to 010° MAG (clockwise) 20 KT with no gust limitations.
- In the sector 020° to 040° MAG (clockwise) 25 KT with no gust limitations.
- In the sector 120° to 190° MAG (clockwise), and if runway in use is 05 25 KT with no gust limitations, and if runway in use is 23 - 20 KT also with no gust limitations.

NOTE: The limitations above do not supersede any operators or AOM limitations if these are more restrictive.

c. Turbulence

- Attention should be paid to the WIND DIRECTION INDICATORS located on the south side of the runway, near each touch-down area. They will reflect unexpected wind changes. Occasionally they will indicate wind from opposite directions.
- When landing on rwy 05 wind differences higher than 5 KT, between Rosario and MID anemometer, may indicate turbulence on final.
- When landing on rwy 23 with winds from southerly and westerly sectors, severe turbulences may be experienced at low altitude over the rwy threshold.
- Headwind or nearly so, up to 15 KT will cause "WEAK" turbulence on final;
- Wind of 15 KT from sector 020° to 050° MAG (clockwise) may cause "MODERATE" turbulence:
- Wind of 15 KT or even less from sector 300° to 020° MAG (clockwise) may cause "SEVERE" turbulence;
- Down or updrafts are to be expected near the threshold of runways 05 and 23.

NOTE: Pilots are strongly requested to report to the Control Tower as soon as possible any turbulence and/or windshear that may affect operational conditions.

VISUAL APPROACH PROCEDURES

See appropriate charts for approaches to rwy 05 and 23

LANDING PROCEDURES

All landings are to be made in visual conditions (see appropriate chart).

DEPARTURE PROCEDURES

CHANGES: Wind Limitations.

Pilots are advised to select full power on take-off in the presence of turbulence or downdraft reports.

Take-off on both runways must be made in a minimum visibility shown on 10-9, required take-off alternate.

© JEPPESEN SANDERSON, INC., 2001, 2003. ALL RIGHTS RESERVED.

There are curved trajectories defined for both runways and for all engines.

Each operator must prepare its own engine failure procedure.

JEPPESEN Licensed to Elefant air. Printed on 06 Sep 2008. JeppView 3.5.2.0 NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 MADEIRA, MADEIRA IS ¼ JEPPESEN LPMA/FNC Apt Elev 192' 15 JUN 07 (10-9) MADEIRA N32 41.7 W016 46.7 MADEIRA Tower ATIS 124.4 118.35 16-47 16-46 WARNING: Birds. 1460' Twy A prohibited for acft with wingspan exceeding 213'/65m. FOR PARKING **POSITIONS** 1063' SEE 10-9A **—** 32-42 32-42 Apron A 378' MET 2000 Feet 0 3000 2000 400 600 800 1000 1200 16-47 Rosario 010° 020° Wind limitations when taking-off (relative to the MID anemometer 25 20KT two minutes mean values only): max permissible wind. **Curved LDIN** 0 ■ Rwy 05: 25 KT Rwy 23: 20 KT NOT TO SCALE 1909 ADDITIONAL RUNWAY INFORMATION USABLE LENGTHS LANDING BEYOND -Glide Slope TAKE-OFF Threshold WIDTH RL 3 CL 4 HIALS TDZ LDIN 5 PAPI 6 148' 8140' 2481m 2 8632' 263 II 23 RL 3 CL 4 ALS TDZ PAPI-L (3.0°) 2 grooved (spacing 60m) (spacing 30m) See inset. (angle 3.00°). Both sides offset 5° to the Right, Right side not visible on short final. ● Including 492'/150m of pavement before threshold. JAR-OPS TAKE-OFF 1 All Rwvs 2800m

Take-off alternate required.

CHANGES: Variation, Rwy bearings.

Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008


JEPP SEN

Jepp View 3.5.2.0

LPMA/FNC SJEPPESEN MADEIRA, MADEIRA IS

15 JUN 07 (10-9A) MADEIRA

MADEIRA



N32 41.5 W016 46.7 A13 thru A15 N32 41.7 W016 46.4 Α1 A2, A3 N32 41.6 W016 46.7 A16 thru A18 N32 41.8 W016 46.4 A4 thru A7 N32 41.6 W016 46.6 A19 N32 41.6 W016 46.7 **A8** N32 41.6 W016 46.5 A9 thru A12 N32 41.7 W016 46.5

PUSH-BACK, START-UP AND TAXI PROCEDURES

Jet acft engine start-up is only permitted after push-back manoeuvre with acft positioned in breakaway area.

All acft must activate anti-collision lights before starting engines.

To prevent blast damage in acft equipment and personnel, all acft operations on the apron must be made using lowest power setting.


JEPPESEN Licensed to Elefant air. Printed on 06 Sep 2008. JeppView 3.5.2.0 NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

MADEIRA, MADEIRA IS MJEPPESEN LPMA/FNC 15 JUN 07 (13-1) CIRCLING VOR DME RWY 05 MADEIRA MADEIRA Tower MADEIRA Approach ATIS 124.4 119.2 118.35 VOR Final Minimum Alt Apt Elev 192' MDA(H) 3500' FUN Apch Crs D7.0 8200' 940' (793') 212° RWY 147 112.2 3000' (2853' MISSED APCH: Turn LEFT onto heading 139° to intercept R-172, proceed to FUSUL climbing to 3000' and hold. Contact APP. FUN VOR Alt Set: hPa Rwy Elev: 5 hPa Trans level: By ATC Trans alt: 5000' D12. D12.0 CAUTION: Execute all turns MHA over the sea due to high terrain 3000 to the North and West of apt. 9 FOR VOR VISUAL APPROACH PATTERN TO RWY 05 SEE 13-1A. **ABUSU** D7.0 32-50 FUNCHAL-112.2 FUN 16-30 **DESERTA IS** MISSED APCH up to 1571' FUSUL 14 NM ESE from apt. D3.6 32-40 1.0 3.0 4.0 5.0 6.0 7.0 FUN DME 2.0 1650 1880 2100 2330 2550 2760' 3000 ALTITUDE **VOR 1** 4000 0 D12.0 **₽** 5000′ via STAR MADAT 3A turn at 3000 D3.6 032°-- 3 Min 1430' **ABUSU** C & D: 212 D7.0 D8.0 2 Min RWY 05147' FUN 3000' 112.2 FUSUL 90 100 120 140 160 Gnd speed-Kts 70 139° Lighting-Descent Gradient 3.7% 262 337 375 450 525 600 Refer to hdg MAP at D3.6 Airport R-172 JAR-OPS CIRCLE-TO-LAND CEILING REQUIRED Wind limitations for TO RWY 05 010°020° landing (relative to the touchdown anemometer 20KT Not authorized Northwest of rwy two minutes mean 90°5KT values only): max 100 permissible wind. 135 ⁸⁰⁰′ - 5000m 180 940'(793') 245m 8 Relative to the MID or Rosario anemometers including gust.

CHANGES: Bearings. IAF designation

© JEPPESEN SANDERSON, INC., 2000, 2007. ALL RIGHTS RESERVED.

Licensed to Elefant air. Printed on 06 Sep 2008. NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008 **JEPPESEN** JeppView 3.5.2.0




Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

JEPPESEN

JeppView 3.5.2.0




© JEPPESEN SANDERSON, INC., 2000, 2007. ALL RIGHTS RESERVED.

CHANGES: Bearings. IAF designation

Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

JEPPESEN JeppView 3.5.2.0




Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

JEPPES E N

JeppView 3.5.2.0



Licensed to Elefant air. Printed on 06 Sep 2008.

NOTICE: PRINTED FROM AN EXPIRED REVISION. Disc 10-2008

JeppView 3.5.2.0 MADEIRA, MADEIRA IS #JEPPESEN LPMA/FNC 15 JUN 07 (16-2) CIRCLING NDB RWV 23 MADEIRA MADEIRA Approach MADEIRA Tower ATIS 124.4 118.35 119.2 NDB Final Minimum Alt Apt Elev 192 MDA(H) 3500 MAD Apch Crs 8200' No FAF 1300'(1108' 200° 318 RWY 192' MISSED APCH: Climb on 200° from NDB to 4500', then turn LEFT to NDB climbing to 5000' and hold. MSA MAD NDB Alt Set: hPa Rwy Elev: 7 hPa Trans level: By ATC Trans alt: 5000 In order to never cross to the North (RIGHT) of R-237 (or 236° from NDB):

-On the visual apch, initiated overhead VOR, the acft should be kept slightly LEFT of this radial until a point where, with TDZ and PAPI in sight, it has to line up with the rwy.

-Maintain MDA(H) until intercepting the 3.00° final descent path defined by the PAPI, which crosses -Maintain MDA(f) until intercepting the 5.00 Third descent paintactions of the thresh at 57'.

-During the apch do not deviate to the North (RIGHT) of the extended CL of rwy 23 due to high terrain.

-At night the hills on your RIGHT may be confused with mist. This obstacle is lighted. -Touchdown rwy 23 out of Control Tower visual range. TDZ lighting is provided. -A go around manoeuvre should be performed if the acft has not landed by the end of these lights. CAUTION: Execute all turns 32-50 00 over the sea due to high terrain to the North and West of apt. MHA 5000 2034 - FUNCHAL-P 112.2 FUN FUNCHAL-**318 MAD** DESERTA IS up to 1571' 14 NM ESE from apt. 16-50 NDB 5000 CAT A & B: 3 Min 3200' CAT C & D: 236° 2 Min RWY 23 192 TO DISPLACED THRESHOLD 3.9 200° 4500' from MAD 318 MAP at NDB JAR-OPS CIRCLE-TO-LAND CEILING REQUIRED Wind limitations for landing 01<u>0°</u>020° TO RWY 23 relative to the touchdown 20KT TO anemometer two minutes Not authorized Northwest of rwy 25KT mean values only): max CEIL-VIS permissible wind. 100 ¹²⁰⁰′ - 7000m 1.30515 0 / 1300' (1108') 180 370m • Relative to the MID OPS 0 anemometer. 2 Relative to the MID or Rosario

(C) JEPPESEN SANDERSON, INC., 2000, 2007. ALL RIGHTS RESERVED.

CHANGES: Bearings.

anemometers including gust.

JEPPESEN