# Systems Thinking Mini Project

# Team members:

• Yashwanth Duggi Roll no :2022102051

• V.V.S.R.Chetan Krishna Roll no :2022102047

• T.S.Mitra Roll no :2022102061

• Shaik Affan Adeeb Roll no :2022102054

• G.S.S Ananya Varma Roll no :2022102064

• Vishnu Priya Chekuru Roll no :2022102023

• Kushang Agarwal Roll no :2022102076

• Sriram Alluri Roll no :2022102016

# Question:

• Consider the following system dynamics of a 2-link manipulator :

$$\mathbf{M}(\mathbf{q})\ddot{\mathbf{q}} + \mathbf{C}(\mathbf{q}, \dot{\mathbf{q}})\dot{\mathbf{q}} + \mathbf{G}(\mathbf{q}) = \boldsymbol{\tau},$$

$$\mathbf{M} = \begin{bmatrix} M_{11} & M_{12} \\ M_{12} & M_{22} \end{bmatrix}, \mathbf{q} = \begin{bmatrix} q_1 \\ q_2 \end{bmatrix},$$

$$M_{11} = (m_1 + m_2) l_1^2 + m_2 l_2 (l_2 + 2l_1 \cos(q_2)),$$

$$M_{12} = m_2 l_2 (l_2 + l_1 \cos(q_2)), M_{22} = m_2 l_2^2,$$

$$\mathbf{C} = \begin{bmatrix} -m_2 l_1 l_2 \sin(q_2) \dot{q}_2 & -m_2 l_1 l_2 \sin(q_2) (\dot{q}_1 + \dot{q}_2) \\ 0 & m_2 l_1 l_2 \sin(q_2) \dot{q}_2 \end{bmatrix},$$

$$\mathbf{G} = \begin{bmatrix} m_1 l_1 g \cos(q_1) + m_2 g (l_2 \cos(q_1 + q_2) + l_1 \cos(q_1)) \\ m_2 g l_2 \cos(q_1 + q_2) \end{bmatrix}$$

- where  $(m_1, l_1, q_1)$  and  $(m_2, l_2, q_2)$  denote the mass, length and joint angle positions of link 1 and 2 respectively.
- The following parametric values are selected:  $m_1 = 10 \text{ kg}, m_2 = 5 \text{ kg}, l_1 = 0.2 \text{ m}, l_2 = 0.1 \text{ m}, g = 9.81 \text{ m/s}^2$ . The joint angles are initially at positions  $[q_1(0)q_2(0)] = \begin{bmatrix} 0.1 & 0.1 \end{bmatrix} \text{ rad}$ .
- The objective is to bring the the joint angles from the initial position to  $\begin{bmatrix} q_1 & q_2 \end{bmatrix} = \begin{bmatrix} 0 & 0 \end{bmatrix}$ .
- Q). Via MATLAB simulations (choose P, I, and D gains of your choice) show differences in responses (i.e., plot  $q_1$  vs. t and  $q_2$  vs. t) when (i) PD (ii) PI and (iii) PID controllers are applied separately

# **Solution:**

# 2-Link Manipulator: System Dynamics

The system dynamic equation for a 2-link manipulator can be expressed as:

$$M(q)\ddot{q} + C(q, \dot{q})\dot{q} + G(q) = \tau$$

Where:

- M(q) is a  $2 \times 2$  matrix.
- q is a  $2 \times 1$  matrix vector:  $\begin{bmatrix} q_1 \\ q_2 \end{bmatrix}$ .
- $C(q, \dot{q})$  is a  $2 \times 1$  matrix.
- $\dot{q}$  is a 2 × 1 matrix vector:  $\begin{bmatrix} \dot{q}_1 \\ \dot{q}_2 \end{bmatrix}$ .
- G is a  $2 \times 1$  matrix.

All the matrices are given.

The equation can also be represented as:

$$M(q)\ddot{q} + C(q,\dot{q})\dot{q} + G(q) = \tau$$

Now, solving for  $\ddot{q}$ , we have:

$$\begin{split} &\Rightarrow M(q)\ddot{q} = \tau - [C(q,\dot{q})\dot{q} + G(q)] \\ &\Rightarrow \ddot{q} = M^{-1}(q)[\tau - (C(q,\dot{q})\dot{q} + G(q))] \\ &\Rightarrow \ddot{q} = M^{-1}(q)\tau - M^{-1}(q)[C(q,\dot{q})\dot{q} + G(q)] \longrightarrow [I] \end{split}$$

Assuming:

$$\hat{\tau} = M^{-1}(q)\tau \tag{1}$$

Let:

$$\tau = \begin{bmatrix} f_1 \\ f_2 \end{bmatrix}$$

and from equation (1)

$$\tau = \begin{bmatrix} \tau_1 \\ \tau_2 \end{bmatrix} = M(q)\hat{\tau}$$

# **Denoting Error Signals:**

The error signals are denoted as follows:

$$e(q_1) = q_{1f} - q_1$$
  
 $e(q_2) = q_{2f} - q_2$ 

Where the target positions of Manipulator Arm 1 and 2 are given by the angles  $q_{1f}$  and  $q_{2f}$ .

#### **Initial Positions:**

The initial positions of the system are given as:

$$q_0 = \begin{bmatrix} q_1(0) \\ q_2(0) \end{bmatrix} = \begin{bmatrix} 0.1 \\ 0.1 \end{bmatrix} \rightarrow \text{as provided in the question}$$

# Modeling PID Group Output:

The PID group output is modeled as:

$$f = k_p e + k_D \dot{e} + k_I \int e dt$$
$$f = \begin{bmatrix} f_1 \\ f_2 \end{bmatrix}$$

For  $f_1$ :

$$f_1 = k_{p_1}e_1(q_1) + k_{D_1}\dot{e}_1(q_1) + k_{I_1} \int e_1(q_1)dt$$

$$= k_{p_1}(q_{1f} - q_1) + k_{D_1}(\dot{q}_{1f} - \dot{q}_1) + k_{I_1} \int (q_{1f} - q_1)dt$$

$$= k_{p_1}(q_1f - q_1) - k_{p_1}\dot{q}_1 + k_{I_1} \int (q_{1f} - q_1)dt$$

For  $f_2$ :

$$f_2 = k_{p_2}e_2(q_2) + k_{D_2}\dot{e}_2(q_2) + k_{I_2} \int e_2(q_2)dt$$

$$= k_{p_2}(q_{2f} - q_2) + k_{D_2}(\dot{q}_{2f} - \dot{q}_2) + k_{I_2} \int (q_{2f} - q_2)dt$$

$$= k_{p_2}(q_2f - q_2) - k_{p_2}\dot{q}_2 + k_{I_2} \int (q_{2f} - q_2)dt$$

#### Actual Torques for the Plant System:

The actual torques for the plant system are given by:

$$\begin{bmatrix} \tau_1 \\ \tau_2 \end{bmatrix} = M(\theta) \begin{bmatrix} f_1 \\ f_2 \end{bmatrix}$$

# Defining State Variables:

The state variables are defined as follows:

$$x_1 = q_1$$

$$x_2 = q_2$$

$$x_3 = \dot{q}_1$$

$$x_4 = \dot{q}_2$$

$$x_5 = \int e_1(q_1)dt$$

$$x_6 = \int e_2(q_2)dt$$

# Finding Derivatives of State Variables:

The derivatives of the state variables are given by:

$$\dot{x}_1 = \dot{q}_1 = x_3 
\dot{x}_2 = \dot{q}_2 = x_4 
\dot{x}_3 = \ddot{q}_1 = \phi(x_1, x_2, x_3, x_4, t, x_5, x_6) 
\dot{x}_4 = \dot{q}_2 = \psi(x_1, x_2, x_3, x_4, x_5, x_6, t) 
\dot{x}_5 = e_1(q_1) = q_1 f - q_1 = q_1 f - x_1 = 0 - x_1 
\dot{x}_6 = e_2(q_2) = q_{2f} - q_2 = q_{2f} - x_2 = 0 - x_2$$

# Final Desired Angles for 2-link manipulator in our dynamics:

The final desired angles for the robot arms are given as:

$$q_{final} = \begin{bmatrix} q_1 f \\ q_{2f} \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \end{bmatrix}$$

From equation [I]:

$$\ddot{q} = M^{-1}(q)\tau - M^{-1}(q)[c(q,\dot{q})\dot{q} + G(q)]$$

$$= \hat{\tau} - M^{-1}(q)[c(q,\dot{q})\dot{q} + G(q)]$$

$$\ddot{q} = \begin{bmatrix} \ddot{q}_1 \\ \dot{q}_2 \end{bmatrix}$$

#### State Variables and Initial Conditions:

The state variables are represented as:

$$\dot{x} = \begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \\ \dot{x}_3 \\ \dot{x}_4 \\ \dot{x}_5 \\ \dot{x}_6 \end{bmatrix} \text{ and } x = \begin{bmatrix} x_1 \\ x_2 \\ x_3 \\ x_4 \\ x_5 \\ x_6 \end{bmatrix}$$

This first order nonlinear differential equation of the form:

$$\dot{x} = \frac{dx}{dt}$$
,  $x(0) = \text{initial conditions for our state variables.}$ 

Regarding x(0), considering the initial conditions as:

$$x(0) = \begin{bmatrix} 0.1\\0.1\\0\\0\\0\\0 \end{bmatrix}$$

Initially, the derivative and integral values of  $q_1$  and  $q_2$  are unknown, and since the system is causal, they are taken initially as zero.

### ODE45 in MATLAB:

In the code, the 'ode45' command is used to obtain the state variables  $\bar{x}$  as output from the differential equation vector  $\dot{\bar{x}}$  of the state variables and the vector representing the initial state as the arguments.

$$[t,s] = \text{ode}45(@(t, \text{state}) \text{func}(t, \text{state}), t_{\text{span}}, y_0)$$

Where:

- $y_0$  represents the initial state.
- func(t, state) : Returns the differentials  $\dot{x}$  vector.

#### Main Outputs for Plotting:


The main outputs to be plotted are  $q_1$  and  $q_2$ , which can be obtained using 'ode45'.

$$x(1) = x_1 = q_1$$
  
 $x(2) = x_2 = q_2$ 

These values represent the desired angles for the robot arms.

### PID Controller:

A proportional—integral—derivative controller (PID controller or three-term controller) is a control loop mechanism employing feedback that is widely used in industrial control systems and a variety of other applications requiring continuously modulated control. A PID controller continuously calculates an error value e(t) as the difference between a desired setpoint (SP) and a measured process variable (PV) and applies a correction based on proportional, integral, and derivative terms (denoted P, I, and D respectively), hence the name.



A block diagram of a PID controller in a feedback loop. r(t) is the desired process value or setpoint (SP), and y(t) is the measured process value (PV).

# Mathematical form:

The overall control function is given by:

$$u(t) = K_p e(t) + K_i \int_0^t e(\tau) d\tau + K_d \frac{de(t)}{dt}$$

where  $K_p$ ,  $K_i$ , and  $K_d$  (sometimes denoted as P, I, and D) are non-negative coefficients for the proportional, integral, and derivative terms, respectively.

# Proportional Term:


The proportional term produces an output value that is proportional to the current error value. The proportional response can be adjusted by multiplying the error by a constant  $K_p$ , called the proportional gain constant.

The proportional term is given by:

$$P_{\text{out}} = K_{\text{p}} \cdot e(t)$$

In this equation:

- $\bullet$   $P_{\text{out}}$  represents the proportional output.
- $K_p$  is the proportional gain constant.
- e(t) represents the current error value.



A high proportional gain results in a large change in the output for a given change in the error. If the proportional gain is too high, the system can become unstable. In contrast, a small gain results in a small output response to a large input error, and a less responsive or less sensitive controller. If the proportional gain is too low, the control action may be too small when responding to system disturbances.

# Integral Term:


The contribution from the integral term is proportional to both the magnitude of the error and the duration of the error. In a PID controller, the integral term is the sum of the instantaneous error over time and gives the accumulated offset that should have been corrected previously. The accumulated error is then multiplied by the integral gain  $K_i$  and added to the controller output. The integral term is given by:

$$I_{\text{out}} = K_i \int_0^t e(\tau) d\tau$$

Where:

- $I_{\text{out}}$  is the integral term output.
- $K_i$  is the integral gain.

This integral term plays a crucial role in PID control systems, helping to eliminate steady-state errors by accumulating and correcting past errors over time.



The integral term accelerates the movement of the process towards setpoint and eliminates the residual steady-state error that occurs with a pure proportional controller. However, since the integral term responds to accumulated errors from the past, it can cause the present value to overshoot the setpoint value.

# **Derivative Term**


The derivative of the process error is calculated by determining the slope of the error over time and multiplying this rate of change by the derivative gain  $K_d$ . The magnitude of the contribution of the derivative term to the overall control action is termed the derivative gain,  $K_d$ .

The derivative term is given by:

$$D_{\rm out} = K_d \frac{de(t)}{dt}$$

Where:

- $D_{\text{out}}$  is the derivative term output.
- $K_d$  is the derivative gain.



Derivative action predicts system behavior and thus improves settling time and stability of the system. An ideal derivative is not causal, so that implementations of PID controllers include an additional low-pass filtering for the derivative term to limit the high-frequency gain and noise.


# MATLAB Code:

```
1 % Simulation settings
2 t_span = 0:0.01:20;
_{3}|y0 = [0.1, 0.1, 0, 0,0,0]; \% Initial joint angles and
     velocities
5 % Run simulation
_{6}|[t, s] = ode45(@(t, state) func(t, state), t_span, y0);
8 % Plotting
9 figure;
10 subplot(2, 1, 1);
plot(t, s(:, 1), 'LineWidth', 2);
12 title('Joint Angle q1 vs Time');
13 xlabel('Time (s)');
14 ylabel('q1 (rad)');
16 subplot (2, 1, 2);
plot(t, s(:, 2), 'LineWidth', 2);
18 title ('Joint Angle q2 vs Time');
19 xlabel('Time (s)');
20 ylabel('q2 (rad)');
22 function der_S = func(t, state)
      % System parameters
23
      m1 = 10;
      m2 = 5;
25
      11 = 0.2;
      12 = 0.1;
      g = 9.81;
28
29
      % Controller gains
30
      kp1 = 200;
31
      kd1 = 5;
      kp2 = 400;
      kd2 = 150;
34
      ki1 = 500;
35
      ki2 = 600;
36
37
      % Extracting state variable
38
      q1 = state(1);
```

```
q2 = state(2);
40
      q1_dot = state(3);
41
      q2_{dot} = state(4);
42
      neg_int_q1 = state(5);
      neg_int_q2 = state(6);
44
45
      % Equations of motion
46
      m11 = (m1 + m2) * (11^2) + m2 * 12 * (12 + 2 * 11 *
47
         cos(q2));
      m12 = m2 * 12 * (12 + 11 * cos(q2));
48
      m22 = m2 * (12^2);
50
      M = [m11, m12; m12, m22];
51
52
      c11 = -m2 * 11 * 12 * sin(q2) * q2_dot;
53
      c12 = -m2 * 11 * 12 * sin(q2) * (q1_dot + q2_dot);
54
      c21 = 0;
55
      c22 = m2 * 11 * 12 * sin(q2) * q1_dot;
57
      C = [c11, c12; c21, c22];
58
59
      g1 = m1 * 11 * g * cos(q1) + m2 * g * (12 * cos(q1 + m2))
60
          q2) + 11 * cos(q1));
      g2 = m2 * g * 12 * cos(q1 + q2);
      G = [g1; g2];
63
64
      % PDI control law
65
      tau1 = -kp1 * q1 - kd1 * q1_dot + ki1 * neg_int_q1;
66
      tau2 = -kp2 * q2 - kd2 * q2_dot + ki2 * neg_int_q2;
67
      % Control input vector
      Tau = [tau1; tau2];
70
71
      % Solve for q1_ddot and q2_ddot
72
      q_dot = M \setminus (Tau - C * [q1_dot; q2_dot] - G);
73
74
      % State derivatives
      der_S = [q1_dot;q2_dot;q_ddot(1);q_ddot(2);-q1;-q2];
77 end
```

# Final outputs of joint angles w.r.t time:

• Case 1:




- The values of proportional gains are:  $K_{p1} = 400$ ,  $K_{p2} = 500$ .
- The values of integral gains are:  $K_{i1} = 5$ ,  $K_{i2} = 5$ .
- The values of derivative gains are:  $K_{d1} = 5$ ,  $K_{d2} = 5$ .

#### **Observations:**

- 1. Oscillatory damping of  $q_1$  and  $q_2$  are observed. The steady-state error values of  $q_1$  and  $q_2$  are non-zero for a timespan of 20 seconds. For example,  $e(q_1) = -0.06$  and  $e(q_2) = -0.008$  at steady state in the given case.
- 2. We are able to observe noise which is damped with time.

To overcome these above problems in our observation, we need to tune the gains  $(K_p, K_d, \text{ and } K_i)$  so as to achieve steady state faster, avoid noise, and reduce steady-state error.

### • Case 2:




- The integral gains  $K_{i1}$  and  $K_{i2}$  have been increased with the goal of achieving a setpoint of 0 as the system reaches steady state.
- $\Rightarrow e(q_1)$  and  $e(q_2)$  approach approximately 0 at steady state.
- The values of integral gains are:  $K_{i1} = 200$ ,  $K_{i2} = 150$ .
- The values of derivative gains are:  $K_{d1} = 5$ ,  $K_{d2} = 5$ .
- We observe that the proportional and derivative gains are kept constant, while the integral gains have been increased:  $K_{i1}$  changed from 5 to 200,
- $K_{i2}$  changed from 5 to 150.
- Since the steady-state error of  $q_2$  was comparatively less than that of  $q_1$ , the integral gain of  $q_1$  was increased to a larger extent than that of  $q_2$ .

#### Observation:

Now we observe that the steady-state errors are close to zero. Our aim now is to reduce the noise before achieving steady state, i.e., we need to achieve steady state quickly within our specified time span.

#### • Case 3:



- In order to reduce oscillations, the derivative gains  $K_{d1}$  and  $K_{d2}$  are increased.
- $q_1$  exhibits rapid oscillations of larger amplitude compared to  $q_2$ . Therefore,  $K_{d1}$  is increased to a larger value than  $K_{d2}$ .
- The values of proportional gains are:  $K_{p1} = 400$ ,  $K_{p2} = 500$ .
- The values of integral gains are:  $K_{i1} = 200$ ,  $K_{i2} = 150$ .
- The values of derivative gains are:  $K_{d1} = 200$ ,  $K_{d2} = 50$ .
- $K_{d1}$  has been increased from 5 to 200, and  $K_{d2}$  has been increased from 5 to 50.

# **Observations:**

The oscillations have reduced, but steady state is achieved in more time for  $q_1$  (approximately 7 seconds) within our time span taken. Our aims are as follows:

- 1. To make  $q_1$  achieve steady state in less time (leading to case 4).
- 2. To avoid the initial variation of  $q_1$  about the setpoint when it reaches the setpoint for the first time.