

Sample Garage Motor Works (Pvt) Ltd

PLACEHOLDER TEST DOCUMENT — NOT A REAL ESTIMATE

Estimate No:	EST-TEST-0002	Date:	2026-09-25
Customer:	Test User Two	Contact:	000-1111111
Vehicle:	Test Motors Model Y	Reg No:	TEST-0001

Estimate Details

#	Description	Qty	Unit Price (LKR)	Amount (LKR)
1	Rear door panel repair (placeholder)	1	18,000.00	18,000.00
2	Side mirror replacement (placeholder)	2	6,500.00	13,000.00
3	Bumper repaint (placeholder)	1	12,000.00	12,000.00
4	Diagnostic & labor charges (placeholder)	1	4,500.00	4,500.00

Subtotal	47,500.00
VAT (18%)	8,550.00
Total Estimate (LKR)	56,050.00

This is a synthetic placeholder document generated for software testing purposes only. All names, figures, and identifiers are fictional and do not correspond to any real vehicle, person, or business.