Turbine scan plan Instruction

Equipment: Faro Scanner + Insta360 Titan camera

Each scan: 5 min (Resolution: 1/32, Quality: 8x)

- Total Faro scanning duration: 17 scans * 5 = 85 min
 - Insta360 Titan camera duration: 15 20 min

Preparation to the site

For the site safety items:

- Please wear closed toe shoes, safety toe if you have them, otherwise we can provide toe guards
- Jeans or pants and long sleeve shirt recommended
- It is considered a confined space, so some additional training will be required onsite, not extensive
- We will provide hard hats and safety glasses

Major steps:

- Check if targets can be place on wall
- 2. Place the targets
- 3. Faro scanner data collection
- 4. 360 camera data collection
- 5. Remove targets

Check if targets can be place on wall



Top-down view



Bottom-up view


Place 6 targets – cannot place targets on wall






Targets

Place 6 targets — can attach the wall




3 targets on the wall, 3 targets on the ground


Place scanner/360 camera at 5' to 6' height







Faro scanner setup



Set up tripod



Check the bubble level



Place scanner by quick-release plate




Lock the locking knob



Remove lens protector





Open battery compartment cover

Check the battery and SD card



Hit power on/off button




Hit button: Start scanning




During Scanning:

- L. Stay outside the turbine
- 2. Find a corner not to avoid targets








- 1. Record the file name
- 2. Go back to main menu

Check the collected scans



Continue to the collect next scan



Until finish all scans: Check the collected scans

1

FARO_LS2957_135 FARO_LS2957_134

FARO_LS2957_130

FARO_LS2957_129

FARO_LS2957_128

FARO_LS2957_127





Shut down scanner: Hit power on/off button





Ensure the scanner shut down and extract SD card



Put lens protector back



unlock the locking knob



Turn the knob and remove scanner carefully

Faro Scanner Data Collection

- Ensure the batteries are fully charged
- Not to move the targets
- Stay outside the turbine when collecting data
- Record: if there's labels on turbine blades

No#	Image name	No # blades
1	Scan_086	1

Color	State
Violet blinking	Battery charging. Charge at < 5%
Red blinking	Battery charging. Charge at 5% - 15%
Orange blinking	Battery charging. Charge at 15% - 25%
Yellow blinking	Battery charging. Charge at 25% - 95%
Green blinking	Battery charging. Charge at >95%
Green	(full charged) ~100%
White	no battery
Cyan blinking quickly	error



Insert SD card to desktop

Insta360 Camera Data Collection

- Ensure the batteries are fully charged
- Ensure 9 SD cards are all inserted
- Place camera at 6' height
- After data collection, insert 9 SD cards to the desktop in CAVC541_A

