
### **Homework 5**

### The system

We consider the case of a hopping robot. It has a body and a single leg. The orientation of the main body with reference to the leg is given by the action of a motor that gives a torque u1. The leg has a translation piston that controls it via u2.



# If we consider:

- m as the mass of the leg
- J as the inertia momentum of the body
- X1 as the (variable) length of the leg
- X3 as the angular position of the body
- X5 as the angular position of the leg

and if we neglect the action of gravity, then the equations that describe our system in matrix form are:

$$\begin{pmatrix} \dot{x}_1 \\ \dot{x}_2 \\ \dot{x}_3 \\ \dot{x}_4 \\ \dot{x}_5 \\ \dot{x}_6 \end{pmatrix} = \begin{pmatrix} x_2 \\ x_1 x_6^2 \\ x_4 \\ 0 \\ x_6 \\ -2 \frac{x_2 x_6}{x_1} \end{pmatrix} + \begin{pmatrix} 0 & 0 \\ 0 & \frac{1}{m} \\ 0 & 0 \\ \frac{1}{J} & 0 \\ 0 & 0 \\ -\frac{1}{m x_1^2} & 0 \end{pmatrix}$$

### **Computation of H2**

The previous system can also be simplified in the generic system

$$\dot{x} = f(x) x + g(x) u$$

So we can write g(x) as:

$$g(x) = \begin{pmatrix} 0 & 0 \\ 0 & \frac{1}{m} \\ 0 & 0 \\ \frac{1}{J} & 0 \\ 0 & 0 \\ -\frac{1}{mx_1^2} & 0 \end{pmatrix}$$

We can now look for H2. We know that, since it must be  $g(x)^{\perp}$ , the dimension of H2 must be equal to:

$$\dim (H_2) = n - k = 6 - 2 = 4$$

This means that there are 4 basis for H2:

$$H_2 = span\{\omega_1, \omega_2, \omega_3, \omega_4\}$$

In order to find them we can take the definition of orthonormal annihilator and look for the elements that will compose the omegas:

$$(h_1 h_2 h_3 h_4 h_5 h_6) \begin{pmatrix} 0 & 0 \\ 0 & \frac{1}{m} \\ 0 & 0 \\ \frac{1}{J} & 0 \\ 0 & 0 \\ -\frac{1}{mx_1^2} & 0 \end{pmatrix} = 0$$

By calculating we obtain:

$$\begin{cases} 0 h_1 + 0 h_2 + 0 h_3 + \frac{1}{J} h_4 + 0 h_5 - \frac{1}{mx_1^2} h_6 = 0 \\ 0 h_1 + \frac{1}{m} h_2 + 0 h_3 + 0 h_4 + 0 h_5 + 0 h_6 = 0 \end{cases}$$

$$\begin{cases} \frac{1}{J} h_4 - \frac{1}{mx_1^2} h_6 = 0 \\ \frac{1}{m} h_2 = 0 \end{cases}$$

 $h_1$ ,  $h_3$ ,  $h_5$  values don't matter, so we can neglect them for a while.

We have constraints on the other values:

$$h_2 = 0$$

lf

$$h_4 = J$$

then

$$h_6 = m x_1^2$$

Now that we know a few of the elements with which we will build the omegas, we can define the general form of an exact basis. In particular,  $\omega_i$  is exact if there exists a function  $\varphi$  belonging to k such that

$$\omega_{i} = \left[ \frac{\partial \varphi}{\partial x_{1}} \frac{\partial \varphi}{\partial x_{2}} \frac{\partial \varphi}{\partial x_{3}} \frac{\partial \varphi}{\partial x_{4}} \frac{\partial \varphi}{\partial x_{5}} \frac{\partial \varphi}{\partial x_{6}} \right]$$

From the values that we know:

$$\varphi = \langle x_1 + \langle x_2 + \langle x_3 + J x_4 + \langle x_5 + m x_1^2 x_6 \rangle$$

Where ~ indicates that the value can be chosen. And

$$d\varphi = \sim dx_1 + \sim dx_2 + \sim dx_3 + J dx_4 + \sim dx_5 + [mx_1^2 dx_6 + 2mx_1x_6 dx_1] =$$

$$= (\sim + 2mx_1x_6) dx_1 + \sim dx_2 + \sim dx_3 + J dx_4 + \sim dx_5 + mx_1^2 dx_6$$

So, for example, one set of bases could be:

$$\omega_{1} = 2mx_{1}x_{6}dx_{1} + J dx_{4} + mx_{1}^{2} dx_{6}$$

$$\omega_{2} = 2mx_{1}x_{6}dx_{1} + dx_{3} + J dx_{4} + mx_{1}^{2} dx_{6}$$

$$\omega_{3} = 2mx_{1}x_{6}dx_{1} + 2dx_{3} + J dx_{4} + mx_{1}^{2} dx_{6}$$

$$\omega_{4} = 2mx_{1}x_{6}dx_{1} + dx_{5} + J dx_{4} + mx_{1}^{2} dx_{6}$$

## Integrability of H2

In order to understand if H2 is fully integrable, we recall that: let  $V = span\{\omega_1, \omega_2, ..., \omega_r\}$  be a subspace of E. V is closed iff it has a basis made of closed one-forms only. In this case we built the bases in such a way, so we can say that H2 is integrable.