cores are defined as a body of soud which is used to form the hollow interior of the casting or a hole shrough the casting. These are prepared separately in a core box.

Core Sand: Houlding Sand + Organic binders + Inorganic binders (resins, ) iron oalde

Core Chaplets:

Chaplets are metal shapes used for supporting large and odd shaped cores which can not be adequately supported by itself.

the riser chills enidely used as they extract heat from the casting metal much more madely than does the moulding sond.

Chills are the small pieces of metal, capable of quick heat absorption. - Internal Chills -External Chills.

Padding is another method to promote directional solidification. Radding!