
5V DC
HDMI Cable, connected to monitor
USB Blaster

Step1: Open project CV_SOC_HDMI_TX.qpf by Quartus II 18.1 or newer version.



Step2: Make sure there’s no compilation issue happen. Then start the Programmer shown in below image.



Step3: Select chip on your board. 5CSEMA6, 5CSEBA6 or 5CSXFC6C6...



Step4: Select the test file: CV_SOC_HDMI_TX.sof



Step5: check the box named as “Program/Configure”. Then click the Start button.



Step6: Program result.



Step7: HDMI TX result.