## **Temperature and Humidity Logger**

Logs temperature and humidity values using DHT11/DHT22 sensor.

## Components:

- Arduino UNO
- DHT11 sensor
- SD Card module

Code will be uploaded using Arduino IDE.

## Connections:

- DHT to D2
- SD Card to SPI Pins

Thank you!

## **Arduino Code:**

```
#include <DHT.h>
#define DHTPIN 2
#define DHTTYPE DHT11
DHT dht(DHTPIN, DHTTYPE);

void setup() {
   Serial.begin(9600);
   dht.begin();
}

void loop() {
   float h = dht.readHumidity();
   float t = dht.readTemperature();
   Serial.print("Temp: ");
   Serial.print(t);
   Serial.print("C, Humidity: ");
   Serial.print(h);
   Serial.println("%");
```

```
delay(2000);
}
```