







R

DESCRIPTION

ITEM NO.

QTY

Assembly Instructions Not Pictured:

The dish is to be mounted to the uprights facing forward with 4 1/2" 8-32 SHCS, and ~3/4" diameter flat washers. Once this is done, the tube clamp screws at the base of the uprights should be fully tightened.

Once the dish is mounted, the counter rod assembly can be installed, and with the dish at near maximum elevation, the spring can be attached between the counter rod and spring anchor.

Spindle oil should be applied occasionally to gear interfaces, and other sliding interfaces.

The tripod mount on the bottom of the Box should only be used when working on the tripod, and removed at all other times.

NONE

DO NOT SCALE DRAWING

COMMENTS:

CORNERS

BREAK ALL EDGES AND SHARE

UNLESS OTHERWISE SPECIFIED:

DIMENSIONS ARE IN INCHES
INTERPRET GEOMETRIC
TOLERANCING PER:
ASME Y14.5-2009

MATERIAL

MFG APPR.
Q.A.

DATE 4/15/20
4/15/20
ASSEMBLY
SIZE DWG. NO.
MRT-ASM-FI

NO.
MRT-ASM-FL
REV

SCALE: 1:2 WEIGHT: SHEET 5 OF 5

B

A