TR34 (3rd edition) Free Movement Floor Tolerance Report

Allen Face Europe TR34 Analysis, ©Allen Face Europe, www.allenface-europe.com

1. Project Name: 방초리

2. Concrete Floor Installer:

5. Floor Tolerance Requirements:

3. Testing Organization:

안성시 일죽 방초리 221 **Project Location:**

인천광역시

일도티씨에스㈜

지상1층 #6 4. Slab ID: #REF! Date of Pouring:

Date of Testing: 2024-03-06

D-Meter® Manufactured by Allen Face&Company, Serial Number: 098 **Test Apparatus:**

TAEHYUN LEE (ALLEN FACE KOREA) **Testing Technician:**

ALLEN FACE KOREA			Test Area	:	89	m ² (for test area organization see attached drawing)								
TR3	TR34 3rd Edition convert into FF/FL ±값													
Floor Classification	Property II (mm)	Property IV (mm)	Property II (mm)	Property IV (mm)	등급	Property II		Property IV		OAFF	OAFL	MLFF	MLFL	
Floor Classification	95% limit	95% limit	100% limit	100% limit	ਰਜ	95%(mm)	100%(mm)	95%(mm)	100%(mm)	UAFF	UAFL	IVILFF	IVILEL	
FM1	2.5	4.5	4.0	7.0	FM1	2.5	4.0	4.5	7.0	31	47	18.6	28.2	
FM2(special)	3.0	6.5	4.5	10.0	FM2 Special	3.0	4.5	6.5	10.0	26	32	15.6	19.2	
FM2	3.5	8.0	5.5	12.0	FM2	3.5	5.5	8.0	12.0	22	26	13.2	15.6	
FM3	5.0	10.0	7.5	15.0	FM3	5.0	7.5	10.0	15.0	15	21	9	12.6	

6. Analysis:

	TR34 3rd Edition FREE MOVEMENT RESULTS																
Run #:		41	42	43	44	45	46	47	48								All Runs:
Run Length (m):		6.00	5.70	5.70	5.70	5.70	5.70	5.70	5.70								45.90
	Property II (95%)	YES	NO	NO	NO	NO	NO	YES	YES								NO
FM1	% Defective	0.00%	5.88%	17.65%	5.88%	11.76%	11.76%	0.00%	0.00%								6.57%
FIVII	Property IV (95%)	YES	NO	YES	NO	NO	NO	NO	YES								NO
	% Defective	0.00%	55.56%	0.00%	55.56%	66.67%	66.67%	22.22%	0.00%								33.12%
	Property II (95%)	YES	NO	NO	NO	NO	NO	YES	YES								NO
FM2(Special)	% Defective	0.00%	5.88%	11.76%	5.88%	11.76%	11.76%	0.00%	0.00%								5.84%
riviz(Special)	Property IV (95%)	YES	YES	YES	NO	NO	NO	YES	YES					 			NO
	% Defective	0.00%	0.00%	0.00%	11.11%	44.44%	11.11%	0.00%	0.00%								8.28%
	Property II (95%)	YES	NO	NO	YES	NO	NO	YES	YES								YES
FM2	% Defective	0.00%	5.88%	5.88%	0.00%	11.76%	11.76%	0.00%	0.00%								4.38%
FIVIZ	Property IV (95%)	YES	YES	YES	YES	NO	YES	YES	YES		<u> </u>	: :					YES
	% Defective	0.00%	0.00%	0.00%	0.00%	33.33%	0.00%	0.00%	0.00%								4.14%
	Property II (95%)	YES	YES	YES	YES	YES	NO	YES	YES								YES
FM3	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	5.88%	0.00%	0.00%								0.73%
FIVI 3	Property IV (95%)	YES	YES	YES	YES	NO	YES	YES	YES								YES
	% Defective	0.00%	0.00%	0.00%	0.00%	22.22%	0.00%	0.00%	0.00%								2.76%

7.	Summary:	The analysed D-Meter® Runs satisfy	FM2	the floor tolerance requirements.	
					ALLENFACE KOREA

TR34 (3rd edition) Free Movement Floor Tolerance Report

Allen Face Europe TR34 Analysis, ©Allen Face Europe, www.allenface-europe.com

1. Project Name: 방초리

2. Concrete Floor Installer:

5. Floor Tolerance Requirements:

안성시 일죽 방초리 221 **Project Location:**

인천광역시

일도티씨에스㈜

3. Testing Organization: ALLEN FACE KOREA

지상1층 #6 4. Slab ID:

#REF! Date of Pouring: Date of Testing: 2024-03-06

D-Meter® Manufactured by Allen Face&Company, Serial Number: 098 **Test Apparatus:**

TAEHYUN LEE (ALLEN FACE KOREA) **Testing Technician:**

m² (for test area organization see attached drawing) Test Area:

TR3	4 (3rd Edition) FRE	TR34 3rd Edition convert into FF/FL ±값											
Floor Classification	Property II (mm)	ty II (mm) Property IV (mm) P		Property IV (mm)	등급	Property II		Property IV		OAFE	O A FI	NALEE	MLFL
Floor Classification	95% limit	95% limit	100% limit	100% limit	0 1	95%(mm)	100%(mm)	95%(mm) 100%(mm)		UAFF	OAIL	IVILIT	IVILFL
FM1	2.5	4.5	4.0	7.0	FM1	2.5	4.0	4.5	7.0	31	47	18.6	28.2
FM2(special)	3.0	6.5	4.5	10.0	FM2 Special	3.0	4.5	6.5	10.0	26	32	15.6	19.2
FM2	3.5	8.0	5.5	12.0	FM2	3.5	5.5	8.0	12.0	22	26	13.2	15.6
FM3	5.0	10.0	7.5	15.0	FM3	5.0	7.5	10.0	15.0	15	21	9	12.6

6. Analysis:

	TR34 3rd Edition FREE MOVEMENT RESULTS																	
Run #:		41	42	43	44	45	46	47	48									All Runs:
Run Length (m):		6.00	5.70	5.70	5.70	5.70	5.70	5.70	5.70									45.90
	Property II (100%)	YES	YES	YES	YES	NO	NO	YES	YES									NO
FM1	% Defective	0.00%	0.00%	0.00%	0.00%	5.88%	11.76%	0.00%	0.00%									2.19%
FIVII	Property IV (100%)	YES	YES	YES	NO	NO	NO	YES	YES									NO
	% Defective	0.00%	0.00%	0.00%	11.11%	44.44%	11.11%	0.00%	0.00%								ĺ	8.28%
	Property II (100%)	YES	YES	YES	YES	NO	NO	YES	YES									NO
FM2(Special)	% Defective	0.00%	0.00%	0.00%	0.00%	5.88%	11.76%	0.00%	0.00%									2.19%
riviz(Special)	Property IV (100%)	YES	YES	YES	YES	NO	YES	YES	YES									NO
	% Defective	0.00%	0.00%	0.00%	0.00%	22.22%	0.00%	0.00%	0.00%								İ	2.76%
	Property II (100%)	YES	YES	YES	YES	YES	YES	YES	YES									YES
FM2	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%									0.00%
FIVIZ	Property IV (100%)	YES	YES	YES	YES	NO	YES	YES	YES						 			NO
	% Defective	0.00%	0.00%	0.00%	0.00%	22.22%	0.00%	0.00%	0.00%								İ	2.76%
	Property II (100%)	YES	YES	YES	YES	YES	YES	YES	YES									YES
FM3	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%									0.00%
FIVI3	Property IV (100%)	YES	YES	YES	YES	YES	YES	YES	YES		İ	Ť			 <u> </u>	T T		YES
	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%									0.00%

 NFACE KOREA