TR34 (3rd edition) Free Movement Floor Tolerance Report

Allen Face Europe TR34 Analysis, ©Allen Face Europe, www.allenface-europe.com

1. Project Name: 방초리

2. Concrete Floor Installer:

5. Floor Tolerance Requirements:

3. Testing Organization:

안성시 일죽 방초리 221 **Project Location:**

한성시

일도티씨에스㈜

지상1층 #1 4. Slab ID:

#REF! Date of Pouring: 2024-03-06 Date of Testing:

D-Meter® Manufactured by Allen Face&Company, Serial Number: 098 **Test Apparatus:**

Testing Technician: TAEHYUN LEE (ALLEN FACE KOREA)

ALLEN FACE KOREA			Test Area	:	89 m² (for test area organization see attached drawing)									
TR3	4 (3rd Edition) FRE	TR34 3rd Edition convert into FF/FL ±값												
Floor Classification	Property II (mm)	Property IV (mm)	Property II (mm)	Property IV (mm)	등급	Property II		Property IV		OAFF	OAFL	MLFF	MLFL	
FIOOT Classification	95% limit	95% limit	100% limit	100% limit	ਰਜ	95%(mm)	100%(mm)	95%(mm) 100%(mm)		UAFF	UAFL	IVILEE	IVILIT	
FM1	2.5	4.5	4.0	7.0	FM1	2.5	4.0	4.5	7.0	31	47	18.6	28.2	
FM2(special)	3.0	6.5	4.5	10.0	FM2 Special	3.0	4.5	6.5	10.0	26	32	15.6	19.2	
FM2	3.5	8.0	5.5	12.0	FM2	3.5	5.5	8.0	12.0	22	26	13.2	15.6	
FM3	5.0	10.0	7.5	15.0	FM3	5.0	7.5	10.0	15.0	15	21	9	12.6	

6. Analysis:

	TR34 3rd Edition FREE MOVEMENT RESULTS																		
Run #:		1	2	3	4	5	6				i			į			i		All Runs:
Run Length (m):		6.90	6.90	6.90	6.90	6.90	6.90									<u> </u>			41.40
	Property II (95%)	NO	YES	NO	YES	YES	YES												YES
FM1	% Defective	9.52%	0.00%	9.52%	0.00%	4.76%	0.00%												3.97%
FIVII	Property IV (95%)	NO	NO	NO	YES	NO	YES												NO
	% Defective	15.38%	23.08%	15.38%	0.00%	7.69%	0.00%	į	-							į			10.26%
FM2(Special)	Property II (95%)	YES	YES	YES	YES	YES	YES	•	•							•			YES
	% Defective	4.76%	0.00%	0.00%	0.00%	0.00%	0.00%									İ			0.79%
	Property IV (95%)	YES	NO	YES	YES	YES	YES												YES
	% Defective	0.00%	15.38%	0.00%	0.00%	0.00%	0.00%												2.56%
	Property II (95%)	YES	YES	YES	YES	YES	YES												YES
FM2	% Defective	4.76%	0.00%	0.00%	0.00%	0.00%	0.00%												0.79%
FIVIZ	Property IV (95%)	YES	NO	YES	YES	YES	YES	! !								<u> </u>			YES
	% Defective	0.00%	7.69%	0.00%	0.00%	0.00%	0.00%		•										1.28%
	Property II (95%)	YES	YES	YES	YES	YES	YES												YES
5140	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%												0.00%
FM3	Property IV (95%)	YES	YES	YES	YES	YES	YES												YES
	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%												0.00%

7. Summary: The analysed D-Meter® Runs satisfy FM2(Special) the floor tolerance requirements.

ALLENFACE KOREA

TR34 (3rd edition) Free Movement Floor Tolerance Report

Allen Face Europe TR34 Analysis, ©Allen Face Europe, www.allenface-europe.com

1. Project Name: 방초리

2. Concrete Floor Installer:

5. Floor Tolerance Requirements:

3. Testing Organization:

안성시 일죽 방초리 221 **Project Location:**

한성시

일도티씨에스㈜

지상1층 #1 4. Slab ID:

#REF! Date of Pouring: Date of Testing: 2024-03-06

D-Meter® Manufactured by Allen Face&Company, Serial Number: 098 **Test Apparatus:**

Testing Technician: TAEHYUN LEE (ALLEN FACE KOREA)

ALLEN FACE KOREA			Test Area	89	m ² (for test area organization see attached drawing)								
TR	34 (3rd Edition) FRE	TR34 3rd Edition convert into FF/FL ±값											
Floor Classification	Property II (mm)	Property IV (mm)	Property II (mm)	Property IV (mm)	등급	Property II		Property IV		OAFF	OAEL	NALEE	MLFL
Floor Classification	95% limit	95% limit	100% limit	100% limit	- Б н	95%(mm)	100%(mm)	95%(mm)	100%(mm)	UAFF	OAFL	IVILFF	IVILFL
FM1	2.5	4.5	4.0	7.0	FM1	2.5	4.0	4.5	7.0	31	47	18.6	28.2
FM2(special)	3.0	6.5	4.5	10.0	FM2 Special	3.0	4.5	6.5	10.0	26	32	15.6	19.2
FM2	3.5	8.0	5.5	12.0	FM2	3.5	5.5	8.0	12.0	22	26	13.2	15.6
FM3	5.0	10.0	7.5	15.0	FM3	5.0	7.5	10.0	15.0	15	21	9	12.6

6. Analysis:

	TR34 3rd Edition FREE MOVEMENT RESULTS																		
Run #:		1	2	3	4	5	6												All Runs:
Run Length (m):		6.90	6.90	6.90	6.90	6.90	6.90					<u> </u>			<u> </u>			<u> </u>	41.40
	Property II (100%)	YES	YES	YES	YES	YES	YES											İ	YES
FM1	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%												0.00%
FIVI	Property IV (100%)	YES	NO	YES	YES	YES	YES					T			T			T	NO
	% Defective	0.00%	15.38%	0.00%	0.00%	0.00%	0.00%	<u> </u>							ļ			ļ	2.56%
FM2(Special)	Property II (100%)	YES	YES	YES	YES	YES	YES												YES
	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%												0.00%
	Property IV (100%)	YES	YES	YES	YES	YES	YES			<u> </u>	1	<u> </u>			1	 <u> </u>		†	YES
	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	<u> </u>											0.00%
	Property II (100%)	YES	YES	YES	YES	YES	YES												YES
FM2	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%												0.00%
FIVIZ	Property IV (100%)	YES	YES	YES	YES	YES	YES					<u> </u>	1		T	 		†	YES
	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	<u> </u>											0.00%
	Property II (100%)	YES	YES	YES	YES	YES	YES												YES
5143	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%												0.00%
FM3	Property IV (100%)	YES	YES	YES	YES	YES	YES	Ì		Ť	İ	Ť		<u> </u>	<u> </u>	 Ť	<u> </u>	Ť	YES
	% Defective	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%												0.00%

FM2(Special) the floor tolerance requirements. 7. Summary: The analysed D-Meter® Runs satisfy

ALLENFACE KOREA

