


More Advanced Step Counter

Step 1: First test out and show accelerometer values:



See what number is used at rest, no movement and what number shows when you take step. These are your two threshold numbers

Step 2: Advanced Step Counter:

The rest threshold we found was 1100 and for movement was 1250 as shown below. Yours may be different. So first figure this out in step 1.

