Reason	Number of	Total Delay
	Incidents	Minutes
Train cancelled at FOC request or	11090	562698
planned not to run		
Delays un-investigated	81424	202455.25
Driver	23544	131029.17
Technical failures below the sole-	15619	105974.624
bar Track circuit failure	17023	103260.25
Traincrew rostering problem	7926	100502.782
Fatalities or injuries caused by be-	9389	92815.8
ing hit by train (including non-		
intentional)		
Broken/cracked/twisted/buckled/fl	awed $15057$	91952.8
rail Technical failures above the Sole-	12136	85265.06
bar Brake and brake systems faults;	8841	71607.07
including wheel flats where no		
other cause had been identified Points failure	10542	70070.15
NZ Pumps T	38749	69702.865
Severe flooding beyond that which	5855	67663.9
could be mitigated on Network		
Rail infrastructure External power supply failure NR	6584	56781.7
Infrastructure		

Number of	Total Delay
Incidents	Minutes
10832	52100.44
19478	51901.1
6397	49365
5586	48001.65
26598	45980.555
7951	43775.03
7169	41738.34
7548	40769.87
4769	40115.92
7217	38210.612
	33631.33
8088	32991.66
2259	31151.3
4442	29855.7
4977	29769.82
4185	28772
	Incidents 10832  19478 6397  5586 26598 7951 7169  7548 4769  7317 3827 8088  2259  4442 4977

Reason	Number of	Total Delay
	Incidents	Minutes
Rail / wheel interface, adhesion	13393	28453.83
problems (including ice on the		
running rail)		
Delays not properly investigated	4469	28090.3
by Network Rail		
Train crew not available	3174	27255.5
Passengers joining/alighting	9264	26613.68
Delays incurred on non-Network	6448	25261.5
Rail running lines incl. LT causes		
(except T&RS)		
Confirmed train cab based safety	3895	25199.97
system fault (including GSMR)		
Waiting acceptance into off Net-	2326	24981.5
work Rail network Terminal or		
Yard		
Late start/yard overtime not ex-	3509	23890
plained by Operator		227-1 25
Other Passenger Train Operating	5772	23571.97
Company causes	9091	01.670.7
Planned underpowered or short-	3931	21679.7
formed service and or vehicle, incl.		
exam set swaps	2075	20570.4
Msc items (inc.trees) causing	3275	20570.4
obstructions not result T&V,		
weather or fallen/thrown from		
trains		

Reason	Number of	Total Delay
	Incidents	Minutes
Possession over-run from planned	2889	20386.81
work Disorder/drunks or trespass	3851	20360.79
Wagons, coaches and parcel vehi-	1803	20170.75
cle faults Train schedule/STP Process in-	4461	19603.5
cluding erroneous simplifiers Axle Counter Failure	3244	19158.8
Telecom equipment failure	2037	17336.3
Waiting Train preparation or	1839	16604.5
completion of TOPS list/RT3973 Delay believed to be due to Operator but no information available	6037	16558.744
from Operato Special working for leaf-fall track	2865	16152.8
circuit operation Delayed by signaller not applying	4015	15796.08
applicable regulating policy Adhesion problems due to leaf	1978	15490.54
contamination Severe weather not snow affecting	2072	15153.6
infrastructure the responsibility of		
Network Rail Delay in running believed due to	4293	15019.6
Operator but no info available		
from Operator		

Reason	Number of	Total Delay
	Incidents	Minutes
WTT schedule and or LTP Pro-	2194	14404.5
cess including erroneous simpli-		
fiers Electic Loco failure, defect, atten-	1595	14003
tion Communication cord or emer-	3087	13925.3
gency train alarm operated Signalling Functional Power Sup-	2062	13815.55
ply Failure Other FOC causes incl. FOC con-	1957	13728.5
trol directive, cause to be speci- fied, including mishaps		
Takeback Pumps	6809	13399.365
Reactionary Delay to "P" coded	4756	12988.1
TSRs Level crossing failure incl. barrow/foot crossings & crossing	2572	12908.6
treadles Vandalism or theft (including the	2037	12819.33
placing of objects on the line)	1500	10041 7
Freight train driver	1528	12241.7
Level Crossing Incidents including	2068	11973.3
misuse Train-crew/loco/stock/unit	1830	11462.94
diagram issues NR staff oversight or error (Maint / Infrastructure)	2050	11436.1

Reason	Number of	Total Delay
	Incidents	Minutes
Cautioning due to railhead leaf	1698	10295.94
contamination Coupler and Coupler system	1730	10260.8
faults Structures -	1929	9989
Bridges/tunnels/buildings/embank	ments	
(not bridge strikes)		
Congestion in off Network Rail	951	9681
network Terminal or Yard External trees, buildings or ob-	1201	9290.544
jects encroaching onto Network		
Rail infrastructure (not due to		
weather or vandalism)		
OTM DAMAGE	1615	9159.85
Power Supply And Distribution	1675	8792.2
System Failure		
Confirmed Pantograph ADD,	1182	8660.86
shoe beam or assoc. system		
faults inlc. positive PANCHEX		
activations		
Block failure	432	8308.1
Flooding not due to exceptional	951	8012.5
weather Reported fleet equipment defect -	1315	7944.48
no fault found		

Reason	Number of	Total Delay
	Incidents	Minutes
Customer or off Network Rail	304	7645
network yard equipment break-		
down/reduced capacity		
Late start or delay to Railhead	3701	7514.422
Conditioning Train (RHC) includ-		
ing any reactionary delay to other		
trains AC/DC trip	889	7473.8
Gas/water mains/overhead power	1208	7431.6
lines Delay at unstaffed station to non-	2145	7422
DOO train	9915	7974
Unexplained station overtime	3315	7374
Other Station Operating causes	2295	7329.3
Failure to maintain vegetation	1703	7261
within network boundaries in ac-		
cordance with prevailing Network		
Rail standards Earthslip/subsidence/breached	3246	7102.4
sea defences (not the result of		
severe weather on the day of		
failure)		
Other Network Rail operating	2571	6975.1
causes Condition of Track TSR outside	4276	6944
the Timetable Planning Rules		

10000011	1 Tulliber of	10tai Delay
	Incidents	Minutes
Vandalism or theft	1098	6692.67
Animal Strike or incursion not	1075	6216.5
within the control of Network Rail Bumps reported - cause not	624	5972.03
known re-booked assistance for a per-	1805	5958.5
son with reduced mobility join-		
ing/alighting, Off Network Rail network Termi-	457	5930.6
nal or Yard staff shortage includ-		
ing reactionary congestion caused		
by shortage		
Technical failure associated with a	1234	5725.4
Railhead conditioning train		
Failure to lay Sandite or oper-	1784	5594.5
ate Railhead Conditioning train		
as programmed		
Other Infrastructure causes	1277	5566.6
Fatalities and or injuries sustained	1345	5533.7
on platform result of struck by		
train or falling from a train		
Confirmed train borne safety sys-	873	5358.31
tem faults (not cab based)		
Engineers on-track equipment	2032	5283
C •1	1	1

Number of

Total Delay

Reason

failure outside possession

Reason	Number of	Total Delay
	Incidents	Minutes
ARS software problem (exclud-	1358	5249
ing scheduling issues and technical		
failures)		
ESR/TSR Work not comp/canx	2311	5168.58
pssn (restriction did not exist		
prior to pssn)		
TSR speeds for Track-work out-	4199	5033
side the Rules of the Route		
Telecom radio failures	868	4773.6
IVRS/GSM-R		
lanning issues including loco dia-	478	4522
grams or RT3973 restriction not		
requested		
Delays a result of track patrolling	1066	4442.1
blocks OHLE/third rail power supply	499	4323.9
failure or reduction Station delays due to special	1048	4202.8
events e.g. sports fixtures	1010	1202.0
Station staff error - e.g wrong an-	902	4110.8
nouncements misdirection Fires starting on Network Rail In-	540	4010
frastructure Train diverted/re-routed at FOC	329	3982.5
request		
Other passenger or external	735	3973.47
causes the responsibility of TOC		

	4	
Ξ	Ξ	
	ン	

Reason	Number of	Total Delay
	Incidents	Minutes
Weather - effect on T&RS equip-	499	3619.84
ment Waiting connections from other	604	3613.42
transport modes		
Station Staff unavailable - missing	871	3592.08
or uncovered Train striking bird (pheasant or	477	3480.035
smaller)		
Late presentation from the conti-	345	3402
nent Freight train running at lower	686	3279
class or speed than planned clas-		
sification or overweight		
Police searching train	612	3201.5
VSTP Schedule/ VSTP Process	851	3118
(TSI created schedule)		
Un-booked assistance for a per-	900	2917.5
son with reduced mobility join-		
ing/alighting,		
Engineers train late or failed in	1209	2749.5
possession	1200	2130.0
Mishap-Train Operating Com-	349	2680.5
	010	2000.0
pany cause Trackside sign blown down, miss-	577	2645.5
ing, defective, mis-placed	011	2040.0
mg, defective, mis-placed		I

Reason	Number of	Total Delay
	Incidents	Minutes
Road related - excl bridge	421	2643.5
strikes/level crossing incident AWS/ATP/TPWS/Train	673	2596.1
stop/On track equipment failure Train cancelled or delayed at	421	2421
Train Operators request Failure of off network infrastruc-	307	2285
ture (FOC or private) Animal Strike or Incursion within	382	2277
the control of Network Rail Security alert affecting stations	319	2153.75
and depots Late TRTS given by station staff	619	1912.5
Blanket speed restriction for ex-	360	1883
treme heat or high wind in accordance with the Group Standards Ticket irregularities or refusals to	437	1834
pay Non severe weather - snow/ice/frost affecting in-	153	1729
frastructure equipment Wagon load incident including ad-	112	1661
justing loads or open door Other Freight Operating Com-	121	1646.5
pany cause, to be specified, in off network terminals or yards		

Reason	Number of	Total Delay
	Incidents	Minutes
Delayed as a result of Route Con-	373	1622.5
trol decision or directive Driver adhering to company pro-	418	1594.37
fessional driving standards or pol-		
icy		
Signal Box not open during	171	1525
booked hours Points failure caused by snow or	249	1452
frost where heaters are not fitted Regulation Decision Made With	354	1426
Best Endeavours Sanders and scrubber faults	134	1370.2
Fire external to railway infras-	236	1318.222
tructure HABD/PANCHEX/WILD Fail-	204	1278
ure (no fault found/wrong detec-		
tion)		
Incorrect train dispatch by station	321	1208.5
staff Attaching/detaching/shunter/wate	ring 259	1192
Other external causes the respon-	297	1183.5
sibility of Network Rail Sunlight on signal or dispatch	324	1180
-	324	1100
equipment Telecom equipment failures legacy	72	1111
(inc.NRN/CSR/RETB link)		
Train held at FOC request	69	1062

Reason	Number of	Total Delay
	Incidents	Minutes
Visability in semaphore signalled	288	1018
areas, or special workings for fog		
and falling snow implemented by		
Network Rail - in all signa		
On train TASS/TILT failure	312	982.5
Security alert affecting Network	150	976.25
Rail		
Delay caused by Operating staff	124	942.5
oversight, issues or absence (ex-		
cluding signallers and Control)		
Incorrect route taken or route	119	899
wrongly challenged by driver incl		
SPADs	055	0745
Planned engineering work - diver-	255	874.5
sion/SLW not timetabled (outside		
the Timetable Planning Rules)		
Severe snow affecting infrastruc-	88	873
ture the responsibility of Network		
Rail Technical Fleet Holding Code	216	835.15
Train Operating Company Direc-	333	828.7
tive		
Customer Information system	168	686
<u>f</u> ailure		
Late presentation from Europe	64	685
Unexplained late start	296	662

Reason	Number of	Total Delay
	Incidents	Minutes
Severe weather affecting pas-	111	631
senger Fleet equipment in-		
cluding follwogin company		
standards/policies or Rule book		
instructions Mishap - Station Operating	110	622
causes Cable vandalism or theft	89	588.91
Station staff split responsibility -	155	490
unable to cover all duties Loading or unloading un-reserved	179	481
bicycles		
Passengers taken ill on platform	118	462.77
Incorrect simplifier	123	462.5
Unattributed Cancellations	30	441.3
Passenger dropped object whilst	118	426
boarding/alighting from train and		
train delayed at TOC request		
Locating lost luggage	103	422
Lightning Strike - damage to pro-	95	409
tected systems		
Driver adhering to company pro-	112	324.5
fessional driving standards or poli-		
cies during severe weather that are		
not fleet related		

Reason	Number of	Total Delay
	Incidents	Minutes
Waiting connections from other	49	311.5
transport modes		
Network Rail staff oversight or	80	306
error (Maintenance / Infrastruc-		
ture)		
Swing bridge open for river or	34	297
canal traffic		
Token Equipment Failure	26	292
Train catering staff (including	44	268
Contractors)		
Waiting connections - not autho-	78	258
rised by TOC Control		
Conn held where the prime inci-	48	255
dent causing delay to the incom-		
ing train is a FOC owned incident		
& serv is more freq than hourly		
Lift/escalator defect/failure	55	248
Driver adhering to company pro-	37	243
fessional driving standards or pol-		
icy		
Delay accepted by Network Rail	92	200.5
as part of commercial agreement		
where no substansive delay reason		
is identified		
Ice on conductor rail/OHLE	30	185
Special Stop Orders	51	179

Reason	Number of	Total Delay
	Incidents	Minutes
Tail lamp or headlamp missing,	32	160
not lit or wrongly displayed		
Loading or unloading reserved bi-	56	155
cycles		
Special Stop Orders - authorised	44	152
by TOC Control (including any		
delay at point of issue)		
Infrastructure Fault Report	32	142
Proven To Be Mistaken		
Points failure due snow/frost	25	140
where heaters fitted but not op-		
erative or defectiv		
Tail lamp/head lamp out or incor-	13	125
rectly shown		
Steam locomotive fail-	71	120.5
ure/defect/attention		
Loading excessive luggage	33	103
Dangerous Goods incident	9	97
Preventative Maintenance to the	29	88
infrastructure in response to a Re-		
mote Condition Monitoring Alert		
Station evacuated due to fire	27	83
alarm		
International/Channel Tunnel lo-	4	67
comotive failure/defect/attention		

Reason	Number of	Total Delay
	Incidents	Minutes
ETCS/ERTMS Equipment Fail-	17	64
ure (excl. communications link		
and balises)		
Fire in station building/platform	14	56
affecting operators not booked to		
call at that stations		
Police searching the line	10	54
Failure of TRUST or SMART sys-	11	52
tem preventing recording and in-		
vestigation of delay		
Waiting passenger connections	11	46
authorised by TOC but out-		
with TOC/Network Rail connec-		
tion policy		
Infrastructure Safety Issue Re-	11	40
ported by Member of the Public		
- No Fault Found		44.5
Fire caused by vandalism	4	38.5
Loading Supplies (including cater-	10	37
ing)		
Connection authorised by TOC	5	17
but outwith Connection Policy		
Passenger charter excludable	5	16
events occurring on the LUL or		
other non NR running lines		
Infrastructure Balise Failure	11	15.5

Reason	Number of	Total Delay
	Incidents	Minutes
Reactionary Delay to 'P' coded	6	13
Possession Delay due to ETCS/ERTMS on-	290	13
board overriding driver command Special stop orders - not autho-	3	11
rised by TOC Control Delay in running due to the in-	1	0
correct operation of the on-board		
ETCS/ERTMS equipment - i.e. wrong input by driver		
Total	619806	3523705.25