


Wiring Diagram



Rotation:

CW Direction	Step	A	C	В	D
	1	+		+	
	2		+	+	
	3		+		+
	4	+			+
	1	+		+	

CW Direction, see from the flange side.

												DONGZHENG MOTOR		
REV.	QTY.	No. SIG.		DATE						57STH56-2804MB				
DESIGN Zhu (anghua 2013.09.		09 STD.			CLS. MA		. MAK	QTY	SCALE	STEPPER MOTOR		
CHECK	-	+		+			S				1:1	007 959 001	REV	
PROC.		\top		APPR.			PA	PAGE		0F		ODZ. 253. 001		