

UYEMURA TECHNICAL CENTER

Danielle Dilley

240 Town Line Road Southington, CT. 06489 TEL: (860) 793-4011 FAX: (860) 793-4020

Email: Ddilley@uyemura.com

Lab Report

IBM

Date of sample	10/15/19	Standard	10/28/19	Standard	10/29/19	Standard
UIC Number	6273	Bath		Bath		Bath
Type of Bath	ANP 1012	Conditions	ANP 1012	Conditions	ANP 1012	Conditions
MTO						
pH	4.38		4.39		4.45	
Specific Gravity (Be)	1.0547		1.0542		1.0616	
MTO dependent						
Type of Plating Test						
Temperature of Test						
Current						
Time						
Agitation Mode						
Bright Plate Range ASF						
Efficiency mg/amp. min.						
Nickel g/Litre	3.55		3.58		4.11	
Hypophosphite g/Litre	21.8		21.4		27.1	
Brightener percent	83%		58%		75%	
Nitrate						
Orthophosphite mol/L	0.0310		0.0315		0.00425	

Comments: 10/15 and 10/28 hypo concentrations are low.

Please reply with questions.