
Fletched arrows
Bare shafts
Good
(a)
Arrows too stiff
or button too firm
(b)
Arrows too weak
or button too soft
(c)
Nocking point too high
(d)
Nocking point too low
(e)