

Good

(a)



Arrows too stiff
or button too firm

(b)



Arrows too weak
or button too soft

(c)



Nocking point too high

(d)



Nocking point too low

(e)