




Sign of reaction torque s_i (in yaw):

-  Clockwise (CW), $s_i = -1$
-  Counter-clockwise (CCW), $s_i = +1$