1 Accuracy and Repeatability

Why is accuracy less than repeatability?

Accuracy is generally defined as how close the manipulator can come to a given point in its workspace. Note that this point is described by the operator. It has to be given coordinates within the robot's internal reference frame for the robot to know where the point is. Therefore, the accuracy of a robot combines two sources of error:

- 1. Differences between the operator coordinate system and robot coordinate system due to measurement error in setting up the robot system.
- 2. Movement errors within the robot coordinate system.

In contrast, the repeatability, which is usually defined as how close a manipulator can return to a previously taught point, eliminates the first source of error. The point may have different descriptions in our coordinate system and the robot's coordinate system. However, during the teaching, the operator verified that the point in the robot coordinate system corresponds perfectly with the point the operator desired it to be. Therefore, error can only come from the robot failing to move perfectly to the point that it intends to move to.

For a robot to be accurate, however, the operator must describe the point in the robot's frame, so that the robot intends to move where the operator intends it to move. It is this additional step which makes accuracy more difficult than repeatability.

2 Improving accuracy with Sensing

How could manipulator accuracy be improved with endpoint sensing? What difficulties might endpoint sensing introduce into the control problem?

2.1 Improving accuracy with Endpoint Sensing

Endpoint sensing refers to placing sensors on the end-effector of a robot manipulator in order to give it information about what it is doing.

These sensors might addess problem (1) above. Let's think of an example.

Suppose a robot manipulator is trying to grasp a fork. The operator will measure the pose of the fork, convert that pose measurement in their frame into a position measurement in the robot's frame, and then instruct the robot to grasp a fork at the desired pose.

If the robot lacks endpoint sensors, all it can do is grasp as if there is a fork at the desired point, bindly trusting the operator. However, if the robot has endpoint sensors, it can compare the instructions with what it senses itself. As the manipulator approaches the fork, it will be able to make more accurate measurements with its endpoint sensor. The closer the robot gets, the more it should trust its endpoint sensors over the operator data. This improves accuracy because it allows new measurements of the location of the specific point in the robot's frame, which let it get more information. This can all be summarized in the Bayesian formalism by using the user- provided data as a prior, and updating the distribution of beliefs in poses with its measurements. Endpoint sensing addresses the description error mentioned in part (1), because it uses sensors to make sure that the robot's intended target isn't far off from the real-world target.

2.2 Additional Difficulties from Endpoint Sensing

Endpoint sensing brings with it additional difficulties. Without endpoint sensing, the control problem is merely moving from one point in manipulator state space to another. Once endpoint sensing is introduced, however, one has to either stop the manipulator with each measurement, or make the measurements while

the manipulator is moving and then retarget the manipulator on the fly. Stopping the manipulator with each measurement would be much slower, and making dynamic measurements might make calculations more difficult because of the additional kinematics.

SO(n)

We show that $SO(n) = \{M \in \mathbb{R}^{n \times n} \mid \det(M) = 1, M^TM = 1_{n \times x}\}$ is a group under matrix multiplication. Since $SO(n) \subseteq \mathbb{R}^{n \times n}$, which is itself a multiplicative group, it suffices to show that, for each $M, N \in SO(n)$, the following properties hold:

- 1. $MN \in SO(n)$
- 2. $M^{-1} \in SO(n)$

along with the additional property that $1_{n \times n} \in SO(n)$.

1) Suppose $M, N \in SO(n)$. Then, $M^TM = 1$, and det(M) = 1. Consider MN.

$$\det(MN) = \det(M) \det(N) = (1)(1) = 1$$

$$(MN)^{T}(MN) = N^{T}M^{T}MN = N^{T}1_{n \times n}N = N^{T}N = 1_{n \times n}$$

Therefore, $MN \in SO(n)$.

2) Suppose $M \in SO(n)$. Then, $M^TM = 1_{n \times n}$. Therefore, $M^{-1} = M^T$. Since $(M^T)^T M^T = MM^T = MM^{-1} = 1_{n \times n}$. Also, $\det(M^T) = \det(M) = 1$. Therefore, $M^T = M^{-1} \in SO(N)$.

3)

$$1_{n \times n} \in \mathbb{R}^{n \times n}$$
$$\det(1_{n \times n}) = 1$$
$$1_{n \times n}^{T} 1_{n \times n} = 1_{n \times n}$$

Therefore, $1 \in SO(n)$.

We have shown that SO(n) is a multiplicative subgroup of $\mathbb{R}^{n \times n}$. We inherit associativity from $\mathbb{R}^{n \times n}$. Therefore, SO(n) is a multiplicative group.

4 Sequence of Rotations

I am tasked with doing the following sequence of rotations:

- 1. Rotate by ϕ around the world x-axis
- 2. Rotate by θ around the world z-axis
- 3. Rotate by ψ around the current x-axis
- 4. Rotate by α around the world z-axis

Recall the rules for composing rotations: If the current rotation matrix is R, and you want to apply a rotation matrix S relative to the current frame, the result is RS. If you want to apply a rotation relative to the fixed frame, the result is SR.

4.1 Describing the Rotations

The first matrix, which rotates ϕ about the x-axis, is:

$$\begin{pmatrix}
1 & 0 & 0 \\
0 & \cos \phi & -\sin \phi \\
0 & \sin \phi & \cos \phi
\end{pmatrix}$$

The second matrix, which rotates by θ about the z axis, is:

$$\begin{pmatrix}
\cos\theta & -\sin\theta & 0 \\
\sin\theta & \cos\theta & 0 \\
0 & 0 & 1
\end{pmatrix}$$

The third matrix, which rotates by ψ about the x-axis, is:

$$\begin{pmatrix}
1 & 0 & 0 \\
0 & \cos \psi & -\sin \psi \\
0 & \sin \psi & \cos \psi
\end{pmatrix}$$

The fourth matrix, which rotates by α about the z-axis, is:

$$\begin{pmatrix} 1 & 0 & 0 \\ 0 & \cos \alpha & -\sin \alpha \\ 0 & \sin \alpha & \cos \alpha \end{pmatrix}$$

We can denote them as R_{ϕ} , R_{θ} , R_{ψ} , and R_{α} .

4.2 Composing the Rotations

We start with 1 as our rotation matrix. Using the rules above, we do the rotations in the following steps:

- 1. R_{ϕ}
- 2. $R_{\theta}R_{\phi}$
- 3. $(R_{\theta}R_{\phi})R_{\psi}$
- 4. $R_{\alpha}((R_{\theta}R_{\phi})R_{\psi})$

Since matrix multiplication is associative, the product is therefore:

$$\begin{pmatrix} 1 & 0 & 0 \\ 0 & \cos \alpha & -\sin \alpha \\ 0 & \sin \alpha & \cos \alpha \end{pmatrix} \begin{pmatrix} \cos \theta & -\sin \theta & 0 \\ \sin \theta & \cos \theta & 0 \\ 0 & 0 & 1 \end{pmatrix} \begin{pmatrix} 1 & 0 & 0 \\ 0 & \cos \phi & -\sin \phi \\ 0 & \sin \phi & \cos \phi \end{pmatrix} \begin{pmatrix} 1 & 0 & 0 \\ 0 & \cos \psi & -\sin \psi \\ 0 & \sin \psi & \cos \psi \end{pmatrix}$$

5 Homogenous Transformations

Refer to diagram 2.14 in Spong. A robot is set up 1 meter from a table. The table top is 1 meter high and 1 meter square. A frame $0_1x_1y_1z_1$ is fixed to the edge of the table as shown. A cube measuring 20 cm on a side is placed at the center of the table with frame $0_2x_2y_2z_2$. established at the center of the cube as shown. A camera is situated directly above the center of the block, 2 meters above the table top with frame $0_3x_3y_3z_3$ attached to it as shown. Find the homogenous transformation relating each of these frames to the base frame. Find the homogenous transformation relating frame 2 to frame 3.

5.1 Frame 1 to Frame 0

Frame 1 and frame 0 agree in orientation, and differ only by a translation. Frame 1 is (0, 1, 1) away from frame 0. Therefore, the following homogenous transformation will go from 1 to 0:

$$\begin{pmatrix} 1 & 0 & 0 & 0 \\ 0 & 1 & 0 & -1 \\ 0 & 0 & 1 & -1 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

5.2 Frame 2 to Frame 0

Like before, frame 2 and frame 0 agree in orientation, and differ only by a translation. The problem said that frame 2 is placed in the center of a cube measuring 20 cm on each side. Therefore, the frame is 0.5 meters in the x and y directions from the corner of the tabletop, and 0.1 meters vertically from the tabletop. We can add this vector to the difference between 1 and 0, to get that a vector $\langle -0.5, 1.5, 1.1 \rangle$ translates frame 0 to frame 2. Therefore the following homogenous transformation goes from 0 to 2:

$$\begin{pmatrix}
1 & 0 & 0 & 0.5 \\
0 & 1 & 0 & -1.5 \\
0 & 0 & 1 & -1.1 \\
0 & 0 & 0 & 1
\end{pmatrix}$$

5.3 Frame 3 to Frame 0

Unlike before, frame 3 and frame 0 do not agree in orientation. The z-axis in frame 3 is the negative of the z-axis in frame 0, and the x and y axes are switched. Therefore, the following rotation matrix puts them in alignment:

$$\begin{pmatrix} 0 & 1 & 0 \\ 1 & 0 & 0 \\ 0 & 0 & -1 \end{pmatrix}$$

The frame is located 2m above the table top, in line with the center of the block. Therefore, it is (0.5, 0.5, 2) from frame 1, with that vector in frame 1's coordinates. Consequently the homogenous transformation sending frame 3 to frame 1 is:

$$\begin{pmatrix}
0 & 1 & 0 & 0.5 \\
1 & 0 & 0 & -1.5 \\
0 & 0 & -1 & -3 \\
0 & 0 & 0 & 1
\end{pmatrix}$$

5.4 Frame 3 to Frame 2

To homogenously transform Frame 3 directly to frame 2, first we need to re-orient in the same way as above. Next, we only need to translate 1.9 meters straight downwards. We yield the following homogenous transformation:

$$\begin{pmatrix}
0 & 1 & 0 & 0 \\
1 & 0 & 0 & 0 \\
0 & 0 & -1 & -1.9 \\
0 & 0 & 0 & 1
\end{pmatrix}$$

5.5 Commutations

Consider the following matrix product:

$$H = Rot_{x,\alpha} Trans_{x,b} Trans_{z,d} Rot_{z,\theta}$$

Notice that this is a DH transformation.

Note that the two translations commute. They are representing translations, and it makes no difference which of two translations is done first. It corresponds to (commutitive) vector addition.

$$Trans_{x,b}Trans_{z,d} = Trans_{z,d}Trans_{x,b} = \begin{pmatrix} 1 & 0 & 0 & b \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 1 & d \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

Thus, if the two translations are adjacent in the product, there are really 3 transformation matrices:

1.
$$\begin{pmatrix} 1 & 0 & 0 & 0 \\ 0 & \cos \alpha & -\sin \alpha & 0 \\ 0 & \sin \alpha & \cos \alpha & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$$2. \begin{pmatrix} 1 & 0 & 0 & b \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 1 & d \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

3.
$$\begin{pmatrix} \cos \theta & -\sin \theta & 0 & 0 \\ \sin \theta & \cos \theta & 0 & 0 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

Of these, none will commute. This is because the rotations will not commute with each other in general (though they may for specific angle values), because they are on different axes.

The rotations will not commute with the translations because the translation vector depends on the current coordinate system, and since there is nontrivial rotation in both rotations in directions the translation vector is nonzero in, the rotations will make the vector point some different direction. Therefore the rotations and translations won't commute with each other.

We conclude that among those three listed transformations, none of them commute.

However, a rotation about a fixed axis will commute with a translation about that axis, because the axis is fixed by the rotation. Therefore, the rotations and translations in the above product about the same axes will commute with each other. Each one can be independently re-ordered without changing the total product.

- 1. $Rot_{x,\alpha}Trans_{x,b}Trans_{z,d}Rot_{z,\theta}$
- 2. $Trans_{x,b}Rot_{x,\alpha}Trans_{z,d}Rot_{z,\theta}$
- 3. $Rot_{x,\alpha}Trans_{x,b}Rot_{z,\theta}Trans_{z,d}$
- 4. $Trans_{x,b}Rot_{x,\alpha}Rot_{z,\theta}Trans_{z,d}$
- 5. $Rot_{x,\alpha}Trans_{z,d}Trans_{x,b}Rot_{z,\theta}$

6 Planar Manipulator

I will derive the forward kinematic equations for the three-link planar manipulator depicted in figure 3.23 of Spong.

Link	a_i	α_i	d_i	θ_i
1	a_1	0	0	θ_1
2	a_2	0	0	θ_2
3	a_3	0	0	θ_3

The base frame $o_0x_0y_0z_0$ is a right-handed frame placed at the first joint. The first control variable is θ_1 . Since the robot is planar, the offset d and tilt α are assumed to be zero.

Therefore, the following homogenous transformation relates frame 0 to frame 1:

$$A_1 = \begin{pmatrix} \cos \theta_1 & -\sin \theta_1 & 0 & a_1 \cos \theta_1 \\ \sin \theta_1 & \cos \theta_1 & 0 & a_1 \sin \theta_1 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

Similarly, the following homogenous transformation relates frame 1 to frame 2:

$$A_2 = \begin{pmatrix} \cos \theta_2 & -\sin \theta_2 & 0 & a_2 \cos \theta_2 \\ \sin \theta_2 & \cos \theta_2 & 0 & a_2 \sin \theta_2 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

and frame 2 to frame 3:

$$A_3 = \begin{pmatrix} \cos \theta_3 & -\sin \theta_3 & 0 & a_3 \cos \theta_3 \\ \sin \theta_3 & \cos \theta_3 & 0 & a_3 \sin \theta_3 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

Since the transformations are with respect to the current frame, they are precomposed, and thus the complete homogenous transformation is:

$$T = A_1 A_2 A_3$$

where the complete matrix product is:

$$\begin{pmatrix} \cos(\theta_1 + \theta_2 + \theta_3) & -\sin(\theta_1 + \theta_2 + \theta_3) & 0 & a_1\cos\theta_1 + a_2\cos(\theta_1 + \theta_2) + a_3\cos(\theta_1 + \theta_2 + \theta_3) \\ \sin(\theta_1 + \theta_2 + \theta_3) & \cos(\theta_1 + \theta_2 + \theta_3) & 0 & a_1\sin\theta_1 + a_2\sin(\theta_1 + \theta_2) + a_3\sin(\theta_1 + \theta_2 + \theta_3) \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

I chose to leave the manipulator frame "as-is", and not rotate the z-direction facing the end of the manipulator. The z-direction faces out of the page, and the manipulator frame x-direction faces along the line of the manipulator.

7 PUMA manipulator

The PUMA is shown in Fig. 3.31 of spong. From the figure, the DH parameters are:

Index	a_i	α_i	d_i	θ_i
1	0	$\pi/2$	l_1	θ_1
2	l_2	0	d_s	θ_2
3	0	$-\pi/2$	d_3	$\theta_3 - \pi/2$
4	0	$\pi/2$	l_{34}	θ_4
5	0	$-\pi/2$	0	$\theta_5 - \pi$
6	0	0	d_e	θ_6

where:

Name	Value		
l_1	13.0 in.		
l_2	8.0 in.		
l_{34}	8.0 in.		

Therefore, the DH matrices are:

$$A_{1} = \begin{bmatrix} \cos\theta_{1} & 0 & \sin\theta_{1} & 0 \\ \sin\theta_{1} & 0 & -\cos\theta_{1} & 0 \\ 0 & 1 & 0 & l_{1} \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$A_{2} = \begin{bmatrix} \cos\theta_{2} & -\sin\theta_{2} & 0 & l_{2}\cos\theta_{2} \\ \sin\theta_{2} & \cos\theta_{2} & 0 & l_{2}\sin\theta_{2} \\ 0 & 0 & 1 & d_{s} \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$A_{3} = \begin{bmatrix} \sin\theta_{3} & 0 & \cos\theta_{3} & 0 \\ -\cos\theta_{3} & 0 & \sin\theta_{3} & 0 \\ 0 & -1 & 0 & d_{3} \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$A_{4} = \begin{bmatrix} \cos\theta_{4} & 0 & \sin\theta_{4} & 0 \\ \sin\theta_{4} & 0 & -\cos\theta_{4} & 0 \\ 0 & 1 & 0 & l_{34} \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$A_{5} = \begin{bmatrix} \sin\theta_{5} & 0 & -\cos\theta_{5} & 0 \\ -\cos\theta_{5} & 0 & \sin\theta_{5} & 0 \\ 0 & -1 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$A_{6} = \begin{bmatrix} \cos\theta_{6} & -\sin\theta_{6} & 0 & 0 \\ \sin\theta_{6} & \cos\theta_{6} & 0 & 0 \\ 0 & 0 & 1 & d_{3} \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

8 Inverse Kinematics of Three-Joint Planar Arm

8.1 Size of Solution Space

Consider the 3-joint planar manipulator described in Fig. 3.32 of Spong. If a desired point is not in the x-y plane, then it cannot be reached by the manipulator. However, if it is in the plane, in general there will be a

continuum of ways to reach it. Since the plane is two-dimensional, and there are three joints, then I expect there to be a one-dimensional manifold (in state space) which reaches any desired point.

If the orientation is also specified, then the problem becomes more difficult. The orientation must be a rotation which is achieved by a rotation about the z axis only, otherwise the planar manipulator won't be able to express it. A choice of orientation limits the total sum of the angles, so therefore, this imposes an additional constraint on the one-dimensional manifold from before. There may be multiple solutions, but there will only be a finite number of them, corresponding to the intersection of the two-dimensional manifold of angles summing to the desired orientation with the one-dimensional manifold of angle paramters which achieve the desired position.

8.2 Finding Solutions with Geometric Approach

Recall that the forward kinematics of the three-link arm are given by:

$$\begin{pmatrix} \cos{(\theta_1 + \theta_2 + \theta_3)} & -\sin{(\theta_1 + \theta_2 + \theta_3)} & 0 & a_1 \cos{\theta_1} + a_2 \cos{(\theta_1 + \theta_2)} + a_3 \cos{(\theta_1 + \theta_2 + \theta_3)} \\ \sin{(\theta_1 + \theta_2 + \theta_3)} & \cos{(\theta_1 + \theta_2 + \theta_3)} & 0 & a_1 \sin{\theta_1} + a_2 \sin{(\theta_1 + \theta_2)} + a_3 \sin{(\theta_1 + \theta_2 + \theta_3)} \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

We have previously derived the inverse kinematics of a two-link arm. If we desire a position (x, y) of the third joint:

$$D = \frac{x^2 + y^2 - a_1^2 - a_2^2}{2a_1 a_2}$$

$$\theta_2 = \pm A \tan 2(D, \pm \sqrt{1 - D^2})$$

$$\theta_1 = A \tan 2(x, y) - A \tan 2(a_1 + a_2 \cos \theta_2, a_2 \sin \theta_2)$$

Suppse we want the angle that the third limb of the manipulator makes with the x-axis to be ϕ . If we want the end-effector to be at a position (x, y) with orientation ϕ . Then the third joint will be at a position $(x - a_3 \cos \phi, y - a_3 \sin \phi)$.

We can solve for θ_1 and θ_2 same as before. To get θ_3 from θ_1 , θ_2 and ϕ , I can notice that $\theta_1 + \theta_2 + \theta_3 = \phi$.

$$D = \frac{(x - a_3 \cos \phi)^2 + (y - a_3 \sin \phi)^2 - a_1^2 - a_2^2}{2a_1 a_2}$$

$$\theta_2 = \pm A \tan 2(D, \pm \sqrt{1 - D^2})$$

$$\theta_1 = A \tan 2(x - a_3 \cos \phi, y - a_3 \sin \phi) - A \tan 2(a_1 + a_2 \cos \theta_2, a_2 \sin \theta_2)$$

$$\theta_3 = \phi - \theta_1 - \theta_2$$

If the desired angle is specified, than we have found and specifified two solutions. If the desired angle is not specified, then we have parametrized a one-dimensional manifold with a variable ϕ .

9 Inverse Kinematics of PUMA 260

Suppose I wish to achieve a desired position o and orientation R with the end-effector of a PUMA 260, as described in problem 7. What should the joint angle values be?

9.1 Desired Wrist Center Coordinates

The wrist center in this case is the point o_4 . This is just a point by itself, and does not have an orientation. If we want to achieve an orientation R and position o, with the z-axis facing the manipulator direction, with o a distance d_e away from the joint center, then:

$$o = o_4 + d_e R \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$$

Therefore:

$$o_4 = o - d_e R \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$$


9.2 Inverse Position Kinematics

With the PUMA, we need to put the end-effector at the position o_4 .

9.2.1 Determining θ_1

Since there's a nonzero offset in joints 2 and 3, I expect there to be distinct left-arm and right-arm configurations. Let x_c and y be the x and y coordinates of o_4 in the frame o_0 .

The left arm configuration:




From the diagram we can read off:

$$\phi = Atan2(y_c, x_c)$$

$$\alpha = Atan2(d_s + d_3, l_{34} + l_2)$$

$$\theta_1 = \phi + \alpha$$

Notice that α is a design parameter, but x_c and y_c change. And the right arm configuration:




Where the other two angles are the same as before, but this time:

$$\theta_1 = \phi - \alpha$$

9.2.2 Determining θ_2 and θ_3

Now that we've determined θ_1 , we can project into a different plane to get our values of θ_2 and θ_3 . This will be the plane of the second two joints, which looks like:



The auxiliary variables r and s correspond to the cylindrical distance from the z_0 axis $\sqrt{x_c^2 + y_c^2}$, and s is z_c . These are, again, the coordinates of o_4 in the frame $o_0x_0y_0z_0$.

In the book, the inverse kinematics of this system are solved. The solutions are (D is an auxiliary variable):

$$D = \frac{r^2 + s^2 - l_2^2 - l_{34}^2}{2l_2 l_{34}}$$

$$\theta_3 = Atan2(D, \pm \sqrt{1 - D^2})$$

$$\theta_2 = Atan2(r, s) - Atan2(l_2 + l_{34}\cos\theta_3, l_{34}\sin\theta_3)$$

where the choice of + or - corresponds to the choice of the elbow-up or elbow-down configuration.

9.2.3 Summary of Inverse Position

To achieve a position o with orientation R, with respect to an origin $o_0x_0y_0z_0$, we can decouple the problem into an inverse position problem and an inverse orientation problem. To attain the orientation R at o, the manipulator frame o_4 must be located at:

$$o_4 = o - d_e R \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$$

Let x_c, y_c, z_c be the coordinates of o_4 . The angles are as follows:

$$\alpha = Atan2(d_s + d_3, l_{34} + l_2)$$

$$\phi = Atan2(y_c, x_c)$$

$$D = \frac{r^2 + s^2 - l_2^2 - l_{34}^2}{2l_2 l_{34}}$$

$$\theta_1 = \phi \pm \alpha$$

$$\theta_2 = Atan2(r, s) - Atan2(l_2 + l_{34}\cos\theta_3, l_{34}\sin\theta_3)$$

$$\theta_3 = Atan2(D, \pm \sqrt{1 - D^2})$$

They are determined in the order (1,3,2). There are two independant choices between positive and negative solutions. This corresponds to the difference between elbow up, elbow down, and right arm, left arm configurations. There are therefore four solutions to the inverse position problem.

9.3 Inverse Orientation Kinematics

After the inverse position problem has been solved, we need to solve the inverse orientation problem. We have chosen the values of θ_1 , θ_2 , and θ_3 to put the arm in a position such that appropriate choices of θ_4 , θ_5 , and θ_6 will put the end-effector frame at o with orientation R. We know the position of o_4 , but we need to determine the orientation of the $o_4x_4y_4z_4$ frame so that we can chose angle values of θ_4 , θ_5 , θ_6 to put the end-effector in orientation R.

We define the rotation of going from frame 0 to frame 3 as R_3^0 , and the totation going from frame 3 to frame 6 as R_6^3 . We can determine these rotation matrices from the A matrices:

$$R_3^0 = \begin{pmatrix} c_1c_2s_3 + c_1s_2c_3 & -s_1 & c_1c_2c_3 - c_1s_2s_3 \\ s_1c_2s_3 + s_1s_2c_3 & c_1 & s_1c_2c_3 - s_1s_2s_3 \\ s_2s_3 & 0 & s_2c_3 + c_2s_3 \end{pmatrix}$$

$$R_6^3 = \begin{pmatrix} c_4s_5c_6 - s_4s_6 & -c_4s_5s_6 - s_4c_6 & -c_4c_5 \\ s_4s_5c_6 + c_4s_6 & -s_4s_5s_6 + c_4c_6 & -s_4c_5 \\ -c_5c_6 & c_5s_6 & s_5 \end{pmatrix}$$

The goal is to find angles θ_4 , θ_5 , and θ_6 such that $R_6^3 = (R_3^0)^{-1}R = (R_3^0)^T R$.

$$\begin{pmatrix} c_4s_5c_6-s_4s_6 & -c_4s_5s_6-s_4c_6 & -c_4c_5 \\ s_4s_5c_6+c_4s_6 & -s_4s_5s_6+c_4c_6 & -s_4c_5 \\ -c_5c_6 & c_5s_6 & s_5 \end{pmatrix} = \begin{pmatrix} c_1c_2s_3+c_1s_2c_3 & s_1c_2s_3+s_1s_2c_3 & s_2s_3 \\ -s_1 & c_1 & 0 \\ c_1c_2c_3-c_1s_2s_3 & s_1c_2c_3-s_1s_2s_3 & s_2c_3+c_2s_3 \end{pmatrix} \begin{pmatrix} r_{11} & r_{12} & r_{13} \\ r_{21} & r_{22} & r_{23} \\ r_{31} & r_{32} & r_{33} \end{pmatrix}$$

From the bottom-right, we see:

$$\theta_5 = \sin^{-1} \left(r_{13} (c_1 c_2 c_3 - c_1 s_2 s_3) + r_{23} (s_1 c_2 c_3 - s_1 s_2 s_3) + r_{33} (s_2 c_3 + c_2 s_3) \right)$$

= $\pi - \sin^{-1} \left(r_{13} (c_1 c_2 c_3 - c_1 s_2 s_3) + r_{23} (s_1 c_2 c_3 - s_1 s_2 s_3) + r_{33} (s_2 c_3 + c_2 s_3) \right)$

These are two choices of gripper angle.

Continuing to read off, we see from the middle-right that, assuming $c_5 \neq 0$,

$$\theta_4 = \frac{\sin^{-1}\left(-s_1r_{12} + c_1r_{22}\right)}{-c_5}$$

Continuing to read off, we see from the bottom-middle that, assuming that $c_5 \neq 0$:

$$\theta_6 = \frac{\sin^{-1}(r_{12}(c_1c_2c_3 - c_1s_2s_3) + r_{22}(s_1c_2c_3 - s_1s_2s_3) + r_{32}(s_2c_3 + c_2s_3))}{c_5}$$

If $c_5 = 0$, then $s_6 = \pm 1$.

Then, from the top-middle and middle-middle entries:

$$\theta_4 \pm \theta_6 = \cos^{-1}(-s_1r_{12} + c_1r_{22})$$

$$\theta_4 \mp \theta_6 = \sin^{-1}(\pm((c_1c_2s_3 + c_1s_2c_3)r_{12} + (s_1c_2s_3 + s_1s_2c_3)r_{22} + s_2s_3r_{32}))$$

9.4 Summary

The PUMA has the following design parameters:

 l_1 l_2 l_{34} d_s d_3 d_e

To achieve an orientation R and position o, we can decouple the problem into an inverse position and inverse orientation problem. The position problem can be solved first. We introduce an additional dependant design parameter:

$$\alpha = Atan2(d_s + d_3, l_{34} + l_2)$$

We then find the desired coordinates for o_4 , the center of the tool. These are

$$o_4 = o - d_e R \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$$

Let $\langle x_c, y_c, z_c \rangle = o_4$ be the coordinates of o_4 in the base frame $o_0 x_0 y_0 z_0$. Then, by the geometric approach, we find:

$$\phi = Atan2(y_c, x_c)$$
$$\theta_1 = \phi \pm \alpha$$

Where this choice of + or - determines whether the arm is in the left-handed or right-handed configuration.

Next, we find an auxiliary variable, D, by the law of cosines, and use it to find θ_3 and then θ_2 .

$$D = \frac{r^2 + s^2 - l_2^2 - l_{34}^2}{2l_2 l_{34}}$$

$$\theta_3 = Atan2(D, \pm \sqrt{1 - D^2})$$

$$\theta_2 = Atan2(r, s) - Atan2(l_2 + l_{34}\cos\theta_3, l_{34}\sin\theta_3)$$

The choice of + or - here refers to the difference between an elbow-up and elbow-down configuration. Finally, we find the orientation angles of the rest of the manipulator.

There are two choices of θ_5 orientation, corresponding to the following choices for the value of θ_5 :

$$\theta_5 = \sin^{-1} \left(r_{13} (c_1 c_2 c_3 - c_1 s_2 s_3) + r_{23} (s_1 c_2 c_3 - s_1 s_2 s_3) + r_{33} (s_2 c_3 + c_2 s_3) \right)$$

= $\pi - \sin^{-1} \left(r_{13} (c_1 c_2 c_3 - c_1 s_2 s_3) + r_{23} (s_1 c_2 c_3 - s_1 s_2 s_3) + r_{33} (s_2 c_3 + c_2 s_3) \right)$

Once we have determined θ_5 , we solve for θ_4 and θ_6 . If $\cos \theta_5 \neq 0$, then:

$$\theta_4 = \frac{\sin^{-1}(-s_1r_{12} + c_1r_{22})}{-c_5}$$
$$= \frac{\pi - \sin^{-1}(-s_1r_{12} + c_1r_{22})}{-c_5}$$

$$\theta_6 = \frac{\sin^{-1}(r_{12}(c_1c_2c_3 - c_1s_2s_3) + r_{22}(s_1c_2c_3 - s_1s_2s_3) + r_{32}(s_2c_3 + c_2s_3))}{c_5}$$

$$= \frac{\pi - \sin^{-1}(r_{12}(c_1c_2c_3 - c_1s_2s_3) + r_{22}(s_1c_2c_3 - s_1s_2s_3) + r_{32}(s_2c_3 + c_2s_3))}{c_5}$$

However, if $\cos \theta_5 = 0$, then if $\theta_5 = \frac{\pi}{2}$:

$$\theta_4 \pm \theta_6 = \cos^{-1}(-s_1r_{12} + c_1r_{22})$$

$$\theta_4 \mp \theta_6 = \sin^{-1}(\pm((c_1c_2s_3 + c_1s_2c_3)r_{12} + (s_1c_2s_3 + s_1s_2c_3)r_{22} + s_2s_3r_{32}))$$

$$\theta_{4} = \frac{\pm \cos^{-1}\left(-s_{1}r_{12} + c_{1}r_{22}\right) + \sin^{-1}\left(\left((c_{1}c_{2}s_{3} + c_{1}s_{2}c_{3})r_{12} + (s_{1}c_{2}s_{3} + s_{1}s_{2}c_{3})r_{22} + s_{2}s_{3}r_{32}\right)\right)}{2}$$

$$= \frac{\pm \cos^{-1}\left(-s_{1}r_{12} + c_{1}r_{22}\right) + \pi - \sin^{-1}\left(\left((c_{1}c_{2}s_{3} + c_{1}s_{2}c_{3})r_{12} + (s_{1}c_{2}s_{3} + s_{1}s_{2}c_{3})r_{22} + s_{2}s_{3}r_{32}\right)\right)}{2}$$

$$\theta_{6} = \frac{\pm \cos^{-1}\left(-s_{1}r_{12} + c_{1}r_{22}\right) - \sin^{-1}\left(\left((c_{1}c_{2}s_{3} + c_{1}s_{2}c_{3})r_{12} + (s_{1}c_{2}s_{3} + s_{1}s_{2}c_{3})r_{22} + s_{2}s_{3}r_{32}\right)\right)}{2}$$

$$= \frac{\pm \cos^{-1}\left(-s_{1}r_{12} + c_{1}r_{22}\right) - \pi + \sin^{-1}\left(\left((c_{1}c_{2}s_{3} + c_{1}s_{2}c_{3})r_{12} + (s_{1}c_{2}s_{3} + s_{1}s_{2}c_{3})r_{22} + s_{2}s_{3}r_{32}\right)\right)}{2}$$

If
$$\theta_5 = -\frac{\pi}{2}$$
, then:

$$\theta_4 = \frac{\pm \cos^{-1}(-s_1r_{12} + c_1r_{22}) + \sin^{-1}(-((c_1c_2s_3 + c_1s_2c_3)r_{12} + (s_1c_2s_3 + s_1s_2c_3)r_{22} + s_2s_3r_{32}))}{2}$$

$$= \frac{\pm \cos^{-1}(-s_1r_{12} + c_1r_{22}) + \pi - \sin^{-1}(-((c_1c_2s_3 + c_1s_2c_3)r_{12} + (s_1c_2s_3 + s_1s_2c_3)r_{22} + s_2s_3r_{32}))}{2}$$

$$\theta_6 = \frac{\mp \cos^{-1}(-s_1r_{12} + c_1r_{22}) + \sin^{-1}(-((c_1c_2s_3 + c_1s_2c_3)r_{12} + (s_1c_2s_3 + s_1s_2c_3)r_{22} + s_2s_3r_{32}))}{2}$$

$$= \frac{\mp \cos^{-1}(-s_1r_{12} + c_1r_{22}) + \pi - \sin^{-1}(-((c_1c_2s_3 + c_1s_2c_3)r_{12} + (s_1c_2s_3 + s_1s_2c_3)r_{22} + s_2s_3r_{32}))}{2}$$

I found 5 choices between 2 options, and therefore 32 solutions.

I have chosen to express the rotation as a rotation matrix. If the user wishes to use euler angles, then they can find the matrix elements with the following formula (Spong 2.27):

$$\begin{pmatrix} c_{\phi}c_{\theta}c_{\psi} - s_{\phi}s_{\psi} & -c_{\phi}c_{\theta}s_{\psi} - s_{\phi}c_{\psi} & c_{\phi}s_{\theta} \\ s_{\phi}c_{\theta}c_{\psi} + c_{\phi}s_{\psi} & -s_{\phi}c_{\theta}s_{\psi} + c_{\phi}c_{\psi} & s_{\phi}s_{\theta} \\ -s_{\theta}c_{\psi} & s_{\theta}s_{\psi} & c_{\theta} \end{pmatrix}$$