



Submit by E-mail

CHS Inc. - Pipelines and Terminals Annual External Floating Roof Tank Inspection Form

Requirement 40 CFR Part 60, Subpart Kb, 40 CFR Part 63, Subpart BBBBBB

This form was last updated: 05/01/2024

By: NKM

Inspection Summary:

Date: Apr 18, 2025

Location: Jayhawk McPherson Station

Inspector's Name: Mike Hubenett

Inspector's Signature: Hubenett, Michael

Digitally signed by Hubenett, Michael
Date: 2025.04.18 14:41:07 -05'00'

Tank Number: 1828

Tank Diameter: 134'

Product: Crude Oil

Product Height at Time of Inspection: 40' 4"

External Floating Roof Type: ☒ Full Contact ☐ Non-Contact

Type of Primary Seal: Mechanical Shoe

Type of Secondary Seal: Wiper

Inspection Observations:

1. Is external floating roof resting on liquid surface? ☒ **Yes** ☐ No
2. Is there any product accumulated on the floating roof? ☐ Yes ☒ **No**
3. Are there visible holes, tears, or other openings in the primary/secondary seal? ☐ Yes ☒ **No**
4. Are access hatches gasketed and free of any visible gaps or leaks? ☒ **Yes** ☐ No
5. Are gauge float wells gasketed and free of any visible gaps or leaks? ☐ **Yes** ☐ No ☒ NA
6. Are guide poles/sample wells gasketed and free of any visible gaps or leaks? ☒ **Yes** ☐ No
7. Is guide pole/sample pole float or pole sleeve in place? ☒ **Yes** ☐ No
8. Are vacuum breakers and rim vents gasketed, closed, and free of any visible gaps or leaks? ☒ **Yes** ☐ No ☐ NA
9. Are there any other openings (except leg sleeves) without gasketed covers? ☐ Yes ☒ **No**
10. Are there any other openings that have visible gaps or leaks? ☐ Yes ☒ **No**

General condition of floating roof including seams/welds: seal in good condition, no gaps

If the answer to any question above is not the bolded response, provide a description and recommended actions:

Question 5-there are no gauge float wells

Seal Gap Information:

External Floating Roof Secondary Seal Gap Measurements - Complete Annually			
Gap Position	Gap Width (inches)	Gap Length (inches)	Total Gap W x L x 0.8 (inches) ²
North			
NE			
East			
SE			
South			
SW			
West			
NW			

0

Total Gap Area (in)²

/

134

Tank Diameter (ft)

=

0

Gap Area/
Ft Tank Diameter

Note: Any opening between the seal and the wall of the storage tank larger than 1/8" is considered a gap. Measure the width and length of each gap to determine gap area. On the secondary seal, the summation of all gap areas cannot exceed 1 in²/ft of tank diameter, and the width of any single gap cannot exceed 1/2".

Record areas of gaps and/or defects/deficiencies in floating roof seals on the diagrams below:

