



(a) Tool Drop

→ Hitting Process →



(b) Imprecise Hitting

→ Hitting Process →



(c) Pass Over

→ Hitting Process →

