```
int ledPin = 9;
int brightness = 0;
void setup(){
    Serial.begin(9600);
    pinMode(ledPin, OUTPUT);
}
void loop(){
    int sensorValue = analogRead(A0);
    Serial.println(sensorValue);
    analogWrite(ledPin, brightness);
    brightness = map(sensorValue,0,1024,0,255);
    analogWrite(ledPin,brightness);
    delay(1);
}
```