School Lead Water Testing - Data Collection Form



School Short Name

Marine Leadership H.S.

Date of test 11/01/16

School Short Name	Facility ID	Sample ID #	Sample Location	Sample Collection Date	Sample Collection Time	Test Result (ppb)	Test Results
Marine Leadership H.S.	51109	51109-1-KIT-KS01-001	1st Floor Kitchen Sink West Island North Side	11/1/16	0600	0.765	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS01-002	1st Floor Kitchen Sink West Island North Side	11/1/16	0600	1.36	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS01-003	1st Floor Kitchen Sink West Island North Side	11/1/16	0600	0.188	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS01-004	1st Floor Kitchen Sink West Island North Side	11/1/16	0600	0.501	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS01-005	1st Floor Kitchen Sink West Island North Side	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-KIT-KS02-001	1st Floor Kitchen Sink East Island Center	11/1/16	0600	1.27	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS02-002	1st Floor Kitchen Sink East Island Center	11/1/16	0600	0.139	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS02-003	1st Floor Kitchen Sink East Island Center	11/1/16	0600	0.202	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS02-004	1st Floor Kitchen Sink East Island Center	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-KIT-KS02-005	1st Floor Kitchen Sink East Island Center	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-KIT-KS03-001	1st Floor Kitchen Triple Sink Left Side	11/1/16	0600	2.06	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS03-002	1st Floor Kitchen Triple Sink Left Side	11/1/16	0600	0.261	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS03-003	1st Floor Kitchen Triple Sink Left Side	11/1/16	0600	0.227	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS03-004	1st Floor Kitchen Triple Sink Left Side	11/1/16	0600	0.212	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS03-005	1st Floor Kitchen Triple Sink Left Side	11/1/16	0600	0.171	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS04-001	1st Floor Kitchen Triple Sink Right Side	11/1/16	0600	0.538	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS04-002	1st Floor Kitchen Triple Sink Right Side	11/1/16	0600	0.294	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS04-003	1st Floor Kitchen Triple Sink Right Side	11/1/16	0600	0.122	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS04-004	1st Floor Kitchen Triple Sink Right Side	11/1/16	0600	0.13	BA
Marine Leadership H.S.	51109	51109-1-KIT-KS04-005	1st Floor Kitchen Triple Sink Right Side	11/1/16	0600	0.409	BA
Marine Leadership H.S.	51109	51109-1-HAL-F07-001	1st Floor Fountain Left Side Across From Room 115	11/1/16	0600	0.166	BA
Marine Leadership H.S.	51109	51109-1-HAL-F07-002	1st Floor Fountain Left Side Across From Room 115	11/1/16	0600	0.168	BA
Marine Leadership H.S.	51109	51109-1-HAL-F07-003	1st Floor Fountain Left Side Across From Room 115	11/1/16	0600	0.139	BA
Marine Leadership H.S.	51109	51109-1-HAL-F07-004	1st Floor Fountain Left Side Across From Room 115	11/1/16	0600	0.155	BA
Marine Leadership H.S.	51109	51109-1-HAL-F07-005	1st Floor Fountain Left Side Across From Room 115	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F08-001	1st Floor Fountain Right Side Across From Room 115	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F08-002	1st Floor Fountain Right Side Across From Room 115	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F08-003	1st Floor Fountain Right Side Across From Room 115	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F08-004	1st Floor Fountain Right Side Across From Room 115	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F08-005	1st Floor Fountain Right Side Across From Room 115	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F09-001	1st Floor Fountain Left Side Across From Room 109	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F09-002	1st Floor Fountain Left Side Across From Room 109	11/1/16	0600	0.235	BA
Marine Leadership H.S.	51109	51109-1-HAL-F09-003	1st Floor Fountain Left Side Across From Room 109	11/1/16	0600	0.157	BA
Marine Leadership H.S.	51109	51109-1-HAL-F09-004	1st Floor Fountain Left Side Across From Room 109	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F09-005	1st Floor Fountain Left Side Across From Room 109	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F10-001	1st Floor Fountain Right Side Across From Room 109	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F10-002	1st Floor Fountain Right Side Across From Room 109	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-1-HAL-F10-003	1st Floor Fountain Right Side Across From Room 109	11/1/16	0600	0.295	BA
Marine Leadership H.S.	51109	51109-1-HAL-F10-004	1st Floor Fountain Right Side Across From Room 109	11/1/16	0600	0.133	BA
Marine Leadership H.S.	51109	51109-1-HAL-F10-005	1st Floor Fountain Right Side Across From Room 109	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F01-001	2nd Floor Fountain Left Side Across From Room 217	11/1/16	0600	0.146	BA
Marine Leadership H.S.	51109	51109-2-HAL-F01-002	2nd Floor Fountain Left Side Across From Room 217	11/1/16	0600	0.123	BA
Marine Leadership H.S.	51109	51109-2-HAL-F01-003	2nd Floor Fountain Left Side Across From Room 217	11/1/16	0600	0.13	BA
Marine Leadership H.S.	51109	51109-2-HAL-F01-004	2nd Floor Fountain Left Side Across From Room 217	11/1/16	0600	0.123	BA
Marine Leadership H.S.	51109	51109-2-HAL-F01-005	2nd Floor Fountain Left Side Across From Room 217	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F02-001	2nd Floor Fountain Right Side Across From Room 217	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F02-002	2nd Floor Fountain Right Side Across From Room 217	11/1/16	0600	<0.120	ND

					_		
Marine Leadership H.S.	51109	51109-2-HAL-F02-003	2nd Floor Fountain Right Side Across From Room 217	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F02-004	2nd Floor Fountain Right Side Across From Room 217	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F02-005	2nd Floor Fountain Right Side Across From Room 217	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F03-001	2nd Floor Fountain Left Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F03-002	2nd Floor Fountain Left Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F03-003	2nd Floor Fountain Left Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F03-004	2nd Floor Fountain Left Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F03-005	2nd Floor Fountain Left Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F04-001	2nd Floor Fountain Right Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F04-002	2nd Floor Fountain Right Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F04-003	2nd Floor Fountain Right Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F04-004	2nd Floor Fountain Right Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-F04-005	2nd Floor Fountain Right Side Across From Room 209	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-2-HAL-S05-001	2nd Floor Sink Teachers Lounge Room 205	11/1/16	0600	0.173	BA
Marine Leadership H.S.	51109	51109-2-HAL-S05-002	2nd Floor Sink Teachers Lounge Room 205	11/1/16	0600	0.182	BA
Marine Leadership H.S.	51109	51109-2-HAL-S05-003	2nd Floor Sink Teachers Lounge Room 205	11/1/16	0600	0.269	BA
Marine Leadership H.S.	51109	51109-2-HAL-S05-004	2nd Floor Sink Teachers Lounge Room 205	11/1/16	0600	0.61	BA
Marine Leadership H.S.	51109	51109-2-HAL-S05-005	2nd Floor Sink Teachers Lounge Room 205	11/1/16	0600	0.362	BA
Marine Leadership H.S.	51109	51109-3-HAL-F01-001	3rd Floor Fountain Left Side Across From Room 317	11/1/16	0600	0.136	BA
Marine Leadership H.S.	51109	51109-3-HAL-F01-002	3rd Floor Fountain Left Side Across From Room 317	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F01-003	3rd Floor Fountain Left Side Across From Room 317	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F01-004	3rd Floor Fountain Left Side Across From Room 317	11/1/16	0600	0.184	BA
Marine Leadership H.S.	51109	51109-3-HAL-F01-005	3rd Floor Fountain Left Side Across From Room 317	11/1/16	0600	0.228	BA
Marine Leadership H.S.	51109	51109-3-HAL-F02-001	3rd Floor Fountain Right Side Across From Room 317	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F02-002	3rd Floor Fountain Right Side Across From Room 317	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F02-003	3rd Floor Fountain Right Side Across From Room 317	11/1/16	0600	0.129	BA
Marine Leadership H.S.	51109	51109-3-HAL-F02-004	3rd Floor Fountain Right Side Across From Room 317	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F02-005	3rd Floor Fountain Right Side Across From Room 317	11/1/16	0600	0.164	BA
Marine Leadership H.S.	51109	51109-3-HAL-F03-001	3rd Floor Fountain Left Side Across From Room 307	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F03-002	3rd Floor Fountain Left Side Across From Room 307	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F03-003	3rd Floor Fountain Left Side Across From Room 307	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F03-004	3rd Floor Fountain Left Side Across From Room 307	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F03-005	3rd Floor Fountain Left Side Across From Room 307	11/1/16	0600	<0.120	ND
Marine Leadership H.S.	51109	51109-3-HAL-F04-001	3rd Floor Fountain Right Side Across From Room 307	11/1/16	0600	0.237	BA
Marine Leadership H.S.	51109	51109-3-HAL-F04-002	3rd Floor Fountain Right Side Across From Room 307	11/1/16	0600	0.142	BA
Marine Leadership H.S.	51109	51109-3-HAL-F04-003	3rd Floor Fountain Right Side Across From Room 307	11/1/16	0600	0.166	BA
Marine Leadership H.S.	51109	51109-3-HAL-F04-004	3rd Floor Fountain Right Side Across From Room 307	11/1/16	0600	0.147	BA
Marine Leadership H.S.	51109	51109-3-HAL-F04-005	3rd Floor Fountain Right Side Across From Room 307	11/1/16	0600	<0.120	ND

EPA ACTION LEVEL FOR LEAD IS 15 ppb or 15 $\mu g/L$

SPREADSHEET LEGEND

ND-Not Detected at the Reporting Limit BA-Below EPA Action Level of 15 ppb AA-Above EPA Action Level

Chicago Public Schools - Department of Facility Operations