

School Short Name Sullivan HS
Date of test 10/28/16

School Short Name	Facility ID	Sample ID #	Sample Location	Sample Collection (Date)	Sample Collection (Time)	Test Result (ppb)	Test Results
Sullivan HS	51539	51539-1-LR-S11-001	Lunchroom - West Wall Sink	10/28/16	0600	0.864	BA
Sullivan HS	51539	51539-1-LR-S11-002	Lunchroom - West Wall Sink	10/28/16	0600	0.883	BA
Sullivan HS	51539	51539-1-LR-S11-003	Lunchroom - West Wall Sink	10/28/16	0600	1.33	BA
Sullivan HS	51539	51539-1-LR-S11-004	Lunchroom - West Wall Sink	10/28/16	0600	0.671	BA
Sullivan HS	51539	51539-1-LR-S11-005	Lunchroom - West Wall Sink	10/28/16	0600	0.693	BA
Sullivan HS	51539	51539-1-LR-F12-001	Lunchroom - West Wall Fountain	10/28/16	0600	0.632	BA
Sullivan HS	51539	51539-1-LR-F12-002	Lunchroom - West Wall Fountain	10/28/16	0600	0.685	BA
Sullivan HS	51539	51539-1-LR-F12-003	Lunchroom - West Wall Fountain	10/28/16	0600	0.636	BA
Sullivan HS	51539	51539-1-LR-F12-004	Lunchroom - West Wall Fountain	10/28/16	0600	0.613	BA
Sullivan HS	51539	51539-1-LR-F12-005	Lunchroom - West Wall Fountain	10/28/16	0600	0.614	BA
Sullivan HS	51539	51539-1-LR-WC14-001	Lunchroom - North Wall Water Cooler Fountain	10/28/16	0600	0.146	BA
Sullivan HS	51539	51539-1-LR-WC14-002	Lunchroom - North Wall Water Cooler Fountain	10/28/16	0600	0.273	BA
Sullivan HS	51539	51539-1-LR-WC14-003	Lunchroom - North Wall Water Cooler Fountain	10/28/16	0600	0.308	BA
Sullivan HS	51539	51539-1-LR-WC14-004	Lunchroom - North Wall Water Cooler Fountain	10/28/16	0600	0.366	BA
Sullivan HS	51539	51539-1-LR-WC14-005	Lunchroom - North Wall Water Cooler Filler	10/28/16	0600	0.379	BA
Sullivan HS	51539	51539-1-LR-WC15-001	Lunchroom - North Wall Water Cooler Filler	10/28/16	0600	0.391	BA
Sullivan HS	51539	51539-1-LR-WC15-002	Lunchroom - North Wall Water Cooler Filler	10/28/16	0600	0.424	BA
Sullivan HS	51539	51539-1-LR-WC15-003	Lunchroom - North Wall Water Cooler Filler	10/28/16	0600	0.645	BA
Sullivan HS	51539	51539-1-LR-WC15-004	Lunchroom - North Wall Water Cooler Filler	10/28/16	0600	0.452	BA
Sullivan HS	51539	51539-1-LR-WC15-005	Lunchroom - North Wall Water Cooler Filler	10/28/16	0600	0.446	BA
Sullivan HS	51539	51539-1-HAL-F16-001	1st FI Hallway - West Wall Across Rm 100 Fountain	10/28/16	0600	0.537	BA
Sullivan HS	51539	51539-1-HAL-F16-002	1st FI Hallway - West Wall Across Rm 100 Fountain	10/28/16	0600	0.779	BA
Sullivan HS	51539	51539-1-HAL-F16-002	1st FI Hallway - West Wall Across Rm 100 Fountain	10/28/16	0600	0.682	BA
Sullivan HS	51539	51539-1-HAL-F16-004	1st FI Hallway - West Wall Across Rm 100 Fountain	10/28/16	0600	0.651	BA
Sullivan HS	51539	51539-1-HAL-F16-005	1st FI Hallway - West Wall Across Rm 100 Fountain	10/28/16	0600	0.855	BA
Sullivan HS	51539	51539-1-HAL-WC17-001	1st FI Hallway - West Wall Across Rm 100 WC Fountain	10/28/16	0600	0.581	BA
Sullivan HS	51539	51539-1-HAL-WC17-001 51539-1-HAL-WC17-002	1st FI Hallway - West Wall Across Rm 100 WC Fountain	10/28/16	0600	0.591	BA
					0600		BA
Sullivan HS Sullivan HS	51539 51539	51539-1-HAL-WC17-003 51539-1-HAL-WC17-004	1st FI Hallway - West Wall Across Rm 100 WC Fountain 1st FI Hallway - West Wall Across Rm 100 WC Fountain	10/28/16 10/28/16	0600	0.662 0.701	BA
						0.701	BA
Sullivan HS	51539	51539-1-HAL-WC17-005	1st FI Hallway - West Wall Across Rm 100 WC Fountain	10/28/16	0600		
Sullivan HS	51539	51539-1-HAL-WC18-001	1st Fl Hallway - West Wall Across Rm 100 WC Bottle Filler Fountain	10/28/16	0600	0.746	BA
Sullivan HS	51539	51539-1-HAL-WC18-002	1st Fl Hallway - West Wall Across Rm 100 WC Bottle Filler Fountain	10/28/16	0600	0.777	BA
Sullivan HS	51539	51539-1-HAL-WC18-003	1st Fl Hallway - West Wall Across Rm 100 WC Bottle Filler Fountain	10/28/16	0600	0.849	BA
Sullivan HS	51539	51539-1-HAL-WC18-004	1st FI Hallway - West Wall Across Rm 100 WC Bottle Filler Fountain	10/28/16	0600	0.873	BA
Sullivan HS	51539	51539-1-HAL-WC18-005	1st FI Hallway - West Wall Across Rm 100 WC Bottle Filler Fountain	10/28/16	0600	0.892	BA
Sullivan HS	51539	51539-1-HAL-F19-001	1st Fl Hallway - South Wall Next to Rm 122 West Fountain	10/28/16	0600	1.17	BA
Sullivan HS	51539	51539-1-HAL-F19-002	1st FI Hallway - South Wall Next to Rm 122 West Fountain	10/28/16	0600	1.32	BA
Sullivan HS	51539	51539-1-HAL-F19-003	1st FI Hallway - South Wall Next to Rm 122 West Fountain	10/28/16	0600	1.95	BA
Sullivan HS	51539	51539-1-HAL-F19-004	1st Fl Hallway - South Wall Next to Rm 122 West Fountain	10/28/16	0600	3.4	BA
Sullivan HS	51539	51539-1-HAL-F19-005	1st Fl Hallway - South Wall Next to Rm 122 West Fountain	10/28/16	0600	3.66	BA
Sullivan HS	51539	51539-1-HAL-F20-001	1st Fl Hallway - South Wall Next to Rm 122 East Fountain	10/28/16	0600	2.71	BA
Sullivan HS	51539	51539-1-HAL-F20-002	1st Fl Hallway - South Wall Next to Rm 122 East Fountain	10/28/16	0600	2.72	BA
Sullivan HS	51539	51539-1-HAL-F20-003	1st Fl Hallway - South Wall Next to Rm 122 East Fountain	10/28/16	0600	2.57	BA
Sullivan HS	51539	51539-1-HAL-F20-004	1st Fl Hallway - South Wall Next to Rm 122 East Fountain	10/28/16	0600	2.48	BA
Sullivan HS	51539	51539-1-HAL-F20-005	1st Fl Hallway - South Wall Next to Rm 122 East Fountain	10/28/16	0600	2.61	BA
Sullivan HS	51539	51539-1-HAL-F21-001	1st Fl Hallway - West Wall Next to Rm 132 West Fountain	10/28/16	0600	0.706	BA
Sullivan HS	51539	51539-1-HAL-F21-002	1st Fl Hallway - West Wall Next to Rm 132 West Fountain	10/28/16	0600	1.1	BA
Sullivan HS	51539	51539-1-HAL-F21-003	1st FI Hallway - West Wall Next to Rm 132 West Fountain	10/28/16	0600	0.826	BA
Sullivan HS	51539	51539-1-HAL-F21-004	1st FI Hallway - West Wall Next to Rm 132 West Fountain	10/28/16	0600	0.878	BA
Sullivan HS	51539	51539-1-HAL-F21-005	1st Fl Hallway - West Wall Next to Rm 132 West Fountain	10/28/16	0600	0.806	BA
Sullivan HS	51539	51539-1-HAL-WC22-001	1st Fl Hallway - West Wall Next to Rm 132 WC Fountain	10/28/16	0600	0.676	BA
Sullivan HS	51539	51539-1-HAL-WC22-002	1st Fl Hallway - West Wall Next to Rm 132 WC Fountain	10/28/16	0600	0.666	BA
Sullivan HS	51539	51539-1-HAL-WC22-003	1st FI Hallway - West Wall Next to Rm 132 WC Fountain	10/28/16	0600	0.679	BA
Sullivan HS	51539	51539-1-HAL-WC22-004	1st Fl Hallway - West Wall Next to Rm 132 WC Fountain	10/28/16	0600	0.706	BA
Sullivan HS	51539	51539-1-HAL-WC22-005	1st FI Hallway - West Wall Next to Rm 132 WC Fountain	10/28/16	0600	0.68	BA
Sullivan HS	51539	51539-1-HAL-WC23-001	1st FI Hallway - West Wall Next to Rm 132 WC Bottle Filler Fountain	10/28/16	0600	0.599	BA
Sullivan HS	51539	51539-1-HAL-WC23-002	1st FI Hallway - West Wall Next to Rm 132 WC Bottle Filler Fountain	10/28/16	0600	0.704	BA
Sullivan HS	51539	51539-1-HAL-WC23-003	1st FI Hallway - West Wall Next to Rm 132 WC Bottle Filler Fountain	10/28/16	0600	0.678	BA
Sullivan HS	51539	51539-1-HAL-WC23-004	1st FI Hallway - West Wall Next to Rm 132 WC Bottle Filler Fountain	10/28/16	0600	0.69	BA
							BA
							BA
Sullivan HS Sullivan HS	51539 51539	51539-1-HAL-WC23-005 51539-1-POL-F24-001	1st Fl Hallway - West Wall Next to Rm 132 WC Bottle Filler Fountain Pool Room - South Wall Fountain	10/28/16 10/28/16	0600 0600	0.692 1.27	E

Sullivan HS	51539	51539-1-POL-F24-002	Pool Room - South Wall Fountain	10/28/16	0600	1.31	BA
Sullivan HS	51539	51539-1-POL-F24-003	Pool Room - South Wall Fountain	10/28/16	0600	1.3	BA
Sullivan HS	51539	51539-1-POL-F24-004	Pool Room - South Wall Fountain	10/28/16	0600	1.42	BA
Sullivan HS	51539	51539-1-POL-F24-005	Pool Room - South Wall Fountain	10/28/16	0600	1.48	BA
Sullivan HS	51539	51539-2-HAL-WC01-001	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Fountain	10/28/16	0600	0.279	BA
Sullivan HS	51539	51539-2-HAL-WC01-002	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Fountain	10/28/16	0600	0.311	BA
Sullivan HS	51539	51539-2-HAL-WC01-003	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Fountain	10/28/16	0600	0.342	BA
Sullivan HS	51539	51539-2-HAL-WC01-004	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Fountain	10/28/16	0600	0.315	BA
Sullivan HS	51539	51539-2-HAL-WC01-005	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Fountain	10/28/16	0600	0.304	BA
Sullivan HS	51539	51539-2-HAL-WC02-001	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Bottle Filler Fountain	10/28/16	0600	0.309	BA
Sullivan HS	51539	51539-2-HAL-WC02-002	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Bottle Filler Fountain	10/28/16	0600	0.316	BA BA
Sullivan HS Sullivan HS	51539 51539	51539-2-HAL-WC02-003 51539-2-HAL-WC02-004	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Bottle Filler Fountain 2nd Fl. Hallway - West Wall Next to Rm. 226 WC Bottle Filler Fountain	10/28/16 10/28/16	0600 0600	0.32 0.328	BA BA
Sullivan HS	51539	51539-2-HAL-WC02-004 51539-2-HAL-WC02-005	2nd Fl. Hallway - West Wall Next to Rm. 226 WC Bottle Filler Fountain 2nd Fl. Hallway - West Wall Next to Rm. 226 WC Bottle Filler Fountain	10/28/16	0600	0.349	BA
Sullivan HS	51539	51539-2-HAL-WC03-001	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Fountain	10/28/16	0600	5.97	BA
Sullivan HS	51539	51539-2-HAL-WC03-002	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Fountain	10/28/16	0600	5.36	BA
Sullivan HS	51539	51539-2-HAL-WC03-003	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Fountain	10/28/16	0600	6.36	BA
Sullivan HS	51539	51539-2-HAL-WC03-004	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Fountain	10/28/16	0600	6.41	BA
Sullivan HS	51539	51539-2-HAL-WC03-005	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Fountain	10/28/16	0600	5.65	BA
Sullivan HS	51539	51539-2-HAL-WC04-001	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Bottle Filler Fountain	10/28/16	0600	7.12	BA
Sullivan HS	51539	51539-2-HAL-WC04-002	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Bottle Filler Fountain	10/28/16	0600	6.32	BA
Sullivan HS	51539	51539-2-HAL-WC04-003	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Bottle Filler Fountain	10/28/16	0600	7.03	BA
Sullivan HS	51539	51539-2-HAL-WC04-004	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Bottle Filler Fountain	10/28/16	0600	7.4	BA
Sullivan HS	51539	51539-2-HAL-WC04-005	2nd Fl. Hallway - West Wall Next to Rm. 211 WC Bottle Filler Fountain	10/28/16	0600	9.05	BA
Sullivan HS	51539	51539-2-HAL-WC05-001	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Fountain	10/28/16	0600	0.197	BA
Sullivan HS	51539	51539-2-HAL-WC05-002	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Fountain	10/28/16	0600	0.263	BA
Sullivan HS	51539	51539-2-HAL-WC05-003	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Fountain	10/28/16	0600	0.311	BA
Sullivan HS	51539	51539-2-HAL-WC05-004	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Fountain	10/28/16	0600	0.393	BA
Sullivan HS	51539	51539-2-HAL-WC05-005	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Fountain	10/28/16	0600	0.462	BA
Sullivan HS	51539	51539-2-HAL-WC06-001	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Bottle Filler Fountain	10/28/16	0600	0.523	BA
Sullivan HS	51539	51539-2-HAL-WC06-002	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Bottle Filler Fountain	10/28/16	0600	0.675	BA
Sullivan HS	51539	51539-2-HAL-WC06-003	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Bottle Filler Fountain	10/28/16	0600	0.606	BA
Sullivan HS	51539	51539-2-HAL-WC06-004	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Bottle Filler Fountain	10/28/16	0600	0.612	BA
Sullivan HS	51539	51539-2-HAL-WC06-005	2nd Fl. Hallway - West Wall Next to Rm. 231 WC Bottle Filler Fountain	10/28/16	0600	0.685	BA
Sullivan HS	51539	51539-3-HAL-WC01-001	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Fountain	10/28/16	0600	0.739	BA
Sullivan HS	51539	51539-3-HAL-WC01-002	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Fountain	10/28/16	0600	0.77	BA
Sullivan HS	51539	51539-3-HAL-WC01-003	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Fountain	10/28/16	0600	0.743	BA
Sullivan HS	51539	51539-3-HAL-WC01-004	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Fountain	10/28/16	0600	0.729	BA
Sullivan HS	51539	51539-3-HAL-WC01-005	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Fountain	10/28/16	0600	0.728	BA
Sullivan HS	51539	51539-3-HAL-WC02-001	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Bottle Filler Fountain	10/28/16	0600	0.359	BA
Sullivan HS	51539	51539-3-HAL-WC02-002	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Bottle Filler Fountain	10/28/16	0600 0600	0.431	BA
Sullivan HS	51539 51539	51539-3-HAL-WC02-003 51539-3-HAL-WC02-004	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Bottle Filler Fountain 3rd Fl. Hallway - South Wall Next to Rm. 326 WC Bottle Filler Fountain	10/28/16 10/28/16	0600	0.555	BA BA
Sullivan HS Sullivan HS	51539	51539-3-HAL-WC02-005	3rd Fl. Hallway - South Wall Next to Rm. 326 WC Bottle Filler Fountain	10/28/16	0600	0.67	BA
Sullivan HS	51539	51539-1-KIT-KS01-001	North Wall - 3-Compartment Sink (Left)	10/28/16	0600	0.878	BA
Sullivan HS	51539	51539-1-KIT-KS01-001	North Wall - 3-Compartment Sink (Left)	10/28/16	0600	0.488	BA
Sullivan HS	51539	51539-1-KIT-KS01-002	North Wall - 3-Compartment Sink (Left)	10/28/16	0600	0.613	BA
Sullivan HS	51539	51539-1-KIT-KS01-004	North Wall - 3-Compartment Sink (Left)	10/28/16	0600	0.591	BA
Sullivan HS	51539	51539-1-KIT-KS01-005	North Wall - 3-Compartment Sink (Left)	10/28/16	0600	0.529	BA
Sullivan HS	51539	51539-1-KIT-KS02-001	North Wall - 3-Compartment Sink (Center)	10/28/16	0600	0.497	BA
Sullivan HS	51539	51539-1-KIT-KS02-002	North Wall - 3-Compartment Sink (Center)	10/28/16	0600	0.762	BA
Sullivan HS	51539	51539-1-KIT-KS02-003	North Wall - 3-Compartment Sink (Center)	10/28/16	0600	0.778	BA
Sullivan HS	51539	51539-1-KIT-KS02-004	North Wall - 3-Compartment Sink (Center)	10/28/16	0600	0.816	BA
Sullivan HS	51539	51539-1-KIT-KS02-005	North Wall - 3-Compartment Sink (Center)	10/28/16	0600	0.863	BA
Sullivan HS	51539	51539-1-KIT-KS03-001	North Wall - 3-Compartment Sink (Right)	10/28/16	0600	2.09	BA
Sullivan HS	51539	51539-1-KIT-KS03-002	North Wall - 3-Compartment Sink (Right)	10/28/16	0600	0.855	BA
Sullivan HS	51539	51539-1-KIT-KS03-003	North Wall - 3-Compartment Sink (Right)	10/28/16	0600	0.989	BA
Sullivan HS	51539	51539-1-KIT-KS03-004	North Wall - 3-Compartment Sink (Right)	10/28/16	0600	1.05	BA
Sullivan HS	51539	51539-1-KIT-KS03-005	North Wall - 3-Compartment Sink (Right)	10/28/16	0600	0.822	BA
Sullivan HS	51539	51539-1-KIT-KS04-001	North Wall - 3-Compartment Sink East (Left)	10/28/16	0600	0.669	BA
Sullivan HS	51539	51539-1-KIT-KS04-002	North Wall - 3-Compartment Sink East (Left)	10/28/16	0600	0.642	BA
Sullivan HS	51539	51539-1-KIT-KS04-003	North Wall - 3-Compartment Sink East (Left)	10/28/16	0600	0.821	BA
Sullivan HS	51539	51539-1-KIT-KS04-004	North Wall - 3-Compartment Sink East (Left)	10/28/16	0600	0.934	BA
Sullivan HS	51539	51539-1-KIT-KS04-005	North Wall - 3-Compartment Sink East (Left)	10/28/16	0600	1.1	BA
Sullivan HS	51539	51539-1-KIT-KS05-001	North Wall - 3-Compartment Sink East (Center)	10/28/16	0600	0.92	BA
Sullivan HS	51539	51539-1-KIT-KS05-002	North Wall - 3-Compartment Sink East (Center)	10/28/16	0600	0.68	BA
Sullivan HS	51539	51539-1-KIT-KS05-003	North Wall - 3-Compartment Sink East (Center)	10/28/16	0600	0.604	BA
Sullivan HS	51539	51539-1-KIT-KS05-004	North Wall - 3-Compartment Sink East (Center)	10/28/16	0600	0.575	BA
Sullivan HS	51539	51539-1-KIT-KS05-005	North Wall - 3-Compartment Sink East (Center)	10/28/16	0600	0.598	BA
Sullivan HS	51539	51539-1-KIT-KS06-001	North Wall - 3-Compartment Sink East(Right)	10/28/16	0600	1.44	BA
Sullivan HS	51539	51539-1-KIT-KS06-002	North Wall - 3-Compartment Sink East(Right)	10/28/16	0600	4.04	BA
Sullivan HS	51539 51539	51539-1-KIT-KS06-003 51539-1-KIT-KS06-004	North Wall - 3-Compartment Sink East(Right) North Wall - 3-Compartment Sink East(Right)	10/28/16 10/28/16	0600 0600	1.03 3.2	BA BA
Sullivan HS Sullivan HS	51539	51539-1-KIT-KS06-005	North Wall - 3-Compartment Sink East(Right)	10/28/16	0600	0.838	BA

Sullivan HS	51539	51539-1-KIT-KS07-001	East Wall 2-Compartment Sink(Left)	10/28/16	0600	1.74	BA
Sullivan HS	51539	51539-1-KIT-KS07-002	East Wall 2-Compartment Sink(Left)	10/28/16	0600	1.32	BA
Sullivan HS	51539	51539-1-KIT-KS07-003	East Wall 2-Compartment Sink(Left)	10/28/16	0600	1.32	BA
Sullivan HS	51539	51539-1-KIT-KS07-004	East Wall 2-Compartment Sink(Left)	10/28/16	0600	1.27	BA
Sullivan HS	51539	51539-1-KIT-KS07-005	East Wall 2-Compartment Sink(Left)	10/28/16	0600	0.998	BA
Sullivan HS	51539	51539-1-KIT-KS08-001	East Wall 2-Compartment Sink(Right)	10/28/16	0600	0.778	BA
Sullivan HS	51539	51539-1-KIT-KS08-002	East Wall 2-Compartment Sink(Right)	10/28/16	0600	0.672	BA
Sullivan HS	51539	51539-1-KIT-KS08-003	East Wall 2-Compartment Sink(Right)	10/28/16	0600	0.813	BA
Sullivan HS	51539	51539-1-KIT-KS08-004	East Wall 2-Compartment Sink(Right)	10/28/16	0600	0.784	BA
Sullivan HS	51539	51539-1-KIT-KS08-005	East Wall 2-Compartment Sink(Right)	10/28/16	0600	0.646	BA
Sullivan HS	51539	51539-1-KIT-KS09-001	Middle Sink	10/28/16	0600	0.515	BA
Sullivan HS	51539	51539-1-KIT-KS09-002	Middle Sink	10/28/16	0600	0.791	BA
Sullivan HS	51539	51539-1-KIT-KS09-003	Middle Sink	10/28/16	0600	0.616	BA
Sullivan HS	51539	51539-1-KIT-KS09-004	Middle Sink	10/28/16	0600	0.472	BA
Sullivan HS	51539	51539-1-KIT-KS09-005	Middle Sink	10/28/16	0600	0.581	BA
Sullivan HS	51539	51539-1-KIT-KS10-001	Above Stove Pot Filler Middle	10/28/16	0600	7.02	BA
Sullivan HS	51539	51539-1-KIT-KS10-002	Above Stove Pot Filler Middle	10/28/16	0600	8.41	BA
Sullivan HS	51539	51539-1-KIT-KS10-003	Above Stove Pot Filler Middle	10/28/16	0600	3.64	BA
Sullivan HS	51539	51539-1-KIT-KS10-004	Above Stove Pot Filler Middle	10/28/16	0600	3.66	BA
Sullivan HS	51539	51539-1-KIT-KS10-005	Above Stove Pot Filler Middle	10/28/16	0600	4.66	BA

EPA ACTION LEVEL FOR LEAD IS 15 ppb or 15 $\mu g/L$

SPREADSHEET LEGEND

ND-Not Detected at the Reporting Limit BA-Below EPA Action Level of 15 ppb AA-Above EPA Action Level

Chicago Public Schools - Department of Facility Operations