tor SIDE SEWER PERMIT

and an income	4.1	\$ 5,44	. 77.7		45 TT			
OUTSI	DE 452	<b>↑</b>	INSI	DE		REP	AIRS	1
		<b>.</b>						1

1.78	1. 18	200	AN AND A	A (10)	The same	d
ر العوارية	<b>T</b>	$\mathbf{O}$			673 J. 1985	S
1	D.		A OF	19	7	ĕ
1904.3	100	Sec. Sec.		163 x	i medi	ė
1.0	ARL	Nο			rand in	Ц
1.11	44 <u>2.</u> EUL	, ,,,,,,,,,		-		- 16

The City of Mountlake Terrace	SIDE SEWER PERMIT OUTSIDE INSIDE REPAIRS	EASEMENT No	
OWNER BOLIS, Daviel P.	CONTRACTOR ED BEVIN		
HOUSE No. 23/05 642 Ave	ω. STREET 6412 Ave w. 28	BLOCK No. B	
	NAME ADD SIN DA 18-13 REAR PROPERTY Line 80'	C + W	
	W. SEAR OF EAMOUT PLUE	1/8 Bend	
	WITH Watertight Concrete Plug	- <del>*</del> +	
	1/4 Band		
	16->	OPEN	
		J g	
		4	
	72	90'	
		<del> </del>	
表的,这一句,我们也不是一个人的。 ····································		ide ;	
$N \longleftrightarrow 5$	421		
W	26-10	72	
Date	Approved:		
BACKFILL WORK ORDER ISSUED	DEPOSIT, \$ 10,00	I mast let won	
SEWER WORK ORDER ISSUED	7-10-CO DATE (-18-60	BY X1/101/101/01/01/1/34	