## SIDE SEWER A JILT

CUTSIDE	П	INSIDE	REPAIRS	r-1
			 ***********	

WHER DENNIS TIBLE DUSE No. 4504	CONTRACTOR Triway Const	PERMIT No. (1-90-9
DUSE No. 97.0 0 44	NAME ADD Sennifor Pork	BLOOK No.
	Hos. # 4504	
	718th 51, 5, W.	
		•
	GR.	
	→ 3 <sup>e</sup>   <del>-</del>	•
	440 CO 15 deep	\$
	Ne of 4" P.V.C.	••
	Co. 7º to 5-10°- Plane of Gr.	
SEWFR WORK ORDER ISSUED	BY Be the Williams FEE	21871 St, S.W.
BACKFILL APPHOVED Dec. 13, 199	10 BY Ben Van Deren ASBILT Dec	.14, 1990 BY Ben