NAD83(91) STATE PLANE COORDINATES: ZONE 3601

(A) N 813459.53 E 7520765.87 UNITS (IFT)

(B) N 813353.58 E 7523395.01 UNITS (IFT)

(C) N 813349.77 E 7523488.73 UNITS (IFT)

(D) N 813247.49 E 7526007.41 UNITS (IFT)

(E) N 813245.18 E 7526065.08 UNITS (IFT)

(F) N 813143.99 E 7528594.74 UNITS (IFT)

COLUMBIA COUNTY GPS CONTROL POINTS (CS # 4269)

"VERNONIA" LAT. 45°51'25.28188"N LONG. 123°10'24.80441"W

"APIARY" LAT. 45°56'57.87036"N LONG. 123°08'52.65050"W

CORNER RESTORATION SURVEY
FIRST STANDARD PARALLEL WEST
SECTIONS 33, 34 & 35, T5N, R4W,
SECTIONS 4, 3 & 2, T4N, R4W, OF THE W.M.

DECEMBER 16, 2009

PAGE 1 OF 7

BEARINGS ARE GEODETIC, BASED ON COLUMBIA COUNTY GPS CONTROL POINTS "VERNONIA" AND "APIARY"



MEASURED DISTANCES SHOWN ARE GRID, TO CONVERT TO GROUND DIVIDE DISTANCES BY A COMBINED FACTOR OF .999948958 CONVERGENCE = -1°53' 10"

PAGE 7).

STANDARD QUARTER CORNER

FOR SECTION 35, T5N, R4W (SEE

OVERALL (N 89°53' W 119.90CHS) BT. BK. "A" PG. 194-196 S 87°41'31" E 7835.22

STANDARD SECTION CORNER FOR SECTIONS 34 & 33, T5N, R4W (SEE PAGE 2).

(\$89°34'E 2632.1') C\$#203 S 87°41'32" E 2631.27'

\$ 87°41'01" E 2725.07' (\$89°34'E 2725.93') C\$#224 (\$89°29'00"W 2725.33') PLAT BK.5 PG. 60

STANDARD QUARTER

CORNER (SET) FOR

SECTION 34, T5N, R4W.

FOUND 5/8" REBAR SET BY

RICHARD MORRIS IN C5#L-1073

S86°56'17"W AT 8.09'

(SEE PAGE 3).

(N 89°29'49" W 5244.88') CS#3353
S 87°41'01" E 5245.83'

B C (S89°17'E 2616.2') CS#203
S 87°40'31" E 2614.55'
S 87°40'31" E 2578.47'
(S89°17'E 2580.2') CS#203
CORNER FOR SECTION 3,
T4N, R4W (SEE PAGE 4).
S 87°40'31" E 93.80'
(S89°17'E 93.8') CS#203
(S89°29'00"W 93.8') PLAT BK.5 PG.60

(S89°29'00"W 93.8') CS# 4212

(\$89°29'00"W 93.53') CS# 4367

STANDARD SECTION CORNER FOR SECTIONS 34 & 35, T5N, R4W (SEE PAGE 5).

S 87°42'30" E 57.71' (\$89°17'E 57.8') C\$#203

(N0°7'W 39.96 2/3 chs.)BT BK. A PG. 195 (N89°31'33"W 2590.27') CS#3353 S 87°42'34" E 2589.39'

> S 87°42'34" E 2531.68' (N89°53'W 39.06 2/3 chs.) BT BK. A PG. 195

CLOSING SECTION CORNER FOR SECTIONS 3 & 2, T4N, R4W (SEE PAGE 6).

LEGEND

- SET 1 1/4" X 30" GALVANIZED IRON PIPE WITH 3 1/4" ALUMINUM CAP.
- FOUND 1" IRON PIPE WITH A
 2 1/2" OLSON ENG. BRASS CAP

(1991) ADJUSTMENT.

() RECCORD BEARING AND/OR DISTANCE NAD83(91) NORTH AMERICAN DATUM OF 1983,


The North American Datum of 1983 (NAD 83) is the horizontal control datum for the United States, Canada, Mexico, and Central America, based on a geocentric origin and the Geodetic Reference System 1980 (GRS 80).

MARKATINE

THE PURPOSE OF THIS SURVEY WAS TO REMONUMENT AND OR SET THE STANDARD AND CLOSING CORNERS ALONG THIS PORTION OF THE FIRST STANDARD PARALLEL WEST.

THE SURVEY WAS PERFORMED USING TOPCON GR3 GPS RECEIVERS AND A TOPCON GTS 300 TOTAL STATION. THE STANDARD SECTION CORNER FOR SECTIONS 33 & 34 AND SECTIONS 34 & 35, THE STANDARD QUARTER CORNER FOR SECTION 35 AND THE CLOSING SECTION CORNER FOR SECTIONS 3 & 2, WHERE DIRECTLY OCCUPIED WITH GPS RECEIVERS, HOLDING COLUMBIA COUNTY GPS CONTROL POINTS "VERNONIA" AND "APIARY". THE CLOSING QUARTER CORNER OF SECTION 3 WAS TIED CONVENTIONALLY FROM TWO GPS CONTROL POINTS, ALONG WITH THE SETTING OF THE STANDARD QUARTER CORNER OF SECTION 34. PLEASE SEE THE NARRATIVE FOR EACH INDIVIDUAL CORNER FOR MORE DETAIL ON EVIDENCE AND REASON FOR SETTING AND/OR HOLDING THE CORNERS.

THE MEASURED DISTANCE BETWEEN MONUMENTS "A" AND "F" IS 78.12 FEET SHORTER THAN THE 1895 MESERVE SURVEY. I AM CERTAIN THAT THE COUNTY HAS THE IDENTICAL POSITIONS OF THESE CORNERS, AS W.N. MESERVE HAD IN 1895. PLEASE SEE PAGE 7 NARRATIVE FOR EXPLANATION.





230 Strand ST. ST. Helens, OR 97051 (503) 397-2322

COLUMBIA COUNTY SURVEYORS OFFICE CORNER RESTORATION SURVEY

FIELD CREW
FIELD BOOK: K2009 Pages 8-13

Nathan A. Woodward
Jerry Keenon
: 400 Ft/In December 16, 2009

CHECKED BY: DRAFTED BY: SHEET
Nathan A. Woodward Nathan A. Woodward 1/7

PROFESSIONAL LAND SURVEYOR

ALL AND SURVEYOR

OREGON
NATHAN A. WOODWARD
JULY 12, 2005
65624LS

EXPIRES: 06/30/2010

REGISTERED

Na Caral de

HISTORY

(ITALICS ARE A DIRECT QUOTE OF RECORD)

(MAY 24, 1871) CORNER ORIGINALLY SET BY W. SMITH UNDER GLO CONTRACT #152.

SET A POST FOR CORNER TO SEC 33 & 34 FROM WHICH A VINEMAPLE 10 IN DIA BEARS 530°W 16 LKS DIST. A W. FIR 40IN DIA BEARS 565°E 29 1/2 LINKS DIST. A VINEMAPLE 6 IN DIA BEARDS N15°E 45 LKS DIST.

(MARCH 8, 1884) BT BOOK "A" PAGE 11 BY THOMAS S. WILKES. FROM STANDARD CORNER TO SECS. 33 & 34, I RAN EAST.

(FEBRUARY 16, 1892) BT BOOK "A" PAGE 104 BY W.N. MESERVE (DEPUTY)

ORIGINAL POST GONE, BUT FIND A POST; THAT ISREAL SPENCER TESTIFIES WAS SET BY T. S. WILKES, C.S. ACCORDING TO THE FIELD NOTES, BUT IT WAS NOT WITNESSED BY HIM. I FIND ONE BEARING TREE WITH SURVEY MARKS ON IT BUT DEAD. AT THE TRUE POINT I SET A POST FOR CORNER FROM WHICH

A FIR 4 INS DIA. BEARS N49°25'W 11 LINKS " " 4" " " N79°40'E 11 "

PRESENT ISREAL SPENCER. GEORGE SALOMAN

(APRIL 24, 1895)

BT BOOK "A" PAGE 194 BY W.N. MESERVE

POST STANDING, SET BY W.N. MESERVE DEPUTY, FEBRUARY 16, 1892 (SEE P. 104) BUT THE BEARING TREES HAD BEEN CUT DOWN. FOR THE CORNER. I SET A CAST IRON WEIGHING ABOUT 40 LBS. MAR. X ON TOP END. SAID IRON HAS A LARGE FOOT ON THE LOWER PART AND IS 24 IN, IN LENGTH 20 IN, IN THE EARTH, OVERLYING A QUART GLASS BOTTLE. FROM WHICH

A PIECE OF CAST IRON WEIGHING ABOUT 40 LBS. VERY IRREGULAR, IN LENGTH, 20 IN. MAR. X ON UPPER END., 24 IN. IN THE EARTH BEARS W. 5. FT.

A FORKED CAST IRON, WEIGHING ABOUT 25 LBS. HAVING BEEN USED ABOUT A PLANER FOR BOXING OR SUPPORT OF SHAFTING. MAR. X ON UPPER END, BURIED IN EARTH 24 IN, BEARS EAST 5 FT. PRESENT- E. RIDGEWAY, ISREAL SPENCER AND J. T. SALOMAN, W. N MESERVE COUNTY SURVEYOR

(AUGUST 1922)

BT BOOK "B" PAGE 69 BY L.J. VAN ORSHOVEN

FOUND CORNER + WITNESSES SET BY FORMER COUNTY SURVEYOR, FROM TRUE CORNER

5" CEDAR BEARING 553°31'E -- 398.1 FT. 20" FIR " 50°55'W -- 391.5 FT. PRESENT W.A. HARRIS, CHAS. MELLINGER

(AUGUST 1924 & MARCH 1926) CS# 203 & CS# 224 BY L.J. VAN ORSHOVEN CS# 203 LABELED CORNER AS" PIPE" CS# 224 LABELED CORNER AS "IRON"

BT BOOK "C" PAGE 237 BY C.R. WAGNER

FOUND CAST IRON WITH 1 1/4" IRON PIPE INSIDE AND 25# CAST IRON EAST 5.0 FEET. IN E-W FENCE LINE SET 4X4 WHITE POST & TAG 1.1 FT. EAST OF CORNER

(AUGUST 1977) CS# 2992 BY A.M. KLIEN (FD. I.P.) (SEPTEMBER 1977) CS# L-1073 BY RICHARD A. MORRIS

FOUND 3/4" I.P. WITH 4"X4" POST WITH TAG MKD. COLUMBIA COUNTY SURVEYOR.

CS# 3025 BY JERRY S. MARIS (OLD 1 1/2" IPF HELD)

(JANUARY 12, 1983)

CS# 3353 BY JERRY C. OLSON

FOUND PIECE OF CASTIRON FOR CORNER AND PIECE OF CASTIRON EAST 5 FEET AS DESCRIBED BY W.N. MESERVE IN 1895. FOUND 1 1/2" IRON PIPE BENT OVER WEST OF CORNER (STRAIGHTENED UP). WEST EDGE OF THE NEHALEM RIVER IS WEST 166' (GLO= 165').

(OCTOBER 12, 1993 - SEPTEMBER 10, 2004) CS#B-242, 3972, 4018, 4283, 4347, 4367, 5193 PARTITION PLAT 1995-51 & 1997-56 **NICKERSON RIDGE ESTATES- SUBDIVISION ALL BY KEENON LAND SERVICES**

FOUND 1 1/2" IRON PIPE

(JANUARY 2, 2001)

BT BOOK "CS" PAGE 203 BY PHILIP DEWEY FOUND 1 1/4" IRON PIPE BESIDE L SHAPED CAST IRON. (HELD)

SET 5/8" I.R. WITH COL. CO. YELLOW PLASTIC CAP N45°E 33.0' & STEEL POST WITH TAG N45°E 1.0'. SET 5/8" I.R. WITH COL. CO. YELLOW PLASTIC CAP 552°E 114.14' & STEEL POST WITH TAG 552°E 1.0'.

SET 5/8" I.R. WITH COL. CO. YELLOW PLASTIC CAP S42°W 137.48' & STEEL POST WITH TAG S42°W 1.0'. SET 5/8" I.R. WITH COL. CO. YELLOW PLASTIC CAP N41°W 35.86' & STEEL POST WITH TAG N41°W 1.0'.

SET STEEL POST & TAG NORTH 1.0' FROM CORNER

(MARCH 2, 2007)

PARTITION PLAT 2007-13 BY DONALD D. WALLACE FOUND 1 1/4" IRON PIPE AS NOTED IN BEARING TREE RECORD "CS" PAGE 203 (HELD)

(SEPTEMBER 30, 2008)

PARTITION PLAT 2008-32 BY JIMMY W. HILLSTROM

FOUND SECTION CORNER SEC 33 AND 34 1 1/2" IRON PIPE (HELD)

BEARINGS AND DISTANCES ARE GRID, BASED ON GPS CONTROL

NAD83(91) STATE PLANE COORDINATES: ZONE 3601

POINTS "VERNONIA" AND "APIARY".

N 813459.55 E 7520765.88 UNITS (IFT)

LEGEND

FOUND 5/8" REBAR WITH YELLOW PLASRTIC CAP MARKED

SET 1 1/4" GALVANIZED IRON PIPE WITH 3 1/4"

ALUMINUM CAP STAMPED AS SHOWN

RECORD BEARING AND/OR DISTANCE

FOUND 6' T- POST & TAG NORTH AT 1.0'

"COLUMBIA CO. SURVEYORS" SET IN BT BK. "CS" PG. 203

CORNER RESTORATION SURVEY

STANDARD SECTION CORNER SECTIONS 33 & 34, T5N, R4 W, OF THE W.M. COLUMBIA COUNTY, OREGON

DECEMBER 9, 2009

FOUND 1 1/2" IRON PIPE N41°00'12"W AT 0.32' FROM THE X MARKED IN THE CAST IRON,

RECORD DATA FOR REFERENCES APPEAR TO BE MEASURED TO THE IRON PIPE AND NOT THE CAST IRON MONUMENT.

PAGE 2 OF 7

M is

N 0

NO



NARRATIVE

THE PURPOSE OF THIS SURVEY WAS TO UPDATE AN EXISTING MONUMENT, KNOWN TO BE AN ORIGINAL. SEVERAL SURVEYS OVER THE YEARS HAVE CALLED FOR A 1 1/2" IRON PIPE FOR THE CORNER; HOWEVER, UPON RESEARCH IT BECAME APPARENT THAT IN 1895 THE CORNER WAS PERPETUATED WITH A CAST IRON OF IRREGULAR SHAPE MARKED WITH AN X AND REFERENCED BY THE SAME.

ON DECEMBER 9, 2009 I FOUND A 1 1/2" IRON PIPE WITH A MUSHROOMED TOP ALONG THE WEST EDGE OF A CAST IRON WITH AN X MARKED ON THE TOP AND THREE REFERENCES PER COLUMBIA COUNTY BT BOOK "CS" PAGE 203, AS SHOWN. I HELD THE LOCATION OF THE X ON THE CAST IRON MONUMENT AND SET A 3 1/4" ALUMINUM CAP IN CONCRETE STAMPED AS SHOWN. I LEFT BOTH THE CAST IRON AND IRON PIPE UNDER THE NEW MONUMENT AND CONCRETE. (PICTURES ON FILE)

I COULD NOT FIND THE OTHER CAST IRON REFERENCES OR THE CLOSING CORNER, LARGELY DUE TO THE ACCUMULATION OF SCRAP METAL AND VEHICLES IN THE VICINITY.

> I, Leslie G. Keenon, Columbia County Surveyor, do hereby acknowledge and accept this monument as the legal and permanent position. This corner reestablished at the identical spot where the original corner was located and approved by the General Land Office or determined to be the best solution for this corner location.

Leslie G. Keenon

MARCH 29, 2010



(503) 397-2322

COLUMBIA COUNTY SURVEYORS OFFICE CORNER RESTORATION SURVEY

FIELD CREW Nathan A. Woodward SCALE: DATE: 20 Ft/In January 28, 2009 CHECKED BY DRAFTED BY: SHEET Nathan A. Woodward Nathan A. Woodward 2/7

REGISTERED **PROFESSIONAL** LAND SURVEYOR Mordano OREGON NATHAN A. WOODWARD JULY 12, 2005 65624LS EXPIRES: 06/30/2010

CS 5707 BT

HISTORY

(ITALICS ARE A DIRECT QUOTE OF RECORD)

CORNER ORIGINALLY SET IN 1871 BY: W SMITH UNDER GLO CONTRACT NO. 152

SET A POST FOR 1/4 SECTION CORNER FROM WHICH A SUGAR 8 IN DIA BEARS 550°E 34 LINKS DIST. A SUGAR 12 IN DIA BEARS N10°W 53 1/2 LINKS DIST

(MAY 2 1891)

BT BOOK "A" PAGE 54 BY MESERVE

I COULD FIND NO CORNER POST NOR BEARING TREE AS BOTH BEARING TREES HAD BEEN CUT DOWN. FIELD NOTES CALLED FOR CORNER 2 CH. 50 L. W. OF CREEK AND 1 CH. 50 L. E. OF ANOTHER CREEK. C.L. PARKER AND OTHERS TESTIGIED THAT HTEY HAD SEEN THE STAKE AND BEARING TREES WHEN STANDING. THEREFORE I SET A POST FOR CORNER FROM WHICH A WHITE FIR 36 IN. DIA. BEARS 5 5°45'W 69 L. AN ALDER 12 IN. DIA. " N 8° E 57 L.

(APRIL 24 & 25 1895) BT BOOK "A" PAGE 194 & 195 BY W.N. MESERVE

FOR THE 1/4 SEC CORNER, SET A 3x4x20IN. CAST IRON MAR. X INSIDE THE RIM OF A 12 IN. PULLEY, BOTH BURRIED 18 IN. IN EARTH. THE CORNER EXTENDS ABOVE GROUND 2 IN. FROM WHICH

A PIT BEARING E. 5 FT. CONTAINS A PIECE OF CAST IRON 2x7x24 IN. MAR. X OF AN IRREGULAR SHAPE. BURRIED IN THE EARTH 24 IN. A PIT CONTAINING 9 PIECES OF CASTIRON BEING PART OF A PULLY GRATE BAR ECT. BURRIED IN THE EARTH 24 IN. BEARS W-FIVE FT.

(FEBRUARY 1924) FIELD BOOK 25 PAGE 55 BY L.J. VAN ORSHOVER FOR CS# 197

1/4 COR. SEC. 34 1/4"x1 1/2"x14" IRON STRAP ON SOUTH SHOULDER OF FILL. BACK 93.8 TO 1/4 COR. SEC. 3, -4-4

(AUGUST 1924) CS# 203 BY L.J. VAN ORSHOVER CS#191B IS THE "WORK MAP" FOR CS# 203 IRON BAR

(AUGUST 9, 1977) CS# 2992 BY ANDREW M. KLEIN

1/4 COR. SEC. 34 LOOKED FOR BUT DID NOT FIND MONUMENT AT THIS CORNER

(AUGUST 1977)

CS# L-1073 BY RICHARD A. MORRIS 1/4 CORNER S. BOUNDARY SECTION 34 MISSING. SET 5/8"x30" IRON ROD 36" IN THE GROUND ON S. SHOULDER OF COUNTY ROAD 7.5' S. OF CL. ALUMINUM NAIL IN 20" FIR 574E 41.70'

(JUNE 30, & NOVEMBER 1, 1997) CS# 4347 & 4367 BY LESLIE G. KEENON

SOUTH 1/4 CORNER SECTION 34 A 5/8" IRON ROD WITH MORRIS CAPPER CS No. L-1073 BEARS 5 89°19' W 8.23'


(OCTOBER 8, 1999) PLAT BOOK 5 PAGE 60. "NICKERSON RIDGE ESTATES" BY LESLIE G. KEENON SOUTH 1/4 CORNER SECTION 34

A 5/8" IRON ROD WITH Y.P.C. MARKED "PLS 401" PER CS No. L-1073 5 89°18'33" W 7.96' FROM THE TRUE 1/4 CORNER.

CORNER RESTORATION SURVEY

STANDARD SOUTH QUARTER CORNER T5N R4W SECTION 34 OF THE W.M. COLUMBIA COUNTNTY, OREGON DECEMBER 2, 2009

8" FIR MARKED WITH 4 NOTCHES 60d SPIKE SET IN THE BOTTOM 5/8" REBAR WITH YELLOW PLASTIC T5N R4W CAP, SET AS A REFERENCE IN BT BOOK "CS" PAGE 201 FOR THE CC OF S34 SECTION 3. 2009 5/8" REBAR CENTERLINE MONUMENT 65624LS WITH NO CAP SET IN "NICKERSON RIDGE N 78°26'50" E 79.55' ESTATES" SUBDIVISION RECORED IN BOOK 5 PAGE 60, COLUMBIA COUNTY. N 83°57'42" W 453.75' S 87°40'26" E 93.79' 5/8" REBAR WITH NO CAP, SET BY RICHARD MORRIS IN CS# L-1073 S 86°56'17" W 8.09' **CLOSING QUARTER CORNER** FOR SECTION 3. SEE PAGE 4



BEARINGS ARE GRID BASED ON GPS CONTROL, ESTABLISED FROM CONTROL POINTS "VERNONIA" AND "APAIRY".



DISTANCES ARE GROUND

LEGEND

- FOUND 5/8" REBAR AS NOTED
- SET 1 1/4" x 30" GALVANIZED IRON PIPE WITH 3 1/4 ALUMINUM CAP STAMPED AS SHOWN

NARRATIVE

THE PURPOSE OF THIS SURVEY WAS TO REESTABLISH THE STANDARD QUARTER CORNER OF SECTION 34, T 5 N, R 4 W, OF THE W.M. THE CORNER WAS CONSIDERED LOST AND RESET IN 1891 BY COUNTY SURVEYOR M.N. MESERVE. I AM TREATING THIS POSITION AS ORIGINAL AND SET A NEW MONUMENT BASED ON L.J. VAN ORSHOVEN TIES OF THIS CORNER TO THE CLOSING CORNER OF SECTION 3, 4N 4W. I HELD SAID CLOSING CORNER FOR LINE AND SET THE STANDARD AT 93.8' FROM THE CLOSING CORNER. I DID NOT USE THE 1977 PROPORTIONED POSITION SET BY RICHARD MORRIS, I DO NOT FEEL THAT THE 1891 CORNER WAS LOST, HAVING BEEN TIED TO THE RECOVERED CLOSING CORNER. ALSO, ALL OF THE SURVEYS FILED AFTER RICHARD MORRIS HAVE CALCULATED THE CORNER IN A SIMILAR FASHION. THIS SOLUTION REDUCES THE IMPACT ON CURRENT OWNERSHIP COMPARED TO A PROPORTIONED POSITION, I SEARCHED FOR 1891 EVIDENCE; HOWEVER, THERE HAS BEEN A LOT OF ROAD WORK, INCLUDING TRENCHING ALONG THIS ROAD AND I BELIEVE THE MONUMENTS WERE DESTROYED DURING THIS PROCESS.

THE CORNER WAS SET FROM GPS CONTROL USING TOPCON GR3 RECEIVERS AND A TOPOC GTS 300 TOTAL STATION WITH A FC 2200 CONTROLER, I THEN OCCUPIED THE CORNER WITH THE INSTRUMENT AND TURNED ANGLES AND MEASURED. DISTANCES TO THE REFERENCES SHOWN.

> I, Leslie G. Keenon, Columbia County Surveyor, do hereby acknowledge and accept this monument as the legal and permanent position. This corner reestablished at the identical spot where the original corner was located and approved by the General Land Office or determined to be the best solution for this corner location


Leslie G. Keenon

FOR DETAILS.

230 Strand ST. ST. Helens, OR 97051 (503) 397-2322

COLUMBIA COUNTY SURVEYOR'S OFFICE CORNER RESTORATION SURVEY

FIELD CREW	FIELD BOOK: K2009 PAGE 12		
Nathan A. Woodward Roy W. Harmond Jerry L. Keenon	SCALE: 10 Ft/In	DRAWING DATE: January 27, 2010	
CHECKED BY: Nathan A. Woodward	DRAFTED BY: Nathan A. Woodward		SHEET 3/7



PAGE 3 OF 7

22

V) L

VO O

UM

(ITALICS ARE A DIRECT QUOTE OF RECORD)

(MAY 2, 1891)

BT BOOK "A" PAGE 54 BY W.N. MESERVE

RESTORATION OF THE QUARTER SECTION CORNER ON THE LINE BETWEEN SECTION 3 AND 34. T.4.N, R4W. AND T5.N, R4W I COULD FIND NO CORNER POST NOR BEARING TREE AS BOTH BEARING TREES HAD BEEN CUT DOWN, FIELD NOTES CALLED FOR CORNER 2 CH 50 L.W. OF CREEK AND 1 CH. 50L. E. OF ANOTHER CREEK. C.L. PARKER AND OTHERS TESTIFIED THAT THEY HAD SEEN THE STAKE AND BEARING TREES WHEN STANDING, THEREFORE I SET A POST FOR CORNER FROM

A WHITE FIR 36 IN. DIA. BEARS 55° 45' W 69 L. AN ALDER 12 IN DIA. . . N 8° E 57 L.

(APRIL 24, 1895)

BT BOOK "A" PAGE 194-196 BY W.N. MESERVE

THENCE 79.93 1/3 ON TRUE LINE BETWEEN SECTIONS, 3 & 34. AND FOR THE 1/4 SEC. CORNER, SET A 3x4x20 IN. CASTIRON MAR. X, INSIDE THE RIM OF A 12 IN. PULLEY, BOTH BURRIED 18 IN. IN THE EARTH, THE CORNER EXTENDS ABOVE GROUND 2 IN. FROM WHICH A PIT BEARING E. 5 FT. CONTAINS A PIECE OF CAST IRON 2x7x24 IN. MAR X, OF AN IRREGULAR SHAPE, BURRIED IN THE EARTH 24 IN. A PIT CONTAINING 9 PEICES OF CASTIRON-BEING PARTH OF A PULLEY GRATE BAR ECT. BURRIED IN THE EARTH 24 IN. BEARS W-FIVE FT.

(AUG 17, 1901)

BT BOOK "A" PAGE 339 BY A.B. LITTLE

RESTORATION OF THE QUARTER SECTION CORNER ON THE NORTH BOUNDARY OF SEC. 3 T.4.N, R4W

I BEGIN AT THE CLOSING COR. OF SECS 3 & 4 AND FIND THE DISTANCE TO THE CLOSING COR. OF SECS 2 & 3, {EACH OF THESE CORS HAVING BEEN ESTABLISHED BY W.N. MESERVE COUNTY SURVEYOR TO BE 78.76 CHS. AT THE EQUIDISTANT POINT OR 39.38 CHS FROM EITHER CORNER, I FOR THIS COR A CAST IRON BAR, OR PART OF A COGGED TRACK OF A SAWMILL CARRIAGE HAVING 13 COGS. FROM WHICH

A FIR 24 INS. DIA. BEARS 5 31° W 306 LKS DIST. "WHITE" 18"" " 5 37° 30' W 265 " " "CEDAR STUMP " 5 52° W 99 " "

EACH TREE BEING MARKED 1/4 CS BT PRESENT AM PARKER & W.M. CASE

CS #191A&B WORK MAP BY L.J. VAN ORSHOVEN STANDARD 1/4 CORNER 93.8 FEET FROM CLOSING 1/4 CORNER

(FEBRUARY 1924)

SUBDIVISION OF THE SW 1/4 OF THE SE 1/4 OF SECTION 34 CS #197 BY L.J. VAN ORSHOVEN SHOWS DISTANCE TO CLOSING QUARTER CORNER AS 93.8'

FIELD BOOK 25, PG. 55-56 1/4 CORNER SEC. 34, 5-4

1/4"x1 1/2"x14" IRON STRAP ON SOUTH SHOULDER OF FILL BACK 93.8 TO 1/4 COR. SEC. 3, 4-4

TWO POSTS BEAR NE + NW - 28.0 FT.

(AUGUST 1924)

SUBDIVISION OF THE 1/2 OF SECTION 3 CS #203 BY L.J. VAN ORSHOVEN SHOWS DISTANCE TO CLOSING QUARTER CORNER AS 93.8'

(NO DATE, ESTIMATE 1930'S) CS # M-523 NO NAME, BELIEVED TO BE CHAS. MARSTON OF CLARK & WILSON LBR. CO.

COR.S EST'D & SET 1" IRON PIPES 1/4 COR N. BDY SEC 3 TAN RAW 1/4 COR S. BDY S. 34 T5N R4W

(AUGUST 9, 1977)

CS #2992 BY ANDREW M. KLEIN CALCULATES STANDARD 1/4 CORNER 93.8 FEET FROM CLOSING 1/4 CORNER

(MAY 25, 1978)

CS #3025 BY JERRY S. MARIS N 1/4 COR. 3 OLD 1 1/2" IPF 0.5' DEEP WITH NARROW TOP HELD

(SEPTEMBER 18, 1980) CS #L-1426 BY DUANE M. FORNEY

FD. N. 1/4 COR. SEC. 3

1 1/2" IP 0.5 BELOW SURFACE ON SOUTH EDGE OF PAVEMENT.

(1989)

BEARING TREE BOOK "CS" PAGE 192 BY: PHILIP DEWEY MR. DEWEY COMBINES THE HISTORY OF THE STANDARD 1/4 CORNER WITH THE FINDINGS OF THE CLOSING CORNER? HE THEN DECIDES THAT THE EVIDENCE IS INCOMPLETE AND DOES NOTHING.

(JULY 16, 1990) CS # B-19 BY: LESLIE G. KEENON

FOUND FOR 1/4 COR.

A 1 1/2" I.P. TOP PINCHED 0.5 DEEP WITH 5/8" I.R. N6.5"

(NOVEMBER 1, 1997 - SEPTEMBER 10, 2004) CS #4212, 4347, 4367, 4678, 5193 AND SUBDIVISION PLAT BOOK 5, PAGE 60 ALL BY: LESLIE G. KEENON

NORTH 1/4 CORNER SECTION 3

1 1/2" IRON PIPE WITH A PINCHED TOP IN MONUMENT BOX.

(JANUARY 2, 2001)

BT BOOK "CS" PAGE 201-202 BY PHILIP DEWEY DESCRIPTION OF EVIDENCE FOUND: CONCRETE MONUMENT CYLINDER AT

EDGE OF OIL ROAD WITH ALUMINUM POST AND COL. CO, TAG S10' NO DATE TONY DEWEY & ROBERT DEWEY. CRIMPED 1 1/4" I.P. WITH SMASHED TOP 0.5' EXPOSED IN CONCRETE MONUMENT BOX, 0.8' BELOW SURFACE OF ROAD. (HELD) 1/2" I.P. EAST 0.28' 0.2' EXPOSED IN MONUMENT BOX.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED: 29" FIR 532°E 19.66' TO RAIL ROAD SPIKE IN BLAZE AND ALUM. TAG. 10" CEDAR 550°W 15.48' TO RAIL ROAD SPIKE IN BLAZE AND ALUM. TAG. 5/8"X30" I.R. WITH YELLOW PLASTIC CAP MARKED COL. CO. SURVEYOR N35° W 25.65' WITH ALUM POST AND TAG N35°W 1' +- OF REFERENCE. 5/8"X30" I.R. WITH YELLOW PLASTIC CAP MARKED COL. CO. SURVEYOR N53° E 31.58' WITH ALUM POST AND TAG N53°E 1' +- OF REFERENCE.

(MAY 27, 2009)

CS # 5649 BY: CHARLES E. SPEAR


LEGEND

NORTH 1/4 CORNER SECTION 3, A 1 1/2" I.P. WITH PINCHED TOP IN MON. BOX. HELD.

CORNER RESTORATION SURVEY

CLOSING CORNER, NORTH QUARTER CORNER SECTION 3 T4N, R4 W, OF THE W.M. COLUMBIA COUNTY, OREGON

DECEMBER 23, 2009



0

Po F

· vo o

UJ

-

BEARINGS FOR THE DIAGRAM ARE BASED ON GPS CONTROL POINTS "VERNONIA" AND "APIARY" THE CORNER REFERENCES ARE BASED ON A HAND COMPASS WITH A DECLINATION OF 21° EAST.



FOUND 1 1/2" IRON PIPE 0.7' FT. BELOW

NARRATIVE

THE PURPOSE OF THIS SURVEY WAS TO EVALUATE. VERIFY AND REMONUMENT THE EXISTING NORTH QUARTER CORNER OF SECTION 3, T4N, R4W, OF THE W.M.

ON DECEMBER 2, 2009 JERRY AND I FOUND A 1"+ IRON PIPE WITH A PINCHED TOP, A 1"+ IRON PIPE .28 EAST, BOTH LOCATED INSIDE A CONCRETE MONUMENT BOX IN KNOTT ST, PER BT. BK. "CS" PG. 201-202. WE FOUND AN OLD LOT CORNER SET BY L.J. VAN ORSHOVEN IN CS #197 AND THE REMAINS OF A CEDAR STUMP THAT FIT WELL WITH THE 1901 RECORD POSITION IN BT BOOK "A" PAGE 339. WE THEN REFERENCED THE PIPE WITH PK NAILS FOR REMOVAL. WHILE REMOVING THE 1"+ PIPE WE REALIZED THAT IT WAS MORE LIKE A PIECE OF CONDUIT, PROPTING US TO DIG FOR MORE EVIDENCE. WE FOUND A PIECE OF CAST IRON (PHOTOS ON FILE) 0.5 FEET NORTH AND 1 FOOT BELOW THE ROAD SURFACE WHICH WE FELT WAS SET IN 1901 BY A.B. LITTLE. THE 1"+ PIPE WAS MOST LIKELY SET BY CHAS. MARSTON IN CS # M-523. HE MENTIONS THAT THE CORNER WAS ESTABLISHED AND SET A 1" IRON PIPE. I BELIEVE THAT HE SET THE PIPE FROM REFERENCES, OF WHICH, ARE A FAIR DISTANCE AWAY, 99 LINKS, 306 LINKS AND 265 LINKS. AT THESE DISTANCES I COULD SEE BEING OFF BY 0.5' FROM THE COG. THE OTHER THEORY IS THAT HE SET A PIPE ABOVE THE ESTABLISHED MONUMENT WHICH LATER WAS DESTROYED DURING ROAD CONSTRUCTION. THEREFORE WE HELD THE POSITION OF THE CAST IRON COG AS THE TRUE CLOSING QUARTER CORNER OF SECTION 3, REPLACING IT WITH THE MONUMENT SHOWN, WITH THE CAST IRON COG BURIED UPSIDE DOWN AND ALONGSIDE.

THE SURVEY WAS PREFORMED USING TOPCON GR3 GPS RECEIVERS AND A TOPCON GTS 300 TOTAL STATION WITH A FC 2200 DATA COLLECTOR.

(\$89°30'E 93.8) CS# 197 N 87°40'31" W 93.79

"N32°W 19.66". VISIBLE SCRIBE AND RR

230 Strand ST.

ST. Helens, OR 97051

(503) 397-2322

SPIKE AT BOTTOM OF FACE.

FOUND 5/8" REBAR WITH COLUMBIA

BT BOOK "CS" PAGE 201-202.

COUNTY YELLOW PLASTIC CAP SET IN

FOUND 36" CEDAR WITH 2000 COUNTY TAG

* NOTE: 2000 COUNTY TAGS ARE REVERSED ON THE TREES. PRIOR REFERENCES WERE MEASURED TO 1" IRON PIPE.

THE SURFACE 1 FT. SOUTH OF ROAD. (\$89°30'E 579.7) CS# 197 BELIEVED TO BE SET IN CS# 197 S 87°26'39" F 579 10" S 3 2009

FOUND 36" WHITE FIR WITH 2000 COUNTY TAG "N50°E 15.48", HEALED FACE AND RR SPIKE AT BOTTOM OF FACE.

COLUMBIA COUNTY SURVEYORS OFFICE CORNER RESTORATION SURVEY

FIELD CREW FIELD BOOK: K2009 Page 10 &11 Nathan A. Woodward SCALE: DRAWING DATE: Jerry Keenon 5 Ft/In February 4, 2010 CHECKED BY: DRAFTED BY: SHEET Nathan A. Woodward Nathan A. Woodward 4/7

REGISTERED **PROFESSIONAL** LAND SURVEYOR A. Norther OREGON NATHAN A. WOODWARD JULY 12, 2005 EXPIRES: 06/30/2010

I, Leslie G. Keenon, Columbia County Surveyor, do hereby acknowledge and accept this monument as the legal and permanent position. This corner reestablished at the identical spot where the original corner was located and approved by the General Land Office or determined to be the best solution for this corner logation

Leslie G. Keenon

Date

STANDARD QUARTER CORNER SECTION

34, T5N, R4W, W.M. SEE PAGE 3 FOR

DETAILS.

FOUND MONUMENT AS NOTED

FOUND ALUMINUM POST AND TAG

SET 1 1/4" X 30" GALVANIZED IRON PIPE

RECORD BEARING AND/OR DISTANCE

WITH 3 1/4" ALUMINUM CAP MARKED AS SHOWN.

FOUND THE REMAINS OF A CEDAR

STUMP WITH POSSIBLE SCRIBE

MARKS. (PHOTOS ON FILE)

CS 5707 BT 40F7

FOUND A BENT 1" IRON PIPE WITH A LEAD FILLED CAP STAMPED T4, 5N R4W 34 35/3 1958, N89° 17'W 3.5' (BENT N89°E 0.4').
A WHITE 4"X4" POST WITH CROWN ZELLERBACH YELLOW TAG AND PROPERTY LINE TAG N38°19'30"E 1.25'
A 48" FIRSTUMP WITH FACE MOSTLY GROWN OVER, SCRIBES VISIBLE BUT NOT ENOUGH SHOWING TO READ, N9°26'50"E 46.63 TO FACE.
AN 18" FIR WITH GROWN OVER FACE (CHOPPED OUT) SCRIBES VISIBLE SCRIBED STD 549 BT, \$27°56'40"E 12.74' TO FACE
ALSO FOUND A STONE AT THE CLOSING CORNER OF SECTIONS 2&3, T.4N., R.4W..

REFERENCED THE STONE WITH A SCRIBED 18" FIR S27°56'40"E 12.05'
TO RAILROAD SPIKE SET IN BASE.
A 12" FIR S61°30'20"W 23.32' TO RAILROAD SPIKE SET IN BASE,
SCRIBED "C5 BT".

THIS CORNER IS 16.88' SOUTH OF THE CENTERLINE OF A THREE STRAND POWER LINE AND 57.77' WSTERLY OF STONE AT 283-4-4 CLOSING CORNER.

(JUNE 26, 1991)


CS# B-86 BY LESLIE G. KEENON

FOUND SEC. CORNER STONE WITH "X" ON TOP AND 1990 COUNTY SURVEYOR BT'S.

CORNER RESTORATION SURVEY

STANDARD SECTION CORNER
SECTIONS 34 & 35, T5N, R4, OF THE W.M.
COLUMBIA COUNTY, OREGON

NOVEMBER 24, 2009



PAGE 5 OF


0

V

NI

NU

BEARINGS FOR THE DIAGRAM ARE BASED ON A HAND COMPASS WITH A DECLINATION OF 21° EAST.



AMENDED CLOSING CORNER SEE SHEET 6 FOR DETAILS.

S 87° E 57.77'

23" FIR S23°E AT 13.25' TO SIDE CENTER 1990 COLUMBIA COUNTY TAG "N26°56'40"W 12.05 TO SPK." VISIBLE HEALED FACE

MARCH 29, 2010

LEGEND

- SET 1/2"X 30" REBAR WITH A RED PLASTIC CAP MARKED " COL. CO. REFERENCE"
- SET 1 1/4" GALVANIZED IRON PIPE WITH 3 1/4"
 ALUMINUM CAP STAMPED AS SHOWN
- STONE WITH X (MESERVE 1895)
-) RECORD BEARING AND/OR DISTANCE

<u>NARRATIVE</u>

THE PURPOSE OF THIS SURVEY WAS TO VERIFY AND REMONUMENT THE STANDARD SECTION CORNER SET BY W.N. MESERVE IN 1895. AS MENTIONED IN THE HISTORY OF THE CORNER, MESERVE SET A STONE AND STONE REFERENCES BY PROPORTIONATE MEASURES. EVEN THOUGH I WOULD NOT DERIVE THE SAME PROPORTIONATE SOLUTION BASED ON MY MEASUREMENTS, I FEEL THAT THE STONE SET IN 1895 SHOULD BE CONSIDERED THE ORIGINAL POSTION FOR THE STANDARD SECTION CORNER COMMON TO SECTIONS 34&35 T 5 N, R 4 W. OF THE W.M.

SC

T5N R4W

S34 | S35

S3

2009

65624LS

19" FIR S67°W AT 24.39' TO SIDE CENTER

corner location

Leslie G. Keenon

1990 COLUMBIA COUNTY TAG

"N61°30'29"E 23.22' TO 5PK."

VISIBLE HEALED FACE

EAST 5.09'

I, Leslie G. Keenon, Columbia County Surveyor, do hereby acknowledge and accept this monument as the

legal and permanent position. This corner reestablished at the identical spot where the original corner

was located and approved by the General Land Office or determined to be the best solution for this

NOVEMBER 24, 2009 JERRY AND I FOUND THE STONE SET BY W.N. MESEREVE IN APRIL OF 1895. WE VERIFIED IT BY THE REFERENCE STONES ALSO SET BY MESERVE AND THE 1990 COUNTY REFERENCES SET. WE DID NOT CHOP OUT THE SPIKES IN THE 1990 REFERENCES TO MEASURE. WE MEASURED THE TREES SIDE-CENTER. W.N. MESERVE SET THIS CORNER 0.9 CHAINS FROM THE CLOSING CORNER POST TO SECTIONS 243 AND WE MEASURED 57.8 FEET BETWEEN THE TWO STONES, MATCHING L.J. VAN ORSHOVENS DISTANCE BETWEEN THE STONE AND THE POST AS PER CS# 203. WE ALSO FOUND A 1" IRON PIPE BENT, WITH A BABBITT FILLED REDUCER STAMPED " T4 5NR4W 34 35/3 1958" THIS MONUMENT WAS SET BY A CROWN ZELLERBACH EMPLOYEE ALONG THE WEST EDGE OF THE STONE, WITH NO FORMAL RECORD. I HELD THE POSITION OF THE STONE AND REMONUMENTED IT AS SHOWN IN THE ACCOMPANYING DIAGRAM. THE STONE WAS BURRIED UPSIDE DOWN AND ALONGSIDE THE NEW MONUMENT AND THE CZ MONUMENT WAS REMOVED AND PLACED HORIZONTAL ALONGSIDE. EQUIPMENT USED, WERE TOPCON GR3 RECEIVERS AND A TOPCON GTS 300 TOTAL STATION.



230 Strand ST. ST. Helens, OR 97051 (503) 397-2322

COLUMBIA COUNTY SURVEYORS OFFICE CORNER RESTORATION SURVEY

FIELD CREW
Nathan A. Woodward
Jerry Keenon
:
CHECKED BY:
Nathan A. Woodward
Nathan A. Woodward
Nathan A. Woodward
Nathan A. Woodward

FIELD BOOK: K2009 Page 8

SCALE:
DRAWING DATE:
February 15, 2010

DRAFTED BY:
Nathan A. Woodward

5/7


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
NATHAN A. WOODWARD
JULY 12, 2005
65624LS

EXPIRES: 06/30/2010

CS 5707 BT

HISTORY (APRIL 24, 1895) (DATE UNKNOWN) (AUGUST 1924) (DECEMBER 1982)



THE STONE AS THE ORIGINAL CLOSING CORNER AND SET AN AMENDED CLOSING CORNER, ONLINE BETWEEN THE STANDARD SECTION CORNER AND THE STANDARD QUARTER CORNER OF THE CONTROLLING TOWNSHIP LINE. IF I WOULD HAVE FOUND EVIDENCE THAT THE STONE WAS SET IN THE EXACT LOCATION OF THE POST SET BY M.N. MESERVE IN

1895, I WOULD HAVE HELD IT AS THE ORIGINAL POSITION AND KINKED THE TOWNSHIP LINE. HOWEVER, THE LAND HAS BEEN LOGGED OVER AND MESERVES'S REFERENCES ARE

JUST NOT DEFINITE ENOUGH TO DO SO. IN 1990 THE COLUMBIA COUNTY SURVEY FOUND A 1895 REFERENCE THAT MEASURED .64 FEET SHORT OF RECORD. I HAVE TO WONDER IF

THE STONE WAS NOT PLACED JUST SOUTH OF THE 6"x6"x60" CEDAR POST. WITH THIS THOUGHT AND THE FACT I COULD VERIFY THE EXACT LOCATION OF THE OTHER TWO

CONTROLLING MONUMENTS, I PLACED THE AMENDED CORNER ON THE TOWNSHIP LINE AND .85 FEET NORTH OF THE FOUND STONE.

230 Strand ST ST. Helens, OR 97051

(503) 397-2322

CORNER RESTORATION SURVEY

FIELD CREW Nathan A. Woodward Jerry Keenon :	FIELD BOOK: K2009 Page 9				
	SCALE: 5 Ft/In	DRAWING DATE: February 15, 2010			
CHECKED BY:	DRAFTED BY:		SHEET		
Nathan A. Woodward	Nathan A. Woodward		6/7		

REGISTERED **PROFESSIONAL** LAND SURVEYOR Hota. Wood OREGON NATHAN A. WOODWARD JULY 12, 2005

PAGE 6 OF

0

NI

V) 0

00

HISTORY

(ITALICS ARE A DIRECT QUOTE OF RECORD)

CORNER ORIGINALLY SET BY W. SMITH UNDER GLO CONTRACT # 152 MAY 24TH 1871

40.00 SET A POST FOR 1/4 SECTION CORNER FROM WHICH A CEDAR 15 IN DIA BEARS S 70° E 18 LINKS DIST A FIR 45 IN DIA BEARS N 23° E 34 LINKS DIST

(APRIL 25, 1895) BT BOOK "A" PAGE 196 BY W.N. MESERVE

ORIGINAL POST COULD NOT BE FOUND. ONE BEARING TREE WAS STANDING, WITH MARKS ON BARK, (GREEN) AND THE OTHER HAD BEEN BLOWN DOWN, AND MARKS HAD BEEN BURNT OFF. BOTH AGREE WITH FIELD NOTES, IN COURSE, DISTANCE AND DESCRIPTION. FOR CORNER I SET A 4 x 4 x 46 IN POST 20 IN. IN THE EARTH, FROM WHICH

A CEDAR 18 IN, BEARS 5 49°25' W 48 LKS.
" FIR 50 " " 5 74° 0' E 301/2 "
" " 16 " " N 52° 35' W 63 "

(DECEMBER 1982) CS# 3353 BY JERRY C. OLSON

FOUND ONE ORIGINAL GLO BT (N22°E) AND 3 COUNTY SURVEYOR
BT'S. WE PULLED GLO BEARING AND DISTANCE FROM THE ORIGINAL
BT AND SHAVED THE GROUND LOOKING FOR THE POST. FOUND 3/4"
PIECE OF CHARCOAL THAT APPEARED TO BE THE TIP OF THE
ORIGINAL POST 20" BELOW GROUND. THIS POINT WAS WITHIN 0.25'
OF WHERE THE VARIOUS BT'S WOULD PUT IT. SET 1" I.P. WITH BRASS
CAP WHERE CHARCOAL WAS FOUND FROM WHICH WE FOUND THE
FOLLOWING:

N 22° E 22.06' (GLO=N23°E 22.44') FND. 50" FIR STUMP WITH 3

NOTCHES IN BARK IN A PYRAMID PATTERN (_-_). THE NOTCHES WERE

ABOUT 6" LONG AND ABOUT 12" APART.

S 73° E 19.95' (MESERVE S 74° E 20.1') FND. 54" FIR STUMP WITH FACE

AND SCRIBE MARKS. FACE HAS BEEN BURNED.

N 53° W 41.45' (MESERVE N 52°35' W 41.6') FND. 16" FIR STUMP WITH

OVERGROWN FACE. DID NOT CHOP OUT.

S 49° W 31.69' (MESERVE S 49°25 W 31.7') FND. 30" CEDAR STUMP

WITH FACE AND SCRIBED "BT". THERE IS 5" OF OVERGROWTH.

(DECEMBER 18, 1989) CS# 3674 BY LESLIE G. KEENON

GLO CEDAR BT GONE (IN OLD SKID TRAIL)

FOUND S 1/4 SEC. 35, A 1" IP WITH BRASS CAP UP 10" AS PER CS 3353 BT/RP A 14" FIR S88E 6.3 TO SPIKE A 17" FIR N6W 17.65 TO SPIKE AN 8" ALDER N79W 8.95 TO SPIKE

I, Leslie G. Keenon, Columbia County Surveyor, do hereby acknowledge and accept this monument as the legal and permanent position. This corner reestablished at the identical spot where the original corner was located and approved by the General Land Office or determined to be the best solution for this corner location.

Leslie G. Keenon

MARCH 29, 2010

FOUND REMAINS OF A FIR STUMP

WITH VISIBLE AXE MARKS

FOUND REMAINS OF A CEDAR STUMP WITH VISIBLE SCRIBE MARKS

S. 1/4 COR.

1982 A.D.

SEC. • 35

FOUND 18" FIR HIGH STUMP WITH 4 HEALED

BLAZES AND A OLSON ENGINEERING TAG.

REFERENCED 6" FIR WITH

FOUR NOTCHES N26°W 5.92 FEET

TO A 60d SPIKE IN BOTTOM NOTCH-

NARRATIVE

THE PURPOSE OF THIS SURVEY WAS TO TIE THE SOUTH QUARTER OF SECTION 35 TOWNSHIP 5 NORTH, RANGE 4 WEST, OF THE W.M., TOGETHER WITH THE SE SECTION CORNER OF SECTION 34, THUS FOLLOWING THE FOOT STEPS OF M.N. MESERVE IN 1895 BT BOOK "A" PAGE 194-196.

NOVEMBER 19, 2009 JERRY AND I FOUND AND HELD THE ABOVE MENTIONED EVIDENCE OF THE ORIGINAL QUARTER CORNER AND ITS PERPETUATION BY JERRY OLSON IN 1982. I WOULD LIKE TO MENTION THAT W.N. MESERVE MEASURED 78 FEET LONGER IN 1895, WITH THE MAJORITY FALLING BETWEEN THE SOUTH QUARTER AND THE SOUTHWEST SECTION CORNER OF SECTION 35. ALL OF THE MONUMENTS FOUND SEEM TO FALL, WITHIN REASON, ON THE 1895 LINE. I HAVE NO EXPLANATION OTHER THAN MESERVE "DROPPED A CHAIN" AFTER HE SET THE TEMP CORNER AT 80.90 CHAINS AND THEN DID NOT RUN BACK ON TRUE LINE, SETTING CORNERS FROM HIS RANDOM LINE. REGARDLESS, CONSIDERING THE LONGEVITY AND HISTORY OF ACCEPTANCE, I TREATED THESE FOUND CORNERS OF W.M. MESERVE AS ORIGINALS.

CORNER RESTORATION SURVEY

STANDARD QUARTER CORNER SECTION 35, T5N, R4, OF THE W.M. COLUMBIA COUNTY, OREGON

NOVEMBER 19, 2009

FOUND REMAINS OF A LARGE FIR STUMP WITH VISIBLE AXE MARKS LOW ON STUMP. (ORIGINAL BT)

> REFERENCED 6" FIR WITH FOUR NOTCHES N19°E 12.11 FEET TO A 60d SPIKE IN BOTTOM NOTCH

FOUND 6' STEEL FENCE POST WITH LONGVIEW FIBRE LOCATION TAG NORTH AT 1.0'

FOUND 17" FIR HIGH STUMP WITH 4 HEALED BLAZES AND A LONGVIEW FIBRE LOCATION TAG SET BY OLSON ENGINEERING

FOUND REMAINS OF A LARGE FIR STUMP
WITH VISIBLE FACE AND POSSIBLE
SCRIBE

LEGEND

FOUND 1" IRON PIPE WITH 2 1/2" BRASS CAP 0.6' ABOVE GROUND, STAMPED AS SHOWN.

() TAG INFORMATION FROM FOUND REFERENCE TAGS
NO MENTION OF REFERENCES IN RECORD



(503) 397-2322

(S 84° W 6.60') TAG

N 90° E 6.79'

COLUMBIA COUNTY SURVEYORS OFFICE CORNER RESTORATION SURVEY

FIELD CREW

Nathan A. Woodward
Jerry Keenon
:

CHECKED BY:

Nathan A. Woodward

Nathan A. Woodward

DRAWING DATE:
February 15, 2010

DRAFTED BY:
Nathan A. Woodward

Nathan A. Woodward

FIELD BOOK: K2009 Page 13

DRAWING DATE:
February 15, 2010

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
NATHAN A. WOODWARD
JULY 12, 2005
65624LS

EXPIRES: 06/30/2010

raverse PC

PAGE 7 OF THE DIAGRAM ARE

 \otimes

0

~

So L

1 N O

ON

BEARINGS FOR THE DIAGRAM ARE BASED ON A HAND COMPASS WITH A DECLINATION OF 21° EAST.

