

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 07-06-2022 at 4:00 PM										
Particulars	Situation as on 07-06-2022 (in last 24 hours)										
Rivers flowing above Danger Level (as per CWC bulletin issued at 8	Nil										
AM)											
District Affected	No. of Districts Affected			ected Distri		Name of Urban Flood Districts					
No. Of Revenue Circles Affected	4	Cachar, Dima-Hasao, Morigaon									
	District										
Name Of	Cachar	2	Katigora	ah, Silchar							
Revenue	Dima-	1	Haflong	_							
Circles	Hasao										
Affected	Morigaon	1	Morigaon								
	Total	4	D	C' I							
3 7 * 11	District	Total	Revenue Circle (Katigorah 6), (Silchar 2)								
Villages Affected	Cachar Morigaon	8 27		aon 27)	ichar (2)						
Affected	Total	35	(Moriga	1011 27)							
Population And Crop	District	Male	Femal e	Childre n	Total Populatio n		Population Details Crop Area (in Hect.)		_	Crop Area Details	
Area Affected	Cachar	4921	3581	1823	10325	(Katigorah 4001), (Silchar 6324)		0.00	(Katigorah Silchar 0.00))	
Affected	Morigaon	1022	856	544	2422	(Morigaon	<u> </u>		(Morigaon	1403.00)	
	Total	5943	4437	2367	12747			1403.00			
Relief	District	Total	Relief C				Relief Distribution Centres				
Camps /	Cachar	1	1(Silcha	r 1)			0(Silchar 0)				
Centres Opened	Dima- Hasao	6	0(Haflor	ng 0)			6(Haflong 6)				
- F	Total	7	1			1	6				
Inmates In Relief	District	Total	Revenue Circlewise			Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit	
Camps	Cachar	530	(Katigor	ah 0), (Silc	har 530)	270	150	110	0	0	
	Total	530				270	150	110	0	0	
Human Lives Lost - Confirmed	Nil										
Human Lives Lost Confirmed - Death Type	Nil										
Human Lives Lost - Missing	Nil										
Human Lives Lost Missing - Type	Nil										

Animals	Nil										
Affected Animals Washed Away	Nil										
Houses Damaged	Nil										
Rescue	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter	Medical Team Deploye d	
Operation	Dima- Hasao	Civil Defence/Trained Volunteers, Fire & Emergency Services (F&ES), Water Resources Department			0	0	0	0	0	15	
	Total		•		0	0	0	0	0	15	
Relief Distributed	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)			
Distributed	Dima- Hasao	34.23	3.26	0.63	154.00	0.00	0.00	0.00			
	Total	34.23	3.26	0.63	154.00	0.00	0.00	0.00			
Relief	District	Baby Foo Liquid	od	Baby Foo	d Solid	Others					
Distributed Others	Dima- Hasao	0.00-Q 78.00-Pkt				Potato-12.05-Q; Onion-4.40-Q; Biscuit-1095.00-Pkt; Candle-466.00-Pkt; Match Box-154.00-Pkt; Mosquito Repellent-272.00-Pkt; Haldi-133.00-Pkt; Milk-163.00-L; Napkin-280.00-Pkt; Mosquito Net-140.00-Pieces					
Infrastructur e Damaged - Embankmen t Breached	Nil										
	District	Numbe r	Details	Details							
Infrastructur e Damaged - Embankmen t Affected	Udalguri	3	Kalaigaon - Emabankment from Jalil Ali House to Samed Ali House. No 2 Singrimari The breached embankment in the L/B of river has further deteriorated on 07/06/2022 due to heavy current of river Noa covering a length of 50ft and breadth of 5ft, Embankment from Kalaigaon Marisali to Bimal Das House No 2 Singrimari The breached embankment in the L/B of river Noa has further deteriorated on 07/06/2022 due to heavy current of river Noa covering a length of 100ft and breadth of 5ft, Embankment at Bananguri (Jhakuachuba) Bananguri The embankment in the L/B of river Chandana has damaged on 07/06/2022 due to erosion covering a length of 100ft and breadth of 2ft								
	Total	3	and saminged on 07700, 2022 day to crosion covering a longar of 100it and broadin of 2it								
	District	Numbe r	Details								
Infrastructur e Damaged - Road	Dibrugar h	2	Moran - Borghuguloni to Ahom Gaon Road Borghugoloni village As per PWRD Tingkhong Territorial Road Sub-Division, Rajgarh report due to heavy and continuous rain the road is badly affected the road surface and side berms are damaged Approximate 0.90 KM. Date of occurance is 18/05/2022., Ghugoloni Bongali to Borbam Road Ghugoloni Bongali village As per PWRD Tingkhong Territorial Road Sub-Division, Rajgarh report due to heavy and continuous rain the road is badly affected the road surface and side berms are damaged Approximate 1.1 KM. Date of occurance is 18/05/2022.								
	South Salmara	7	Mankachar - 1. Fekamari to South Bhurakata(Manullapara) Road. 2.Gazarikandi Pipulbari Road. 3.Tengnamari to Bhutiadanga Road. 4.Hatsingimari Kokradanga Road. 5. Baghapara Bouskata Road. 6. Diara Kalapani Road. 7. Sadullabari kalapani Road. 1.Manullapara 2.Gazarikandi 3.Tengnamari 4.Kokradanga 5.Bouskata. 6.Diara 7.Sadullabari. As per report submitted PWRD Mankachar for road damaged due to heavy rainfall on 06-06-2022. 1) Fekamari to South Bhurakata (Manullapara) Road has submerged(CH 300.00M to 1000.00M) and damaged the hard crust, side berm and side slopes. 2)Hard crust, side berm and side slopes of Gazarikandi Pipulbari road has badly damaged due to heavy rain fall. 3) Hard crust, Side berm and side slopes to Tengnamari to Bhutiadanga road has badly damaged due to heavy rain fall. 4) Hard crust, Side berm and side slopes of Hatsingimari Kokradanga road has badly damaged due to heavy rain fall. 5) Hard crust, side berm and side slopes of Baghapara Bouskata Road has badly damaged due to heavy rain fall. 6) Hard crust, side berm and side slopes of Diara Kalapani Road has badly damaged due to heavy rain fall. 7) Sadullabari Kalapani Road has								

1			1 (CH 20 00M) 100 00M					
	Udalguri	13	submerged(CH 20.00M to 100.00M) and damaged the hard crust, side berm and side slopes. Kalaigaon - Road from Nibhas das house to Nikhil Das house Bhehuguri The road has breached and deteriorated on 07/06/2022 due to erosion and incessant rainfall covering a length of around 15 meters and breadth of 1.5 meters, Road from west side Batiamari river No 1 Singrimari The road condition has deteriorated on 07/06/2022 due to erosion and incessant rainfall covering a length of around 100 ft and breadth of 2 ft, From MB road to Phukan Ghatowals house Habibhanga The road has damaged on 07/06/2022 due to erosion and incessant rainfall covering a length of around 60 ft and 2 ft, Punia Bazar to Kalaigaon link road Bardowaneza The damaged road which has breached further on 07/06/2022 due to heavy current of the river Laljhora (Rangsa) covering a length of around 30 meter and breadth of 7.5 meter in the R/B of the river.					
	District	Numbe r	Details					
Infrastructur e Damaged - Bridge	Kamrup	1	Nagarbera - Bhukradia nagarbera bridge Village - Bhukradia Approch road to bhukradia nagarbera bridge was affected due to erosion on 6-6-2022 and the same has been reported by EE PWD Boko territorial road sub division dated 7-6-2022					
Infrastructur	Total	1						
e Damaged - Wildlife	Nil							
	District	Other De						
Infrastructur e Damaged - Others	Nalbari	Nalbari - Bridge Approach Road Damaged As per the report received from PWRD, Nalbari Territorial Divison, Nalbari via whatsapp group on 06.06.2022, BBNG to Bhuyarkuchi bridge approach road damaged due to rain water, Ghograpar - Bridge Approach Road Damaged As per information received from PWRD, due to incessant rainfall, on 06/06/2022 Rangia -Dhamdhama road RCC bridge no.20/1 approach damage, Length - 10 M, Bridge Approach Road Damaged As per information received from PWRD, due to incessant rainfall, on 06/06/2022 Rangia -Dhamdhama road RCC bridge no.16/1 approach damage, Length - 5 M, Bridge Approach Road Damaged As per information received from PWRD, due to incessant rainfall, on 06/06/2022, 3No Balitara to 4No Balitara BR.No.1/1 Approach road damaged. Length 10 MTR						
	Udalguri	Kalaigaon - Culvert Approach Road Damaged The culvert has damaged on 07/06/2022 due to roadside erosion at village Kabirali covering a length of 15 ft and 5 ft. Long: 92.017063, Lat: 26.63775, Culvert Approach Road Damaged The culvert has damaged on 07/06/2022 due to roadside erosion at village Jhilkakhat covering a length of 15 ft and 5 ft. Long: 92.012928, Lat: 26.63409, Udalguri - Bridge Approach Road Damaged Bridge approach road severly damaged at Bhalukmari to Purani Goroibari road at Bhalukmari village around 25m on 06.06.2022. GPS - Lat - 26.710525 Long - 92.129757., Irrigation Canal/Scheme Damaged Damage of earthen canal embankment of No. 02 Moudubi bund at 1 No. Botabari (Thuribari) village around 30m on 06.06.2022. GPS - Lat - 26.728326 Long - 92.084754, Mazbat - Gully Control Damaged Damage occured due to rain water at khusurabari village near Nabajyoti Kurmi's house on 6/6/2022.(Quantum of Damage in RM/Vol- 100.00 RM)(26.82406, 92.31654)., Gully Control Damaged gully control measures at Kalbari Habi village(Dhansirighat) near NH-15(26.69887, 92.26423), Protection Bundh Damaged damage of guide bundh(Charku Bundh) occured at village Merabil on 6/6/2022.(26.753022, 92.234723). Length- 10m(Approx)						
	District	Details						
	Biswanat	Halem - Paken Mild erosion observed at Paken area on R/B of river Brahmaputra since 06/06/22 by length						
Erosion	h Dhemaji	Jonai - On 06/06/2022 at Buria Chapori under Mesaki chapori Revenue Village approx. 10 hectare of government land got eroded due to siang river affecting approximately 270 people As report received from Lot Mandal & Gaon Pradhan as on 06/06/2022 at Buria Chapori under Mesaki Chapori Revenue Village approx. 10 hectare of government land got eroded due to Siang River affecting approximately 270 people. 270						
	South Salmara	Mankachar - Berabhanga Pt-I As repot submitted Water Resource Department Berabhanga Pt-I river side erosion due to Brahmaputra river on 07-06-2022.Appx- Lanth-1500M and Berath-12M. 0						
	Tinsukia	Doomdooma - 1. Village: No. 1 Kordoiguri(Darjijan), 2. Village: No. 2 Kordoiguri (Simoluguri Satra). 1. River Bank erosion is being observed at No. 1 Kordoiguri (Darzijan)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 07/06/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 400 m in length. (Long: 95.450531, Lati: 27.651217), population affected 37. 2. River Bank erosion is being observed at No.2 Kordoiguri (Simoluguri Satra)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 07/06/2022. As per information received from concerned Lot Mandal and WR department officials, the affected stretch is about 460 m in length. (Long: 95.4505, Lati: 27.65196) 0						
	Udalguri	Kalaigaon - No 2 Kalaigaon Severe erosion occurred at village No 2 Kalaigaon near Adarshagaon LP School on 07/06/2022 due to heavy current of the river in the R/B of the river covering a length of around 100 meters. 0, Mazbat - Murkati village severe erosion occurred at village Murkati near Siv Mandir on 6/6/2022 due to Goldanga river. Length- 200m(Approx) 200						
Landslide	District Cachar	Details Silchar - Chuto Dudhpatil 2 nos of houses partially damage, 1 Pucca House & 1 Kutcha house, due to incessant						

		rain, as reported by LR Staff of Silchar Sadar Revenue Circle on dated 17.05.2022. 10
	Karimgan j	Badarpur - Badarpur Town Jum Pt- VI and Barthal Pt- XI On 06-06-2022, landslide reported at 02 (Two) nos of revenue villages namely 1) Badarpur Town Jum Pt VI and 2) Barthal Pt- XI due to incessant rainfall; resulting 02 (Two) nos of Assam Type Pucca Houses got severely affected. The GPS Co-ordinates of the incident site are 1) Latitude- 24.863117, Lon-92.570108 & 2) 24.802094 & 92.533927. The same has been verified and reported today on 07-06-22 17
Urban Flood	Nil	