

FRIMS Assam



Flood Reporting And Information Management System

	1	Assam Daily Flood Report as on 20-05-2022 at 4:00 PM Situation as on 20-05-2022 (in last 24 hours)							
Particulars			•	24 hours)					
Rivers	Rivers flowi	ng above d	anger	Konili (Dharamtul) Disa	ng (Nanglamuraghat), Brahmaputra (Neamatighat)				
flowing	level			Tropin (Bilaramar), Bisa	ing (1 tungianiang inter), 2 tunniap atau (1 teuniang inter)				
above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowi flood level	ng above h	ighest	Kopili (Kampur)					
1111)	No. of								
	Districts Affected			ected Districts	Name of Urban Flood Districts				
District Affected	29	Charaided Dibrugard Golaghat Kamrup, Karimgar Morigaor	o, Darrang h, Dima-H , Hailakan Kamrup (I nj, Kokrajh	, Bongaigaon, Cachar, , Dhemaji, Dhubri, asao, Goalpara, di, Hojai, Jorhat, M), Karbi Anglong West, ar, Lakhimpur, Majuli, Nalbari, Sonitpur, South	Darrang, Jorhat				
No. Of		Builliuru,	Tinounu,	Cangair					
Revenue Circles Affected	84								
	District	Total	Revenue	e Circle					
	Barpeta	5		Baghbar, Barpeta, Sarthebari, Kalgachia, Chenga					
	Biswanath	4	Naduar RC part, Biswanath, Gohpur, Halem						
		7	•						
	Bongaigao n	3		ır, Srijangram, Boitamari					
	Cachar	5	Katigorah, Silchar, Udharbond, Sonai, Lakhipur						
	Charaideo	1	Mahmor	mora					
	Darrang	4	Mangalo	loi, Dalgaon, Patharighat, S	, Dalgaon, Patharighat, Sipajhar				
	Dhemaji	2	Dhemaji	, Jonai					
	Dhubri	6		Dhubri, Gauripur, Golakganj, Bilasipara, Athani					
	Dibrugarh	1	Chabua						
	Dima-	1	Haflong						
	Hasao	4	D 1''	M (' D ' 1' I 11'					
	Goalpara	4	Balijana, Matia, Rongjuli, Lakhipur						
	Golaghat	2		Khumtai, Sarupathar					
Name Of	Hailakandi	1	Algapur						
Revenue	Hojai	3		Iojai, Doboka					
Circles	Jorhat	2		ast, Jorhat West					
Affected	Kamrup	9	Hajo, Ka	ayan, Rangia, Chamaria, Bo	oko, Chaygaon, Nagarbera, Kamalpur, Goroimari				
	Kamrup (M)	1	Chandra	pur					
	Karbi Anglong West	1	Donkam	okam					
	Karimganj	2	Karimos	nj, Badarpur					
	Karmgan	2		guri, Bagribari					
	Lakhimpur	1	,	, ,	our Narayannur				
	Majuli	2		0 0					
	Morigaon	2		, Morigaon					
	Nagaon	3		Kampur, Raha					
	Nalbari	6			m Nalbari, Nalbari, Barbhag				
	Sonitpur	4	Dhekiajı	ıli, Naduar, Chariduar, Tez	pur				
	South Salmara	1	Mankacl	nar					

			D 1									
	Tinsukia	1	Doomdo									
	Udalguri	2	Udalgur	i, Kalaigaon								
	Total	84										
	District	Total	Revenue									
	Barpeta	259	(Baghba	ar 39), (Ba	rpeta 19), (Sarthebari 54), (Kalgachi	a 88), (Che	nga 59)				
	Biswanath	23	(Naduai	r RC part 4), (Gohpur 7), (Halem 5), (Biswana	th 7)					
	Bongaigao			1000								
	n o	80	(Manıkı	pur 27), (S	rijangram 23), (Boitamari 30)						
	Cachar	365	(Udharl	ond 26). (Sonai 58). (Lakhipur 16). (Silchar	121). (Katigo	orah 144)				
	Charaideo	1	(Udharbond 26), (Sonai 58), (Lakhipur 16), (Silchar 121), (Katigorah 144) (Mahmora 1)									
	Darrang	144		(Mahmora 1) (Dalgaon 48), (Mangaldoi 45), (Patharighat 25), (Sipajhar 26)								
	Dhemaji	17		iji 2), (Jona		, (1 atharignat 23), (51pa	jiiai 20)					
	Dhubri	268				olakganj 10), (Gauripur	40) (D:1:-	<i>56</i>				
					DH 54), (GC	orakganj 10), (Gauripur	49), (b ilasip	ara 50), (Amani 69)				
	Dibrugarh	2	(Chabua	a 2)								
	Dima-	28	(Haflon	g 28)								
	Hasao											
	Goalpara	182				ongjuli 15), (Lakhipur 9	6)					
	Golaghat	4		(Khumtai 3), (Sarupathar 1)								
	Hailakandi	3	(Algapu									
	Hojai	71	(Lanka	11), (Hoja	i 37), (Dobo	oka 23)						
	Jorhat	1	,	West 1)								
Villages	Kamrup	114				maria 24), (Boko 2), (C	Chaygaon 3)	, (Kayan 14), (
Affected	Kannup	114	Nagarbe	ra 3), (Kar	nalpur 21), ((Goroimari 8)						
Affected	Kamrup	9	(Chanda	mom.um 0)								
	(M)	9	(Chandi	rapur 9)								
	Karbi											
	Anglong	2	(Donka	mokam 2)								
	West											
	Karimganj	14	(Karims	ganj 8), (B	adarpur 6)							
	Kokrajhar	44		(Karimganj 8), (Badarpur 6) (Bagribari 37), (Bhawraguri 7)								
	Lakhimpur	59	(Subansiri 1), (North Lakhimpur 1), (Narayanpur 33), (Bihpuria 24)									
	Majuli	15	(Ujani Majuli 5), (Majuli 10)									
	Morigaon	154	(Mayong 83), (Morigaon 71)									
			(Kampur 98), (Nagaon 28), (Raha 78)									
				-		2aha 78)						
	Nagaon	204	(Kampu	ır 98), (Na	gaon 28), (I		lhari 15) ()	Nalbari 17) (Barbbag				
			(Kampu (Tihu :	ır 98), (Na	gaon 28), (I	Raha 78) ograpar 13), (Paschim Na	lbari 15), (l	Nalbari 17), (Barbhag				
	Nagaon Nalbari	204 119	(Kampu (Tihu : 32)	or 98), (Na 5), (Barkhet	gaon 28), (I ri 37), (Gho	ograpar 13), (Paschim Na		Nalbari 17), (Barbhag				
	Nagaon Nalbari Sonitpur	204	(Kampu (Tihu : 32)	or 98), (Na 5), (Barkhet	gaon 28), (I ri 37), (Gho			Nalbari 17), (Barbhag				
	Nagaon Nalbari Sonitpur South	204 119	(Kampu (Tihu 32) (Dhekia	or 98), (Na 5), (Barkhet	gaon 28), (I ri 37), (Gho	ograpar 13), (Paschim Na		Nalbari 17), (Barbhag				
	Nagaon Nalbari Sonitpur South Salmara	204 119 42 12	(Kampu (Tihu 5 32) (Dhekia (Manka	ur 98), (Na; 5), (Barkhet ujuli 16), (N char 12)	gaon 28), (I ri 37), (Gho	ograpar 13), (Paschim Na		Nalbari 17), (Barbhag				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia	204 119 42 12 4	(Kampu (Tihu : 32) (Dhekia (Manka	ur 98), (Nag 5), (Barkhet Ljuli 16), (N char 12)	gaon 28), (I ri 37), (Gho Naduar 3), (ograpar 13), (Paschim Na		Nalbari 17), (Barbhag				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri	204 119 42 12 4 11	(Kampu (Tihu : 32) (Dhekia (Manka	ur 98), (Na; 5), (Barkhet ujuli 16), (N char 12)	gaon 28), (I ri 37), (Gho Naduar 3), (ograpar 13), (Paschim Na		Nalbari 17), (Barbhag				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia	204 119 42 12 4	(Kampu (Tihu : 32) (Dhekia (Manka	ur 98), (Nag 5), (Barkhet Ljuli 16), (N char 12)	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1)	ograpar 13), (Paschim Na	4)	Nalbari 17), (Barbhag				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total	204 119 42 12 4 11 2251	(Kampu (Tihu 1 32) (Dhekia (Manka (Doomo (Kalaig:	ur 98), (Nag 5), (Barkhet ujuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Jdalguri 1)	ograpar 13), (Paschim Na Chariduar 9), (Tezpur 1	4) Crop					
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri	204 119 42 12 4 11	(Kampu (Tihu : 32) (Dhekia (Manka (Doomo (Kalaiga	ur 98), (Nag 5), (Barkhet Ljuli 16), (N char 12)	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1)	ograpar 13), (Paschim Na	Crop Area (in	Nalbari 17), (Barbhag Crop Area Details				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total	204 119 42 12 4 11 2251	(Kampu (Tihu 1 32) (Dhekia (Manka (Doomo (Kalaig:	ur 98), (Nag 5), (Barkhet ujuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Jdalguri 1)	ograpar 13), (Paschim Na Chariduar 9), (Tezpur 1 Population Details	4) Crop	Crop Area Details				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total	204 119 42 12 4 11 2251	(Kampu (Tihu : 32) (Dhekia (Manka (Doomo (Kalaiga	ur 98), (Nag 5), (Barkhet ujuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio	Population Details (Barpeta 0), (Crop Area (in	Crop Area Details (Barpeta 1289.00), (
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 1 32) (Dhekia (Manka (Doome (Kalaige	rr 98), (Nag 5), (Barkhet rjuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total	204 119 42 12 4 11 2251	(Kampu (Tihu : 32) (Dhekia (Manka (Doomo (Kalaiga	ur 98), (Nag 5), (Barkhet ujuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Crop Area (in	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 1 32) (Dhekia (Manka (Doome (Kalaige	rr 98), (Nag 5), (Barkhet rjuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar	Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 1 32) (Dhekia (Manka (Doome (Kalaige	rr 98), (Nag 5), (Barkhet rjuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67)				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 1 32) (Dhekia (Manka (Doome (Kalaige	rr 98), (Nag 5), (Barkhet rjuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0)	Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part				
	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Dooma (Kalaiga Femal	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part	Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath				
Population	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 1 32) (Dhekia (Manka (Doome (Kalaige	rr 98), (Nag 5), (Barkhet rjuli 16), (N char 12) dooma 4) aon 10), (U	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath	Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur				
And Crop	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Dooma (Kalaiga Femal	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709	Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem				
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Doomo (Kalaiga Femal	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108)	Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00)				
And Crop	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Doome (Kalaiga Femal e	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Population 0	Population Details (Barpeta 0), (Tezpur 1 (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Crop Area (in Hect.) 8015.77	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Doomo (Kalaiga Femal	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n	Population Details (Barpeta 0), (Tezpur 1 (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Srijangram 0), (Crop Area (in Hect.)	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Doome (Kalaiga Femal e	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Population 0	Population Details (Barpeta 0), (Tezpur 1 (Barpeta 0), (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Srijangram 0), (Boitamari 0)	Crop Area (in Hect.) 8015.77	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Boitamari 638.00)				
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Doome (Kalaiga Femal e	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Population 0	Population Details (Barpeta 0), (Sarthebari 0), (Sarthebari 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Boitamari 0), (Boitamari 0) (Katigorah 110575),	Crop Area (in Hect.) 8015.77	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Boitamari 638.00) (Katigorah 3052.00),				
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath Bongaigao n	204 119 42 12 4 11 2251 Male 0 2597	(Kampu (Tihu 132) (Dhekia (Manka (Doome (Kalaige Femal e	198 Nag Nag	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n 6747	Population Details (Barpeta 0), (Tezpur 1 (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Srijangram 0), (Boitamari 0) (Katigorah 110575), (Silchar 32500), (Crop Area (in Hect.) 8015.77	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Boitamari 638.00) (Katigorah 3052.00), (Silchar 1385.00), (
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath	204 119 42 12 4 11 2251 Male	(Kampu (Tihu 132) (Dhekia (Manka (Doome (Kalaiga Femal e	rr 98), (Nag 5), (Barkhet ijuli 16), (N char 12) dooma 4) aon 10), (U Children	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Population 0	Population Details (Barpeta 0), (Tezpur 1 (Sarthebari 0), (Sarthebari 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Srijangram 0), (Boitamari 0) (Katigorah 110575), (Silchar 32500), (Udharbond 1755), (Crop Area (in Hect.) 8015.77	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Boitamari 638.00) (Katigorah 3052.00), (Silchar 1385.00), (Udharbond 275.00), (
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath Bongaigao n	204 119 42 12 4 11 2251 Male 0 2597	(Kampu (Tihu 132) (Dhekia (Manka (Doome (Kalaige Femal e	198 Nag Nag	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n 6747	Population Details (Barpeta 0), (Tezpur 1 (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Srijangram 0), (Boitamari 0) (Katigorah 110575), (Silchar 32500), (Udharbond 1755), (Sonai 12800), (Crop Area (in Hect.) 8015.77	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Srijangram 3052.00), (Silchar 1385.00), (Udharbond 275.00), (Sonai 1838.30), (
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath Bongaigao n Cachar	204 119 42 12 4 11 2251 Male 0 2597	(Kampu (Tihu 32) (Dhekia (Manka (Dooma (Kalaiga e))))))))))))))))))	or 98), (Nag 5), (Barkhet 12) 16 oma 4) 2 om 10), (U Children 0 1952 0 46702	gaon 28), (I ri 37), (Gho Naduar 3), (Jdalguri 1) Total Population 0 6747 0	Population Details (Barpeta 0), (Tezpur 1 (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Srijangram 0), (Boitamari 0) (Katigorah 110575), (Silchar 32500), (Udharbond 1755), (Sonai 12800), (Lakhipur 8996)	Crop Area (in Hect.) 8015.77 563.00	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Boitamari 638.00) (Katigorah 3052.00), (Silchar 1385.00), (Udharbond 275.00), (Sonai 1838.30), (Lakhipur 340.20)				
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath Bongaigao n	204 119 42 12 4 11 2251 Male 0	(Kampu (Tihu 132) (Dhekia (Manka (Doome (Kalaige Femal e	198 Nag Nag 198 Nag Nag	gaon 28), (I ri 37), (Gho Naduar 3), (Udalguri 1) Total Populatio n 6747	Population Details (Barpeta 0), (Tezpur 1 (Barpeta 0), (Crop Area (in Hect.) 8015.77	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Srijangram 3052.00), (Silchar 1385.00), (Udharbond 275.00), (Sonai 1838.30), (Lakhipur 340.20) (Mahmora 1.60)				
And Crop Area	Nagaon Nalbari Sonitpur South Salmara Tinsukia Udalguri Total District Barpeta Biswanath Bongaigao n Cachar	204 119 42 12 4 11 2251 Male 0 2597	(Kampu (Tihu 32) (Dhekia (Manka (Dooma (Kalaiga e))))))))))))))))))	or 98), (Nag 5), (Barkhet 12) 16 oma 4) 2 om 10), (U Children 0 1952 0 46702	gaon 28), (I ri 37), (Gho Naduar 3), (Jdalguri 1) Total Population 0 6747 0	Population Details (Barpeta 0), (Tezpur 1 (Sarthebari 0), (Kalgachia 0), (Chenga 0), (Baghbar 0) (Naduar RC part 1450), (Biswanath 480), (Gohpur 1709), (Halem 3108) (Manikpur 0), (Srijangram 0), (Boitamari 0) (Katigorah 110575), (Silchar 32500), (Udharbond 1755), (Sonai 12800), (Lakhipur 8996)	Crop Area (in Hect.) 8015.77 563.00	Crop Area Details (Barpeta 1289.00), (Sarthebari 3717.10), (Kalgachia 1457.00), (Chenga 1153.00), (Baghbar 399.67) (Naduar RC part 208.00), (Biswanath 0.00), (Gohpur 238.00), (Halem 117.00) (Manikpur 188.00), (Srijangram 319.00), (Boitamari 638.00) (Katigorah 3052.00), (Silchar 1385.00), (Udharbond 275.00), (Sonai 1838.30), (Lakhipur 340.20)				

					Patharighat 20809), (Sipajhar 125)), (Patharighat 385.40), (Sipajhar 386.50)
Dhemaji	315	260	69	644	(Jonai 0), (Dhemaji 644)	339.20	(Jonai 327.20), (Dhemaji 12.00)
Dhubri	0	0	0	0	(Dhubri 0), (Gauripur 0), (Golakganj 0), (Bilasipara 0), (Athani 0), (Chapar 0)	5974.33	(Dhubri 1061.00), (Gauripur 937.50), (Golakganj 151.00), (Bilasipara 1647.70), (Athani 1726.13), (Chapar 451.00)
Dibrugarh	1949	1490	1148	4587	(Chabua 4587)	3.50	(Chabua 3.50)
Dima- Hasao	140	125	70	335	(Haflong 335)	115.00	(Haflong 115.00)
Goalpara	0	0	0	0	(Lakhipur 0), (Balijana 0), (Matia 0), (Rongjuli 0)	9525.50	(Lakhipur 6750.00), (Balijana 722.50), (Matia 1750.00), (Rongjuli 303.00)
Golaghat	0	0	0	0	(Sarupathar 0), (Khumtai 0)	38.14	(Sarupathar 12.14), (Khumtai 26.00)
Hojai	62736	38270	10015	111021	(Lanka 1919), (Hojai 55943), (Doboka 53159)	5213.00	(Lanka 650.00), (Hojai 3332.00), (Doboka 1231.00)
Jorhat	0	0	0	0	(Jorhat West 0)	130.00	(Jorhat West 130.00)
Kamrup	11	10	5	26	(Chamaria 0), (Chaygaon 0), (Nagarbera 0), (Hajo 0), (Rangia 26), (Boko 0), (Kayan 0), (Kamalpur 0), (Goroimari 0)	4099.55	(Chamaria 1829.50), (Chaygaon 82.00), (Nagarbera 99.50), (Hajo 1146.05), (Rangia 277.00), (Boko 56.00), (Kayan 80.00), (Kamalpur 44.00), (Goroimari 485.50)
Kamrup (M)	0	0	0	0	(Chandrapur 0)	778.00	(Chandrapur 778.00)
Karbi Anglong West	344	348	388	1080	(Donkamokam 1080)	0.00	(Donkamokam 0.00)
Karimganj	5673	4434	4055	14162	(Karimganj 10996), (Badarpur 3166)	6.90	(Karimganj 0.00), (Badarpur 6.90)
Kokrajhar	0	0	0	0	(Bagribari 0), (Bhawraguri 0)	278.55	(Bagribari 241.90), (Bhawraguri 36.65)
Lakhimpur	1000	658	207	1865	(Subansiri 40), (North Lakhimpur 1825), (Narayanpur 0), (Bihpuria 0)	906.40	(Subansiri 20.00), (North Lakhimpur 3.00), (Narayanpur 628.40), (Bihpuria 255.00)
Majuli	0	0	0	0	(Ujani Majuli 0), (Majuli 0)	219.43	(Ujani Majuli 38.25), (Majuli 181.18)
Morigaon	1341	1229	615	3185	(Mayong 0), (Morigaon 3185)	8060.51	(Mayong 5853.50), (Morigaon 2207.01)
Nagaon	144924	13138 5	60109	336418	(Nagaon 17385), (Kampur 237158), (Raha 81875)	12443.42	(Nagaon 1676.00), (Kampur 5600.00), (Raha 5167.42)
Nalbari	2218	1481	776	4475	(Barbhag 0), (Tihu 3692), (Barkhetri 0), (Ghograpar 0), (Paschim Nalbari 783), (Nalbari 0)	3035.60	(Barbhag 255.00), (Tihu 36.00), (Barkhetri 2351.00), (Ghograpar 64.00), (Paschim Nalbari 161.00), (Nalbari 168.60)
Sonitpur South	2192	2139	1553	5884	(Naduar 958), (Dhekiajuli 0), (Chariduar 4632), (Tezpur 294)	1387.10	(Naduar 151.00), (Dhekiajuli 1088.10), (Chariduar 0.00), (Tezpur 148.00)
Salmara	0	0	0	0	(Mankachar 0)	140.00	(Mankachar 140.00)
Tinsukia	0	0	0	0	(Doomdooma 0)	19.00	(Doomdooma 19.00)
Udalguri	971	789	381	2141	(Harisinga 0), (0.00	(Harisinga 0.00), (

						Kalaigaon Udalguri			Kalaigaon 0		
	Total	311356	26076 9	139780	711905		· ·	80036.90	Ų .	,	
	District	Total	Relief C	l Camp			Relief Dist	ribution Cent	res		
	Biswanath	2	1(Halen	n 1)			1(Halem 1	1(Halem 1)			
	Cachar	216		narbond 1, S 82, Lakhipu	onai 6, Katig r 0)	gorah 62,	65(Udharbond 3, Sonai 0, Katigorah 30, Silchar 8, Lakhipur 24)				
	Darrang	18	1(Pathar	righat 1, Mar	ngaldoi 0)		17(Patharig	ghat 6, Manga	ldoi 11)		
	Dima-	4	2(Haflor	ng [2)			2(Haflong	12)			
	Hasao		2(Haflong 2)				_				
Relief	Hailakandi	2	0(Algap				2(Algapur				
Camps /	Hojai Karbi	61	47(Hoja	i 36, Dobok	a 11)		14(Hojai 2	2, Doboka 12))		
Centres Opened	Anglong West	2		amokam 0)			2(Donkamo				
	Karimganj	16		pur 6, Karin	nganj 0)			ır 1, Karimga	nj 9)		
	Lakhimpur 1			ria 0)			1(Bihpuria	• •			
	Morigaon	1	1(Morig				0(Morigaoi	• •			
	Nagaon	36	1		aon 7, Raha	(3)		r 0, Nagaon 1	11, Raha 0)		
	Sonitpur	1	0(Nadua				1(Naduar				
	Udalguri	2	0(Udalg	urı 0)			2(Udalguri	[2]			
	Total	362	234				128	1	1	D	
	District	Total	Revenue	e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit	
	Biswanath	30	[0), (Go	RC part 0), hpur 0), (Ha	alem 30)	10	17	3	0	0	
It I	Cachar	28424	7975), (1 1013), (1	ah 19360), (Udharbond ´ Lakhipur 0)	76), (Sonai	10419	10179	7798	21	7	
Inmates In Relief Camps	Darrang	91		doi 0), (Dal r 0), (Pathar		15	58	15	1	2	
Cumps	Dima- Hasao	161	(Haflong		17427	70	65	26	0	0	
	Hojai	32595 607	(Hojai	0), (Doboka 25158) anj 0), (Bad		19396 326	9971 197	3210 58	16 26	0	
	Karimganj Morigaon	45		g 0), (Morig		20	15	10	0	0	
			, ,	r 6287), (Na				10		U	
	Nagaon	12752		Raha 306)	iguon	6491	4302	1854	104	1	
	Total	74705	,,,	. ,		36747	24804	12974	168	12	
	District	Total	Male	Female	Children	Revenue C	Circlewise			l	
Human	Cachar	2	0	1	1	(Katigorah (Udharbon		ır 0), (Silchar	0), (Sonai 0),	
Lives Lost - Confirmed	Lakhimpur	1	0	0	1	(Subansiri	0)	our 0), (North	Lakhimpur 1),	
	Nagaon	1	1	0	0	(Kampur	1), (Nagaon	0), (Raha 0)			
Human Lives Lost	Total District	Total	Flood Death	General Drownin g (Non Flood)	2 Landslide						
Confirmed -	Cachar	2	2	0	0						
Death Type	Lakhimpur	1	1	0	0						
	Nagaon Total	1 4	1 4	0	0						
Human Lives Lost - Missing Human Lives Lost	Nil	17	7	V	l o						
Missing - Type Animals	Nil	Tetal	Ria	Cmoll	Double						
Ammais	District	Total	Big	Small	Poultry						

Affected	Barpeta	29710	13781	8429	7500							
	Biswanath	1926	1593	333	0							
	Cachar	132962	65455	22107	45400							
	Darrang	117503	58527	24866	34110							
	Dhemaji	92	58	34	0							
	Dibrugarh	799	712	87	0							
	Hojai	9882	2404	984	6494							
	Kamrup	20258	9474	4857	5927							
	Lakhimpur	3774	2029	1705	40							
	Morigaon	15033	3360	2332	9341							
	Nagaon	94558	52720	27724	14114							
	Nalbari	17569	7138	8631	14114							
	Sonitpur	4210	2876	1334	0							
	Total	448276	22012 7	103423	124726							
Animals	District	Total	Big	Small	Poultry							
Washed	Cachar	1	1	0	0							
Away	Total	1	1	0	0							
Houses	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total		
Damaged	Goalpara	1	0	1	0	0	0	0	0	0		
Zumugeu	Hojai	2	0	2	0	0	0	0	0	0		
	Total	3	0	3	0	0	0	0	0	0		
	District	Agency	·		Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter	Medical Team Deploye d		
	Cachar	Administr Emergence Local Pec Civil Defe Volunteer Resources	cy Services ople, NDR ence/Train rs, SDRF,	s (F&ES), F, Police, led Water	5	840	0	0	0	14		
Rescue	Darrang	SDRF	F		2	25	0	0	0	6		
Operation	Dima-							_				
	Hasao				0	0	0	1	145	1		
	Hojai	Circle Of Administr NDRF, SI Army/Par Country I	ration, Loc DRF, Arm ramilitary	cal People, y boat,	70	1075	88	0	0	10		
	Morigaon				4	100	110	0	0	0		
	Nagaon	Fire & Er (F&ES), l Army/Par	NDRF, SE	PRF,	11	680	30	0	0	6		
	Total	_			92	2720	228	1	145	37		
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)				
	Biswanath	1.21	0.22	0.03	2.70	0.00	0.00	0.00				
	Cachar	369.00	19.78	10.04	804.00	0.00	658.00	0.00				
	Darrang	327.45	59.90	17.88	1788.00	0.00	0.00	792.50				
Relief Distributed	Dima- Hasao	20.00	25.00	13.00	9.00	0.00	0.00	0.00				
	Hailakandi	36.12	6.64	2.08	201.00	0.00	0.00	0.00				
	Hojai	277.45	51.96	15.58	998.56	0.00	0.00	100.00				
	Kamrup	0.00	0.00	0.00	0.00	0.00	384.44	0.00				
	Karbi Anglong West	13.13	2.40	0.72	0.72	0.00	0.00	0.00				
	Karimganj	112.02	21.55	6.47	0.00	0.00	0.00	0.00				

	Lakhimpur	0.00	0.00	0.00	0.00	0.00	0.00	39.00	
	Morigaon	13.10	2.68	0.80	0.00	0.00	0.00	0.00	
	Nagaon	229.40	42.36	12.71	0.00	0.00	440.00	0.00	
	Sonitpur	3.60	0.66	0.20	0.00	0.00	0.00	0.00	
	Udalguri	20.10	3.82	1.15	114.54	0.00	0.00	0.00	
	Total	1422.58	236.97	80.66	3918.52	0.00	1482.44	931.50	
		Baby Foo					1102111	761.60	
	District	Liquid		Baby Food	Sona	Others			
	Biswanath	0.00-Q		0.00-Q		Nestum for Baby-3.00-Pkt; Chira-0.53-Q; Jaggery -0.09-Q; Candle-13.00-Pkt; Mosquito repellent coil-13.00-Pkt; Match Box-13.00-Pkt; Sanitary Pads -5.00-Pkt; Hand wash-5.00-Pieces; Soap-26.00-Pieces			
	Cachar	0.00-Q		0.00-Q		Cheera-3.00-Kg; Jaggery-0.25-Kg; Candle-1369.00-Pkt; Match Box-1369.00-Pkt; Paked Drinking Water-2.00-L; Biscuit-26.00- Pkt; Mortien-50.00-Pkt; Mortein-1368.00-Pkt; Soyabean- 184.20-Kg; Potato-6474.00-Kg; Soyaean-19.00-Kg; Amul Taza- 12.00-L			
	Darrang	0.00-Q, 2	.00-L	240.00-Pkt	, 0.00-Q		200.00-Pieces; ito coil-5.00-F	Candles-7.00-Pkt; sanitary pads-50.00-Pkt	
Relief	Dima- Hasao	0.00-L		0.00-Kg					
Distributed Others	Hailakandi	0.00-Q		0.00-Q			60.00-Pieces; ter Packets-30	Water Purification Tablet-2300.00- 00.00-Pkt	
	Нојаі	2287.00-I Q	_, 0.00-	0.00-Q, 230	02.00-Pkt	bottle-2050	0.00-L; biscui	2-Q; Amul Taza-1302.00-Pkt; water it-2000.00-Pkt; Tarpaulin-200.00- Pkt; Water-18858.00-L	
	Kamrup	0.00-Q		0.00-Q		0-0.00-Q			
	Karbi Anglong West	0.00-Q		0.00-Q					
	Karimganj	0.00-Q		100.00-Pkt, 0.00-Q		0-0.00-Q; MOSQUITO COIL -10.00-Pkt; CANDLE-20.00-Pkt; PHENYL-15.00-L; SANITARY NAPKIN-30.00-Pkt			
	Lakhimpur	0.00-Q		0.00-Q			,		
	Morigaon	0.00-Q		0.00-Q		0-0.00-Q			
	Nagaon	0.00-Q		0.00-Q, 450000.00-ml Tarpaulin-365.00-Pieces					
	Sonitpur	0.00-Q		0.00-Q					
	Udalguri	0.00-Q		0.00-Q		Sanitary Pa	d-294.00-Pkt		
	District	Numbe r	Details	thebari - Ring bundh of Kaldia river Kawaimari Gha Block damaged approx. 150 m. at near					
Infrastructur e Damaged - Embankmen t Breached	Barpeta	4	Sukur A Panchay Mondal Panchay damageo Panchay	li house to A at bundh of T to Purba Dek at bundh of T I at near culv at Bundh of T	ynal Haque ho Fihu river Ka a house (repo Fihu river Ka ert side (repo Fihu river Ka	ouse (reported waimari 6 No rted by LM, 2 waimari Kha rted by LM, 2 waimari 6 No	d by LM, 20.0 b. Block Dam 20.05.2022), Block (Neula 20.05.2022),	05.2022), haged approx. 50m at near Sibashi harbhita to Kawaimari 6 No. Block) haged approx. 150m. at near Dhanjit	
	Cachar	1	Occurred Bund Su	d at Ring Bur ddenly Slum	nd Village Bei	renga at aroun	nd 12.15 PM o n Approx 22 N	00 M 822 M Berenga Breach of LB Borak due Seepage Leakage the of (Ch. 800 M 822 M) as Reported by	
	Total	5							
	District	Numbe	Details						
Infrastructur e Damaged	Dibrugarh	1	Dibruga received rain cuts Bridge.	from Assista and major sl The concerne l Bridge Proj	ant Executive ump down hat ad dyke is und ect, Several m	tra Dyke Phase II Bogibeel Bridge Project As per report Engineer WR Department Dibrugarh, as on 20.05.2022 that Severe s been observed at B-dyke Phase II at downstream of Bogibeel er the jurisdiction of Dy. Chief Engineer/Con, N.F Railway, ajor rain cuts and slump downs has been observed in between Ch			
Embankmen t Affected	Majuli	1	Majuli - Severe r	Balijokaibovaincuts occur	wa and Namo red under PGJ	ue to incessant rainfall and movement of cattle and heavy vehicles ni Jokaibowa Balijokaibowa and Namoni Jokaibowa dyke H dyke on 20.05.2022. Length=3 mtr. Breadth= 0.6 mtr. Depth= ing is going on for recoupment by Water Resource Department.			
	Nalbari	4	Barkhet occurred 20/05/20	cri - B/dyke o due to erosio 122,	on R/B of river on. reach leng	r Brahmaputra th of damage	a from Adaba 500m. as repo	ri to Kukarjan larkuchi damage orted by AEE, WRD, Mukalmua on n peradhara damage occurred due to	

	Total District	6 Numbe r	erosion at channel mouth near peradhara. reach length of damage 300m. as reported by AEE, WRD, Mukalmua on 20/05/2022, B/dyke on R/B of river Pagaldia from Bijulighat to Adabari hanapara damage occurred due to erosion at Hanapara. reach length of damage 200m. as reported by AEE, WRD, Mukalmua on 20/05/2022, Barbhag - L/B of river Pagladiafrom Dusutimukh to Adabari Dusutimukh As per report submitted by Asst. Executive Engineer Mukalmua W.R. Subdivsion Mukalmua as on dated 20/05/ 2022 Details Baghbar - Baghbar satra to Baghbar thana road Baghbar gaon Date of damage- 15/5/22 Type of damage- shoulder and H/C damage Damage length- 450 m, Mandia Rowmari road to Dapnasing road 1 no. Bordoloni village Date of damage- 15/5/22 Type of
	Barpeta	5	damage- shoulder and H/C damage Damage Length- 450m, Bamundongra tiniali to Bakshabadha road pkg no. As-01-339 Bakshabadha village Date of damage- 16/5/22 Type of damage- shoulder and H/C damage Damage Length- 300 m, Kalpana bazar to Satrakanara 5 no seat pkg. no. As-01-281 Satrakanara 5 no seat Date of damage- 16/5/22 Type of damage- shoulder and H/C damage Damage Length- 150 m, Kalgachia - 1. Guileza to Minisimla Road Guileza to Minisimla village at various points. As per report received from PWD (R) dept on 20/05/22, due to raising of Beki river water one breach gap has formed at PMGSY Road package No. AS-01-88 Guileza to Minisimla road from chainage 200.00m to 300.00m (Length=100.00m, width=5.50m and Depth=2.00m)
Infrastructur e Damaged - Road	Bongaigao n	12	Manikpur - Bhandara-I to Bhandara-V road Bhandara Erosion of Aie river bank adjacent to the road and threatening the existing Br. No. 3/1 and approaches (River bank protection) as per report received from PWRD, Bongaigaon. Date of incident 19.05.2022, Dangaigaon Kirtanpara Road Dangaigaon Slipage of side berm and side sloves of the road between Ch. 1400 m to Ch. 1630m. as per report received from PWRD, Bongaigaon. Date of incident 19.05.2022, Dangtol - Bakhaigaon Dakuapara Road Bakhaigaon Br. Approach of RCC Br. No. 3/1 as per report received from PWRD, Bongaigaon. Date of incident 19.05.2022, Betbari to Jogdoba via Choapara Pt. I road Betbari Br. Approach damage of STPBr No. 5/1 as per report received from PWRD, Bongaigaon. Date of incident 19.05.2022, SH-2 Road Dangtal Shoulder damaged due to rain cut at at 9th & 10 th km. as per report received from PWRD, Bongaigaon. Date of incident 19.05.2022, Srijangram - Jogighopa Salbari Road Jogighopa Salbari Road Rain cut occurred at 12th km as per report receive from PWRD, Bongaigaon. Date of incident 19.05.2022, Dumerguri Latibari Road Dumerguri Latibari Road Rain cut occurred at 1st and 2nd km as per report receive from PWRD, Bongaigaon. Date of incident 19.05.2022, Kushbari Dubachuri Road Kushabri Dubachuri Road The road is in danger position from river Manas at 1st and 2nd km as per report receive from PWRD, Bongaigaon. Date of incident 19.05.2022, SH-2 Road SH-2 Road Rain cut occurred at 2nd 34th km as per report receive from PWRD, Bongaigaon. Date of incident 19.05.2022, Khoragaon Besimari Road as per report receive from PWRD, Bongaigaon. Date of incident 19.05.2022, Khoragaon Besimari Road as per report receive from PWRD, Bongaigaon. Date of incident 19.05.2022, Malegarh Barjana Road Malegarh Barjana Road Rain cut occurred at 1st km as per report receive from PWRD, Bongaigaon. Date of incident 19.05.2022, Boltamari - Sankarghola Kherpuji Road Sankarghola Land slide Occurred at 7th km as per report received from PWRD,
	Darrang	6	Mangaldoi - Mahaliajhar to Dalgaon Grant Road Dalgaon Grant under Mangaldai Rev. Circle. The road is submerged due to flood water and the culvert present in the road is damaged. The damage length as reported by PWRD is 60m (approx) as of now. Dated 20/05/2022, Mahaliajhar to Bhakatpara road Bhakatpara under Mangaldai Rev. Circle. The road is submerged due to flood water .The submergence length as reported by PWRD is 500m (approx) as of now. Dated 20/05/2022., Ramhari to Mahaliajhar Road Ramhari under Mangaldai Rev. Circle. The road is submerged due to flood water .The submergence length as reported by PWRD is 1.2 km (approx) as of now. Dated 20/05/2022., Dalgaon - Arimari No. 2 to Arimari No.1 road Arimari No. 2 to Arimari No.1 road at CH-2600M as per report received from SDO,PWRD, Dalgaon Territorial Road sub-division Arimari No. 2 to Arimari No.1 road at CH-2600M has been damaged. Damage length - 15M, date of occurrence-16/05/2022, Kachomari Char to Badlichar road Kachomari Char to Badlichar road at CH-950, CH-1120, CH-1350, CH-3700 as per report received from SDO,PWRD, Dalgaon Territorial Road sub-division Kachomari Char to Badlichar road at CH-950, CH-1120, CH-1350, CH-3700 has been damaged. Damage length - 105M, date of occurrence-16/05/2022, Sipajhar - Singimari Dampur Road under PMGSY packge no AS 16-184 Submarge in water from ch 2500m to 4700mDepth av 0.80m, Length of submerge 2200m as reported by PWD (Roads) dated 20-

		ı	Lor account of the state of the
			O5-2022 Singimari
	Dhemaji	2	Jonai - PWD territorial road Lachit Nagar to No.1 Mohmora Road, 15.00 meter side berm got eroded on 20/05/2022 due to Mohmorajan channel. From Ch.55.00 M to Ch.70.00 M As per report received from PWRD, Jonai Territorial Road Sub-Division-II, Jonai, a PWD territorial road Lachit Nagar to No.1 Mohmora Road, 15.00 meter side berm got eroded on 20/05/2022 due to Mohmorajan channel. To mitigate further damage contractor Rickey Taye is engaged for immediate restoration.
	Dima- Hasao	1	Haflong - KK Road Maibang Block Maibang Block Restroration of the road
-	Tusuo		Balijana - Ab. NH 37 to Bhalukdubi Pt V Bhalukdubi Pt V Length affected- 0.150 KM Average
	Goalpara	2	depth of submergence- 0.900 M Date- 19.5.2022, Matia - PWD Road from Forest Gate to Krishnai Near Krishnai Garo Bazar Affected length = 1 km (approx.), Average depth of submerged = 0.25 m (from 19/05/2022 to 20/05/2022)
			Doboka - Sarupather to Jamunamukh road Jamunamukh Sarupather to Jamunamukh road from 4th
			km PWD Deptt dated 16/05/2022,
			Doboka to Jamunamukh road Doboka Doboka to Jamunamukh road from 8th km to 15th km PWD
			Deptt dated 16/05/2022,
			Patia pather to Kathkatia Bhakat gaon road Patia pather Patia pather to Kathkatia bhakat gaon road
			1st and 3rd km PWD Deptt dated 16/05/2022,
			Kampur jamunamukh road jamunamukh Kampur jamunamukh road 1st and 2nd km PWD Deptt
	Hojai	8	dated 16/05/2022,
	J		Doboka Jamunamukh road Doboka Doboka Jamunamukh road to Patibaya gaon from 1st to 3rd km
			PWD Depttdated 16/05/2022, Sarlock to Binakandi Binakandi Sarlock to Binakandi via jugijan at 1st to 2nd km PWD Deptt dated 16/05/2022,
			Sarlock to Nikhari Mukh Nikhari Mukh Sarlock to Nikhari Mukh 1st and 2 nd km PWD Deptt
			dated 16/05/2022,
			Borjhari Majhagoan to Baliram gaon Borjhari Majhagoan Borjhari Majhagoan to Baliram gaon via
			Kalia daman than 1st km. PWD Deptt dated 16/05/2022
			Jorhat West - 1. Malow Ali Dhekorgorah, Monaimajhi, Dagaon, Malowali, Alengmora, Khutiapota
			etc Due to continuous heavy rain, Artificial water logging occurred at 1st KM of Malow Ali for a stretch of 220.00 M submerging the entire stretch damaging the BT surface road resulting in pot holes
			. (Report prepared by PWD Jorhat, Dergaon and Titabar Territorial Road Division). Date:
			20/05/2022,
			2. 2 No. Kuhumjogania Road Da gaon, Kuhumjogania, Gamtou Chuk etc Due to continuous heavy
			rain, damage occurred at 2 No. Kuhumjogania Road for a length of 600.00 M. (Report prepared by
	Jorhat	4	PWD Jorhat, Dergaon and Titabar Territorial Road Division). Date : 20/05/2022,
			3. Kamalabariya Bihaliya Path Kamalabaria, Bihalya gaon, Bhabalichuk Due to continuous heavy
			rain, damage occurred at the Kamalabariya Bihaliya road for a length of 500.00 M. (Report prepared
			by PWD Jorhat, Dergaon and Titabar Territorial Road Division). Date: 20/05/2022,
			4. Sarucharai Extension Road Kalbari, Dhankhuloi, Bormer, Chengeliati Due to continuous heavy
			rain, damage occurred at bridge approach at 1st KM of Sarucharai Extension Road for a length of 150.00 M (Report prepared by PWD Jorhat, Dergaon and Titabar Territorial Road Division). Date:
			20/05/2022
			RK Nagar - Dhalibill Ramkrishnagar Road Dhalibill Near Singla River Dhalibill Ramkrishnagar
	Karimganj	1	Road (AS-13-239) damaged length 200.00 m on date 19-05-2022 due to incessant rains and drained
			out of accumulated rain water from catchment area
			Ujani Majuli - Bongaon to Meragarh colony road Meragarh Colony Gaon Bongaon to Meragarh
	Majuli	1	Colony road CH80.00M to CH 380.00 M got submerged and road communication got disrupted due
			to rise of water level in river Brahmaputra on 20.05.2022.
			Mayong - Homen Borgohain Road From Kacharigaon to 1no Murkata road at 1st km Damaged
			length 150mts as reported by PWD Morigaon dist territorial road division deptt on 19/05/22,
			Dimoruguri to Kamarpur Near Irrigation Pump at 3rd km Effective length 100mts as reported on
	Morios		20/05/22 by PWD Morigaon district territorial road division, Marigaon Besseschet Whendeign to Bordeinether via Azerbari (20, 05, 2022) length 1 VM (Approx)
	Morigaon	4	Morigaon - Basanaghat Khandajan to Bordoipathar via Azarbari (20-05-2022) lenght 1 KM (Approx) Basanaghat- Khandajan, Morigaon Basanaghat Khandajan to Bordoipathar via Azarbari road
			submerged.,
			2 No. Gunamara to Ajarbari RCC Br (20-05-2022) Lenght 1 KM (Approx) Kalbari, Morigaon 2
			No. Gunamara to Ajarbari RCC Br. via Bengali party Road submerged.
			Nagaon - Gumutha Gaon to Ghagaril Road Ghagarial Gumutha Gaon to Ghagaril Road
			submerged/damaged L-3 KM, Dtd-19.05.2022 under PWD territorial Road division.,
			Kampur - L087-KSB Road to Madhapara Jeetgaon, Madhapara Jeetgaon L087-KSB Road to
	Nagaon	17	Madhapara Jeetgaon Road Package No. AS-19-409 submerged/damaged Dtd-19.05.2022 under
			Barhampur Territorial Road Sub-Division,
			Bhalbhaliagaon to Banpaligaon Road Kampur Bhalbhaliagaon to Banpaligaon Road PMGSY, AS-
			19-459 Submerged/damaged Dtd-19.05.2022 under Barhampur Territorial Road Sub-Division,

Lutumari Longjup rd to juripara Road | Kampur | Lutumari Longjup rd to juripara, PMGSY, AS-19-527 Submerged/damaged Dtd-19.05.2022 under Barhampur Territorial Road Sub-Division, L043-KK Rd to Tetelisora grant | Kampur | L043-KK Rd to Tetelisora grant, PMGSY, AS-19-528 Submerged/damaged Dtd-19.05.2022 under Barhampur Territorial Road Sub-Division, L065-Charaihagi to Uttar Chanchaki gohaingaon | Kampur | L065-Charaihagi to Uttar Chanchaki gohaingaon Road PMGSY, Package No. AS-19-554 Submerged/damaged Dtd-19.05.2022 under Barhampur Territorial Road Sub-Division, Raha - Dharmukh Bazar to Minabazar | Dharmukh | Date of Occurrence- 18/05/2022 submerged/eroded-2000 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Kampur Chaparmukh Raha road | Chaparmukh | Date of Occurrence- 18/05/2022 submerged/eroded-800 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Bridge no 12/1 over kapili on Amsoi Dighali ati road | Amsoi | Date of Occurrence- 18/05/2022 Eroded-120 M (approx.) Department-PWRD, Raha Territorial Road Sub -division, Hatigarh to Balijuri road | Hatigarh | Date of Occurrence- 19/05/2022 submerged/eroded-5800 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Laopani to Timung Gaon | Laopani | Date of Occurrence- 19/05/2022 submerged/eroded-1300 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Rahachaki to Hariamukh Road | Rahachaki | Date of Occurrence- 19/05/2022 Eroded-200 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Petborha to Borkula | Petborha | Date of Occurrence- 19/05/2022 submerged/eroded-3000 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Pahupurikhaiti to Hugaltali | Pahuparikhaiti | Date of Occurrence- 19/05/2022 submerged/eroded-1550 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Jukuta Khaigarh Road to Cheuguri road | Khaigarh | Date of Occurrence- 19/05/2022 Eroded-1400 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Sri Sri Maa Basundhari than approached road | Basundhari Than | Date of Occurrence- 19/05/2022 submerged/eroded-200 M (approx) Department-PWRD, Raha Territorial Road Sub -division, Jukuta Khaigarh road to Midaimari | Khaigarh | Date of Occurrence- 19/05/2022 submerged/eroded-800 M (approx) Department-PWRD, Raha Territorial Road Sub -division Tihu - Tihu Town Road | Ward 2 Tihu Town | Roads lengh 500 approx date of submriged18/05/2022Rat/Lang 26. 47381/91.26516 information received from JE PWD Roads., Barkhetri - Baraliarpar to Bardhap Road | Kandhbari | due to incessant rain side berms of the road damaged at four portions measuring total length 20m as reported by PWRD Mukalmua on 20/05/2022, Paschim Nalbari - Bangaon- Bhagawati Chupa to Simaliya road | Between Bangaon and Simaliya village | Side beam eroded and edge restrain earns due to heavy rain fall at many stretches. Information received from PWRD Department on 20/05/2022, Nalbari - nalbari palla road submerged | nalbari palla road submerged | as per WT msg vide Memo No 1168-71 Dated 19.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Nalbari Palla road submerged due to rain water. Approx Length is 700 M and culvert Bhakatpara road sumberged | Bhakatpara road sumberged | as per WT msg vide Memo No 1168-71 Dated 19.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Bhakatpara road submerged due to rain water., Balilesha Devalay Approach road submerged | Balilesha Devalay Approach road submerged | as per WT msg vide Memo No 1168-71 Dated 19.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Balilesha Devalay Approach road submerged due to rain water. Circuit House approach road submerged | Circuit House approach road submerged | as per WT msg vide Memo No 1168-71 Dated 19.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari 15 Nalbari on 20.05.2022 Circuit House Approach road submerged due to rain water., Alternative Road submerged | Infront of nalbari Eye Hospital | as per WT msg vide Memo No 1168-71 Dated 19.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Alternative road submerged due to rain water., Bishnurabha path submerged | Bishnurabha path submerged | as per WT msg vide Memo No 1168-71 Dated 19.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Bishnurabha Path submerged due to rain water., Majdia to PHED office road submerged | Majdia to PHED office road submerged | as per WT msg vide Memo No 1168-71 Dated 19.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Majdia to PHED office road submerged due to rain water. Approximate legth is 400 M, Forest colony road to Pratul Medhi's House Road Submerged | Forest colony road to Pratul Medhi's House Road Submerged | as per WT msg vide Memo No 1208-11 Dated 20.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Forest colony road to Pratul Medhi's House road submerged due to rain water. Approximate legth is 180 M, Kumarikata to niz bahjani road submerged | Kumarikata to niz bahjani road submerged | as per WT msg vide Memo No 1208-11 Dated 20.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Forest colony road to Pratul Medhi's House road submerged due to rain water. Approximate legth is 200M, Bagals road chowk to khadir chowk budrukuchi road submerged | Bagals road chowk to khadir

			chowk budrukuchi road submerged Las ner WT msg vide Memo No 1208-11 Dated 20 05 2022
	Sonitpur	2	chowk budrukuchi road submerged as per WT msg vide Memo No 1208-11 Dated 20.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Bagals road chowk to khadir chowk budrukuchi road submerged due to rain water. culvert damaged., Paschim Khatar Kalakuchi to jaha road submerged Paschim Khatar Kalakuchi to jaha road submerged as per WT msg vide Memo No 1208-11 Dated 20.05.2022 Received from PWRD, Nalbari territorial Road Division Nalbari on 20.05.2022 Paschim Khatar Kalakuchi to jaha road submerged due to rain water. submerged length-200M, Chaminar Chowk to Nalbari Medical road submerged Chaminar Chowk to Nalbari Medical road submerged Received from PWRD, Nalbari Territorial Division, Nalbari via whatsapp group on 19.05.2022 Charminar Chowk to nalbari medical road submerged. approximate length 8.9 M Thelamara - Teliagaon to Garuduba Road. Teliagaon, DATE-20/05/2022 Damage of culvert placed in Teliagaon to Garuduba road as reported by concerned LM on 20/05/2022. Dhekiajuli - As reported by PWRD Barchalla Territorial Road Sub Div. Singri to Borsola road via Sitalmari submerged from 30cm to 60cm from CH.6533.00M to 7260.00M and CH.7826.00M to 9220.00M. date 19.5.22 Singri to Borsola road via Sitalmari Mazbat - Natun Bazar to NC Phatasimalu road NC Phatasimalu village 1/ Due to incessant rain for last few days, the HPC no 3/1 at Ch. 1000m and HPC No. 2/1 at Ch. 1200.00m has been damaged on road connecting Natun Bazar to NC Phatasimalu road on 19/5/2022.Length - 1.8m(approx), Baligaon to Panbari road Panbari village The road connecting Baligaon to panbari has been eroded at Ch. 500.00 on 19/5/2022 Length-2.8m(approx), Bogarabari to Garubandha road Garubandha village The road connecting Bogaribari to Garubandha at CH. 2200m has been eroded on 19/5/2022.Length-3m(approx), Udalguri - Chamuapara to Murabari road Chamuapara Road washed away Ch. 450.00m at Chamuapara to Murabari road around 30m on 19.05.2022., Khairabari - Andherikhat to Harisinga Road K
			Khas Bokrajhar to Ojhagaon road (PMGSY PKG AS 16 145)- Br No 1/1, Br No 3/4 Uttar Bokrajhar Bridge Approach of BR No 1/1 & 3/4 have damaged. Hard Crust, Side Berm and boulder pitching on slopes have also been damaged. The above mentioned road has damaged on 20/05/2022 due to submergence of flood water by river Kulshi covering a length of 300 meters and breadth of 7.5 meters
	Total	90	submergence of mood water by fiver Kuisiii covering a length of 300 flicters and of adult of 7.3 flicters
	District	Numbe r	Details
Infrastructur	Barpeta	2	Sarthebari - Nasatra -Belbari Bridge Nasatra (Baghmara) Nasatra to Belbari connecting SPT Brigde 2/1 Partially damaged (reported by JE, PWD Road)Date-20-5-2022, Chenga - RCC Bridge: No. 6/1 on Mahchara Holongapara Road Shimulbari village Side berm & Camp; Hard crust damaged, damaged length in 150.00 M, Reported by PWD Date-20-05-2022
e Damaged - Bridge	Nagaon	1	Raha - Bridge No. 12/1 over Kapili river Amsoi Date of Occurrence- 19/05/2022 Eroded-120 M (approx) Department-PWRD, Raha Territorial Road Sub -division
	Udalguri	2	Mazbat - Dhupguri village to Pauripota village Dhupguri A foot bridge connecting village Dhupguri to pauripota has been washed away on 19/5/2022. Length- 10m, Harisinga - RCC Bridge no.32/1 Satgari Length of 10m eroded on 19th May 2022 at MB road, RCC bridge approach damage.
	Total	5	
Infrastructur e Damaged - Wildlife	Nil		
	District	Other De	
Infrastructur e Damaged - Others	Barpeta	LP school school is a school is submerge Path mari Moinbari char ventu	- Elementary Schools Damaged 33 nos. Of elementary school s are submerged. 1. 859 no. Bhairarpam is submerged. 2. 338 Bhatnapaity LP school is submerged. 3. 1884 Bhatnapaity Alot kandapara LP submerged. 4. 2 no. Bhatnapaity NC MP VLP school is submerged. 5. Gobindapur LPS is submerged. Ituzafa Memo LP school is submerged. 7. Pub Hapachar LP school is submerged. 8. Sayedpur LP submerged. 9. 1420 Fulara Bandarmura LP school is submerged. 10. Fulara char MV school is d. 11. Pub Bhera gaon VLP school is submerged. 12. 275 Tapajuli LP school is submerged. 13. 775 Majaorchar LP school is submerged. 14. 1137 Chutirpar LP school is submerged. 15. 1160 Pachim LP school is submerged. 16. 1798 Bhairarpam DS LP school is submerged. 17. Baghmara Nichanar are LP school is submerged. 18. 1109 Ramapara NC girls LP school is submerged. 19. 1810 Dala pam is submerged. 20. 1077 chapuri LP school is submerged. 21. 749 Ramapara Gasbari LP school is submerged. 22. 1646 Mowamari Jahanarpar LP school is submerged. 23. Ramapara MEM school is submerged.

24. Nur Hussain Dola pathar LP school is submerged. 25. Pachim Mowamari Jahanar gaon Mokbul Hussain LP school is submerged. 26. 1392 Mowamari LP school is submerged. 27. Ramapara highschool is submerged. 28. 802 Alipur Raofala LP school is submerged. 29. 1214 Kawimari LP school is submerged. 30. Sath vitha MEM school is submerged. 31. Pachim Tapajuli LP school is submerged. 32. Kalampur char Balika LP school is submerged. 33. Joypur Majar gaon LP school is submerged. date-19-05-2022(evening), Sarthebari - Anganwadi Centres Affected | 1. 199 No. Nasatra - Namsala Pallar Pam AWC, 2. 128 No. Kawaimari -7, 3. 198 No. Jabrikuchi AWC, 4. 195 No. Eragaon Pashim supa AWC, 5. 83 No. Kawaimari 7 No. Block, 6. 200 No. Kawaimari 7 No. Block, 7. 197 No. Erartari AWC, 8. 146 No. Kawaimari 5 No. Block, 9. 174 No. Karagari C, 10. 174 No. AWC (Nalirpam-Karagari C) (reported by CDPO Pakabetbari, 20.05.2022), Anganwadi Centres Affected | 1. 60 No. Rangia Nadir Pam AWC, 2. 51 No. Joshodar Pam AWC (reported by CDPO, Sarukhteri), Kalgachia - Anganwadi Centres Affected | As per report received from CDPO office on 19/05/22 (evening) total 17 nos of AWC are submerged. The AWCs are as follows- 1. 64 No Balarpather(A), 2. 212 No Balarpather(F), 3. 262 No Balarpather Uttar, 4. 71 No Tapeswara(C), 5. 265 No Tapeswara Madhya, 6. 218 No Nadiapara(B), 7. 72 No Dabandia(A), 8.216 No Tapeswara (F), 9. 68 No Aditpur(B), 10. 62 No Digjani(B), 11. 263 No Digjani char, 12. 116 No Bartary, 13. 106 No Hatchara(A), 14. 107 No Hatchara(B), 15. 176 No Khudrakhuwa(C), 16. 228 No Pub Chikni Pub Char, 17. 129 No Solmari(A). Naduar RC part - Fisheries/Pond | As per report received from fishery demonstrator, Sootea Dev.Block--Nos. of tank affected at No. 2 borbheti -6nos. Water area affected 1.52 ha total lost approx 31,008 Rs., Nos. of tank affected at bakarapathar 5nos. Water area affected 2.38 Ha Total lost approx 48,552 Rs. Nos.of tank affected at balighat 3nos. Water area affected 2.24Ha, total lost approx Rs 45,696 .20.05.2022, **Biswanath** - Fisheries/Pond | As per report received from fisheries Dev. Officer Biswanath on 20.05.2022, damages at villages: 1 No. Chalia & Dramp; amp; Garehagi are as follows: Farmers affected=3, Tanks affected=3, water area affected=3.19 Ha, Total loss= Rs 64639.00, Fisheries/Pond | As per report received from fisheries Dev. Officer Biswanath on 19.05.2022, damages at villages: 4 No. Chalia & Dramp; amp; Nabapur are as follows: Farmers affected=42, Tanks affected=50, water Biswanath area affected= 74.27 Ha, Total loss= Rs 1500254.00, Gohpur - Anganwadi Centres Affected | Dubia Karbi AWC damaged on 17.05.2020 but reported on 20.05.2022 by ICDS Pub-Chaiduar, Anganwadi Centres Affected | Dubia Pothar AWC damaged on 17.05.2020 but reported on 20.05.2022 by ICDS Pub-Chaiduar, Fisheries/Pond | 2 Nos. of Fisheries of area 0.60 Hect were flooded on 18.05.2022 but Fishery Dept has reported it on 20.08.2022. Halem - Secondary Schools Damaged | Damaged observed at Gohpur Bodo High School by flood on 17/05/2022. Coordinates 93.608060, 26.880817, Anganwadi Centres Affected | 16 Nos. of Angwandai Centres affected by flood on 17/05/2022 Katigorah - Veterinary Deptt Infrastructure | Veterinary Institute are submerged viz. SVD Borjatrapur as per the information received from District A.H and VETY Officer dated 20.05.2022, Silchar - Veterinary Deptt Infrastructure | Veterinary Institute are submerged viz. Borkhola Vety. Hospital as per the information received from District A.H and VETY Officer dated 20.05.2022, Cachar Udharbond - PWSS Damaged | Madhurgram WSS, Bahadurpur WSS, Tikalpar WSS, Bethukandi WSS, Kashpur Bager Kuna WSS, Veterinary Deptt Infrastructure | Veterinary Institute are submerged viz. SVD Borjatrapur, Gossaipur AIC as per the information received from District A.H and VETY Officer dated 20.05.2022 Mangaldoi - Fisheries/Pond | As reported by fishery department a total of 1426 nos (approx) Fish farmers are affected and Total of 126.96Ha(approx.) water area is affected. Dated 20/05/2022, Anganwadi Centres Affected | As reported by Pub-Mangaldai ICDS a total of 371 nos of children's are affected. Dated 20/05/2022, Dalgaon - Culvert Approach Road Damaged | As per report received from SDO, PWRD, Dalgaon Territorial Road Sub-Division Nadirpar to Rowmari Chapori road 1/1 RCC slab culvert approach has been damaged about Darrang 20M length. Date of occurrence- 16/05/2022, Fisheries/Pond | as per report received from District fishery development officer, Darrang 24 nos of villages, 718nos of farmers and 140.78 Ha water area affected under dalgaon revenue circle, Sipajhar - Fisheries/Pond | Fisheries got affected in 11 nos. of villages namely Kabeichuba, Satgharia, Basachuba, Patgirichuba, Pakabangipara, Gopalpur, Solpam, Khassonapur, Haldha, Maijeli, Malibari. Total water area 16.1 Hactre and 258nos. of Fishfarmers got affected as reported by Fishery Depptt. dated 20-05-2022 Chabua - Anganwadi Centres Affected | Dodhia AWC submerged as information received from Social Welfare dep. on 20/5/2022, Anganwadi Centres Affected | Dodhia Tengabari AWC submerged as information received from Social welfare dept. on 20/5/2022, Health Sub-Centre | Dodhia Kuligaon Sub center submerged as information received from Health dept. on 20/5/2022. Dibrugarh Elementary Schools Damaged | Dodhia ME school submerged as information received from Education Dept. on 20/5/2022. Elementary Schools Damaged | Dodhia Kuligaon LPS submerged as information received from Education Dept. on 20/5/2022, Elementary Schools Damaged | Dodhia Karmi LPS submerged as information received from education Dept. on 20/5/2022, Elementary Schools Damaged | Dodhia Tengabari LPS submerged as information received from education Dept.

	on 20/5/2022
Dima- Hasao	Haflong - Irrigation Canal/Scheme Damaged Purana Dihajeng FIS, Natun Motibra FIS, Semkhor FIS, Dakhinhaplai FIS, Lumvumbra FIS, Wajao Langaobra FIS, Nivang FIs, Natun Haja LIS, Gereso FIS, Hoglu Nallah IS.
Hailakandi	Lala - PWSS Damaged one Steel Floating Barge of PWSS damaged due to capsizing of barge due to heavy rain at river Katakhal on 19.05.2022 at 2.30PM under Lala Revenue Circle
Hojai	Hojai - Elementary Schools Damaged Name - Rajbari ME School , Vill- Rajbari , Wall of the school damaged due to flood on dated 20/05/2022 , GPS Coordinates 26.03451 N and 92.85762 E,
J	PWSS Damaged Ashinagar PWSS scheme under PHE ,Hojai partially damaged due to flood at vill- Ashinagar on dated 20/05/2022.
	Rangia - Power Dept. Poles 2 LT poles were damaged in village Tarani as per report submitted by SDE, APDCL, Sub Div-II on 19.05.2022., Power Dept. Conductors 200m conductor were damaged in village Tarani as per report submitted by SDE,
Kamrup	APDCL, Sub Div-II on 19.05.2022., Power Dept. Poles 1 LT pole was damaged in village Ichapur as per report submitted by SDE, APDCL, Sub Div-II on 19.05.2022.,
	Power Dept. Conductors 500m conductor were damaged in village Ichapur as per report submitted by SDE, APDCL, Sub Div-II on 19.05.2022.,
	Power Dept. Conductors 300m LT conductor were damaged in village Karara Garbhitor as per report submitted by SDE, APDCL, Sub Div-II on 19.05.2022.
Karbi Anglong West	Donkamokam - Culvert Approach Road Damaged Due to Incessant Rain Culvert at Umteli river bridge to Ambinong road was partially damage as per report received from PWD (R) Hamren Division that on 17/05/2022, Fisheries/Pond Due to incessant rain several villages was submerge and 116 Nos (20.00 Ha) of Pond/Fishery affected 17/05/2022 as per report received from Fishery department, Hamren
Kokrajhar	Gossaigaon - Culvert Approach Road Damaged As per reported by The Assistant Executive Engineer, PWD, Gossaigaon Rural Road Sub-Division, Due to Heavy Rain since 12 May 2022 the Kadamguri to Dhawliguri road HP Culvert have been Damaged.
	Bihpuria - Fisheries/Pond Approximately, 250 nos. of ponds/tanks affected at Fatehpur-Ahmedpur area and 350 nos. affected at Kutubpur Dharmapur area as reported by FDO, Karunabari Development Block on 19/05/2022,
Lakhimpur	Narayanpur - Fisheries/Pond Flood affected ponds- 9 nos area affected -182 ha at village no.1 tatibahar and no.2 not gaon as reported by FDO, Narayanpur Dev Block on 20/05/2022, Kadam - Bridge Approach Road Damaged Due to incessant rain and raising of water level the bank of river Konajan is eroded at approaches of Bridge No.3/1 (Length = 50.00M) on tadang Mirigaon Road as reported by PWD Roads, Ghilamara Divn. Date: 20/05/2022
Nagaon	Nagaon - Fisheries/Pond 212 nos. fisheries submerged under Sadar Rev. Circle Dtd-19.05.2022 reported by Fishery department, Power Dept. Poles HT/LT 8.5 m Pole-1 no. reported by APDCL Kathiatoli Dtd-19.05.2022, Power Dept. Poles LT 7.5 m Pole-1 no. reported by APDCL Kathiatoli Dtd-19.05.2022, Power Dept. Poles LT 7.5 m Pole-1 no. reported by APDCL Kathiatoli Dtd-19.05.2022, Power Dept. Poles LT 7.5 m Pole-1 no. reported by APDCL Kathiatoli Dtd-19.05.2022, Power Dept. Poles LT 7.5 m Pole-1 no. reported by APDCL Kathiatoli Dtd-19.05.2022, Power Dept. Poles LT 7.5 m Pole-1 no. reported by APDCL Kathiatoli Dtd-19.05.2022, Power Dept. Conductors Conductor-1.1 Km reported by APDCL Kathiatoli Dtd-19.05.2022, Rampur - Fisheries/Pond 2500 nos. fisheries submerged at Kampur Revenue Circle reported by Fishery Department Dtd-19.05.2022, Raha - Fisheries/Pond Village Name – Kahargaon Total Pond/Tank Submerged-10, Total ha-5.4, Fisheries/Pond Village Name – Pub Bulla, Total Pond/Tank Submerged-5, Total ha-1.5, Fisheries/Pond Village Name – Barunguri, Total Pond/Tank Submerged-30, Total ha-4.5 Tihu - Health Sub-Centre Bhojkuchi Sub Center submerged due to flood. Damage assessment is going on. Lat & Amp; amp; Long: 26.424573/91.290532, Date of Submerged:17/05/2022, Barkhetri - Bridge Approach Road Damaged due to incessant rain side berms of RCC Bridge approaches of BCC Bridge approaches and BCC Bridge approaches and BCC Bridge approaches and BCC Br
Nalbari	RCC Br No1/1 on Mukalmua to Bhangnamri Ferry Ghat road at Mukalmua Bazar damaged and eroded. North side Br. Approach damage 22 m and south side Br. Approach damage 23m. as reported by AEE, PWRD Barkhetri on 20/05/2022., Paschim Nalbari - Handloom & Textile Deptt Looms , accessories and weaven cloth of 8 numbers of weavers in Lokhopur (Gandhibasti) area are affected. Information received from Handloom and Textile department 0n 20/05/2022 , Barbhag - Irrigation Canal/Scheme Damaged Erosion occurred at lenth 260.00 mtr date as on 20-05-2022, Irrigation Canal/Scheme Damaged Erosion occurred at lenth 320.00 mtr dated as on 20-05-2022, Irrigation Canal/Scheme Damaged Erosion occurred at lenth 220.00 mtr dated as on 20-05-2022
Sonitpur	Thelamara - Fisheries/Pond Date-20/05/2022, As reported by Fishery Deptt., fish ponds enundated of three villages namely Baligaon, Puthimari and 2 No. Borpukhuri ., Dhekiajuli - Agri Bundh Damaged As reported by concerned villagers, a guide bundh constructed by the general public (farmers) of Gangapur Forest Village for agricultural purpose was damaged due to rising agricultural water. dated 19.5.22, Bridge Approach Road Damaged As reported by PWRD Barchalla Territorial Road Sub Div. bridge approach No. 11/2 on Palash Pathar to No5 Singri Bagan damaged due to incessant rain. date 19.5.22,

Bridge Approach Road Damaged | As reported by PWRD Barchalla Territorial Road Sub Div. bridge approach No. 2/1 on Balijan Kachari to Singri via Natun Jamuguri damaged due to incessant rain. date 19.5.22, Culvert Approach Road Damaged | As reported by PWRD Barchalla Territorial Road Sub Div. slab culvert approach No. 2/1 on Balijan to Pub Bhangamandir LP School damaged due to incessant rain. date 19.5.22, Bridge Approach Road Damaged | As reported by PWRD Barchalla Territorial Road Sub Div. side berm on right side from CH.11900.00M to 12000.00M and bridge approach of bridge No. 3/1 damaged on NH-15 to Singri Bagan. date 19.5.22,

Bridge Approach Road Damaged | As reported by PWRD Barchalla Territorial Road Sub Div. damage observed at Natun Pam to NH-52 from CH.1100.00M to 1200.00M, hard crust and shoulder washed out and side berm damaged. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block road and culvert damage observed at Keherukhanda village ward no 1 under Keherukhanda GP. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block culvert damages observed at Hirajuli to Shivapur Santipur link road and Hirajuli Hospital to Khanbari road under Panbari GP. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block road and culvert damages observed at Dibrudarrang TE and Praja Line under Batashipur GP. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block road and culvert damage observed at Gorjuli village and roads damaged at Barpeta and Garpara villages under Chenimari GP. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block damage observed at Gejengaguri village under Mizibari GP. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block damage observed at Naharbari village under Mazrowmari GP. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block damage observed at Sopai Nalbari village under Sopai GP. date 19.5.22,

Culvert Approach Road Damaged | As reported by Dhekiajuli Dev. Block side erosion and damages observed on culvert and road approaches at villages Mazgaon Pathar, Sopai Rowmari, Narengkati Bangali, Pachnoi Nepali and Narengkati Kachari under Omeopur GP. date 19.5.22

Mazbat - Washed away Culverts | slab culvert at CH 1850.00 of Chubura Chuburi village road has been washed away due to incessant rain on 19-5-2022. The road communication has been disrupted for all kinds of vehicular traffics.(26.669951, 92.294685). length- 3.65m,

Washed away Culverts | Slab culvert at Ch. 3100 at NH 15 in Udalguri Jungle village has been damaged on 19-5-2022. The road communication has been disrupted for all kinds of vehicular traffics.(26.620298, 92.328943). Length- 3m(approx),

Washed away Culverts | one HP culvert has been washed away in Garogaon to Chaotal gaon road on 19/5/2022. The road communication has been disrupted for all kinds of vehicular traffics. (26.797779411373664, 92.27663432140447). length- 3.65m(approx),

Washed away Culverts | One slab culvert has been washed way at village Chenglimari on 19/5/2022. The road communication has been disrupted for all kinds of vehicular traffics. Length- 4m(approx) (26.638960545165652, 92.37556168280312).

Washed away Culverts | One slab culvert has been damaged completely in Jamuguri to Pub Kuruabahi road on 19/5/2022. The road communication has been disrupted for all kinds of vehicular traffics.(26.722619777901862, 92.28523630539681). Length-4m(approx),

Washed away Culverts | One HP culvert has been washed in Naoherua to Thakuriapara road on 19/5/2022. The road communication has been disrupted for all kinds of vehicular traffics.(26.844002733034888, 92.22933872408686). length-4m(approx),

Washed away Culverts | One culvert and road surface of 50m has been eroded in Mowamari village to Dafalapota bazar on 19/5/2022. The road communication has been disrupted for all kinds of vehicular traffics. (26.737681260375226, 92.31554363950515). Length-4m(approx),

Udalguri - Bridge Approach Road Damaged | Approach road of bridge no. 1/1 eroded at Nalbari to Maoriabasti road around 5m on 19.05.2022. GPS - Lat - 26.74777 Long - 92.11202.,

Culvert Approach Road Damaged | Approach road of culvert breached at Panumudi connecting road from Borigaon Mini Stadium to Ghagra road around 15m on 19.05.2022. GPS - Lat - 26.789654 Long - 998838., Culvert Approach Road Damaged | Approach road of RCC Slab culvert eroded badly at Kathorbari road around 10m on 19.05.2022. GPS - Lat - 26.686168 Long - 92.06318.,

Culvert Approach Road Damaged | RCC slab culvert damaged at No. 03 Amjuli to Garobasti road around 15m on 19.05.2022. GPS - Lat - 26.818289 Long - 045283.,

Culvert Approach Road Damaged | RCC Slab culvert damaged at Sandhyabari to Harisinga road around 30m on 19.05.2022. GPS - Lat - 26.677307 Long - 92.994032,

Culvert Approach Road Damaged | HPC damaged at Landarchuburi to Sastrapara road around 15m on 19.05.2022. GPS - Lat - 26.685042 Long - 92. 998324.,

Washed away Culverts | HPC Culvert washed away at Mohanpur to Rangagara village road at Ch. 100.00m around 15m on 19.05.2022. GPS - Lat -26.684691 Long - 92.097323.,

Harisinga - Power Dept. Poles | Due to heavy rainfall along with wind occurred on 15/05/22 at around 9:10 am damaged 7 nos LT poles at village Jalah arabari, Totlapara, Niz Ghagra and 2 no. of HT poles at village Mantikiri . HT & LT conductors were also snapped at various places namely Niz Ghagra , Anadhuwapara, , Totlapara, Singrimari, Mantikiri, Dingdangpara, Bhootiachang, kristianpara, Garkash, Hahchara, Kalikhola, Khatowalpara. Letpetkhat, Murmela, No1. Bholatar,, No.2 Newly, No.2 tankibasti, Suklaikhuti, Rajagarh, Pachim Patala, Parbahuchuba, Purandia,, Teliyapara, Uttar Garuajhar, Uttar Gejerkuchi etc under Tangla Electrical Sub-Division.,

Udalguri

		Irrigation Canal/Scheme Damaged Right Canal embankment breached at Ch.458m of 7m. Left main canal
		embankment breached at ch.458m of 3m Latitude-26.7070/Longitude 91.9768.,
		Culvert Approach Road Damaged Approach of RCC slab culvert no. 15/on Mekanzee road 5.1m eroded at
		Kaulibhanga Village. on 19th May 2022. Latittude 26.6996/ Longitude 91.9494,
		Culvert Approach Road Damaged Approach of RCC slab culvert no. 4/2 and 5/3 4.4 m damaged on Nagrachara
	District	to Tangla Dimakuchi road on 19th May 2022 . Longitude 91.8269/ latitude 26.6655.
	District	Details Sarupeta - Village : Kahara Pathar Erosion at pahumara right bank , 60 M at Kahara Pathar (Reported by
	Bajali	SDO, Water Resource Department, Bajali on 20/5/2022) 0
		Chenga - Roumari Gaon, Roumari Pathar, Chenimari Severe bank erosion at - 1)B/dyke on R/B of river
		Brahmaputra from Adabari to Kukarjan from ch 5.80 km to at Roumari Pathar 2). B/dyke on R/B of river
		Brahmaputra from Adabari to Kukarjan from ch. 5.80 km to at Roumari Bazar reported by Mukalmua W.R. Sub
	D. (division occurance on 20/5/22 3). 17nos. of PMAY house under Roumari Gaon and 1 no agriculture bundh under
	Barpeta	Chenimari village fully affected by erosion reported by BDO, Chenga Dev. Block and GP secretary concerned on 20/5/2022 4) In Roumari Pathar village 2 nos. houses affected due to erosion and 2 bighas land eroded by the
		river Brahmaputra, reported by Gaon Pradhan on 20/5/22. 5) In Roumari Gaon village 15 nos. houses damaged
		and approx. 6 bighas land eroded by the river Brahmaputra reported by Gaon Pradhan and lot mandal on
		20/5/2022 170
		Biswanath - Mijikajan T.E SPP 1 As per report received from concerned LM, erosion continues to occur near
	Biswanath	the bridge over burigang river at village Mijikajan T.E SPP 1. 20.05.2022 0,
		Halem - Paken Miled erosion observed at Paken area on 20/05/2022 by 25 meters 0
	Bongaigao	Boitamari - Chatpara At chatpara with affected reach of about 500 m due to gully erosion on R/B of river Brahmaputra under Boitamari Rev. Circle. Date of incident-19/05/2022. As per recieved from WR sub division
	n	Abhayapuri 0
		Bilasipara - At vill:- Mayarchar Pt-i, Mayarchar pt-ii at Vill: Mayarchar Pt-i, Mayarchar pt-ii under Bilasipara
	Dhubri	Revenue Circle the River Brahmaputra is getting eroded badly. Land eroded:- Land measuring around 52 Bigha
	Diluoii	04Katha 10 Lessa Date of incident:- 16-05-2022 to 19-05-2022 GPS co-ordinates:- Lat:- 26. 147304 N &
		Longitude:- 90.231204E Lat:- 26. 1496997 N & Description of the control of the co
		Dibrugarh West - At downstream of Bogibeel Guide Bund from Sampa Gaon to Chaulkhowa Gaon area As
		per report received from Executive Engineer, WR Division on 20.05.2022 that damages have been observed at downstream of Bogibeel Guide Bund from Sampa Gaon to Chaulkhowa Gaon area at the south bank of river
	Dibrugarh	Brahmaputra. Damage length of 3480mtrs. 0,
		Tengakhat - Borbali Gaon near Panchsuti Borbali gaon near Panchsuti Ch.4750m to Ch.4950m, T/dyke along
		the Right bank of river Buridehing from Bhekulajan to Tipling as per report received from Water Resources
		Department as on 20/5/2022. Length=200m. Lat.:27.20.1'20"N, Long.:95.14'48"E 0
		Balijana - Balbala Marginal Bund, Vill- Kalpani Balbala Marginal Bund is in the grip of erosion by river Jinari.
Erosion	Goalpara	Reach length at Ch. 250m is 90m and average width is 2m & Reach length at Ch. 1200m is 25m and average width is 1 m. Date- 20.05.2022 0,
	Gouipuru	Matia - Baladmari Char Pt-IV Left Bank erosion of river Jaljali at Baladmari Char Pt-IV. Total length = 200
		meters (approx.) as on 20/05/2022 0
	Golaghat	Khumtai - Kamargaon Dowel bund at Old Kamargaon approx 50 M. on 20-05-2022 0,
	Golugilat	Sarupathar - Kordoiguri Erosion occurred at river bank of Dhansiri river of approx 300 M. on 19-05-2022. 0
	Kamrup	Chaygaon - Singkhat As per field visit by FO Chhaygaon, active erosion of span-10 meter aprrox is seen on
V		19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0
	Kamrup	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5
	Kamrup (M)	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0
	_	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma
	(M)	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by
	_	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma , Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May
	(M)	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0
	(M)	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at
	(M) Kokrajhar Lakhimpur	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0
	(M) Kokrajhar	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0
	(M) Kokrajhar Lakhimpur	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-
	(M) Kokrajhar Lakhimpur	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at
	(M) Kokrajhar Lakhimpur	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar, Under Nazira Revenue circle 0,
	(M) Kokrajhar Lakhimpur	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma , Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar, Under Nazira Revenue circle 0, Sivsagar - 1).Bahgarh to AT Road, Sivasagar Revenue Circle , 2)N.H Bridge to Dikhowmukh at Sripuria ,
	(M) Kokrajhar Lakhimpur	19/5/2022 around 4:30 PM at Singkhat to balashidi Road. 0 Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar, Under Nazira Revenue circle 0,
	(M) Kokrajhar Lakhimpur Nagaon	Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar,Under Nazira Revenue circle 0, Sivsagar - 1).Bahgarh to AT Road,Sivasagar Revenue Circle , 2)N.H Bridge to Dikhowmukh at Sripuria , 3).Banhgarh to A.T Road at Raghuguri, 1).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 3100 m to 3103 m of Darika bund Left bank from Bahgarh to AT Road, under Sivasagar Revenue Circle (26.59'34.05"N, 94.40'2.58"E) 2).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch
	(M) Kokrajhar Lakhimpur Nagaon	Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar, Under Nazira Revenue circle 0, Sivsagar - 1).Bahgarh to AT Road, Sivasagar Revenue Circle , 2)N.H Bridge to Dikhowmukh at Sripuria , 3).Banhgarh to A.T Road at Raghuguri, 1).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 3100 m to 3103 m of Darika bund Left bank from Bahgarh to AT Road, under Sivasagar Revenue Circle (26.59'34.05'N, 94.40'2.58"E) 2).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 41340 m to 41343 m of Dikhow bund right Bank from N.H. Bridge to Dikhowmukh at Sri Puria, under Sivasagar
	(M) Kokrajhar Lakhimpur Nagaon	Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar, Under Nazira Revenue circle 0, Sivsagar - 1).Bahgarh to AT Road, Sivasagar Revenue Circle, 2)N.H Bridge to Dikhowmukh at Sripuria, 3).Banhgarh to A.T Road at Raghuguri, 11).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 3100 m to 3103 m of Darika bund Left bank from Bahgarh to AT Road, under Sivasagar Revenue Circle (26.59'34.05"N, 94.40'2.58"E) 2).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 41340 m to 41343 m of Dikhow bund right Bank from N.H. Bridge to Dikhowmukh at Sri Puria, under Sivasagar Revenue Circle, (26.58'20"N,94.31'22"E) 3).Sloughing and river bank Erosion has been observed on 16/05/2022
	(M) Kokrajhar Lakhimpur Nagaon	Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma , Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar, Under Nazira Revenue circle 0, Sivsagar - 1).Bahgarh to A.T Road, Sivasagar Revenue Circle , 2)N.H Bridge to Dikhowmukh at Sripuria , 3).Banhgarh to A.T Road at Raghuguri, 1).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 3100 m to 3103 m of Darika bund Left bank from Bahgarh to A.T Road, under Sivasagar Revenue Circle (26.59'34.05"N, 94.40'2.58"E) 2).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 41340 m to 41343 m of Dikhow bund right Bank from N.H. Bridge to Dikhowmukh at Sri Puria, under Sivasagar Revenue Circle (26.59'34.05"N, 94.31'22"E) 3).Sloughing and river bank Erosion has been observed on 16/05/2022 at ch 240 m to ch 250 m of Darika bund left Bank from Banhgarh to A.T Road at Raghuguri, Under Sivasagar
	(M) Kokrajhar Lakhimpur Nagaon	Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource, area :- 1.5 km approx both. Hatisila coordinate Longitude: 91.887997, Latitude:-26.219384 Tatimara coordinatoe Longitude:- 91.917294,latitude:- 26.243107 occured on 17/05/20222 0 Dotma - VILL- DUMARIGURI AND SHYAMTHAIBARI 1. As reported by AEE-PWD Roads, Dotma Erosion and damage of Culvert at village Shyamthaibari Tram Line road on 19th May 2022. 2. As reported by AEE-PWD Roads, Dotma, Erosion at Alengmari village culvert, Dumariguri to Alengmari Road on 19th May 2022. 0 North Lakhimpur - Bogalijan Erosion has been active since 18/05/2022 for a reach of about 500 meter at Bogolijan area river Ronganod as reported by Water Resources Dept, North Lakhimpur Divni. 0 Kaliabor - Rabarbari village (Silghat area) Erosion witnessed near silghat area caused by River Brahmaputra, approx. 3-4 bighas. Dtd-19.05.2022 0 Nazira - Monipuribosti A.T Road Sloughing and River bank erosion has been observed on 16-05-2022 to 19-05-2022at ch 14655m to 14905m of Dikhow Bund right bank from Monipuri bosti to A.T road at Cherekapar, Under Nazira Revenue circle 0, Sivsagar - 1).Bahgarh to AT Road, Sivasagar Revenue Circle, 2)N.H Bridge to Dikhowmukh at Sripuria, 3).Banhgarh to A.T Road at Raghuguri, 11).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 3100 m to 3103 m of Darika bund Left bank from Bahgarh to AT Road, under Sivasagar Revenue Circle (26.59'34.05"N, 94.40'2.58"E) 2).Sloughing and river bank Erosion has been observed on 18/05/2022 at Ch 41340 m to 41343 m of Dikhow bund right Bank from N.H. Bridge to Dikhowmukh at Sri Puria, under Sivasagar Revenue Circle, (26.58'20"N,94.31'22"E) 3).Sloughing and river bank Erosion has been observed on 16/05/2022

		reported by Water Resource deptt. Co-ordinates of Meghaijaroni- 92.622171 E, 26.720523 N 0
	South	Mankachar - Fulerchar Pt-III (Newjespur) As per reported water resource department at Fulerchar Pt-III
	Salmara	(Newjespur) Brahmaputra river site erosion going on date 20-05-2022. Appx-700 M 0
	Tamulpur	Goreswar - 1. West Bank of River Borolia at Village Bihapara 2. East Bank of River Borolia at Village Chenimara. 1. Bank erosion at right bank of river Borolia reported by WRD dated 20/05/2022 Village Bihapara. 2. Bank erosion at the left bank of river Borolia reported by WRD dated 20/05/2022 Village Chenimara the coordinates of 2nd are Lat- 26.475268 Long 91.621629 0
	Tinsukia	Sadiya - 1. Majgaon (Amarpur) 2. Koilabasti 3. Gurungbasti. 1. River Bank erosion is being observed at Majgaon (Amarpur) on the North Bank of River Datung since 12/05/2022 till 20/05/2022. As per information received from concerned Gaon Pradhan , the affected stretch is about 280m. 2. Active erosion is reported from Koilabasti area by Kundil river since 12/05/2022 till 20/05/2022. As per report received from the WR department and concerned Gaon Pradhan , the stretch area is 50m. (Lati 27.84688889, Long 95.71255556) 3. River bank erosion at Gurung Basti area reported by WR department since 15/05/2022 till 20/05/2022. the stretch area is 50m. (Lati 27.89750000, Long 95.77833333) 0, Doomdooma - 1. Village: Phelai NC (Nawkata NC), 2. Village: No. 3 Kordoiguri (Goriyating), 3. Village: No. 1 Kordoiguri 1. Severe erosion is being observed at Phelai(Nawkata) area on the left Bank of River Brahmaputra since 5/04/2022 till 20/05/2022. The affected stretch is about 1500 m. 10 m offset remains as of now from the Brahmaputra Embankment. (Long: 95.523457, Lati:27.745786) 2. River Bank erosion is being observed at No. 3 Kordoiguri on the left Bank of River Dangari since 2/04/2022 till 20/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 200 m in length. (Long: 95.468184, Lati: 27.650410), population affected 122. 3. River Bank erosion is being observed at No. 1 Kordoiguri on the left Bank of River Dangari since 18/05/2022 till 20/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 300 m in length. (Long: 95.450531, Lati: 27.651217), population affected 37 37
	Udalguri	Mazbat - Garogaon Due to incessant rain, erosion occurred on L/B of river Rowta at village Garogaon on 19/5/2022(26.481490314, 92.154734). Length- 150m(approx) 0, Udalguri - 1. Nalkhamara (Koch Chuba) 2. 3 No. Sapkhaity 1. Erosion at Nalkhamara (Koch Chuba) village by Kawadanda river around 250m on the right bank on 19.05.2022. GPS - Lat - 26.66694 Long - 92.04694. 2. Erosion at 3 No. Sapkhaity village on back side of Udalguri Civil Hospital by Sapkhaity river around 100m on the right bank on 19.05.2022. GPS - Lat - 26.719016 Long - 92.08003. 0
	District	Details
Landslide	Goalpara	Balijana - Gobindapur Due to heavy rainfall landslide occurred in village Gobindapur under Balijana Revenue Circle due to which one family got affected. The Area is approx Length: 5.486 M, breadth: 6.706 M. The data / report is collected by Field Officer, Balijana. Date: 19-05-2022 4
	District	Details
Urban	Darrang	Mangaldoi - Mangaldai town Ward No 1,2,3,4,5,6,7&8 The people affected due to waterlogging and flooding of river Bega is same as earlier. Dated 20/05/2022. 750
Flood	Jorhat	Jorhat East - 9 No. Block, 13 No. Block, 14 No. Block, Kenduguri (2no bamun Gaon) Water logging at 9 No. Block, 13 No. Block, 14 No. Block, Kenduguri (2no bamun Gaon) on 20/05/2022 due to continuous rainfall. 36