

FRIMS Assam



Flood Reporting And Information Management System

				Assam	Daily Flood Report as on 22-05-2022 at 4:00 PM				
Particulars	Situation as	on 22-	-05-20	022 (in las	t 24 hours)				
Rivers flowing above Danger	Rivers flowi	ng abo	ove da	anger	Kopili (Dharamtul/Kampur), Disang (Nanglamuraghat)			
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above hi flood level		ghest	Nil Nil					
	No. of Distr Affected	icts	Nar	ne of Floo	d Affected Districts	Name of Urban Flood Districts			
District Affected	22 Golag Anglo			aghat, Hai glong West	anath, Cachar, Darrang, Dhemaji, Dhubri, Goalpara, lakandi, Hojai, Jorhat, Kamrup, Kamrup (M), Karbi r, Karimganj, Lakhimpur, Majuli, Morigaon, Nagaon, pur, Udalguri				
No. Of Revenue Circles Affected	64								
	District	Tota	al	Revenue	e Circle				
	Barpeta	5		Barpeta,	Baghbar, Kalgachia, Chenga, Sarthebari				
	Biswanath	1		Gohpur					
	Cachar	5		Katigora	h, Udharbond, Silchar, Lakhipur, Sonai				
	Darrang	4			hat, Dalgaon, Mangaldoi, Sipajhar				
	Dhemaji	1		Jonai					
	Dhubri	3		Dhubri,	South Salmara Part, Gauripur				
	Goalpara	4		Matia, Rongjuli, Lakhipur, Balijana					
	Golaghat	2		1	, Bokakhat				
	Hailakandi	1		Algapur					
	Hojai	3		Lanka, Hojai, Doboka					
	Jorhat	2		Jorhat West, Jorhat East					
Name Of	Kamrup	10		Rangia, Boko, Goroimari, North Ghy, Hajo, Chamaria, Kayan, Nagarbera, Kamalpur, Chaygaon					
Revenue Circles	Kamrup (M)	2		Chandrapur, Sonapur					
Affected	Karbi Anglong West	1		Donkamokam					
	Karimganj	2		Karimga	nj, Badarpur				
	Lakhimpur	2		Bihpuria	, Narayanpur				
	Majuli	2		Majuli, Ujani Majuli					
	Morigaon	2		Mayong	Morigaon				
	Nagaon	3		Kampur,	Nagaon, Raha				
	Nalbari	6		Barkhetr	i, Tihu, Barbhag, Ghograpar, Nalbari, Paschim Nalbari				
	Sonitpur	2			ıli, Naduar				
	Udalguri	1		Mazbat					
	Total	64							
	District	Tota	al	Revenue	e Circle				
	Barpeta	220			ar 16), (Kalgachia 88), (Sarthebari 55), (Chenga	59), (Barpeta 2)			
	Biswanath	2		(Gohpu					
	Cachar 4				ond 53), (Sonai 69), (Lakhipur 84), (Katigorah	158), (Silchar 126)			
	Darrang	88			ghat 14), (Dalgaon 3), (Sipajhar 25), (Mangaldoi				
Villages	Dhemaji	19		(Jonai					
Affected	Dhubri	151			55), (Gauripur 53), (South Salmara Part 43)				
	Dibrugarh	1		(Chabua	* * * * * * * * * * * * * * * * * * *				
	Goalpara	258			43), (Lakhipur 121), (Rongjuli 21), (Balijana 73)			
	Goalpara	4			ai 3), (Bokakhat 1)	,			
	Hojai	39			2), (Doboka 24), (Hojai 13)	-			
	Hojai	JJ		(Lalika	2), (DOUONA 24), (HOJAI 13)				

	Lowhot	7	(Loub at	Wast 6) (1	Iombot Foot 1	`				
	Jorhat				orhat East 1) nari 8), (North Ghy 1),	(Haio 23) (Chamaria 22) (
	Kamrup	131				Chaygaon 3), (Kamalpur		Chamara (22), (
	Kamrup (M)	23	(Sonapu	ır 13), (Ch	andrapur 10)				
	Karbi Anglong West	3	(Donka	Donkamokam 3)						
	Karimganj	15	(Karim	ganj 8), (B	adarpur 7)					
	Lakhimpur	61			Bihpuria 27)				
	Majuli	13		9), (Ujani						
	Morigaon	204		•	Iorigaon 82)	100)				
	Nagaon	237			na 83), (Kar	npur 98) bhag 23), (Ghograpar 2	2) (N. 11 - 11	0 \ (D 1 1 N 11 1		
	Nalbari	118	15)			onag 23), (Gnograpai 2	3), ([NaiDaii	o), (Fasciiiii Naibaii		
	Sonitpur	10		ijuli 9), (N	aduar 1)					
	Udalguri	1 2005	(Mazba	t 1)						
	Total	2095			Total					
	District	Male	Femal e	Children	Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details		
	Barpeta	27	11	0	38	(Barpeta 38), (Kalgachia 0), (Chenga 0), (Sarthebari 0), (Baghbar 0)	6861.50	(Barpeta 0.00), (Kalgachia 1457.00), (Chenga 1125.10), (Sarthebari 3102.00), (Baghbar 1177.40)		
	Biswanath	63	51	17	131	(Gohpur 131)	83.00	(Gohpur 83.00)		
	Cachar	91636	83309	54330	229275	(Katigorah 97579), (Udharbond 10203), (Silchar 37000), (Lakhipur 44538), (Sonai 39955)	5915.00	(Katigorah 3125.00), (Udharbond 146.00), (Silchar 1268.00), (Lakhipur 223.00), (Sonai 1153.00)		
	Darrang	12123	10075	5803	28001	(Patharighat 9717), (Dalgaon 292), (Mangaldoi 17992), (Sipajhar 0)	20197.40	(Patharighat 298.90), (Dalgaon 7441.50), (Mangaldoi 11963.00), (Sipajhar 494.00)		
	Dhemaji	0	0	0	0	(Jonai 0)	372.20	(Jonai 372.20)		
Population	Dhubri	0	0	0	0	(Dhubri 0), (South Salmara Part 0), (Gauripur 0)	4097.50	(Dhubri 1413.00), (South Salmara Part 1172.00), (Gauripur 1512.50)		
And Crop Area Affected	Goalpara	0	0	0	0	(Lakhipur 0), (Balijana 0), (Matia 0), (Rongjuli 0)	15477.00	(Lakhipur 10060.00), (Balijana 2408.00), (Matia 2522.00), (Rongjuli 487.00)		
	Golaghat	0	0	0	0	(Bokakhat 0), (Khumtai 0)	42.00	(Bokakhat 25.00), (Khumtai 17.00)		
	Hojai	30037	22667	5689	58393	(Lanka 975), (Doboka 52458), (Hojai 4960)	1916.00	(Lanka 221.00), (Doboka 1183.00), (Hojai 512.00)		
	Jorhat	0	0	0	0	(Jorhat West 0), (Jorhat East 0)	154.00	(Jorhat West 119.00), (Jorhat East 35.00)		
	Kamrup	130	46	40	216	(Chamaria 0), (Nagarbera 0), (Chaygaon 0), (Rangia 0), (Boko 0), (Goroimari 0), (North Ghy 0), (Hajo 0), (Kayan 0), (Kamalpur 216)	5298.20	(Chamaria 1829.50), (Nagarbera 1296.00), (Chaygaon 50.00), (Rangia 37.50), (Boko 69.00), (Goroimari 485.50), (North Ghy 2.13), (Hajo 1385.57), (Kayan 99.00), (Kamalpur 44.00)		
	Kamrup (M)	0	0	0	0	(Chandrapur 0), (Sonapur 0)	1185.50	(Chandrapur 883.00), (Sonapur 302.50)		
	Karbi Anglong West	800	922	280	2002	(Donkamokam 2002)	541.00	(Donkamokam 541.00)		

	Karimganj	7144	5074	4164	16382	(Karimgan Badarpur :	j 10996), (5386)	0.00	(Karimganj Badarpur 0		
	Lakhimpur	0	0	0	0	(Narayanpı	ur 0), (1060.20	(Narayanpu	r 581.20	
		_				Bihpuria C), (Bihpuria		
	Majuli	0	0	0	0	(Majuli 0), (Ujani Majuli 0)		68.44	(Majuli 42.51), (Ujani Majuli 25.93)		
	Morigaon	15100	14574	8864	38538	(Mayong Morigaon		13061.33	(Mayong 9402.00), (Morigaon 3659.33)		
	Nagaon	150069	13406 1	61708	345838	(Kampur Nagaon 24 Raha 8370	1973), (14710.24	(Kampur 5 Nagaon 340 Raha 5701.	09.00),(
	Nalbari	Nalbari 49 44 22 115 (Barbhag 0), (Barkhetri 0), (Tihu 0), (Ghograpar 0), (Nalbari 10), (Paschin Nalbari 115)		0), (Tihu rapar 0), (), (Paschim			295.00), (), (100.50), (2.00), (
	Sonitpur	100	95 25 220			(Naduar 2 Dhekiajuli		498.00	(Naduar 50 Dhekiajuli		
	Udalguri	100	68	68 108 276			0), (0), ((6)	0.00	(Harisinga Kalaigaon (Mazbat 0.0	0.00),(
	Total	307378	27099 7	27099 141050 719425				95473.51			
	District	Total	Relief C	Relief Camp			Relief Distr	ribution Cent	res		
	Barpeta	5		0(Sarthebari 0)			5(Sarthebar				
	Cachar	304	199(Katigorah 76, Sonai 23, Udh Silchar 99, Lakhipur 0)			narbond 1,	105(Katigorah 38, Sonai 1, Udharbond 7, Silchar 10, Lakhipur 49)				
Relief	Darrang	4	0(Manga	aldoi 0)			4(Mangaldo	oi 4)			
Camps /	Hailakandi	2	0(Algap	ur 0)			2(Algapur 2)				
Centres	Hojai	22	22(Hoja	i 11, Dobok	a 11)		0(Hojai 0, Doboka 0)				
Opened	Karimganj	22	7(Badar	our 7, Karin	nganj 0)		15(Badarpur 5, Karimganj 10)				
	Morigaon	14	1(Morig		<u> </u>		13(Morigaon 13)				
	Nagaon	48			a 7, Kampur	15)	8(Nagaon 8, Raha 0, Kampur 0)				
	Total	421	269	. ,		,	152				
	District	Total	Revenue	e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
Inmates In	Cachar	63611	76), (Si	ah 37771), Ichar 13061 nai 12703)	(Udharbond l), (Lakhipur	34255	15261	14039	42	14	
Relief Camps	Hojai	9667	(Lanka (Hojai	0), (Doboka 2230)	7437),	4772	3189	1704	2	0	
	Karimganj	531		anj 0), (Bad	larpur 531)	286	168	53	24	0	
	Morigaon	45		g 0), (Morig		20	15	10	0	0	
	Nagaon	17664	(Nagaon (Kampu	9290), (Ra r 6947)	ha 1427),	8495	6228	2820	119	2	
	Total	91518				47828	24861	18626	187	16	
	District	Total	Male	Female	Children	Revenue C					
Human	Cachar	1	0	0	1	(Katigorah (Udharbond		r 0), (Silchar	1), (Sonai 0),	
Lives Lost -	Hojai	1	1	1 0 0			oka 1), (Hojai 0), (Lanka 0)				
Confirmed	Nagaon	4	3				npur 3), (Nagaon 0), (Raha 1)				
	Total	6	4	0	2						
Human Lives Lost	District	Total	Flood Drownin g (Non Flood) General Drownin g (Non Flood) Landslide								
Confirmed -	Cachar	1	1	0	0						
Death Type	Hojai	1	1	0	0						
	Nagaon	4	4	0	0						
II	Total	6	6	0	0						
Human Lives Lost - Missing	Nil										

Human Lives Lost										
Missing - Type	Nil									
Type	District	Total	Big	Small	Poultry					
	Barpeta	29710	13781	8429	7500					
	Darrang	58376	20655	15314	22407					
	Dibrugarh	214	189	25	0					
	Goalpara	1250	720	530	0					
Animals	Hojai 5426 872		872	366	4188					
Affected	Kamrup	1359	425	310	624					
	Morigaon	58034	21706	13178	23150					
	Nagaon	101554	56196	27945	17413					
	Nalbari	13963	5832	6331	1800					
	Total	269886	12037 6	72428	77082					
Animals Washed Away	Nil		<u> </u>							
Houses	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
Damaged	Cachar	0	0	0	196	89	285	0	0	0
C	Hojai	12	0	12	0	0	0	0	0	0
	Total	12	0	12	196	89	285	0	0	0
	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
	Cachar	Circle Office/Local Administration, Local People			0	0	0	0	0	22
D	Darrang				0	0	0	0	0	3
Rescue Operation	Hojai	Administr	Circle Office/Local Administration, Loca NDRF, SDRF, Army		0	0	0	0	0	4
	Morigaon	Fire & En (F&ES)	nergency S	Services	1	52	0	0	0	0
	Nagaon	Fire & Emergency Services (F&ES), NDRF, SDRF, Army/Paramilitary force			12	201	3	0	0	13
	Total				13	253	3	0	0	42
	District	Rice (in Q) Salt (in Q)		Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed	- Rice Bran (i	in Q)
	Barpeta	0.00	0.00	0.00	0.00	0.00	548.24	0.00		
Relief	Cachar	595.00	100.15	31.73	2323.80	0.00	0.00	0.00		
Distributed	Darrang	38.10	7.05	2.09	211.00	0.00	0.00	219.20		
	Hailakandi	0.00	0.00	0.00	0.00	0.00	2.24	0.00		
	Hojai	119.82	14.92	6.75	443.00	0.00	0.00	57.50		
	Karimganj	55.38	10.49	3.13	77.94 0.00	0.00	0.00	0.00		
	Morigaon Nagaon	271.51 157.98	49.38 28.49	14.81 8.55	0.00	0.00	118.00	0.00		
	Total	137.98 1237.79	210.48	67.06	3055.74	0.00	668.48	276.70		
		Baby Foo					000.40	210.10		
	District	Liquid		Baby Food	l Solid	Others 0-0.00-Q				
Relief Distributed Others	Barpeta Cachar	0.00-Q 0.00-Q		0.00-Q 0.00-Q		Mortein -2000.00-Pkt; Candle-6120.00-Pkt; Match Box-6120.00-Pkt; Tarpaulin -1000.00-Pieces; Soyabean-990.45-Kg; Potato-11010.00-Kg; Mortein-4120.00-Pkt				
Outers	Darrang	0.00-Q		0.00-Q, 28	.00-Pkt	Tarpailin-5				
	Hailakandi	0.00-Q		0.00-Q			7.00-Pieces			
	Hojai	0.00-Q		0.00-Q		•			12.00-L; Drink 1-100.00-Piece	•

				Bleaching power-50.00-Kg; Sanitary pads-100.00-Pkt	
Karimgan	0.00-Q, 4	8.00-Pkt	0.00-Q	0-0.00-Q; MOSQUITO COIL-30.00-Pkt; PHENYL-9.00-L; NAPKIN-80.00-Pkt; CANDLE-40.00-Pkt; MATCH BOX- 30.00-Pkt	
Morigaon	1200.00-	Pieces	1000.00-Pieces	Charge Light-70.00-Pieces; Tarpaulin-1500.00-Pieces; Candle-1000.00-Pieces	
Nagaon	0.00-Q, 1	40.00-L	75.00-Kg, 700.00-Pkt, 0.00-Q	TARPULIN-1350.00-Pieces; Tarpaulin-700.00-Pieces; Candle-100.00-Pkt	
Infrastructur District	Numbe r	Details			
e Damaged - Embankmen Udalguri t Breached	1	embankı		village Balipara in the R/B of river Noa Balipara The DRDA 15/2022 due to erosion from river Noa covering a length of 25 proximately	
Total	1				
Infrastructur e Damaged - Embankmen ts Affected Nil					
District	Numbe r	Details			
Infrastructur e Damaged - Road Barpeta	49	Pajarbha Suha Sil (21.05.2 Bhella T (21.05.2 Baghba damage- PWD de Takakata damage- 2 no. Ba of dama PWD de Bhatnap 17/5/22 departm Mandia damage- PWD de Agmand damage- PWD de Agmand damage- PWD de Nabaroo Type of Mandia damage- PWD de 1 no. Ba damage- PWD de 1 no. Ba damage- PWD de 1 no. Ba damage- PWD de Satrakar damage- PWD de Bordolo Date of Reporter Satrakar damage- Pachim 16/5/22 departm Moukhu and H/C Br. App Chaysin length- App. of	anga Side berm and hard la Bhella Road (As-01-515 022), Catikuchi road Bhella Side 022), Tr - Sikatary MES to Pub Tr - 17/5/22 Type of damage-partment, a tojaurimari road pkg no. Shoulder and H/C damage-partment, aity to kopahtoli via kador Type of damage-partment, aiti chariali to Bamundongrepartment, a chariali to Niz Baghbar verbard to	alhaji Tarabari road via Pajarbhanga and Dakreswae (As-01-463) crust damage 200.00 m PWDR Barpeta (21.05.2022), b) Bhella Side berm damage 1500.00 m PWDR Barpeta de berm and hard crust damage 1500.00 m PWDR Barpeta de berm and hard crust damage 100.00 m PWDR Barpeta de berm and H/C damage Damage length- 250m Reported by AS-01-265 At Sonabari Date of damage- 17/5/22 Type of the Damage length- 2500m Reported by PWD department, char via kawnerchar road pkg no. As-01-206 At kaonerchar Date the ges- Shoulder and H/C damage Damage length- 3500m Reported by mtola Road pkg no. As-01-216 At kopahtoli Date of damage- r and H/C damage Damage length- 4250m Reported by PWD to. Bordoloni via jalimuddin house. At 2 no. Bordoloni Date of shoulder and H/C damage Damage length- 400m Reported by tra road At Bamundongra Date of damage- 16/5/22 Type of the Damage length- 1000m Reported by PWD department, ria sathvitha ME school pkg no. As-01-205 At Sathvitha Date of shoulder and H/C damage Damage length- 1430m Reported by d pkg no. As-01-240 At Dapnasing Date of damage- 16/5/22 C damage Damage length- 1300m Reported by PWD department, b) 1 to Mourigaon pkg no. As-01-283 At Mourigaon Date of shoulder and H/C damage Damage length- 550m Reported by to Tedhera pathar road pkg no. As-01-247 At Tedhera pathar damage- Shoulder and H/C damage Damage length- 1850m a LPS road At Bhuyapara Date of damage- 16/5/22 Type of the Damage length- 600m Reported by PWD department, to Tedhera pathar road pkg no. As-01-253 At Dooldi Date of the Damage length- 600m Reported by PWD department, damage- Shoulder and H/C damage Damage length- 1850m a LPS road At Bhuyapara Date of damage- 16/5/22 Type of the Damage length- 600m Reported by PWD department, to a LPS road At Bhuyapara Date of damage- 16/5/22 Type of the Damage length- 600m Reported by PWD department, to a Hydro damage- Sub str. /Super str. and Apps Damage tength- 130m the Market Pyder Str. Str. Super str. and Apps Damage tength- 130m	

Reported by PWD department,

Br. App. of br no. 1/1 on Dr. Zakir hussain HS to shantipur road | At Alopati | Date of damage-16/5/22 Type of damage-Sub str. / super str. & p;amp;amp;Apps. Damage length- 125m Reported by PWD department,

Br. App. Br no 2/1 on Moishkhuti MEM to 2 no Baghmara via Milonpur | At Milonpur | Date of damage- 16/5/22 Type of damage- Sub str. / super str. & Samp; amp; Apps. Damage length- 100m Reported by PWD department,

Br. App. Br no 3/1 on Moishkhuti MEM to 2 no. Baghmara via Milonpur road. | At Milonpur | Date of damage- 16/5/22 Type of damage- Sub str. / super str. & Damage length- 105m Reported by PWD department,

Br. of br no 1/1 on 384 no Ramaparapam LPS to 115 no. Ramaparapam Boys LPS road | At Ramaparapam | Date of damage- 16/5/22 Type of damage- Sub str. / super str. & amp; amp; Apps. Damage length- 120m Reported by PWD department,

Br. App of br no 1/1 on pachim Moinbari to uttar Moinbari road. | At uttar Moinbari | Date of damage- 16/5/22 Type of damage- Sub str. / super str. & Damage length- 175m Reported by PWD department,

Approach of Tr foot br no 1/1 on uttar fakirpara to Fakirpara road | At Fakirpara | Date of damage-16/5/22 Type of damage- Sub str. / super str. & Samp; amp; Apps. Damage length-100m Reported by PWD department,

Br. App. Of br no 1/1 on Bhatnapaity to shanti bazaar road | At Bhatnapaity | Date of damage-16/5/22 Type of damage- Sub str. / super str. & Samp; amp; Apps. Damage length-110m Reported by PWD department,

Silochi tiniali to Niz Baghbar road pkg no. As-01-500 | At Niz Baghbar | Date of damage- 16/5/22 Type of damage- Shoulder & Damage length- 400m Reported by PWD department,

Majorchar Eidgaah to kahatiamai via Milon Bazaar road | At Khatimari | Date of damage- 16/5/22 Type of damage- Shoulder & Damage Length- 550m Reported by PWD department,

Pachim chaysimana to baladmari via Rahmania MEM road pkg no. As-01-211 | At Pachim chaysimana | Date of damage- 17/5/22 Type of damage- Shoulder & Damage; H/C damage Damage length- 3500m Reported by PWD department,

Dighirpam bazaar to Tedhera gaon road pkg no. As-01-277 | At Tedhera gaon | Date of damage-17/5/22 Type of damage- Shoulder & Damage Damage Length-750m Reported By PWD department,

Satrakanara bazaar to kanara satra pkg no. As-01-246 | At Satrakanara | Date of damage- 17/5/22 Type of damage- Shoulder & Damage Damage length- 650m Reported by PWD department,

App. Of brno 1/1 (near Akbar ali house) on Bhatnapaity road | At Bhatnapaity | Date of damage- 17/5/22 Type of damage- Sub str. / super str. & Samp; amp; Apps. Damage length- 75m Reported by PWD department,

4 no. Baghmara char to Alupati Mandalpara road | At Alupati Mandalpara | Date of damage- 17/5/22 Type of damage- Shoulder & Damage Damage length- 750m Reported by PWD department.

Garalapam LP school road | At Garalapam | Date of damage- 17/5/22 Type of damage- Shoulder & Camp; Amp; H/C damage Damage length- 850m Reported by PWD department,

Salimpur Gopalpur Bhoirarpam MPNA road | At Salimpur, Bhairarpam | Date of damage- 16/5/22 Type of damage- Shoulder & Damage Damage length- 1250m Reported by PWD department,

Milijuli bazaar to Allengipathar road | At Allengipathar | Date of damage- 16/5/22 Type of damage- Shoulder & Damage Damage length- 630m Reported by PWD department, Rajib nagar to Satrakanara 9 no. seat road | At Satrakanara 9 no seat | Date of damage- 16/5/22 Type of damage- Shoulder & Damage Damage length- 550m Reported by PWD department,

Mandia Rowmari road to Bhelengi parghat road | At satrakanara 3 no. Seat | Date of damage- 17/5/22 Type of damage- Shoulder & Damage Length- 500m Reported by PWD department,

Kalgachia - Village road start from Chenimari SH2 to 765 LPs | vill-Chenimari | As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall road st. from chenimari SH2 to 765 LPS paver block road damaged(L=25m, B=3.6m, H=1.5m).,

Village road st from Kashem Ali house to Baki Par Ghatt | viil- Shawrachara Pather | As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall road st from Kashem Ali house to Beki parghatt damaged (L=280m, B=4m, H=1.60m),

Shawrachara Pather to Beki Parghatt | vill- Shawrachara pather | As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall village road st from shawrachara pather to Beki parghatt damaged (L=250m, B=4m, H=1.50m),

Shawrachar Bazar to Bonghugi GP boder | Vill- Shawrachara Gaon | As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall village road st from shawrachara bazar to Bonghugi GP border damaged (L=280m, B=4m, H=1.20m),

Village road st from Johar Uddin house to Baharul Islam house | vill- Rampur | As per report

·		
		received from Rupshi BDO on 22/05/2022, due to heavy rainfall repairing of sand gravel road st from Johar uddin house to Baharul Islam house damaged (L=20m, B=2.40m, H=0.90m), CCMC road near Sahidul Islam house vill- Rampur As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall a CCMC road near Sahidul Islam house damaged (L=20m, B=3.5m, H=0.30m), Earthen field bundh(road) vill- Chandmama Pather As per report received from Rupshi BDO on
		22/05/2022, due to heavy rainfall, const. of Earthen field bundh (road) st from Ismail Hussain landto west side of A Rahman land damaged(L=10m, B=4m),
		Earthen Field bund(Road) vill- Barbitha As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall, const. of Earthen field bundh st from Azaharul Islam land to west side of Mozibar Rahman land damaged (L=15m, B=3.5m),
		Earthen field bundh(road) vill- Mohia As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall, const. of earthen field bundh st from Samsul Alom house to Nuruddin house damaged (L=50m, B=3.0m, H=1.52m),
		Earthen field bundh(road) vill- Hatchara As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall, const. of earthen field bundh st from Rahiz uddin house to west side of Mora manas river damaged (L=20m, B=4m, H=0.90m),
		Earthen field bundh(road) vill- Mohia As per report received from Rupshi BDO on 22/05/2022, due to heavy rainfall, const. of earthen field bundh st from Mohia ME Maddrassa to Nur Hussain house damaged (L=7m, B=3.5m, H=0.90m)
		Bongaigaon - Salbari Bongaigaon PWD road salbari Bongaigaon Road surface damaged, potholes occurs on the road surface and side berm damaged from 6th to 9th km Reported by PWRD
		Bongaigaon. Date of incident-21.05.2022, Salbari Bongaigaon PWD road Salbari Bongaigaon Road surface damaged potholes occurs on the road surface and side berm damaged from 10th to 12th km Reported by PWRD Bongaigaon. Date of incident-21.05.2022,
		Manikpur - Gerukabari Jamdoha PMGSY road Gerukabari Jamdoha Road submerged between ch. 750.00 m to ch. 800.00 m. Submerged depth=25 cm. Erosion occurred on side slopes, side berm and damage of hard crust. Reported by PWRD Bongaigaon, Date of incident-21.05.2022, Dangaigaon Kirtanpara road Dangaigaon Kirtanpara Water logging (at Bhndra Bazar) from ch. 900.00 m to ch. 1100.00 m. damaged hard crust of the road. Reported by PWRD Bongaigaon. Date
Bongaigao n	9	of Incident-21.05.2022, Gerukabari Kirtanpara road Gerukabari Kirtanpara Damage of road embankment including hard crust at 7th & 11th km. Reported by PWRD Bongaigaon. Date of Incident-21.05.2022, Srijangram - Saripunia II to saripunia –I PMGSY road Saripunia II to saripunia Damege of approach of Br No.2/1 at ch. 1.50 km. Reported by PWRD Bongaigaon. Date of incident-21.05.2022, Tulungia Borghola road Tulungia Borghola Damage of culvert approach at 2nd km Reported by PWRD Bongaigaon. Date of incident-21.05.2022,
		Darkinamari Village road connecting Botguri PWD road Darkinamari Damage of side berm and side slope between ch.300.00m and ch. 900.00 m. Reported by PWRD Bongaigaon. Date of incident-21.05.2022, Tulungia Borghola road Tulungia Borghola Damage of joint of hume pipe and culvert cushioning
		including hard crust at culvert No. 6/1 on 6th km Reported by PWRD Bongaigaon. Date of incident-21.05.2022 Katigorah - Molnagram to Jabda Road via Hiluatilla Molnagram Molnagram to Jabda Road via
		Hiluatilla, (1st km to 3th" Km) Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022, Dumkar to Baikuntapur Road Dumkar Dumkar to Baikuntapur Road via Kurkuri, PMGSY Fig. No
		AS-03-239. (2nd km) Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022, Santipur to S.K.Road via Dudpur village. Santipur Santipur to S.K.Road via Dudpur village. (1st Km. to 7th Km) Submerged, As per the report received from PWD Katigorah (T) Road division as on
		20.05.2022, Siddhipur to Mohanpur Road Siddhipur Siddhipur to Mohanpur Road (1st Km)Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022,
Cachar	30	NH 44 at Lakhipur-I to Boroitoll Road Lakhipur-I NH44 at Lakhipur-t to Boroitoll Road Bridge approaches of Br.No.3/2 (PMGSY Pkg. No.45-03-193) Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022,
		G.N.Road near Chandipur Ramkrishna Akhra to Digarkhal Garden Chandipur G.N.Road near Chandipur Ramkrishna Akhra to Digarkhal Garden T.E. under BADP (1st Km.)Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022,
		G.N.Road to Saraspur via Itbhatta Saraspur G.N.Road to Saraspur via Itbhatta under BADP. (1st Km.) Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022,
		Bishambapur to G.N.Road Bishambapur Bishambapur to G.N.Road at Gumra Grant PMGSY Pkg. No.AS-03-189 (2nd K.M.)Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022,
		Kinnorkhal Subodhnagar Road Subodhnagar Kinnorkhal Subodhnagar Road from Haritikar Sadirkhal PWD Road to Bhairabbari at Candinagar (1st & 2nd Km)Submerged, As per the

report received from PWD Katigorah (T) Road division as on 20.05.2022,

Kinnorkhal Bus Stand to Subodhnagar Road | Kinnorkhal | Kinnorkhal Bus Stand to Subodhnagar Road (1st KM)Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022.

Office Campus including Staff Quarters of PWRD | Katigorah | Office Campus including Staff Quarters of PWRD, Borkhola & Division. Submerged, As per the report received from PWD Katigorah (T) Road division as on 20.05.2022,

Udharbond - Arkatipur to Badripar | Digor Kashipur | MRL-02-Arkatipur to Badripar via Maidanbeel and Digor Kashipur, Package No. AS-03-262.Ch. 550.00M to 1050.00M, road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022.

SILCHAR KUMBHIRGRAM ROAD (V.I.P. ROAD) | Udharbond | SILCHAR KUMBHIRGRAM ROAD (V.I.P. ROAD) FROM CH. 1800.00M TO CH. 2000.00 M road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

KOROIKANDI ROAD | KOROIKANDI | KOROIKANDI ROAD FROM CH. 0.00M TO CH. 500.00 M road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

ARKATIPUR GOSSAIPUR VIA NEPALIBASTI ROAD | ARKATIPUR GOSSAIPUR | ARKATIPUR GOSSAIPUR VIA NEPALIBASTI ROAD FROM CH. 50.00M TO CH. 400.00 M & amp; CH. 1200.00M TO 1800.00M road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

NATHPARA KANDIRGRAM ROAD | KANDIRGRAM | NATHPARA KANDIRGRAM ROAD FROM CH. 30.00M TO CH. 700.00 M road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

DOYAPUR ARKATIPUR ROAD | DOYAPUR | DOYAPUR ARKATIPUR ROAD 1ST, 7TH AND 8TH KM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

RONGPUR-SHANTIPARA ROAD | RAJPATH | RONGPUR-SHANTIPARA ROAD (RAJPATH) road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

S.K. ROAD TO BLOCK H.Q. | PATHARIA | S.K. ROAD TO BLOCK H.Q. VIA PATHARIA AT CH. 2900.00M. DEPTH OF 100.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

S.K. ROAD TO DAYAPUR-I | DAYAPUR-I | S.K. ROAD TO DAYAPUR-I AT CH. 3700.00M DEPTH OF 100.00 CM. road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

UDHARBOND BANSKANDI ROAD | BANSKANDI ROAD | UDHARBOND BANSKANDI ROAD AT CH. 6600.00M DEPTH OF 100.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

DUNGRIPAR Road | DUNGRIPAR Road | CULVERT APP. OF DUNGRIPAR FROM CH. 0.00M TO CH. 140.00M DEPTH OF 90.00 CM. road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

DOYAPUR TO DIGOR KASHIPUR | CHAPPANAHAL ROAD | DOYAPUR TO DIGOR KASHIPUR VIA CHAPPANAHAL ROAD (PKG. NO. AS-03-249) FROM CH. 4000.00M TO CH. 4800.00M DEPTH OF 90.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

PANGRAM AMARANAGAR ROAD SUBMERGENCE | AMARANAGAR | PANGRAM AMARANAGAR ROAD SUBMERGENCE FROM CH. 4200.00M TO CH. 7700.00 M IN STRETCHES 200 M DEPTH OF 10.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

NH-54 TO GOSSAIPUR PT-II ROAD | GOSSAIPUR PT-II ROAD | NH-54 TO GOSSAIPUR PT-II ROAD SUBMERGENCE FROM CH. 0.00M TO CH. 800.00 M IN STRETCHES 800 M DEPTH OF 30.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

DOYAPUR TO DIGAR KASHIPUR | CHAPPANAHAL ROAD | DOYAPUR TO DIGAR KASHIPUR VIA CHAPPANAHAL ROAD PKG NO.AS-03-249 SUBMERGENCE FROM CH. 3980.00M TO CH. 4600.00 M IN STRETCHES 620 M DEPTH OF 30.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022, CHATRADOYAL TO HARINAGAR VIA PASCHIM DISKA ROAD | PASCHIM DISKA | CHATRADOYAL TO HARINAGAR VIA PASCHIM DISKA ROAD PKG NO.AS-03-254 SUBMERGENCE FROM CH. 2050.00M TO CH. 2300.00 M IN STRETCHES 250 M DEPTH OF 30.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022,

ARKATIPUR TO BADRIPAR VIA MAIDANBEEL AND DIGOR KASHIPUR ROAD | MAIDANBEEL AND DIGOR KASHIPUR | ARKATIPUR TO BADRIPAR VIA MAIDANBEEL AND DIGOR KASHIPUR ROAD PKG NO.AS-03-262 SUBMERGENCE FROM CH. 2500.00M TO CH. 3000.00 M IN STRETCHES 500 M DEPTH OF 30.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022, BAHADURPUR TO MOINERBOND ROAD | BAHADURPUR and MOINERBOND |

Darrang	4	BAHADURPUR TO MOINERBOND ROAD SUBMERGENCE FROM CH. 100.00M TO CH. 500.00 M DEPTH OF 60.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022, LATHIGRAM ROAD LATHIGRAM LATHIGRAM ROAD SUBMERGENCE FROM CH. 240.00M TO CH. 1000.00 M IN STRETCHES 560 M DEPTH OF 15.00 CM road Submerged, as per the report received from PWD Silchar & Udharbond (T) Roads division, as on 21.05.2022 Patharighat - C/C block road at Borpothar Borpothar Block road damages on 20/5/2022 & 21/05/2022 as reported by Deptt. Engineer, Dalgaon - Rajapukhuri to No.2 Borjhar road Rajapukhuri to No.2 Borjhar road at CH-3540, CH-3700 as per report received from SDO, PWRD, kalaigaon Territorial road sub-division, Rajapukhuri to No.2 Borjhar road side berm erroded at CH-3540(L-60M) and CH-3700(L-60M) under dalgaon revenue circle. Date of occurrence- 17/05/2022, Rajapukhuri to No.2 Borjhar road Rajapukhuri to No.2 Borjhar road at CH-1st KM as per report received from SDO, PWRD, kalaigaon Territorial road sub-division, Rajapukhuri to No.2 Borjhar road side berm erroded at CH- 1st KM in two portion. (L-50m and 70m), ate of occurrence - 17/05/2022, Chenibari to Shyamtilla road Chenibari to Shyamtilla road at CH- 1st KM as per report received from SDO, PWRD, kalaigaon Territorial road sub-division, Chenibari to Shyamtilla road side berm eroded, hard crust is completely damaged at CH- 1st KM (L-200M) date of occurrence - 17/05/2022
Dibrugarh	2	Moran - Borbill Road Borbill village As per report of PWD Moran Territorial Road Sub- division due to recent continuous heavy rainfall the road is submerged and severely affected leading to waterlog and side berm erosion for which movement of vehicular traffic and commuters is disrupted. Length affected- 0.80 K.M, Date of occurance: 19/05/2022, Borbill Demow Kiner Changmai Gaon Road. Borbill village As per report of PWD Moran Territorial Road Sub - division due to recent continuous heavy rainfall the road is submerged and severely affected leading to waterlog and side berm erosion for which movement of vehicular traffic and commuters is disrupted. Length affected- 1.000 K.M, Date of occurance: 19/05/2022.
Goalpara	7	Matia - Paharsingpara to Mama Vagin Field road (SH-46) Dubapara Total affected length = 0.500 Km and average submergence = 0.300 m as on 21/05/2022 as received from PWRD, Dudhnoi and Goalpara East Territorial Road Division., Namapara to Jaipara road Tukura Total affected length = 1.00 Km and average submergence = 0.250 m as on 21/05/2022 as received from PWRD, Dudhnoi and Goalpara East Territorial Road Division., Balijana - Sotokashi Khagra to Boro Kasikhagra PMGSY Road Sotokashi Khagra Date of occurrence- 20.05.2022 Length/dimension- Length affected 0.200 KM (From Ch. 2.8 KM to 2.90 KM and Ch. 3.400 to 3.500) Average depth of submergence- 0.300 M 1 nos. Culvert approach damaged Traffic Disrupted Reported by Department - Dudhnoi and Goalpara East Territorial Road Div. Date and time of information received- 21.05.2022 at 11.30 pm, Panikheti Nolonga Road Panikheti Nolonga Date of occurrence- 21.05.2022 Length/dimension- Length affected 300.00 m (from Ch. 700.00 M to Ch. 800.00M, Ch. 950.00M to Ch. 150.00 M and Ch. 1300.00 M to Ch. 1450.00 M) Average depth of submergence- 30.00 CM Traffic disrupted Department- Goalpara West and JaleswarTerritorial Road Div. Date and time of information received- 21.05.2022 at 09.51 pm, Simlabari Markula Road Simlabari Markula Date of occurrence- 21.05.2022 Length/dimension- Length affected 350.00 m (At 1st KM, 2nd KM and 3rd KM) Average depth of submergence- 30.00 CM Traffic disrupted Department- Goalpara West and JaleswarTerritorial Road Div. Date and time of information received- 21.05.2022 to 9.51 pm, Ambari (Petrol Pump) to Katlatari via Kaljani Road Ambari (Petrol Pump) to Katlatari via Kaljani Date of occurrence- 21.05.2022 at 09.51 pm, Ambari (Petrol Pump) to Katlatari via Kaljani Road Ambari (Petrol Pump) to Katlatari via Kaljani Date of occurrence- 21.05.2022 at 09.51 pm, Kalyanpur to Kaljani Road Kalyanpur to Kaljani Date of occurrence- 21.05.2022 at 09.51 pm, Kalyanpur to Kaljani Road Kalyanpur to Kaljani Date of occurrence- 2
Hailakandi	7	Katlicherra - Sultanicherra Grant Pkg. No. AS-09-43, Under Katlicherra Revenue Circle dtd- 21.05.2022 1st & 2nd KM Damage due to Runoff water, Ganjakhauri Tukorgram Rongpur Pt-IIUnder Katlicherra Revenue Circle dtd- 21.05.2022 1st KM Damage due to Runoff water, Dinonathpur PWD road to Mulapur Moragang roadUnder Katlicherra Revenue Circle dtd- 21.05.2022 1st KM Submerged, Algapur - 01T5 to Bakrihawar PtII, AS-09-29, Under Algapur Revenue Circle, Dtd21.05.2022 1st, 2nd & 3rd KM Submerged, 01T4 Bakrihawar Pt-VI, 01T4 at Bakrihawar PtIX, Bakrihawar Pt-X, Pkg. No AS-09-24, Under Algapur Revenue Circle, Dtd21.05.2022 2nd KM Submerged, T5- Algapur Pt5 Pkg. No As-09-18, Under Algapur Revenue Circle, Dtd21.05.2022 7th, 8th & 9th KM Submerged, 01T5 to Kalinagar Pt-III, Pkg. No As-09-21, Under Algapur Revenue Circle, Dtd21.05.2022 1.

		Ch. 300.00 to Ch. 600.00 m, 2.Ch. 1600.00m to 1700.00m, 3. Ch. 2900.00m to 3250.00m
		Submerged
		Kamalpur - Jalimura to Changsari road Vill-Jalimura Total Lenght of the Road 10.30km. Submerged at 2nd km for a length of 100 Meter as per report of the Executive Engineer PWD North
Vammin	2	KMP Territorial road division rangia Dated: 21-05-2022,
Kamrup	2	Madanpur to Katanipara Vill-Madanpur Total Lenght of the Road 2.00 km. Submerged at 1st km
		for a length of 250 Meter as per report of the Executive Engineer PWD North KMP Territorial road division rangia Dated: 21-05-2022
		Donkamokam - As report received from PWD (R) Baithalangso Rd. div on 21/05/2022 that several
		roads was submerge and was affect from 15/05/2022 due to loosen of side bump soil causing affect
Karbi	o	different Chainages. Satgaon Don-Bosco to Mugasong, Jengkha to Menmeji, Sitolijan to
Anglong West	8	Phangtenphrang,Sitolijan to vomu Atar,Kolonga to sildubi,Priloo to borbali, and Menmeji to deramukh Roads. After receding flood water side bump of different chainage roads was eroding As
		report received from PWD (R) Baithalangso Rd. div on 21/05/2022 that several roads was submerge
		and was affect from 15/05/2022 due to loosen of side bump soil causing affect different Chainages.
		Karimganj - FN ROAD TO BHEDRANG PT I ,PMGSY PKG NO.AS 13 206,DAMAGED ROAD PORTION AT CH.800.00M,CH.4100.00M,CH4600.00M,CH.3400.00M BHEDRANG DUE TO
		INCESSANT RAIN FOR LAST FEW DAYS THE ABOVE ROAD WAS DAMAGED
		PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE SUBMITTED BY
Karimganj	2	ASSTT.EXECUTIVE ENGINEER, PWRD, KARIMGANJ ON 20/05/2022,
		F.N ROAD TO CHALIYADI,PMGSY PKG.NO-AS-13-297 CHALIYADI DUE TO INCESSANT RAIN FOR LAST FEW DAYS THE ABOVE ROAD WAS DAMAGED
		PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE SUBMITTED BY ASSTT.
		EXECUTIVE ENGINEER, PWRD, KARIMGANJ ON 21/05/2022
		Nowboicha - Pandhowa to Mohghuli Road Pandhowa Pandhowa to Mohghuli Road.Flood water
Lakhimpur	1	overtopped from Ch: 1400.00m to Ch: 1860.00m average depth 45.00m, Erosion occurs at CH:1500.00m to 1530.00m and from Ch: 1670.00m to Ch: 1700.00m Reported by PWRD
		Nowboicha Territorial road Division, Nowboicha on 21/05/2022
		Mayong - Amlighat Sonaikuchi Road Submerged at 1st and 2nd km Patch of road Submerged as
M	2	reported by PWD District Territorial Road Division on 22/05/22,
Morigaon	2	Morigaon - 1 No Morakolong toTarani Kalbari Road (22-05-2022) 1 No Morakolong Receive from PWD Territorial Road Division 1 No Morakolong toTarani Kalbari Road submerged at 1st 2nd
		KM length of submergence = 900M depth of Submergence = 300 to 600MM
		Kampur - L076-KSB Road to Ulumguri NC Village Kampur L076-KSB Road to Ulumguri NC
		Village, PMGSY, Package No. AS-19-367, Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-21.05.2022,
		L074-Rengbang grant to Patiapam Kampur L074-Rengbang grant to Patiapam, PMGSY, Package
		No. AS-19-368, Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-
		Division, Dtd-21.05.2022,
		L040-Kathalguri to Upper Borgaon Lalunggaon Kampur L040-Kathalguri to Upper Borgaon Lalunggaon Rd, PMGSY, Package No. AS-19-370, Damaged/Submerged, reported by ,PWD(R)
		Barhampur Territorial Road Sub-Division, Dtd-21.05.2022,
		L023-NH 36 Singrabasti to Uriagrant Rangolo Road Kampur L023-NH 36 Singrabasti to Uriagrant
		Rangolo Road, PMGSY, Package No. AS-19-371, Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-21.05.2022,
		L071-Topakuchi to Haldhiati, PMGSY, Package No. AS-19-399 Kampur L071-Topakuchi to
		Haldhiati, PMGSY, Package No. AS-19-399, Damaged/Submerged, reported by ,PWD(R)
		Barhampur Territorial Road Sub-Division, Dtd-21.05.2022 , L066-Dakhin Changehaki to Topakuchi via Garubat and Kuhimari No 2 Kampur L066-Dakhin
		Changehaki to Topakuchi via Garubat and Kuhimari No 2, PMGSY, Package No. AS-19-417,
Nagaon	20	Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-
J		21.05.2022, L059-Dakhinjar Borgaon to Amdubi via Dakhin Amari Kampur L059-Dakhinjar Borgaon to
		Amdubi via Dakhin Amari, PMGSY, Package No. AS-19-424, Damaged/Submerged, reported by
		,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-21.05.2022,
		L042-KK Road Mahoniati to Kachaikhania Rd, PMGSY, Package No. AS-19-445 Kampur L042-
		KK Road Mahoniati to Kachaikhania Rd, PMGSY, Package No. AS-19-445, Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-21.05.2022,
		Garubandha to Barapam Kampur Garubandha to Barapam, PMGSY, Package No. AS-19-446,
		Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-
		21.05.2022, Puthuimari to Radha Nagar Kampur 27. Puthuimari to Radha Nagar, PMGSY, Package No. AS-
		19-457, Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-
		21.05.2022,
		Pramila ati to Baligaon Kampur Pramila ati to Baligaon, PMGSY, Package No. AS-19-553, Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-
		21.05.2022,
		L080-Lutumari Longjup Rd to Tangiabangaon Kampur L080-Lutumari Longjup Rd to
		Tangiabangaon, PMGSY, Package No. AS-19-635, Damaged/Submerged, reported by ,PWD(R)

			Barhampur Territorial Road Sub-Division, Dtd-21.05.2022, L048-DK Road Paraliguri to Ati Kampur Kampur L048-DK Road Paraliguri to Ati Kampur, PMGSY, Package No. AS-19-362, Damaged/Submerged, reported by ,PWD(R) Barhampur Territorial Road Sub-Division, Dtd-21.05.2022, Nagaon - Dakhinpat To Madhupur Khagarijan, Nagaon Dakhinpat To Madhupur, Length-50M, Date-21/5/2022,DeptPWRD Nagaon Territorial Sub-Division, Nagaon , Dakhinpat To Tulshimukh Burhaguhainthan Dakhinpat, Nagaon Dakhinpat To Tulshimukh Burhaguhaintha , Length-5Klm, Date-21/5/2022,DeptPWRD Nagaon Territorial Sub-Division, Nagaon , Dakhinpat Kampur Road to Kachuguri Kachowguri Dakhinpat Kampur Road to Kachuguri , Length-5Km, Date-21/5/2022,DeptPWRD Nagaon Territorial Sub-Division, Nagaon , Nonoi Dakhipat Road to Tulshimukh Nonoi Nonoi Dakhipat Road to Tulshimukh ,Length-1Km, Date-21/5/2022,DeptPWRD Nagaon Territorial Sub-Division, Nagaon , Tulshimukh to Rangalomukh Road Rangalomokh Tulshimukh to Rangalomukh Road ,Length-2Km, Date-21/5/2022,DeptPWRD Nagaon Territorial Sub-Division, Nagaon , Burhaguhainthan to Kachoguri Kachuguri Burhaguhainthan to Kachoguri ,Length- 2 Km ,Date-
	Udalguri	5	21/5/2022, DeptPWRD Nagaon Territorial Sub-Division, Nagaon Udalguri - Dhibisora to Santipur Link Road Ekrabari The road connecting Dhibisora to Santipur Link Road eroded at Ekrabari Village around 30m on 21.05.2021., Harisinga - Totolapara to Jabangapothar village road Totolapara Due to excessive rainfall occurring from 15th May the Village road damage around 30ft., Kalaigaon - MB road at ch 17th km (1st strech) No 2 Singrimari The road has damaged on 22/05/2022 due submergence of flood water from river Noa and logged water due to blockages in the drain in the each side of the road covering a length of 120 meters and breadth of 12 meters, MB road at ch 17th km (2nd strech) No 2 Singrimari The road has damaged on 22/05/2022 due submergence of flood water from river Noa and logged water due to blockages in the drain in the each side of the road covering a length of 60 meters and breadth of 12 meters, Deorgaon to hapabari link road Deorgaon The MGNREGA road has breached on 22/05/2022 due submergence of flood water from river Noa at village Deorgaon covering a length of 8 meters and breadth of 4 meters
	Total	148	
I f t	District	Numbe r	Details
Infrastructur e Damaged - Bridge	Hailakandi	1	Algapur - RCC bridge No. 1/1 under RIDF XXIV at Sayedbond Pt-III , Under Algapur Revenue Circle, Dtd21.05.2022 . Sayedbond under Algapur Revenue Circle Bridge approach damage due to Runoff water around 400 mtr. both side.
- 0	Total	1	
Infrastructur e Damaged - Wildlife	District Morigaon		affected under protected areas description - Pobitora Wild Life Sanctuary 8nos of camps affected and 2nos of camp inundated as report received
vv iidiiic			ge Officer PWI S on 22/05/2022
	District	from Ran	ge Officer PWLS on 22/05/2022
	District Barpeta	Other De Kalgachi rainfall 2 Ali house 90.751202	

Flemenury Schools Damaged [Janaigane I PS has been fonded and damaged as reported by BFFG Chaidnar Education Block on 21 10.5 2022. Kutigorsh - PWSS Damaged [Burung Pt. III we/scheme flows/scheme Titor Burung a we/scheme Scut Pt. IV we/scheme floramb we/scheme Lamagram Manikppr we/scheme Pabergram we/scheme Sthangampur we/scheme Purbo Gebrindpur we/scheme Lathgram we/scheme Damagram we/scheme Burunariany re/scheme flowsold Pt. II we/scheme Boorolla We/scheme Lathgram we/scheme Damagary re/scheme Boorolla Pt. II we/scheme Boorolla We/scheme Scheme Scheme Boorolla We/scheme Scheme Scheme Boorolla We/scheme Scheme Scheme Scheme Boorolla We/scheme We/scheme Scheme Schem		
Senti P. I. V wischeme Giumala wischeme Lanuargarun Manikuru wischeme Pübergram wischeme Blurarainpar wischeme Bruthro Göhndager wischeme Brotinoli wischeme Lakhipur wischeme Kadirgam wischeme Khlma P. V wischeme Brotinoli P. II wischeme Ganagar wischeme Kalinagar Khlenha wischeme Budikadergur Pt. IV wischeme anna Dudgur wischeme Ganagar wischeme Kalinagar Khlenha wischeme Budikadergur Vt. IV wischeme anna Dudgur wischeme Ganagar wischeme Kalinagar Khlenha wischeme Budikadergur vischeme Simpur wischeme Sarapar wischeme Nilam Basi wischeme Budikadergur wischeme Sarapar wischeme Khlenha P. VI wischeme Timikree wischeme Shannadur wischeme Sarapar wischeme Nilam Basi wischeme Budikara wischeme Bahandur wischeme Sarapar wischeme Nilam Basi wischeme Timikree wischeme Bahandur wischeme Sarapar wischeme Sarapar wischeme Radirahapur Pt. I wischeme Bahandur wischeme Sarapar wischeme Bahandur wischeme Bahandur wischeme Radirahapur wischeme Bahandur wischeme Sarapar wischeme Bahandur wischeme Bahandur wischeme Sarapar wischeme Bahandur wischeme Kalina Bazar wischeme Saraham wischeme Bahandur II II Wischeme Wischeme Ni Katigoriah wischeme Kalina Bazar wischeme Saraham wischeme Sarapar II II Wischeme Wischeme Ni Katigoriah wischeme Kalina Bazar wischeme Saraham wischeme Katirala wischeme Mohanpur wischeme Khlina wischeme Zanagar wischeme Sarapar vischeme Katirala wischeme Mohanpur wischeme Khlina wischeme Zanagar wischeme Sarapar kan zu Barapar kan zu Bazar zu		
Dubag ws/scheme Niz Joynagar ws/scheme Tarapur Pt. I ws/scheme under Silchar Sadar RC as on 22.05.2022 Patharighat - PWSS Damaged Damage of piped line network along with C/C Block road at Dishlatoprothar) PWSS as reported by PHE Deptton 21/5/2022, 28nos of villages, 726 nos of fish farmers and 159.28 Ha water area affected under Dalgaon Rev Circle Lanka - Power Dept. Poles 12 nos poles, date: 20-05-2022. Power Dept. Conductors 2.5 km, date: 20-05-2022. PWSS Damaged Dist. Pipe line, FHTC, UGR, TP, Filter media & Dishlatoproper Purper Purper PwSS, Manduli PWSS, Utar Laskar Pather PWSS, Kapilipar PWSS, Dated: 20-05-2022, Anganwadi Centres Affected Dakhin Laskar Pather AWC, Dakhin Laskar Pather HM School AWC, Dakhin Laskar Pather Mikir Gaon AWC, Thaisubali aWC partially damage. Dated: 20-05-2022, Hojai - PWSS Damaged Vill- Barofuti, Distribution line, pipe line FHTC, UGR and filter media damaged on dated 22/05/2022 with GPS Coordinates 26.05555 N and 92.78097 E. PWSS Damaged vill- Saotal Basti, Distribution line, pipe line, FHTC, UGR and filter media, pump houses are damaged on dated 22/05/2022 with GPS Coordinates 26.1547 N and 92.8521 E, PWSS Damaged vill- Kandulimari, Dist. line, pipe line, FHTC, LiGR and pump houses are damaged on dated 22/05/2022 with GPS Coordinates 26.05297 N and 92.802976 E, PWSS Damaged vill- Raikata Kacharigaon, Distribution line filter media and pump houses are damaged on dated 22/05/2022 with GPS Coordinates 26.05297 N and 92.802976 E, PWSS Damaged vill- Raikata Kacharigaon, Distribution line filter media and pump sets are damaged on dated 22/05/2022 with GPS Coordinates 25.0978 N and 92.84951 E, Hojai PWSS Damaged vill- Raikata Kacharigaon, Distribution line filter media and pump sets are damaged on dated 22/05/2022 with GPS coordinates 25.996122 N and 92.84951 E, Handloom & Textile Deptt vill- Komorakata, Raikata, Dakhin Kenduguri, Kumurakata, bishnupur, Nabhanga, Rajbari, Shibpur and hayangaon, no of weavers affected 500 nos, damage of looms, equipments, ra	Cachar	Seuti Pt. IV w/s/scheme Gumrah w/s/scheme Lamargram Manikpur w/s/scheme Pubergram w/s/scheme Sibnarayanpur w/s/scheme Purbo Gobindapur w/s/scheme Lathgram w/s/scheme Daspara w/s/scheme Buraraiarpar w/s/scheme Boroitoli Pt. II w/s/scheme Boroitoli w/s/scheme Lakhipur w/s/scheme Kandigram w/s/scheme Khelma Pt. V w/s/scheme Baishnabpara w/s/scheme Goalnagar w/s/scheme Kalinagar Khelma w/s/scheme Mahadevpur Pt. IV w/s/scheme Baishnabpara w/s/scheme Dudpur Pt. I w/s/scheme Dudpur Pt. II w/s/scheme Boalikhalerpar w/s/scheme Sripur w/s/scheme Niz Fulbari w/s/scheme Ganirgram Pt. I w/s/scheme Paschim Kadamtola w/s/scheme Sripur w/s/scheme Saraspur w/s/scheme Rilam Basti w/s/schemeBatulmara w/s/scheme Sindhura T.E. w/s/scheme Choudhury Gram w/s/scheme Behara Pt. VI w/s/scheme Tintikree w/s/scheme Ishanabad w/s/scheme Sarishaquiri w/s/scheme Balapur w/s/scheme Biswambarpur w/s/scheme Baleshwar Grant w/s/scheme Holypara w/s/scheme Eushiarkul w/s/scheme Rongpur w/s/scheme Bahirabpur Pt. I w/s/scheme Bhairabpur Pt. V w/s/scheme Digabor Bagan w/s/scheme Koroikandi w/s/scheme Paschim Natanpur w/s/scheme Chaligram w/s/scheme Niz Katigorah w/s/scheme Koroikandi w/s/scheme Saidheswar w/s/scheme Katirail w/s/scheme Mohanpur w/s/scheme Katigorah w/s/scheme Katigorah w/s/scheme Saidheswar w/s/scheme Saidpur Pt. III w/s/scheme Mazirbeel w/s/scheme Khelma w/s/scheme Karachura w/s/scheme Mahadevpur Pt. II w/s/scheme Srinagar w/s/scheme under Katigorah RC dated 22.05.2022, Silchar - Health Sub-Centre Rajnagar MPHC, Arikol SC, Masimpur HWC, Algin HWC, Manikpur SC, Kumaepara SC, Kalinagar SC, Nischantapur SC, Arunchal SC, Borjatrapur SC, Machghat, Nandigram SC, Surtara SC, Bairagitilla SC under BORKHOLA BPHC as on 20.05.2022, PWSS Damaged Silchar Town w/s/scheme Kuarpar w/s/scheme Tapang w/s/scheme Tapang w/s/scheme Subong Garden w/s/scheme Jarailtola w/s/scheme Borbond w/s/scheme Dhalcherra Grant w/s/scheme Borbonal w/s/scheme Boronal w/s/scheme Boronampur w/s/scheme Boronampur w/s/scheme Boronampur W/s/scheme Boronampur W/s/schem
Lanka - Power Dept. Poles 12 nos poles, date: 20-05-2022, Power Dept. Conductors 2.5 km, date: 20-05-2022, Power Dept. Conductors 2.5 km, date: 20-05-2022, PWSS Damaged Dist. Pipe line, FHTC, UGR, TP, Filter media & Dist. Pipe line, FHTC, UGR, Againwadi Centres Affected Dakhin Laskar Pather PWSS, Kapilipar PWSS, Dated: 20-05-2022, Anganwadi Centres Affected Dakhin Laskar Pather PWSS, Kapilipar PWSS, Dated: 20-05-2022, Anganwadi Centres Affected Dakhin Laskar Pather PWSS, Kapilipar PWSS, Dated: 20-05-2022, Hojai - PWSS Damaged Vill- Barofuti, Distribution line, pipe line FHTC, UGR and filter media damaged on dated 22/05/2022 with GPS Coordinates 26.05555 N and 92.78097 E. PWSS Damaged vill- Saotal Basti, Distribution line, pipe line, FHTC, UGR and filter media, pump houses are damaged on dated 22/05/2022 with GPS Coordinates 26.1547 N and 92.45321 E, PWSS Damaged vill- Kandulimari, Dist. line, pipe line, FHTC, filter media and pump houses are damaged on dated 22/05/2022 with GPS coordinates 26.05297 N and 92.802976 E, PWSS Damaged vill- Raikata Kacharigaon, Distribution line filter media and pump sets are damaged on dated 22/05/2022 with GPS Coordinates 25.0978 N and 92.6754 E, PWSS Damaged vill- Moina pathar, Distribution line, filter media and pump sets are damaged on dated 22/05/2022 with GPS coordinates 25.996122 N and 92.84951 E, Handloom & Textile Deptt vill- Komorakata, Raikata, Dakhin Kenduguri, Kumurakata, bishnupur, Nabhanga, Rajbari, Shibpur and hayanggaon,no of weavers affected 500 nos, damage of looms,equipments,raw materials ie yarm,clothes etc. dated 22-05-2022, Fisheries/Pond Vill- Baliram Pathar, Amtola, Hayong basti, Pub Bogori, Pachim Bogori, Kandulimari,Solmarijan. No of fish farmers affected 650, no of ponds and tanks affected 600 nos and total water area affected 61 hect. dated 22-05-2022, Doboka - Handloom & Textile Deptt nos. of weavers affected 500. Damage of Looms and Raw materials i.e. yarn and finished goods i.e. cloths at the following villages, Patiapa	Darrang	Dubag w/s/scheme Niz Joynagar w/s/scheme Tarapur Pt. I w/s/scheme under Silchar Sadar RC as on 22.05.2022 Patharighat - PWSS Damaged Damage of piped line network along with C/C Block road at Dimila(borpothar) PWSS as reported by PHE Deptton 21/5/2022, Dalgaon - Fisheries/Pond As per report received from Fishery Development officer, darrang as on 22-05-2022,
Kamalpur - Fisheries/Pond 14.48 ha(Fish ponds are either over flooded or broken the agribund) as per report	Hojai	Lanka - Power Dept. Poles 12 nos poles, date: 20-05-2022, Power Dept. Conductors 2.5 km, date: 20-05-2022, Power Dept. Conductors 2.5 km, date: 20-05-2022, PWSS Damaged Dist. Pipe line, FHTC, UGR, TP, Filter media & amp; Pump set etc damaged under Dakhin Laskar Pather PWSS, Manduli PWSS, Uttar Laskar Pather PWSS, Kapilipar PWSS, Dated: 20-05-2022, Anganwadi Centres Affected Dakhin Laskar Pather AWC, Dakhin Laskar Pather HM School AWC, Dakhin Laskar Pather Mikir Gaon AWC, Thaisubali AWC partially damage. Dated: 20-05-2022, Hojai - PWSS Damaged Vill- Barofuti, Distribution line ,pipe line FHTC,UGR and filter media damaged on dated 22/05/2022 with GPS Coordinates 26.05555 N and 92.78097 E, PWSS Damaged vill- Saotal Basti , Distribution line ,pipe line ,FHTC ,UGR and filter media,pump houses are damaged on dated 22/05/2022 with GPS Coordinates 26.1547 N and 92.45321 E, PWSS Damaged Vill- Kandulimari , Dist. line,pipe line ,FHTC,filter media and pump houses are damaged on dated 22/05/2022 with GPS coordinates 26.05297 N and 92.802976 E, PWSS Damaged vill- Raikata Kacharigaon , Distribution line filter media and pump sets are damaged on dated 22/05/2022 with GPS coordinates 25.0978 N and 92.6754 E, PWSS Damaged vill- Moina pathar , Distribution line, flter media and pump sets are damaged on dated 22/05/2022 with GPS coordinates 25.996122 N and 92.84951 E, Handloom & Textile Deptt vill- Komorakata, Raikata, Dakhin Kenduguri, Kumurakata, bishnupur, Nabhanga, Rajbari, Shibpur and hayanggaon,no of weavers affected 500 nos , damage of looms,equipments,raw materials ie yarn,clothes etc. dated 22-05-2022, Fisheries/Pond Vill- Baliram Pathar, Amtola, Hayong basti, Pub Bogori, Pachim Bogori, Kandulimari,Solmarijan. No of fish farmers affected 650, no of ponds and tanks affected 600 nos and total water area affected 61 hect. dated 22-05-2022, Doboka - Handloom & Textile Deptt nos. of weavers affected 500. Damage of Looms and Raw materials i.e. yarn and finished goods i.e. cloths at the following vill
of the Fishery Development Officer Bihdia-Jajikona Block Dated: 22-05-2022	Kamrup	
Karbi Donkamokam - Power Dept. Poles due to submerged of L.T 34 Nos Pole base was affect and collapse on	Karbi	

Anglong West	21/05/2022, affecting from its functioning at different location at the Geographical location of Longitude:92.699973 & Latitude: 25.929738 as per report received from SDE, Donkamokam Electrical division and, Power Dept. Poles due to submerged of H.T 62 Nos Pole base was affect and collapse on 21/05/2022 affecting from its functioning at different location at the Geographical location of Longitude:92.699346 & Latitude: 25.929567 as per report received from SDE,Donkamokam Electrical division Kampur - Power Dept. Poles Pole damaged-31 nos. under Kampur Rev. Circle reported by APDCL Kathiatoli Division, Dtd-21.05.2022, Power Dept. Conductors LT Conductor damaged-3.00 KM under Kampur Rev. Circle reported by APDCL Kathiatoli Division, Dtd-21.05.2022, Power Dept. Transformers 4 nos. DTR damaged under Kampur Rev. Circle reported by APDCL Kathiatoli Division, Dtd-21.05.2022, Power Dept. Transformers 4 nos. DTR damaged under Kampur Rev. Circle reported by Fishery dpt. Nagaon - Fisheries/Pond 2Nos. of pond affected under Khagarijan Dev. Block reported by Fishery dpt. Nagaon - Fisheries/Pond 2Nos. of pond affected under Khagarijan Dev. Block reported by Irrigation department Dtd-21.05.2022, Irrigation Canal/Scheme Damaged Name of the Scheme-Dakarghat(Rt) reported by Irrigation department Dtd-21.05.2022, Irrigation Canal/Scheme Damaged Dakarghat (Left) submerged/damaged reported by Irrigation department Dtd-21.05.2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DYWS, submerged/damaged reported by Irrigation department Dtd-21.05.2022, Irrigation Canal/Scheme Damaged Solar powered MDTW scheme at Daklhinpat, submerged/damaged reported by Irrigation department Dtd-21.05.2022, Irrigation Canal/Scheme Damaged Solar powered MDTW scheme at Daklhinpat, submerged/damaged reported by Irrigation department Dtd-21.05.2022, Irrigation Canal/Scheme Damaged Illshimukh DTWS, submerged/damaged reported by Irrigation department Dtd-21.05.2022, Irrigation Canal/Scheme Damaged LIS from T
	department Dtd-21.052022, Irrigation Canal/Scheme Damaged Chalchali ELIS, submerged/damaged reported by Irrigation department Dtd-21.052022, Irrigation Canal/Scheme Damaged Total 19 nos. of TW points under PMKSY HKKP, submerged/damaged reported by Irrigation department Dtd-21.052022, Raha - Spot Sources Damaged Jarabari SS Limited under NFSA/PMGKY and MDM scheme (Godown) was submerged reported by cooperative society on 21/05/2022 Dhekiajuli - Culvert Approach Road Damaged As reported by PWRD Barchalla Territorial Road Sub Div.
Sonitpur	approach of Slab culvert no 5/1 at CH.4120.00M damaged at 2no Nurpurjut to Singri road. date 21.5.22
Udalguri	Udalguri - Culvert Approach Road Damaged The box cell culvert at Boscobari to Belguri connecting road damaged around 30m on 21.05.2022. GPS - Lat - 26.68577 Long - 92.019381., Fisheries/Pond As per report by Fishery Department, 16 nos. of villages namely Sarbaherua, Gerua, Simaluguri, Mahaliapara, Chutiapara, Chengelimari, Khajuabeel, Koupati Bagicha, Koupati, Jhakuapara, Medhipara, No. 1 Gormara, Kajiamati, Lowdang, Shibpur & Campikampi, Ranipukhuri constituting approximately 207 farmers and 22.3 ha. of water bodies are affected., Kalaigaon - Bridge Approach Road Damaged The bridge approach on Kalaigaon-Khoirabari road at village Ranthali Bagisha has deteriorated at both end on 22/05/2022 due to incessant rainfall in recent days covering a length of around 40 meters and breadth of 5 meters. Longitude: 91.93937, Latitude: 26.569258, Irrigation Canal/Scheme Damaged Bega FIS afflux bundh has breached at to 5.00m on 22/05/2022 at village Kalitapara due to overflow of water from river Bega covering a length of 10m and breadth of 3m. Longitude: 92.074845, Latitude: 26.58472, Irrigation Canal/Scheme Damaged Huduma FIS right canal embankment has breached at at down stream of toe wall on 22/05/2022 at village Pub Jangalpara due to overflow of water from river Nanoi covering a length of 10m and breadth of 3 m. Longitude: 92.923945, Latitude: 26.641365, Irrigation Canal/Scheme Damaged Kahiram Baruah FIS right canal embankment has breached at ch 400m on 22/05/2022 at village Majarchuba-Niz kalaigaon due to overflow of water from river Noa covering a length of 10m and breadth of 5m. Longitude: 91.98557, Latitude: 26.608567, Irrigation Canal/Scheme Damaged Bokrajhar FIS canal embankment has breached on 22/05/2022 at village Khas Bokrajhar due to overflow of water from river Kulshi covering a length of 10m and breadth of 2.5m. Longitude: 91.952075, Latitude: 26.550699, Spot Sources Damaged Construction of RCC Check Dam at Khoirabari Paddy field (SOPD-BTC) of Soil Conservation Department has damaged on 22/05/
Erosion District	Details Paghbor Venera Coop and Majorahar village Due to the land erasion by the river Probabilities
Barpeta	Baghbar - Kanara Gaon and Majorchar village Due to the land erosion by the river Brahmaputra, 8 families

		lost their houses in the village kanara gaon and 5 nos. Of families lost their house s in the village Majorchar,
		Total 13 families. (Reported by LM on 22/05/22) 55,
		Kalgachia - 1. Shawrachara Pather village, 2. Paschim Moinbari village 1.As per concerned LM report
		received on 22/05/22 in Shawrachara village total 4 nos of KUTCHA house are eroded, family affected- 4 Nos,
		land eroded- 2B-0K-0L(Basti land), location Co-ordinates- 26.26746, 90.83709. 2. As per concerned LM report
		received on 22/05/22 in Paschim Moinbari village total 6 Nos of KUTCHA houses are eroded, family affected-6
		Nos, land eroded- 2B-1K-0L(Basti land), location Co-ordinates- 26.25536, 90.75446. 47,
		Chenga - Roumari Gaon 1 no. house eroded by the river Brahmaputra at Roumari Gaon on 22.5.22 reported by
		Gaon Pradhan 6
		South Salmara Part - Borkalia Surjomoni, Char Katdanga pt-i As per information received from concerned Lot Mondal erosion occured on 21/05/22 to 22/05/2022. At follwing Villagees 1. Borkalia Surjomoni, 70 nos
	Dhubri	family has been eroded due to erosion by river Brahmaputra. Area lenth 2 km and breath 50 m. Lat-25.95 Long-
	Dilubii	90.03 2. Char Katdanga pt-i, 101 nos family has been eroded due to erosion by river Brahmaputra. Area lenth 2.5
		km breath 100 m. Lat - 25.85 Long-89.96 All affected families has been shifted to the safe place. 649
		Dibrugarh East - Behia Chetia-6 at downstream Mohonaghat As per information received from Water
	Dibrugarh	Resource Department Bank damage at behia chetia -6 downstream of Mohonaghat as on from 20-05-2022. Lat
		& Long - 27.28;25.13N/94.53.98.48E to 27.28.39;12.91 N/94.52.39;57.64E. Area damage 500m 0
		Matia - Baladmari Char Pt-IV Left Bank erosion of river Jaljali at Baladmari Char Pt-IV. Total reach length =
	Goalpara	300m (approx.) and Average Width = 3 m as on 22/05/2022 as received from Water Resources Department,
	F	Goalpara. 0
	17	Chandrapur - 1. Tatimara, 2. Hatisila Erossion took place on 17/05/20022 to till date 22/05/2022 Report
	Kamrup	received- Lot Mondal, Gaobura Tatimara Coordinates Longitude- 91.917294, Latitude- 26.243107 Hatisila
	(M)	Coordinates Longitude- 91.887997, Latitude- 26.219384 0
	Moriacan	Laharighat - Bhajhakhaiti gaon Erosion is observed on 22/05/22 at Bhojaikhaiti area of B.dyke.Rate of erosion
	Morigaon	2m per day. Temporary measure continuing like lunching of Bamboo bundle. 0
		Barkhetri - Bhangnamari River bank erosion of river Brahmaputra at Bhangnamari. Length 100m approx.
		Date 22/05/2022 30,
		Nalbari - 1.Erosion at Khudra Katara village 2. Erosion at village Goroimara As per report received from W.R
	Nalbari	Deptt on 22/05/2022 via whatsapp group, erosion takes place at village khudra katara and Goiroimara.
		Approximate length is 200.00 M at Khudra katara village and 600.00 M at village goiroimara 0,
		Paschim Nalbari - Amoni village near Babathan Erosion at Burhadia River LB. Information received from
		Water Resource Department on 21/05/2022 0
	Sonitpur	Dhekiajuli - Keherukhanda Pathar to No3 Rangagora village Severe erosion observed along the bank of the
		Belsiri river at Keherukhanda Pathar village. aprox length 850mtr. date 21.5.22 0
		Sadiya - 1. Majgaon (Amarpur) 2. Koilabasti 3. Gurung Basti 1. River Bank erosion is being observed at Majgaon (Amarpur) on the North Bank of River Datung since 12/05/2022 till 22/05/2022. As per information
		received from concerned Gaon Pradhan, the affected stretch is about 280m. 2. Active erosion is reported from
		Koilabasti area by Kundil river since 12/05/2022 till 22/05/2022. As per report received from the WR
		department and concerned Gaon Pradhan, the stretch area is 50m. (Lati 27.84688889, Long 95.71255556) 3.
		River bank erosion at Gurung Basti area reported by WR department since 15/05/2022 till 22/05/2022. the
		stretch area is 50m. (Lati 27.89750000, Long 95.77833333) 0,
		Doomdooma - 1. Village: Phelai NC (Nawkata NC), 2. Village: No. 3 Kordoiguri (Goriyating), 3. Village:
		No. 1 Kordoiguri(Darjijan), 4. Village: No. 2 Kordoiguri (Simoluguri Satra). 1. Severe erosion is being
		observed at Phelai(Nawkata) area on the left Bank of River Brahmaputra since 5/04/2022 till 22/05/2022. The
	Tinsukia	affected stretch is about 1500 m. 10 m offset remains as of now from the Brahmaputra Embankment. (Long:
		95.523457, Lati:27.745786) 2. River Bank erosion is being observed at No. 3 Kordoiguri on the left Bank of
		River Brahmaputra (Ananta Nallah)since 2/04/2022 till 22/05/2022. As per information received from concerned
		Lot Mandal and WR department officials the affected stretch is about 200 m in length. (Long: 95.468184, Lati:
		27.650410), population affected 122. 3. River Bank erosion is being observed at No. 1 Kordoiguri (Dorzijan) on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 22/05/2022. As per information
		received from concerned Lot Mandal and WR department officials the affected stretch is about 300 m in length.
		Long: 95.450531, Lati: 27.651217), population affected 37. 4. River Bank erosion is being observed at No.2
		Kordoiguri (Simoluguri Satra)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till
		22/05/2022. As per information received from concerned Lot Mandal and WR department officials, the affected
		stretch is about 400 m in length.(Long: 954505, Lati: 27.65196) 0
		Udalguri - 1. Baithonia 2. Medhipara 1. Erosion at Boithonia village on the left bank of Chandana river around
		300m on 21.05.2022. GPS - Lat - 26.695569 Long - 92.03972. 2. Erosion at Medhipara village on the right bank
	Udalouri	of Golondi river around 400m on 21.05.2022. GPS - Lat - 26.66844167 Long - 92.14337222. 0,
		Harisinga - Pub jangalpara Erosion continuing due to overflow of Huduma river at pub jangalpara village on
		1 201 35 2022 4 5 5 1 5 5 2 5 2 5 2
	Hdəlmisi	20th May 2022. Approximate damage 50ft./25ft. 0,
	Udalguri	Khairabari - Village: Malmura (Khashibari village) Severe erosion of paddy fields and households by
	Udalguri	Khairabari - Village: Malmura (Khashibari village) Severe erosion of paddy fields and households by Khasibari Dong / River (local name), due to intensive rainfall and flood. Approx. 180 M (in length) has been
	Udalguri	Khairabari - Village: Malmura (Khashibari village) Severe erosion of paddy fields and households by Khasibari Dong / River (local name), due to intensive rainfall and flood. Approx. 180 M (in length) has been eroded by the dong / river. Date of Occurrence: 20.05.2022 300,
	Udalguri	Khairabari - Village: Malmura (Khashibari village) Severe erosion of paddy fields and households by Khasibari Dong / River (local name), due to intensive rainfall and flood. Approx. 180 M (in length) has been eroded by the dong / river. Date of Occurrence: 20.05.2022 300, Kalaigaon - Sagunbahi near sagunbahi LP School The erosion has deteriorated on 22/05/2022 in the R/B of
Lond-1:3		Khairabari - Village: Malmura (Khashibari village) Severe erosion of paddy fields and households by Khasibari Dong / River (local name), due to intensive rainfall and flood. Approx. 180 M (in length) has been eroded by the dong / river. Date of Occurrence: 20.05.2022 300,
Landslide Urban Flood	Udalguri Nil Nil	Khairabari - Village: Malmura (Khashibari village) Severe erosion of paddy fields and households by Khasibari Dong / River (local name), due to intensive rainfall and flood. Approx. 180 M (in length) has been eroded by the dong / river. Date of Occurrence: 20.05.2022 300, Kalaigaon - Sagunbahi near sagunbahi LP School The erosion has deteriorated on 22/05/2022 in the R/B of