

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 02-08-2022 at 4:00 PM										
Particulars	Situation as o	on as on 02-08-2022 (in last 24 hours)									
Rivers flowing above Danger Level (as per	Rivers flowing	ng above dar	nger level	Beki (Road	l Bridge), Pagla	adiya (Nt R	oad Crossin	ıg)			
CWC bulletin issued at 8 AM)	Rivers flowing above highest flood level Nil										
District Affected	No. of Districts Affected	Name of Flood Affected Districts fected					Name of Urban Flood Districts				
	8	Bajali, Baksa, Chirang, Darrang, Dhemaji, Lakhimpur, Tamulpur, Udalguri									
No. Of Revenue Circles Affected	12										
	District	Total	Revenue								
1	Bajali	2	Sarupeta, Bajali								
	Baksa	1	Baska								
Name Of	Chirang	2		Bengtal, Bijni							
Revenue	Darrang	1	Sipajhar	~ 11							
Circles Affected	Dhemaji	2		Gogamukh							
Affected	Lakhimpur	1		Subansiri							
	Tamulpur	2	Goreswar Khairabari, Harisinga								
	Udalguri Total	12	Kilaliaba	iii, maiisiiiga							
	District	Total	Revenue Circle								
	Bajali	9	(Sarupeta 2), (Bajali 7)								
	Baksa	3	(Baska 3)								
	Chirang	10	(Bengtal 8), (Bijni 2)								
Villages	Darrang	10		doi 4), (Si							
Affected	Dhemaji	44		ji 6), (Gog							
	Lakhimpur	5	(Subans								
	Tamulpur	3	(Goreswar 3)								
	Udalguri	7	(Khairabari 4), (Harisinga 3)								
	Total	91									
	District	Male	Female	Children	Total Population	Populatio		Crop Area (in Hect.)	Crop Area Details		
	Bajali	3447	2990	789	7226	(Sarupeta (Bajali 1		0.00	(Sarupeta 0.00), (Bajali 0.00)		
	Baksa	0	0	0	0	(Baska 0)		14.00	(Baska 14.00)		
	Chirang	853	855	1521	3229	(Bengtal 2988), (Bijni 241)		0.00	(Bengtal 0.00), (Bijni 0.00)		
Population And Crop	Darrang	55	47	31	133	(Mangaldoi 0), (Sipajhar 133)		0.00	(Mangaldoi 0.00), (Sipajhar 0.00)		
Area Affected	Dhemaji	9105	9096	4501	22702	(Dhemaji 2713), (Gogamukh 19989)		4041.00	(Dhemaji 170.00), (Gogamukh 3871.00)		
	Lakhimpur	450	365	238	1053	(Subansii	ri 1053)	130.00	(Subansiri 130.00)		
	Tamulpur	204	160	61	425	(Goreswa		19.32	(Goreswar 19.32)		
	Udalguri	886	740	207	1833	(Khairabari 1450), (Harisinga 383)		119.00	(Khairabari 65.00), (Harisinga 54.00)		
	Total	15000	14253	7348	36601			4323.32			
Relief Camps	District	Total	Relief Ca			Relief Distribution Centres					
/ Centres	Chirang	2	2(Bijni 2) 0(Bijni 0)								
Opened	Dhemaji	6	6 2(Dhemaji 2, Gogamukh 0) 4(Dhemaji 2, Gogamukh 2)					ukh 2)			

	Lakhimpur	7	1(Subans	siri 1)			6(Subansi	ırı 6)		
	Udalguri	6	6(Khairabari 3, Harisinga 3)				0(Khairabari 0, Harisinga 0)			
	Total	21	11				10			
	District	Total	Revenue	e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disability
Inmates In Relief Camps	Chirang	241	(Bengtal 0), (Bijni 241)			94	89	58	0	0
	Dhemaji	327	(Gogamukh 0), (Dhemaji 327)			99	115	88	25	0
	Lakhimpur	38	(Subansi			12	13	13	0	0
	Udalguri	1250	(Khairab 348)	ari 902), (F	Harisinga	548	561	139	2	0
	Total	1856				753	778	298	27	0
Human Lives Lost - Confirmed	Nil									
Human Lives Lost Confirmed - Death Type Human Lives	Nil									
Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
	District	Total	Big	Small	Poultry					
	Bajali	1644	667	752	225					
Animals	Dhemaji	47204	14141	9802	23261					
Affected	Lakhimpur	4342	1435	927	1980					
	Udalguri	1590	800	768	22					
	Total	54780	17043	12249						
Animals	District	Total	Big	Small	Poultry					
Washed	Udalguri	30	0	8	22					
Away	Total	30	0	8	22					
Houses Damaged	Nil									
Rescue Operation	Nil									
		Rice (in	Dal (in	Salt (in	M. Oil (in	Cattle Feed -	Cattle Feed - Wheat	Cattle Fee	d Dies Dron	
Relief	District	Q)	Q)	Q)	L)	Green Fooder (in Q)	Bran (in Q)		u - Kice Dian	(in Q)
Relief Distributed	Chirang	Q) 44.18	8.82	2.65	264.51	Fooder (in Q) 0.00	Bran (in Q) 0.00	0.00	u - Rice Dian	(in Q)
	Chirang Dhemaji	Q) 44.18 47.05	8.82 8.75	2.65 2.62	264.51 261.55	Fooder (in Q) 0.00 0.00	Bran (in Q) 0.00 0.00	0.00	u - Rice Di an	(in Q)
	Chirang Dhemaji Lakhimpur	Q) 44.18 47.05 3.01	8.82 8.75 0.56	2.65 2.62 0.17	264.51 261.55 16.92	Fooder (in Q) 0.00 0.00 0.00	Bran (in Q) 0.00 0.00 0.00	0.00 0.00 200.00	u - Rice Dian	(in Q)
	Chirang Dhemaji Lakhimpur Udalguri	Q) 44.18 47.05 3.01 19.22	8.82 8.75 0.56 3.39	2.65 2.62 0.17 1.02	264.51 261.55 16.92 101.55	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00	Bran (in Q) 0.00 0.00 0.00 0.00 0.00	0.00 0.00 200.00 0.00	u - Aice Dian	(in Q)
	Chirang Dhemaji Lakhimpur Udalguri Total	Q) 44.18 47.05 3.01 19.22 113.46	8.82 8.75 0.56 3.39 21.52	2.65 2.62 0.17 1.02 6.46	264.51 261.55 16.92 101.55 644.53	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00	Bran (in Q) 0.00 0.00 0.00	0.00 0.00 200.00	u - Aice Dian	(in Q)
	Chirang Dhemaji Lakhimpur Udalguri Total District	Q) 44.18 47.05 3.01 19.22 113.46 Baby Foo	8.82 8.75 0.56 3.39 21.52	2.65 2.62 0.17 1.02 6.46 Baby Foo	264.51 261.55 16.92 101.55 644.53 d Solid	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 Others	Bran (in Q) 0.00 0.00 0.00 0.00 0.00 0.00	0.00 0.00 200.00 0.00	u - Aice Dian	(in Q)
	Chirang Dhemaji Lakhimpur Udalguri Total District Chirang	Q) 44.18 47.05 3.01 19.22 113.46 Baby Foo 0.00-Q	8.82 8.75 0.56 3.39 21.52	2.65 2.62 0.17 1.02 6.46 Baby Foo 0.00-Q, 8.0	264.51 261.55 16.92 101.55 644.53 d Solid	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 Others Candle-3-	Bran (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 4.00-Pkt	0.00 0.00 200.00 0.00 200.00	u - Aice Dian	(in Q)
	Chirang Dhemaji Lakhimpur Udalguri Total District	Q) 44.18 47.05 3.01 19.22 113.46 Baby Foo	8.82 8.75 0.56 3.39 21.52	2.65 2.62 0.17 1.02 6.46 Baby Foo	264.51 261.55 16.92 101.55 644.53 d Solid	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others Candle-3d Tarpulin-POTATO Kg; CAN DISPOSA 2.00-Kg; Pieces; D 20.00-Pkt	### Bran (in Q) 0.00 0.00 0.00 0.00 4.00-Pkt 22.00-Piece 0-60.00-Q; S DLE-30.00 DRY CHIL ETERGEN' ETERGEN' ETER LEA	0.00 0.00 200.00 0.00 200.00 200.00 SOYABEAN-Pkt; BISCUITE & GLASS LI-1.00-Kg; T POWDER	5.00-Kg; ON T-60.00-Pkt; 5-700.00-Piece BATHING SC -50.00-Pkt; M g; SUGAR-4.0	ION-20.00- es; HALDI- DAP-50.00- AXO-
Relief Distributed Others	Chirang Dhemaji Lakhimpur Udalguri Total District Chirang Dhemaji	Q) 44.18 47.05 3.01 19.22 113.46 Baby Foo 0.00-Q 0.00-Q	8.82 8.75 0.56 3.39 21.52 d Liquid	2.65 2.62 0.17 1.02 6.46 Baby Foo 0.00-Q, 8.0	264.51 261.55 16.92 101.55 644.53 d Solid 00-Pkt	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others Candle-3d Tarpulin-POTATO Kg; CAN DISPOSA 2.00-Kg; Pieces; D 20.00-Pkt BAR-10.0 Mosquito 156.00-Pl	Bran (in Q) 0.00 0.00 0.00 0.00 0.00 4.00-Pkt 22.00-Piece 0-60.00-Q; St DLE-30.00 ABLE PLAT DRY CHILL ETERGEN' t; TEA LEA 00-Pieces; Mo Coil-50.00	0.00 0.00 200.00 0.00 200.00 200.00 s GOYABEAN-Pkt; BISCUITE & GLASS LI-1.00-Kg; T POWDER VES-1.00-K MATCH BOX Pkt; Matches Napkin-116.0	5.00-Kg; ON T-60.00-Pkt; 5-700.00-Piece BATHING SC -50.00-Pkt; M g; SUGAR-4.0	ION-20.00- es; HALDI- DAP-50.00- AXO- 00-Kg; VIM
Distributed Relief Distributed	Chirang Dhemaji Lakhimpur Udalguri Total District Chirang Dhemaji Lakhimpur	Q) 44.18 47.05 3.01 19.22 113.46 Baby Foo 0.00-Q 0.00-Q 0.00-Q	8.82 8.75 0.56 3.39 21.52 d Liquid	2.65 2.62 0.17 1.02 6.46 Baby Foo 0.00-Q, 8.0 0.00-Q	264.51 261.55 16.92 101.55 644.53 d Solid 00-Pkt	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others Candle-3d Tarpulin-POTATO Kg; CAN DISPOSA 2.00-Kg; Pieces; D 20.00-Pkt BAR-10.0 Mosquito 156.00-Pl	Bran (in Q) 0.00 0.00 0.00 0.00 0.00 4.00-Pkt 22.00-Piece 0-60.00-Q; State 30.00 ABLE PLAT DRY CHIL ETERGEN't; TEA LEA 00-Pieces; Mo Coil-50.00 kt; Sanitary	0.00 0.00 200.00 0.00 200.00 200.00 s GOYABEAN-Pkt; BISCUITE & GLASS LI-1.00-Kg; T POWDER VES-1.00-K MATCH BOX Pkt; Matches Napkin-116.0	5.00-Kg; ONI T-60.00-Pkt; 5-700.00-Piece BATHING SC -50.00-Pkt; M g; SUGAR-4.0 K-8.00-Pkt s-20.00-Pkt; C	ION-20.00- es; HALDI- DAP-50.00- AXO- 00-Kg; VIM

Damaged - Embankment	Darrang	1	Mangaldoi - Left guide bank of Kushik Naharbari FIS under Irrigation. Under Mangaldai Revenue Circle As reported by Irrigation department Left guide bank of Kushik Naharbari FIS				
Affected			has been submerged due to flood water. Dated 02/08/2022. (Long - 91.940000, Lat - 26.500000) Teok - Jhanji LB (Robi Bora Gaon) Robi Bora Gaon (Robi Gaon) Distance: 360m Damaged by				
	Jorhat	3	river water of Jhanji river. Date: 01-08-2022 (Long - 94.436699, Lat - 26.859024), Jhanji RB (Boralimora) Boralimora (2 No Kawoimari) Distance: 150m Damaged by river water of Jhanji river. Date: 01-08-2022 (Long - 94.402568, Lat - 26.913333),				
			Jhanji LB (Napamua) Napamua Gaon (Bonai Pathar) Distance: 300m Damaged by river water of Jhanji river. Date: 01-08-2022 (Long - 94.450581, Lat - 26.880940)				
	Total	4					
	District	Number	Details Baska - Village Road at Ahopa Pub Chuburi Ahopa Damage of Village Road at Ahopa Pub				
	Baksa	1	Chuburi due to incessant rainfall on 1/08/2022 (Long - 26.704447, Lat - 91.314497)				
Infrastructure Damaged - Road	Barpeta	16	Sarthebari - Rajaghat Barsimla Road to Kaharpara Kabarsthan Road Barsimla Road submerged completely. Road suface & shoulders damaged from 1st to 3rd Km. Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.131518, Lat - 26.466535), Balapara to Kirkira Road. Balapara Road completely submerged. Road embankment eroded by the River Kaldia at 1st & 2nd Km.Road surface and shoulders damaged . Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.146510, Lat - 26.430369), Balapara to Rampur (Rajakhat Barsimla)Segment 2. Rampur Road submerged from 10th to 15th Km in stretches. Road surface with shoulders badly damaged. Approaches of RCC bridges damaged. Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.159143, Lat - 26.423438), Bharegaon Hatirtari Road. Bharegaon Road completely submerged. Road surface with shoulder badly damaged from 2nd to 4th Km. Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.13614, Lat - 26.423438), Bharegaon Hatirtari Road. Bharegaon Road completely submerged. Road damaged at 1st & 2nd Km. Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.132509, Lat - 26.466181), Naligaon (Ear) to Newlarbhita(Eratrari). Naligaon Road completely submerged. Road damaged at 1st & 2nd Km. Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.163734, Lat - 26.375195), Road from Debra to Golibandha via Niz Saldah Road. Golibandga-Debra- Nizsaldah Road completely submerged. Road suface and formation damaged. Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.143716, Lat - 26451316.000000), Chaparbori to Amdah Gaon via Fingua Gaon. Chaparbari Road completely submerged. Road suface and formation damaged. Reported by AEE, PWRD on 17.06.2022 (Damaged occurred on 17.06.2022) (Long - 91.148504, Lat - 26.439051), Rajakhat Barsimla Road to Moriom Chupa. Barsimla Road comp				
	Bongaigaon	11	Popragaon (Ujanpara to Bhatipara) Side berm erroded and ICBP damaged at ch. 1800.00m. Reported by PWRD Bongaigaon, date- 02.08.2022 (Long - 90.609744, Lat - 26.511317), Manikpur - NH-31 to Darkinamari Road NH-31 to Darkinamari Road Side shoulder damaged at 1st, 2nd & 3rd km, Reported by PWRD, Bongaigaon . date-02.08.2022 (Long - 90.638191, Lat - 26.492250), Sidalsuti Gerukabari road Sidalsuti Gerukabari road Side berm side slopes damaged on various stretches of 1st km. Reported by PWRD, Bongaigaon . date-02.08.2022 (Long - 90.692183, Lat - 26.456500), Patiladoha Lungjhar road Patiladoha Lungjhar road Road embankment and side berm badly				

Bridge Infrastructure Damaged - Wildlife District Other Details Baska - Culvert Approach Road Damaged Slab culvert approach road and slab culvert damage at Pub Athiabari to Bennabari road at village Pub Athiabari on 1/08/2022. Co-ordinate: 26.612807, 91.289411, Agri Bundh Damaged Amarabati Dakhin supa dong near Kamleswar Kalitas Land agri bund damage on 1/08/2022. Co-ordinate: 26.671892, 91.3614342, Agri Bundh Damaged Charaimari to Nahorbari agri bund damage at village Charaimari with Dekadong rivulet, on 1/08/2022, Co-ordinate: 26.67900, 91.308187., Barama - Bridge Approach Road Damaged A wooden bridge approach damaged at vill: Puransripur near				damaged from ch. 500.00m to ch. 2000.00m and road surface badly damaged from ch. 0.00m to				
Tilapara Ambari kacharipeit road Tilapara Ambari kacharipeit road Rober Oz. 8, 2022 Cong. 9-0,705912, Lat. 2, 25,344645). Chakla kokila PMGSY road Chakla kokila PMGSY road Side berm side slopes and hard crust danaged on various stretches of 1st, 2nd & 3rd km. Reported by PWRD Bongaigano, date- (20,82022) (Long. 9-0,805178, 1000). Chakla Antola road Chakla Amtola road Approach hamped of Culvert No. 1/1 at 1st km. Reported by PWRD Bongaigano, date- (20,82022) (Long. 9-0,860256, Lat. 2-2537618).000000). Approach road to Kakoijana Fco Tourism Spor Approach road fco Kuntur Approach Kabour Ap				(Long - 90.800604, Lat - 26.496133), Gerukabari Kirtanpara road Gerujabari Kirtanpara road Road submerged at 10th and 11th km. Average submergence depth 60 cm. Reported by PWRD, Bongaigaon. date-02.08.2022 (Long - 90.753841, Lat - 26.410846), Srijangram - T01 to Chotobaregarh road T01 to Chotobaregarh road Side shoulder erroded at 1st and 2nd km. Reported by PWRD Bongaigaon, date- 02.08.2022 (Long - 90.707121, Lat -				
damaged on various stretches of 1st, 2nd & 3rd km. Reported by PWRD Bongaigaon, date- 0.02.8.7222 (LGag. 9.0.83725.). kar. 26374718.000000). Chakfa Amtola road Chakfa Amtola road Approach damaged of Culvert No. 1/1 at 1st km. Reported by PWRD Bongaigaon, date- 0.02.8.7222 (LGag. 9.0.836256. Lat. 2637818.1000000). Approach road to kakoijana Eco Tourism Spot Approach of STB En. 05.1 damaged. Reported by PWRD Bongaigaon, date- 02.08.2021 (Long. 9.0.64559. Lat. 26427792.000000). Borghola Kirtappar road Borghola Kirtappar road Approach of RCC Box Culvert No. 1/1 damaged. Reported by PWRD Bongaigaon, date- 02.08.2022 (Long. 90.434700, Lat. 2233.1000000) Siesiborgaon. PWD Road from Kauchii to Jengrai Jak. Ch. 2100.00 M to 2500.00 M The road tuburerge, dated not 1.482.002 and propara road Approach of RCC Box Culvert No. 1/1 damaged. Reported by PWRD Road, Baligaor = Bordoibarn. (PMGSY Package no. AS-04-77) [From Ch. 4100.00 n to Ch. 4200.00 n Road Bread 400 netres (1.0.00 mg. 94.166678), Lat. 27.359213), PWRD Road, Bordoibarn. Appara PWD Timali to Napum Kaiborta via Gurarhali At Ch. 650.00 m and Ch. 8200.00 m Road Bread 400 netres (1.0.00 mg. 94.16607), Lat. 27.359213), PWRD Road, Jorgan McLore. Jorgan Road PWRD Road, Jorgan McLore. Jorgan Road Road Road Road Road Road Road Road				Tilapara Ambari kacharipeti road Tilapara Ambari kacharipeti road Road embankment damage at 4th km. Reported by PWRD Bongaigaon, date- 02.08.2022 (Long - 90.705912, Lat -				
Reported by PWRD Bongaigagon, date- 0.20 8.2022 (Long9.0860256, Lat - 26371618 0000000). Approach of Arch Bridge No.67 and approach of SAP Brish as Eo Tourism Spot Approach of Arch Bridge No.67 and approach of SAPT Brish o.57 damaged. Reported by PWRD Bongaigagon, date- 0.20 8.2022 (Long9.0843700, Lat - 26231.000000). Borghola Kirtanpara road Borghola Kirtanpara road Approach of RCC Box Culvert No. 1/1 damaged. Reported by PWRD Bongaigagon, date- 0.20 8.2022 (Long9.04.34700, Lat - 26231.000000). Sissiborgaon. PWD Road from Kamechi to Jengrai. Arc Ch.200.000 Mto 2500.000 Mt The road submerge, dated on 1-08-2022. Length around 400 meters (Long9.4.546757, Lat27.567594). Gogamukh - PWRD Road, Badigaon. Bordolban, (PMGSY Package no. As 04-77) From Ch. 4100.000 mto Ch.4320.000 mt Road washed away for a length of 100.000 m. 2008.2022 (Long94.346757, Lat27.354152). PWRD Road, Bordolban Napam PWD Triniali to Napam Kaiborta via Gurathali At Ch.650.00 m and Ch.820.00 mto Road Breached at Ch.650.00 m and Ch.820.00 mto Road Breached at Ch.650.00 mto Ch.1825.00 mto Ch.1825.00 mto Ch.1825.00 mto Ch.1825.00 mto Ch.4450.00 mto Ch.2920.00 mto K from Ch.1525.00 mto Ch.1825.00 mto Ch.1825.00 mto Ch.4450.00 mto Ch.2920.00 mto K from Ch.1525.00 mto Ch.1825.00 mto C				damaged on various stretches of 1st, 2nd & 3rd km. Reported by PWRD Bongaigaon, date-02.08.2022 (Long - 90.837253, Lat - 26374718.000000),				
dumaged. Reported by PWRD Bongaigaon, date- 02.08.2022 [(Long = 90.434700, Lat - 26231.000000)				Reported by PWRD Bongaigaon, date- 02.08.2022 (Long - 90.860256, Lat - 26376181.000000), Approach road to Kakoijana Eco Tourism Spot Approach road to Kakoijana Eco Tourism Spot Approach of Arch Bridge No.6/1 and approach of SPT Br.No.5/1 damaged. Reported by PWRD Bongaigaon, date- 02.08.2022 (Long - 90.654539, Lat - 26427792.000000),				
Submerge, dated on 1-08-2022. Length around 400 meters [Long - 94-610862, Lat - 27.567594), Gogamukh - PWRD Road, Baligason - Bordolisham (PMGSY Package no. AS-04-77) From Ch. 4100.00 m to Ch.4200.00 m Road washed away for a length of 100.00 m. Dated : 02/08/2022 (Long - 94.346737, Lat - 27.354152), PWRD Road, Bordolisham Napam PWD Tiniali to Napam Kaiborta via Gurathali At Ch.650.00 m and Ch.820.00 m Road Breached at Ch.650.00 m and Ch.820.00 m Dated : 02/08/2022 (Long - 94.36691, Lat - 27.339213), PWRD Road, Dirpa NLGR - Jairampur via Nalbari. (PMGSY Package no. AS-04-45) (Tarajan Bridge) From Ch.450.00 m to Ch.9290.00 m & from Ch.15250.00 m Surface of road damaged from Ch.4450.00 m to Ch.9290.00 m & from Ch.15250.00 m Surface of road damaged from Ch.4450.00 m to Ch.9290.00 m & from Ch.15250.00 m PWRD Road, Even Road The Ch.000.00 m Road Breached at Ch.6600.00 m Road Breached at				damaged. Reported by PWRD Bongaigaon, date- 02.08.2022 (Long - 90.434700, Lat - 26231.000000)				
Dhemaji 6 PWRD Road, Dirpa NLGR - Jairampur via Nalbari. (PMGSY Package no. AS-04-45) (Tarajan Bridge) From Ch.4450.00 m to Ch.9290.00 m & from Ch.15250.00 m to Ch.18250.00 m Surface of road damaged from Ch.4450.00 m to Ch.9290.00 m & from Ch.15250.00 m to Ch.18250.00 m Dated : 0208/2022 (Long - 94.336900, Lat - 27.521300), PWRD Road, Kowpatani - Nalbari Road At Ch.7600.00 m Road Breached at Ch.7600.00. Dated : 0208/2022 (Long - 94.381272, Lat - 27.508490), PNRD Road, From P.W.D. road to Bodoti Paddy Pather At Ch. 000m to 420m at Bodoti Damaged of of Gravel road from P.W.D. road to Bodoti Paddy Pather. Dated: 0208/2022 (Long - 94.35187, Lat - 27.519299) Jorhat				submerge, dated on 1-08-2022. Length around 400 meters (Long - 94.610862, Lat - 27.567594), Gogamukh - PWRD Road, Baligaon — Bordoibam. (PMGSY Package no. AS-04-77) From Ch. 4100.00 m to Ch.4200.00 m Road washed away for a length of 100.00 m. Dated : 02/08/2022 (Long - 94.346757, Lat - 27.354152), PWRD Road, Bordoibam Napam PWD Tiniali to Napam Kaiborta via Gurathali At Ch.650.00 m and Ch.820.00 m Road Breached at Ch.650.00 m and Ch.820.00 m Dated : 02/08/2022 (Long -				
Jorhat		Dhemaji	6	PWRD Road, Dirpa NLGR - Jairampur via Nalbari. (PMGSY Package no. AS-04-45) (Tarajan Bridge) From Ch.4450.00 m to Ch.9290.00 m & from Ch.15250.00 m to Ch.18250.00 m Surface of road damaged from Ch.4450.00 m to Ch.9290.00 m & from Ch.15250.00 m to Ch.18250.00 m. Dated: 02/08/2022 (Long - 94.336900, Lat - 27.521300), PWRD Road, Kowpatani – Nalbari Road At Ch.7600.00 m Road Breached at Ch.7600.00. Dated: 02/08/2022 (Long - 94.381272, Lat - 27.508490), PNRD Road, From P.W.D. road to Bodoti Paddy Pather At Ch. 0.00m to 420m at Bodoti Damaged of Gravel road from P.W.D. road to Bodoti Paddy Pather. Dated: 02/08/2022 (Long -				
Lakhimpur 1 Subansiri - Siyalmari to Sagunpara road Siyalmari to Sagunpara road is submerged (L-500M) On dated 02-08-2022, as reported by Dhakuakhana road division (Long - 0.000000, Lat - 0.000000)		Jorhat	1	Titabor - Gar Ali Road Govindpur TE Damage Length : 20 M Approx Dated : 02/08/2022 Source : PWD Roads, Jorhat Dergaon Titabar Territorial Roads (Long - 94.204209, Lat -				
Infrastructure Damaged - Bridge Infrastructure Damaged - Will Wildlife District Damaged District		Lakhimpur	1					
Damaged - Bridge Infrastructure Damaged - Wildlife District District District District Damaged - Others District Damaged - Others District District Damaged - Others Damaged - Others Damaged - Others District Damaged - Others Damaged - O	I C	Total	36					
Damaged - Wildlife District Baska - Culvert Approach Road Damaged Slab culvert approach road and slab culvert damage at Pub Athiabari to Bennabari road at village Pub Athiabari on 1/08/2022. Co-ordinate: 26.612807, 91.289411, Agri Bundh Damaged Amarabati Dakhin supa dong near Kamleswar Kalitas Land agri bund damage on 1/08/2022. Co-ordinate: 26.671892, 91.3614342, Agri Bundh Damaged Charaimari to Nahorbari agri bund damage at village Charaimari with Dekadong rivulet, on 1/08/2022. Co-ordinate: 26.67900, 91.308187., Barama - Bridge Approach Road Damaged A wooden bridge approach damaged at vill: Puransripur near Puransripur Dewalay. Date of occurrence: 01/08/22. Lat: 26.556141 Lon: 91.324152 Sarthebari - PWSS Damaged Niz- Barala PWSS (Pipe Line & FHTC), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), PWSS Damaged Neularbhita PWSS (Pipe Line), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), Barpeta - Bridge Approach Road Damaged Br. Approach damage 25.00m "Latitude - 26.317475 Longitude - 91.011905" date of occurrence- 23.06.2022, PWRD Barpeta	Damaged - Bridge	Nil						
Baksa - Culvert Approach Road Damaged Slab culvert approach road and slab culvert damage at Pub Athiabari to Bennabari road at village Pub Athiabari on 1/08/2022. Co-ordinate: 26.612807, 91.289411, Agri Bundh Damaged Amarabati Dakhin supa dong near Kamleswar Kalitas Land agri bund damage on 1/08/2022. Co-ordinate: 26.671892, 91.3614342, Agri Bundh Damaged Charaimari to Nahorbari agri bund damage at village Charaimari with Dekadong rivulet, on 1/08/2022, Co-ordinate: 26.67900, 91.308187., Barama - Bridge Approach Road Damaged A wooden bridge approach damaged at vill: Puransripur near Puransripur Dewalay. Date of occurrence: 01/08/22. Lat: 26.556141 Lon: 91.324152 Sarthebari - PWSS Damaged Niz- Barala PWSS (Pipe Line & FHTC), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), PWSS Damaged Neularbhita PWSS (Pipe Line), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), Barpeta - Bridge Approach Road Damaged Br. Approach damage 25.00m "Latitude - 26.317475 Longitude - 91.011905" date of occurrence- 23.06.2022, PWRD Barpeta	Infrastructure Damaged - Wildlife	Nil						
Baksa		District						
Damaged - Others Puransripur Dewalay. Date of occurrence: 01/08/22. Lat: 26.556141 Lon: 91.324152 Sarthebari - PWSS Damaged Niz- Barala PWSS (Pipe Line & FHTC), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), PWSS Damaged Neularbhita PWSS (Pipe Line), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), Barpeta - Bridge Approach Road Damaged Br. Approach damage 25.00m "Latitude - 26.317475 Longitude - 91.011905" date of occurrence- 23.06.2022, PWRD Barpeta	Infrastructure	Baksa	Athiabari to Bennabari road at village Pub Athiabari on 1/08/2022. Co-ordinate: 26.612807, 91.289411, Agri Bundh Damaged Amarabati Dakhin supa dong near Kamleswar Kalitas Land agri bund damage on 1/08/2022. Co-ordinate: 26.671892, 91.3614342, Agri Bundh Damaged Charaimari to Nahorbari agri bund damage at village Charaimari with Dekadong rivulet, on 1/08/2022, Co-ordinate: 26.67900, 91.308187.,					
Barpeta Barpeta Sarthebari - PWSS Damaged Niz- Barala PWSS (Pipe Line & FHTC), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), PWSS Damaged Neularbhita PWSS (Pipe Line), Reported by AEE, PHE on 01.08.2022, (damaged occured on 27.06.2022), Barpeta - Bridge Approach Road Damaged Br. Approach damage 25.00m "Latitude - 26.317475 Longitude - 91.011905" date of occurrence- 23.06.2022, PWRD Barpeta	Damaged -							
91.011905" date of occurrence- 23.06.2022, PWRD Barpeta	Others	Barpeta	Sartheba 01.08.202 PWSS Da on 27.06.2	ri - PWSS Damaged Niz- Barala PWSS (Pipe Line & FHTC), Reported by AEE, PHE on 22, (damaged occured on 27.06.2022), umaged Neularbhita PWSS (Pipe Line), Reported by AEE, PHE on 01.08.2022, (damaged occured 2022),				
Chirang Bijni - Culvert Approach Road Damaged As reported by PWD, Bijni(R&B) Sub Division, RCC culvert			91.01190	5" date of occurrence- 23.06.2022, PWRD Barpeta				
	1	Chirang	Bijni - Cu	llvert Approach Road Damaged As reported by PWD, Bijni(R&B) Sub Division, RCC culvert				

damaged at Tangabari II of Tangabari I to Tangabari II road on 31-07-2022. Length=6mtr, Breadth=7.5 mtr, Depth=3 mtr. Latitude=26.5717 Longitude=90.608865
Gogamukh - Bridge Approach Road Damaged PWRD Road, NH-15 to Kawpatani Tiniali, From 0.00 m to Ch.2000.00 m, Longitude: 94.379684 E Latitude: 27.507468 N, Erosion of Bridge approach occured at Ch.7370.00 m. Dated 02/08/2022,
Bridge Approach Road Damaged PWRD Road, Mohoricamp to Daporijoo Road (Br.No3/1), At Ch.2100.00 m Longitude: 94.319723 E Latitude: 27.485404 N, Erosion of Bridge Approach of Br. No3/1 at Ch.2100.00 M, Dated: 02/08/2022,
Bridge Approach Road Damaged PWRD Road, Dirpa NLGR - Jairampur via Nalbari. (PMGSY Package no. AS-04-45) (Tarajan Bridge), At Ch.12000.00 m (at Tarajan Bridge Approach Nalbari Side) Longitude: 04.406387 E Latitude: 27.537405 N, Erosion of Bridge Approach (Tarajan Bridge) towards Nalbari Side at Ch.12000.00 m, Dated: 02/08/2022, Bridge Approach Road Damaged PWRD Road, Bordoibam Napam PWD Tiniali to Napam Kaiborta via Gurathali, At Ch.100.00 m(Bridge Approach) and Ch.150.00 m Longitude: 94.361635 E Latitude:
27.339238 N, Erosion of Bridge Approach at Ch.100.00 m and erosion of road at Ch.150.00 m, Dated: 02/08/2022, Fisheries/Pond 5 nos of Pond (1.4 Hectare) affected in Bogolijan Sapekhati Village, 17 nos of Pond (1.8 Hectare) affected in Khana Krishnapur Village, 7 nos of Pond (.9 Hectare) affected in No.2 Paniemorani Village, Fishery Department Data, Dated 02/08/2022,
Elementary Schools Damaged 107 No. Chutiakari LP School, Dated: 02/08/2022, Elementary Schools Damaged Sapekhati Bor Namghar, Village: Sapekhati, Longitude: 94.399208 Elementary Schools Damaged Sapekhati Bor Namghar, Village: Sapekhati, Longitude: 94.399208 Elementary Schools Damaged Sapekhati Bor Namghar, Village: Sapekhati, Longitude: 94.399208
Latitude: 27.371589 N, Dated: 01/08/2022
Bhawraguri - Culvert Approach Road Damaged AS REPORTED BY AEE, PWRD, KACHUGAON RR SUB-DIVISION DUE TO INCESSANT HEAVY RAINFALL FROM 31ST JULY /2022 TO TILL TODAY THE FOLLOWING ROADS/CULVERTS/BRIDGES AND ROAD FORMATIONS ARE BADLY DAMAGED : 1. IMMEDIATE RESTORATION OF CULVERT NO 6/2 APPROACH DAMAGED AT 6TH KM. ON KACHUGAON BHOWRAGURI PWD ROAD AT KASHIMARI, Gossaigaon - Damaged SPT Bridge AS REPORTED BY AEE PWD KACHUGAON RURAL ROADS SUBDIVN. KACHUGAON ON 01-08-2022, IMMEDIATE RESTORATION OF SPT BRIDGE NO. 1/3 WASHED OUT LENGTH 30.00M ON NH 31C TO HATIGARH PART II ROAD WAS BADLY
DAMAGED, Damaged SPT Bridge AS REPORTED BY AEE PWD KACHUGAON RURAL ROADS SUB DIVN. KACHUGAON ON 01-08-2022, IMMEDIATE RESTORATION OF SPT BRIDGE NO. 1/3 WASHED OUT LENGTH 60.00M ON PWD ROAD NASRAIBIL SANTAL BOSTI TO DOLGAON ADJOINT VILLAGE WAS BADLY DAMAGED, Damaged RCC Bridge AS REPORTED BY AEE PWD KACHUGAON RURAL ROADS SUB DIVN.
KACHUGAON ON 01-08-2022, IMMEDIATE RESTORATION ON BONGAON Y POINT TO GAMBARIGHAT ROAD FORMATION DAMAGED AND 2 NOS. RCC BOX CULVERT NO. 1/2 BADLY DAMAGED AND CAUSE WAT AT GINDRINALA FULLY DAMAGEDWAS BADLY DAMAGED, Damaged RCC Bridge AS REPORTED BY AEE PWD KACHUGAON RURAL ROADS SUB DIVN. KACHUGAON ON 01-08-2022, IMMEDIATE RESTORATION ON BONGAON SSB, BOP TO BALLAMJHORA ROAD BADLY DAMAGED RCC BOX CULVERT NO. 1/1 APPROACH WAS BADLY
DAMAGED, Damaged RCC Bridge AS REPORTED BY AEE PWD KACHUGAON RURAL ROADS SUB DIVN. KACHUGAON ON 01-08-2022, IMMEDIATE RESTORATION ON SAPKATA FOREST RESERVE/RIPU TO DHONOGHAT DAMAGED 1 NO. 2 CELL RCC BOX CULVERT 1KM ROAD WAS DAMAGED, Bridge Approach Road Washed Away AS REPORTED BY AEE PWD KACHUGAON RURAL ROADS SUB DIVN. KACHUGAON ON 01-08-2022, IMMEDIATE RESTORATION ON GURUFELA RAJADABRI ROAD TO HATIGARH WOODEN BRIDGE (BR NO. 1/1) DAMAGED AND WASHED DUT FOR HEAVY RAINFALL
Subansiri - Fisheries/Pond FISHERY AFFECTED AT MOHBAL, BORDOIBAM, BILMUKH, RAIDONGIA, SAPEKHATI, KESERUGURI, KALABARI, GA- DANGERCHUCK, BANGKLENG, DAKHIN GAON, MEDAK GAON, BALIYANI GAON, NO 1 GHILAMARA, DIGHALI BASTI, NA- PAM BEBEJIA, SONARI CHAPORI AREA. TOTAL FARM FAMILY AFFECTED 108NOS AND AREA- 25.78 HA AS REPORTED BY FDO, DHAKUAKHANA ON 02-08-2022
Details
Baska - Pakhamara Erosion on the R/B of River Morapagladia at village Pakhamara near Ganesh Temple. Length of erosion: 315 metres approx. Date: 1/08/2022 0, Jalah - Alengamari Approximately 300 meter at alengamari revenue village at the left bank of river beki has been eroding as per field report from LM and VCDC chairman on 02 August 2022 15
Manikpur - Bashbari Part 2 Erosion of around 1300 mtr. had occurred w.ef 17/06/2022 to 30/06/2022.Two 2) Nos of Relief camp opened due to the said erosion (1) Tilpukhuri ME Madrasa "Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 no. Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 01.07.2022/Bashbari no 2 Temp.Shelter, Male=55, Femele=45, Child=25,(Toatl=125,Latitude-26.4709483 Longitude-90.748884)Total Inmates 843. Medical Team- 2 Nos. date- 02.08.2022, Total Population-843 0, Srijangram - Tinkonia part III (90.64464 26.236926)and Santoshpur part III (90.736551 26.301471) As on
School, since 17 Child=2 late- 02

		have been dismantled at Tinkonia part III and 3 nos. Of houses have been dismantled at Santoshpur part III. The erosion has taken place on the river bank of Manas -Brahmaputra in a length of 1.5 km approximately at Tinkonia part III and on river bank of Manas in a length of 1 km approximately at Santoshpur part III. 68						
	Chirang	Bijni - Koliagaon, Sisubari As reported by Chirang W.R. Division, Kajolgaon, bank erosion of L/B of riv Nangalbhanga due to river Nangalbhanga at Koliagaon. Length=300 mtr(approx), Breadth=3.20 mtr(approx) Depth=2.30 mtr(approx). Date of Occurrence=1-08-2022. (Longitude=90.558413 Latitude=26.614272) As reported by Chirang W.R. Division, Kajolgaon, erosion on L/B of offshoot channel due to Kanamakra rive sisubari. Date of Occurrence=01-08-2022 Length=1050 mtr Breadth=45 mtr Depth=3.10 mtr.(Longitude=90.3480 Latitude=26.4131). 0						
	Kamrup	Hajo - Sasterghat on R/B of River Puthimari As per report of AEE, Hajo WR Sub-Division, Erosion occured aproximate 300 m on dated 1-08-2022, and visited with Gaonpradhan and AEE, WR Hajo Sub-Division 0						
	Kokrajhar	Bhawraguri - BALAPARA PT II AS REPORTED BY IN-CHARGE CONTROL ROOM GOSSAIGAON WR DIVISION, GOSSAIGAON ON DATED 02-08-2022 1. SEVERE BANK EROSION OBSERVED AT VILLAGE BALAPARA BAZAR U/S OF RIVER TIPKAI ON R/B LENGTH 300 M 0, Dotma - Vill- Bangaljhora Dated: 02/08/2022 Bank erosion at village Bangaljhora by river Saralbhanga. Length- 150M (Approx.) 0, Gossaigaon - 1. BOSHGAON FV, 2. SURENDRAPUR NAOGHAT, 3. UPENDRAPUR, 4. BALLAMJHORA FV, 5. NO.1 MAJADABRI, 6. SORAIGAON, 7. DUMBAJAR AS REPORTED BY GOSSAIGAON WR SUB-DIVN. GOSSAIGAON ON 02-08-2022, 1. SEVERE BANK EROSION OBSERVED AT VILLAGE BOSHGAON FV OF RIVER JANALI ON R/B LENGTH 260M 2. SEVERE BANK EROSION OBSERVED AT VILLAGESURENDRAPUR NAOGHAT OF RIVER SONKOSH ON L/B LENGTH 280M 3. SEVERE BANK EROSION OBSERVED AT VILLAGE UPENDRAPUR OF RIVER BURACHARA ON R/B LENGTH 280M 4. SEVERE BANK EROSION OBSERVED AT VILLAGE BALLAMJHORA FV OF RIVER SINDRI ON L/B LENGTH 200M 5. SEVERE BANK EROSION OBSERVED AT VILLAGE BANK EROSION OBSERVED AT VILLAGE NO. 1 MAJADABRI OF RIVER DAMRA ON R/B LENGTH 220M 6. SEVERE BANK EROSION OBSERVED AT VILLAGE SORAIGAON OF RIVER JANALI REACH LENGTH 300M 7. SEVERE BANK EROSION OBSERVED AT VILLAGE SORAIGAON OF RIVER PEKUYA REACH LENGTH 200M 0						
	Morigaon	Laharighat - Barchapori As per report received from the water Resources dept on 02/08/2022, erosion is observed in Borchapori area with maximum erosion of 8 m is seen. 0						
	South Salmara	South Salmara - Brahmaputra Berabhanga As per information received from concerned Gaon Pradhan 4 nos family has been eroded due to erosion by river Brahmaputra at village Brahmaputra Berabhanga under south salmara rev Circle, Dist South Salmara mankachar as on 1/08/2022. The area Aprox 4B-2K-0L 21						
Landslide	Nil	-						
Urban Flood	Nil							
	1							