

FRIMS Assam



Flood Reporting And Information Management System

			Assan	Daily Flood Report as on	16-06-2022 at 4:00 PM				
Particulars	Situation as	on 16-06-2							
Rivers flowing above Danger Level (as	Rivers flowing above danger level			Manas (Nh Road Crossing), Pagladiya (Nt Road Crossing), Puthimari (Nh Road Crossing), Kopili (Kampur), Brahmaputra (Dhubri; Neamatighat), Gaurang (Kokrajhar)					
per CWC bulletin issued at 8 AM)	Rivers flowi flood level	ng above h	ighest	Nil					
	No. of Districts Affected	Name of	Flood Aff	ected Districts	Name of Urban Flood Districts				
District Affected	25	Bongaiga Dhubri, I Hojai, Ka West, Ko	on, Chirar Dibrugarh, nmrup, Kar krajhar, La	eta, Biswanath, ng, Darrang, Dhemaji, Dima-Hasao, Goalpara, mrup (M), Karbi Anglong nkhimpur, Majuli, onitpur, Tamulpur,	Bajali, Darrang, Goalpara, Kamrup (M), Kokrajhar, Morigaon, Nalbari, Udalguri				
No. Of Revenue Circles Affected	77								
	District	Total	Revenue	e Circle					
	Bajali	2	Sarupeta						
	Baksa	5	Barnaga	Barnagar RC part, Baganpara, Barama, Baska, Jalah					
	Barpeta	5	Barpeta,	Barpeta, Barnagar, Kalgachia, Sarthebari, Chenga					
	Biswanath	1	Halem						
	Bongaigao n	3	Manikpı	Manikpur, Bongaigaon, Dangtol					
	Chirang	3	Bengtal, Bijni, Sidli						
	Darrang	4	Mangalo	loi, Dalgaon, Patharighat, S	ipajhar				
	Dhemaji	3		, Jonai, Sissiborgaon					
	Dhubri	3		Bilasipara, Athani					
	Dibrugarh	1	Chabua						
	Dima- Hasao	1	Haflong						
Name Of	Goalpara	3	Balijana, Lakhipur, Rongjuli						
Revenue	Hojai	3		Jojai, Doboka					
Circles	Kamrup	6		Kayan, Kamalpur, Palashba	ari Boko Haio				
Affected	Kamrup				an, Bono, Myo				
	(M)	2	Guwaha	ti, Dispur					
	Karbi Anglong West	1	Donkam	Donkamokam					
	Kokrajhar	5	Bagriba	i, Bhawraguri, Gossaigaon	, Kokrajhar, Dotma				
	Lakhimpur	3		akhimpur, Nowboicha, Bihj					
	Majuli	2	Majuli,	Ujani Majuli					
	Morigaon	1	Laharigh	5 5					
	Nagaon	2	Kampur						
	Nalbari	7			Barbhag, Tihu, Paschim Nalbari, Nalbari				
	Sonitpur	4		ra, Dhekiajuli, Chariduar, T					
	Tamulpur	2		r, Tamulpur	A				
	Udalguri	5		ari, Mazbat, Udalguri, Kala	igaon, Harisinga				
	Total	77	Tanunuo	, Muzoui, Oduiguii, Raia	-Davin,mindingu				
	District	Total	Revenue	e Circle					
Villages	Bajali	172		ta 78), (Bajali 94)					
Affected	Baksa	58		<u> </u>	ara 9), (Barama 18), (Baska 11), (Jalah 8)				
Antecica		183			Kalgachia 37), (Sarthebari 63), (Chenga 7)				
	Barpeta	103	(Darpet	a <i>31)</i> , (Damagar 39), (1	rangacina 37), (Sannicuan 03), (Chenga 7)				

	D: 4		(11.1	12)				
	Biswanath	3	(Halem	[3)				
	Bongaigao	86	(Manik	our 79), (B	ongaigaon 3), (Dangtol 4)		
	n Chirang	72	(Panata	1 7) (Diini	53), (Sidli	112)		
	Darrang	152				(Patharighat 42), (Sipa	ihar 31)	
	Darrang	29			ni 9), (Sissib		1101 31)	
	Dhubri	45			ipara 34), (A			
	Dibrugarh	1	(Chabua		puru 54), (1	<u> </u>		
	Dima-	2	(Haflon					
	Hasao Goalpara	83	(Balijan	a 17), (Lak	chipur 56), (Rongjuli 10)		
	Hojai	46	(Lanka	5), (Hojai	30), (Dobok	a 11)		
	Kamrup	213	(Rangia	77), (Kaya	an 28), (Kai	nalpur 61), (Palashbari	3), (Boko 1	5), (Hajo 29)
	Kamrup (M)	19	(Guwah	ati 9), (Dis	spur 10)			
	Karbi Anglong West	5	(Donkar	mokam 5)				
	Kokrajhar	192	(Bagriba	ari 51), (Bl	nawraguri 37), (Gossaigaon 77), (Ko	okrajhar 10),	(Dotma 17)
	Lakhimpur	15	`		, , ,	ha 7), (Bihpuria 5)		
	Majuli	10	(Majuli	8), (Ujani	Majuli 2)			
	Nagaon	12	_	ır 7), (Raha				
	Nalbari	147		ıchi 19), (F 9), (Nalbar		(Ghograpar 41), (Barbh	ag 23), (Til	nu 27), (Paschim
	Sonitpur	25				, (Chariduar 4), (Tezpui	: [2]	
	Tamulpur	33	(Goresv	var 21), (Ta	amulpur 12)	_		
	Udalguri	99	(Khaira	bari 20), (N	Mazbat 15),	(Udalguri 27), (Kalaigac	on 36), (Har	isinga 1)
	Total	1702						
			Femal		Total		Crop	
	District	Male	e	Children	Populatio	Population Details	Area (in	Crop Area Details
			14000		n	(Sarupeta 195000), (Hect.)	(Sarupeta 20.00), (
	Bajali	180000	0	35000	355000	Bajali 160000)	20.00	Bajali 0.00)
	Baksa	4987	4168	781	9936	(Barnagar RC part 0), (Baganpara 1284), (Barama 1231), (Baska 1356), (Jalah 6065)	764.50	(Barnagar RC part 387.00), (Baganpara 219.50), (Barama 68.00), (Baska 0.00), (Jalah 90.00)
	Barpeta	33054	27501	14445	75000	(Barpeta 9168), (Barnagar 0), (Kalgachia 0), (Sarthebari 64530), (Chenga 1302)	2116.00	(Barpeta 646.00), (Barnagar 829.00), (Kalgachia 604.00), (Sarthebari 37.00), (Chenga 0.00)
	Biswanath	83	59	38	180	(Halem 180)	18.00	(Halem 18.00)
Population	Bongaigao n	31779	26666	19325	77770	(Manikpur 75850), (Dangtol 995), (1201.00	(Manikpur 1201.00), (Dangtol 0.00), (
And Crop						Bongaigaon 925)		Bongaigaon 0.00)
Area Affected	Chirang	6915	5129	3966	16010	(Bengtal 1632), (Sidli 1805), (Bijni 12573)	688.32	(Bengtal 253.00), (Sidli 321.00), (Bijni 114.32)
	Darrang	40211	35810	24215	100236	(Mangaldoi 15268), (Dalgaon 52395), (Patharighat 31972), (Sipajhar 601)	4149.51	(Mangaldoi 1104.00), (Dalgaon 2435.50), (Patharighat 580.35), (Sipajhar 29.66)
	Dhemaji	2303	2147	1503	5953	(Jonai 4462), (Dhemaji 395), (Sissiborgaon 1096)	1098.00	(Jonai 819.00), (Dhemaji 3.00), (Sissiborgaon 276.00)
	Dhubri	1726	1459	586	3771	(Chapar 900), (Bilasipara 2687), (Athani 184)	185.52	(Chapar 179.00), (Bilasipara 6.52), (Athani 0.00)
	Dibrugarh	1567	1240	1050	3857	(Chabua 3857)	2.50	(Chabua 2.50)
	Goalpara	80172	48998	9830	139000	(Balijana 12000), (Lakhipur 127000), (Rongjuli 0)	1839.00	(Balijana 43.00), (Lakhipur 1781.00), (Rongjuli 15.00)
	Hojai	24421	13156	3279	40856	(Lanka 212), (Hojai 39194), (Doboka 1450)	1745.00	(Lanka 349.00), (Hojai 1295.00), (Doboka 101.00)

	Kamrup	20740	19308	10089	50137	(Kayan 66 Rangia 43 Kamalpur Palashbari 0), (Hajo	508), (0), (0), (Boko	3226.15	(Kayan 110.00), (Rangia 578.00), (Kamalpur 234.20), (Palashbari 198.00), (Boko 6.95), (Hajo 2099.00)
	Kamrup (M)	18915	12649	2865	34429	(Sonapur Chandrapur Guwahati Dispur 215	(0),(12879),(0.00	(Sonapur 0.00), (Chandrapur 0.00), (Guwahati 0.00), (Dispur 0.00)
	Karbi Anglong West	758	758	392	1908	(Donkamol	cam 1908)	0.00	(Donkamokam 0.00)
	Kokrajhar	22688	21428	13609	57725	(Bagribari Bhawraguri Gossaigaon Kokrajhar Dotma 153	15437), (1783), (6528), (359.19	(Bagribari 14.89), (Bhawraguri 122.50), (Gossaigaon 221.80), (Kokrajhar 0.00), (Dotma 0.00)
	Lakhimpur	4365	3082	2151	9598	(North Lak 2646), (No 5175), (Bi 1777)	owboicha hpuria	19.00	(North Lakhimpur 19.00), (Nowboicha 0.00), (Bihpuria 0.00)
	Majuli	0	0	0	0	(Majuli 0 Majuli 0)), (Ujani	48.00	(Majuli 30.00), (Ujani Majuli 18.00)
	Nagaon	481	392	253	1126	(Kampur Raha 0)	1126),(206.00	(Kampur 119.00), (Raha 87.00)
	Nalbari	27472	24003	15273	66748	(Ghograpar Barbhag 7 Tihu 1674 Paschim Na), (Nalbari Banekuchi Barkhetri 2	5), (llbari 5900 7420), (16790), (991.70	(Ghograpar 0.00), (Barbhag 86.00), (Tihu 465.00), (Paschim Nalbari 271.60), (Nalbari 140.60), (Banekuchi 28.50), (Barkhetri 0.00)
	Sonitpur	1222	1119	738	3079	(Thelamara Dhekiajuli Chariduar Tezpur 30	1411), (1638), (183.60	(Thelamara 25.00), (Dhekiajuli 150.60), (Chariduar 0.00), (Tezpur 8.00)
	Tamulpur	13759	10971	3863	28593	(Goreswar Tamulpur		399.50	(Goreswar 167.50), (Tamulpur 232.00)
	Udalguri	12468	8591	7329	28388	(Khairabar Mazbat 45 Udalguri 8 Kalaigaon Harisinga	i 1801), (20), (644), (13365), (881.50	(Khairabari 28.50), (Mazbat 0.00), (Udalguri 62.00), (Kalaigaon 791.00), (Harisinga 0.00)
	Total	530086	40863	170580	1109300			20141.99	
	District	Total	Relief C	amp			Relief Dist	ribution Cent	res
	Bajali	12	12(Bajal		10 D 1	16 1111	0(Bajali 0)	1	
	Baksa	11	10(Baga 1)	npara I, Ba	rama 2, Bask	ta 6, Jalah	1(Baganpar	a 0, Barama	1, Baska 0, Jalah 0)
	Barpeta	2	2(Barpet	ta 2)			0(Barpeta	0)	
	Bongaigao n	6	6(Manik	pur 1, Bong	gaigaon 1, Da	angtol 4)	0(Manikpui	0, Bongaiga	on 0, Dangtol 0)
	Chirang	9		1, Sidli 0)			8(Bijni 0,		
Relief	Darrang	1		ighat 0)	aono 1.7. A -1	:12)	1(Patharigh) Athon: 10)
Camps / Centres	Dhubri Dibrugarh	11	0(Chabu		para 7, Athar	11 5)), Bilasipara (J, Atnani U)
Opened	Dima- Hasao	29	22(Hafle				1(Chabua 1) 7(Haflong 7)		
	Goalpara	13	10(Balij	ana 7, Lakh	ipur 3)		3(Balijana	0, Lakhipur	3)
	Hojai	18	18(Hoja:				0(Hojai 0)		
	Kamrup	6	6(Rangia	a 3, Kayan	3)		0(Rangia 0), Kayan 0)	
	Kamrup (M)	17		hati 2, Dispi		TZ 1 " ·	12(Guwaha	ti 2, Dispur	10)
	Kokrajhar	26	26(Bhav 11)	vraguri 6, G	ossaigaon 9,	Kokrajhar	0(Bhawragu	ıri 0, Gossaig	aon 0, Kokrajhar 0)

	Nalbari	14	14(Ghog	grapar 2, Pas	schim Nalbari	5, Nalbari	0(Ghograp	0(Ghograpar 0, Paschim Nalbari 0, Nalbari 0)				
	Tamulpur	15	3(Tamul	pur 3)			12(Tamulpur 12)					
	Udalguri	5		uri 4, Kalaig	gaon 0)		1(Udalguri 0, Kalaigaon 1)					
	Total	196	150				46					
	District	Total	Revenue	e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y		
	Bajali	1349	(Sarupeta 0), (Bajali 1349)			619	589	124	17	0		
	Baksa	2304	102), (B	(Barnagar RC part 0), (Jalah 102), (Baganpara 614), (Barama 754), (Baska 834)			883	482	1	1		
	Barpeta	186	(Barnagar 0), (Kalgachia 0), (Sarthebari 0), (Barpeta 186)			95	47	44	0	0		
	Bongaigao n	1148		ur 0), (Bong angtol 995)	gaigaon	480	431	235	2	0		
	Chirang	128		0), (Sidli 0	0), (Bijni	47	49	29	3	0		
	Dhubri	853	(Bilasipa (Athani	ara 648), (Cl 184)	hapar 21),	321	352	180	0	0		
	Dima- Hasao	1530	(Haflong			551	576	350	52	1		
Inmates In Relief	Goalpara	1630		a 1157), (La ongjuli 0)	khipur	776	453	374	15	12		
Camps	Hojai	43033		0), (Hojai 4	3033),	22000	18000	3030	3	0		
	Kamrup	4732	(Kayan 4332), (Kamalpur 0), (Palashbari 0), (Boko 0), (Hajo 0), (Rangia 400)			2142	1543	1027	20	0		
	Kamrup (M)	697		r 0), (Chand ati 77), (Dis		241	371	85	0	0		
	Kokrajhar	6833		0), (Bhawra gaon 1917),	•	2684	2324	1779	45	1		
	Nalbari	3372	(Baneku (Barbhag 2498),	chi 0), (Barl g 0), (Tihu (Ghograpar n Nalbari 61	0), (Nalbari 264),	1541	1101	722	7	1		
	Tamulpur	188		ar 0), (Tamı		76	56	56	0	0		
	Udalguri	348	(Khairab	oari 0), (Maz on 0), (Hari	zbat 0),	162	113	73	0	0		
	Total	68331		l	I	32672	26888	8590	165	16		
	District	Total	Male	Female	Children	Revenue (Circlewise					
Human	Dima- Hasao	1	1	0	0	(Haflong						
Lives Lost -	Goalpara	2	0	0	2			0), (Rongjuli		1		
Confirmed	Udalguri	1	0	1	0	(Harisinga (Udalguri		on 0), (Knair	abari 0), (Maz	bat 0),		
	Total	4	1	1	2							
Human Lives Lost	District	Total	Flood Death	General Drownin g (Non Flood)	Landslide							
Confirmed -	Dima- Hasao	1	0	1	0							
Death Type	Goalpara	2	0	0	2							
	Udalguri	1	1	0	0							
	Total	4	1	1	2							
Human Lives Lost - Missing	Nil											
Human Lives Lost Missing - Type	Nil											

	District	Total	Big	Small	Poultry					
	Bajali	96148	64181	31967	0					
	Baksa	18901	10213	7088	1600					
	Barpeta	180590	59622	21968	99000					
	Chirang	1035	210	275	550					
	Darrang	52121	30990	14131	7000					
	Dhemaji	3300	2510	790	0					
	Goalpara	62780	32441	23302	7037					
	Hojai	944	121	223	600					
Animals	Kamrup	63604	21525	11601	30478					
Affected	Kokrajhar	5670	1600	870	3200					
	Lakhimpur	5676	3884	1637	155					
	Nagaon	2050	1025	375	650					
	Nalbari	156225	78728	66635	10862					
	Sonitpur	1521	1000	521	0					
	Tamulpur	22237	4894	3281	14062					
	Udalguri	6476	3550	1712	1214					
	Total	679278	31649 4	186376	176408					
Animals Washed Away	Nil									
Houses	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
Houses Damaged	Goalpara	0	0	0	1	0	1	0	0	0
Damaged	Kamrup	1	0	1	1	7	8	0	0	0
	(M)								_	_
	Total	1	0	1	2	7	9	0	0	0
	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
	Bajali	Circle Of		force, RF, Police,	6	812	22	0	0	0
	Baksa	(F&ES), S		Services	5	50	0	0	0	3
	Barpeta		ration, SD		2	11	0	0	0	0
	Bongaigao n		pple, Engir nergency S		3	140	0	0	0	1
	Darrang		ple, SDRI		4	3725	6500	0	0	1
Rescue Operation	Dhubri	(F&ES), l	nergency S Local Peop cal Admin ORF	ole, Circle	8	251	0	0	0	3
	Dima- Hasao	Civil Defe Volunteer	ence/Trainrs, SDRF	ed	1	0	0	0	0	15
	Goalpara	Fire & En (F&ES), S	nergency S SDRF	Services	1	15	0	0	0	0
	Hojai	Circle Off Administr SDRF		al People,	22	310	52	0	0	0
	Kamrup				0	0	0	0	0	2
	Kamrup (M)	Emergeno	ration, Fire by Services olice, SDR	s (F&ES),	6	0	0	0	0	3
	Kokrajhar				0	0	0	0	0	14
	Lakhimpur Nalbari	_	ramilitary 1	force,	5	506	75	0	0	0
		SDRF								

	Tamulpur				1	20	0	0	0	0	
	Total				64	5840	6649	0	0	46	
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)		- Rice Bran (
	Bajali	2.00	0.50	0.40	40.00	0.00	0.00	0.00			
	Baksa	55.49	9.98	35.66	299.17	0.00	0.00	0.00			
	Chirang	71.99	12.97	3.90	389.62	0.00	0.00	0.00			
Relief	Darrang	8.50	1.50	0.45	46.00	0.00	0.00	0.00			
Distributed	Dibrugarh	63.13	11.57	3.47	0.00	0.00	0.00	0.00			
	Dima- Hasao	29.40	2.80	0.50	140.00	0.00	0.00	0.00			
	Hojai	200.00	0.00	0.00	0.00	0.00	0.00	22.50	22.50		
	Kamrup (M)	4.59	5.03	1.51	159.20	0.00	0.00	0.00	0.00		
	Kokrajhar	52.74	9.67	2.90	290.10	0.00	0.00	0.00			
	Tamulpur	180.71	32.35	9.72	972.90	0.00	0.00	0.00			
	Udalguri	8.97	1.68	0.51	0.00	0.00	0.00	0.00			
	Total	677.52	88.05	59.02	2336.99	0.00	0.00	22.50			
	District	Baby Foo Liquid	od	Baby Food	Solid	Others					
	Bajali	0.00-Q		0.00-Q		Tarpaulin-6	00.00-Pieces;	Biscuit -10.00)-Pkt; Potato-:	5.00-Kg	
	Baksa	35.00-Pkt, 0.00-Q		0.00-Q, 120).00-Pkt	Candel-166 Pkt; Candle 140.00-Pkt;	Candel-166.00-Pkt; Biscuit-500.00-Pkt; Mother horliks-1.00 Pkt; Candle -30.00-Pkt; Biscuit -140.00-Pkt; Mosquito coil -140.00-Pkt; 0-0.00-Q; Cattle feed-957.00-Kg			ks-1.00- to coil -	
	Chirang	0.00-Pkt, 0.00-Q		23.00-Pkt, 0.00-Q		Napkin-20.0	paulin-10.00-Pieces; Mosquito Net-21.00-Pieces; Sanitary pkin-20.00-Pkt paulin-10.00-Pieces; Chira-5.00-Q; Gur-1.50-Q; cake-				
	Darrang	0.00-Q		0.00-Q		•	0.00-Pieces; 0 Biscuit-504.0		Gur-1.50-Q; c	ake-	
	Dibrugarh	0.00-Q		0.00-Q							
Relief Distributed	Dima- Hasao	0.00-Q		0.00-Q		280.00-Piec	es; Torch-140				
Others	Hojai	0.00-Q		0.00-Q		Chira 120 bag (30 Kg per Pkt)-36.00-Q; Gur 10 bag (per bag 30 kg)-3.00-Q; Water (1 Ltr per bottle)-1200.00-L; Amoul-480.00-L; Candle (Per Pkt-6)-100.00-Pkt; Tarpaulin-200.00-Pieces; Biscuits 10 Box(Per Box 38 Pkts)-380.00-Pkt; Tarpualin - 300.00-Pieces					
	Kamrup (M)	0.00-Q		0.00-Q		Tarpouline-560.00-Pieces; Water Bottle 2Ltr-170.00-L; Bread-9037.00-Pkt; Biscuit-14074.00-Pkt; Candle-1770.00-Pkt; Tarpaulin-40.00-Pieces; Water Bottle-20232.00-L					
	Kokrajhar	0.00-Q		0.00-Q		Chira-276.00-Kg; Gur-48.70-Kg; CANDLES-625.00-Pkt; MATCHBOX-64.00-Pkt; GOOD DAY BISCUIT-2923.00-Pkt; TARPAULINE-110.00-Pieces					
	Tamulpur Udalguri	0.00-Q 0.00-Pkt		0.00-Q 0.00-Pkt		0-0.00-Pkt					
		Numbe	Details			2 2.00 TRU					
	District	r	Details								
	Bajali	1	_	l report receiv			_	aralpara (Naya 22 (Long - 91	-		
	Baksa	1	Barama	- R/B emban				ki village (Biha 2, Lat - 26.5155		breach of	
Infrastructur e Damaged - Embankmen t Breached	Darrang	1	Mangale under M embankt heavy ra discharg flood wa built stru	doi - Saktola angaldai Rev ment at Ch. 1' infall at the u e of flood wa ater overtoppe acture is with: e down streat	Embankment under Water Resource Department. At Village Borathiabari enue Circle. New Breach Extended another 15 m at Saktola left bank 200 m at around 1.30 AM as per WRD department. Dated 16/06/2022. Due to pper catchment and breach of DRDA bund on Noanadi at udalguri, huge ter is flowing through the Saktola river resulting in high rise in water level. The det the cofferdam structure built at the breached site last night. Though the newly standing in support of BType bags, the overtopped flow developed a new flow m and continuing flow through this new way. (Long - 91.948204, Lat -						
	Lakhimpur	1	Nowboic (15Mtr)	cha - Bokano at 2 No. Sona		2022. Report		anodi Panchay n Nowboicha E			
	Nalbari	3					Kaithalkucl	hi (Lourapara)	As reported	by Gaon	

	Sonitpur	5	pradhan on 16/6/2022 at 9am Nadala channel had breached apro.80 Mtr. (Long - 91.308234, Lat - 26.434909), Tihu - LB Mora-Pagladia Vill - Paschim Gobaradal As per report of WR department and GB. Length - 50 mtr. Approx. on 16/06/2022 (Long - 26.486360, Lat - 91.332912), RB Mora-Pagladia Vill Lanka Gabaradal As per report of WR department and GB. Length - 45 mtr. Approx. on 16/06/2022 (Long - 91.324167, Lat - 26.483790) Chariduar - JORASHAR RIVER CHARIDUAR REVENUE CIRCLE ROAD SIDE BREACHED AT JORASHAR RIVER AT DIGHALI DTD 16/06/2022 (Long - 26.835808, Lat - 92.773781) Goreswar - Tengajhar east Bank Village Tengajhar Dated 16/06/2022, breach occurred at East Bank of River Suklai, approximately 150 m (Long - 91.691325, Lat - 26.599031), Tengajhar West Bank Village Tengajhar Dated 16/06/2022 breach occurred at West Bank of River Suklai approximately 50 m damage (Long - 91.690936, Lat - 26.606073), Nathkuchi east Bank Nathkuchi Dated 16/06/2022, breach occurred at East Bank of River Suklai at Village Nathkuchi approximately damage 50 m (Long - 91.697264, Lat - 26.613462), Nathkuchi West Bank Nathkuchi Dated 16/06/2022 breach occurred at Village Nathkuchi approximately 100m damage (Long - 91.697136, Lat - 26.618875), Bangalipara Ring Bandh Village Bangalipara Dated 16/06/2022, breach occurred at West Bank of sub tributary river Deosunga the repaired part. Approximately damage 50 m (Long - 91.711811, Lat
	m . 1	12	- 26.715517)
	Total	13 Numbe	
	District	r	Details Details
Infrastructur e Damaged - Embankmen	Darrang	2	Patharighat - Nonoi R/B embankment Beside Ratnawali Mandir boiling, leakages at Bariapara Nonoi R/B embankment as reported by AEE W/R Deptt. on 16.5.2022 (Long - 91.871186, Lat - 26.466432), Nonoi R/B embankment Hatimara village boiling, leakage, slump down, depression at Hatimara embankment pertaining to W/R Deptt as reported by AEE W/R on 16.5.2022 (Long - 91.858885, Lat - 26.477716)
t Affected	Udalguri	1	Kalaigaon - Embankment at village Rupatal near Pradip Das's house Rupatal The embankment has further deteriorated as flood water passed through the breached portion from river Noa in the R/B of the river on 16/06/2022 covering a length of around 40 meters and breadth of 5 meters. (Long - 91.975912, Lat - 26.621011)
	Total	3	
	District	Numbe r	Details
	Bajali	1	Bajali - Anandapur to ghelengpara Anandapur Apprx 1200 meter erosion at road side and this report is received from PWD Roads (Long - 91.233747, Lat - 26.584088)
	Baksa	3	Baganpara - Moithabari to Saulkara road Moithabari On dated 15/06/2022 bridge approach approx 8 m has been cut off (Long - 91.436700, Lat - 26.728000), Guwalbil to Sundarpur road Guwalbil On dated 15/06/2022 due to inundation of road eroded approx 30 m (Long - 91.487135, Lat - 26.576100), Barama - Barama - Dhamdhama Road Alagjar village (Deulguri Chowk) (Long - 91.376628, Lat - 26.526894)
Infrastructur e Damaged - Road	Barpeta	11	Barpeta - Ata Bhokuamari to Pahumara river road Bhokuamari 14.2 m , damaged at 2nd Km DOO 15.06.2022,PWRD, Barpeta (Long - 91.087800, Lat - 26.398800), Barnagar - Barpeta Road to Bashbari Road Village- Khairabari As per WT message received from The Ex. Engineer, Sorbhog & Jania Territorial Road Divn, Barpeta Road vide Memo No. BR/SJTRD/W.T. MESSAGE/2019-20/242 on 15/06/2022 Barpeta Road to Bashbari Roadhas damaged from CH. 2.550 KM to CH, 3.00 KM due to heavy rainfall. (Long - 90.969048, Lat - 26.507989), Sorbhog Station Feeder Road Vill- Dakhin Ganakgari & Ketekibari As per WT message received from The Ex. Engineer, Sorbhog & Jania Territorial Road Divn, Barpeta Road vide Memo No. BR/SJTRD/W.T. MESSAGE/2019-20/245 on 15/06/2022 Sorbhog Station Feeder Road has submerged from CH. 800 M to CH, 1800 M due to heavy rainfall. (Long - 90.893135, Lat - 26.471873), Noontola Santoradaha Road Vil- Noontola & Santoradaha As per WT message received from The Ex. Engineer, Sorbhog & Jania Territorial Road Divn, Barpeta Road vide Memo No. BR/SJTRD/W.T. MESSAGE/2019-20/245 on 15/06/2022 Noontola Santoradaha Road has submerged from CH. 100 M to CH, 800 M due to heavy rainfall. (Long - 90.854592, Lat - 26.510965), Chandamari Pub Para Road Vill- Chandamari As per WT message received from The Ex. Engineer, Sorbhog & Jania Territorial Road Divn, Barpeta Road vide Memo No. BR/SJTRD/W.T. MESSAGE/2019-20/245 on 15/06/2022 Chandamari Pub Para Road has submerged from CH. 200 M to CH, 1000 M due to heavy rainfall. (Long - 90.804399, Lat - 26.438139), Chandamari Boropara Road Vill- Chandamari As per WT message received from The Ex. Engineer, Sorbhog & Jania Territorial Road Divn, Barpeta Road vide Memo No. BR/SJTRD/W.T. MESSAGE/2019-20/245 on 15/06/2022 Chandamari Pub Para Road Road has submerged from CH. 200 M to CH, 1000 M due to heavy rainfall. (Long - 90.799523, Lat - 26.438139), Chandamari Boropara Road Vill- Chandamari Boropara Road Road has submerged from CH. 0.00 M to CH, 800 M due to heav

		Charles of Head David Will Charles the Will the District Charles the Will
		Chandamari Uttar Para Vill- Chandamari As per WT message received from The Ex. Engineer,
		Sorbhog & Jania Territorial Road Divn, Barpeta Road vide Memo No. BR/SJTRD/W.T. MESSAGE/2019-20/245 on 15/06/2022 Chandamari Uttar Para Road Road has submerged from CH.
		0.00 M to CH, 600 M due to heavy rainfall. (Long - 90.800090, Lat - 26.441328),
		Kalgachia - State High Way-2 At various points from Manas bridge approach to Barpeta Medical
		college As per report received from PWD department on 16/06/22, due to continuous heavy rainfall
		from last several days road side berm with hard crust damaged at SH2 (Manas bridge approach to
		Barpeta Medical college) at ch. 49th km and 50th Km (Length=300.00 mm, avg width=3.00m and
		avg depth=2.00m) location coordinates- 26.333439, 90.868635. (Long - 0.000000, Lat - 0.000000),
		Sarthebari - village road of kawaimari gaon kawaimari gaon Kawaimari gaon (chowk) to Barakahi
		village connecting village road damage approx 25 meter, Bhawanipur Dev Block (Reported by LM on
		16/06/2022) (Long - 0.000000, Lat - 0.000000),
		PWD road of Sarthebari Pathsala Batia Reported by LM on 16/06/2022 (Long - 0.000000, Lat -
		0.000000),
		Chenga - Chenga Block Boundary to BD road via Musalman gaon, Package No. As 01 510
		Musalman gaon Road submerged from Ch. 4500.00 m to 4700.00 m, average submerged depth 0.
		25m, Side berm eroded . reported by PWD deptt on 16/6/22 (Long - 91.188027, Lat - 26.276504)
		Boitamari - Jogighopa Salbari Road, Jogighopa Landslide occured at oudubi at 16 th km. as per report received from PWRD, Bongaigaon date-16/06/2022 (Long - 90.487351, Lat - 26.296631),
		Sankarghola picnic spot approach road Sankarghola One HP culvert partially damage at 1st km as
		per report recieved from PWRD, Bongaigaon Date-16.06.2022 (Long - 90.531980, Lat - 26.309695),
		Jogighopa salbari road Salbari Rain water stagnent at balapara at 6th km. as per report recieved
		from PWRD, Bongaigaon Date-16.06.2022 (Long - 90.544020, Lat - 26.263554),
		Manikpur - NH-31 to Thakuranipara MPNA road NH-31 to Thakuranipara MPNA road Side berm
		& side slopers and hard crtust of bridges\ approach damaged at Ch. 55.00m reported by PWRD,
		Bongaigaon date of incident 15.06.2022 (Long - 902924.000000, Lat - 26.251700),
		Bhandara-I to Bhandara-V PMGSY road Bhandara-I to Bhandara-V PMGSY road Side shoulder
		and hard crust damaged at Ch.2700.00 to Ch 2900.00m Averagen submergence depth 50cm reported
		by PWRD, Bongaigaon date of incident 15.06.2022 (Long - 90.793637, Lat - 26.466348),
		Bashbari to Salabila Road Bashbari to Salabila Road Approach of SPT Br. No 1/1 damaged at Ch.
		450.00 m reported by PWRD, Bongaigaon date of incident 15.06.2022 (Long - 90.774229, Lat -
		26.417489), Gerukabari Jamdoha PMGSY road Gerukabari Jamdoha PMGSY road Road Breached out at Ch.
		810 m to Ch. 840m & submerged at Ch. 800.00 m to Ch 840.00m (Av. Submergence depth=30cm) &
Bongaigao		damaged hard crust reported by PWRD, Bongaigaon date of incident 15.06.2022 (Long - 90.701968,
n	13	Lat - 26.451735),
		Bongaigaon - Salbari Bongaigaon Road Salbari Bongaigaon Road Side shoulder erroeded by river
		Tunia at ch. 11th km reported by PWRD, Bongaigaon date of incident 15.06.2022 (Long -
		90.519009, Lat - 26.420800),
		Mulagaon Chengmari road Mulagaon Chengmari road Side shoulder damaged at ch 2500.00m
		reported by PWRD, Bongaigaon date of incident 15.06.2022 (Long - 90.508600, Lat - 26.434300),
		Mulagaon Ravapara Road Mulagaon Ravapara Road Side shoulder damaged at Ch. 100.00m Ch.
		350.00 m Ch. 1350.00m reported by PWRD, Bongaigaon date of incident 15.06.2022 (Long -
		90.524953, Lat - 26.430579), Srijangram - Ambari PWD road to Gauranga Mandir road Ambari PWD road to Gauranga Mandir
		road Road embankment partially damaged at 1st km reported by PWRD Bongaigaon date of incident
		15.06.2022 (Long - 26.340752, Lat - 90.730672),
		Nowagaon to Rangapani Road Nowagaon to Rangapani Road Road embankment damaged and
		approach of RCC Bridge No. 4/1 damaged at Ch. 2nd, 3rd & 4th km. reported by PWRD Bongaigaon
		date of incident 15.06.2022 (Long - 90.818311, Lat - 26.391612),
		Dangtol - Borjhora waterfall approach road Borjhora waterfall approach road Side shoukder
		damaged at Ch.450.00 m to Ch.750.00m reported by PWRD Bongaigaon date of incident 15.06.2022
		(Long - 90.482492, Lat - 26.418995)
		Bengtal - South Banduguri village road Ashrabari As reported by PWD (R&B) Bengtal Division,
		Road Surface shoulders damaged on 16-06-2022 , L-10m B-7m D-2m (Long - 90.390682, Lat - 26.621567),
		Sidli - 1. Sidli Nalbari village road Sidli As reported by PWD (R&B) Chirang, Sidli Nalbari village
		road (Road embankment eroded) on 16-06-2022 at Sidli, Damage details - Length :40m, breadth : 7
		m, Depth: 2.5 m, (Long - 90.449225, Lat - 26.521000),
Chirang	4	2. Chapaguri to Koilamoila Road Chapaguri As reported by PWD (R&B) Chirang, Chapaguri to
		koilamoila road (Road surface shoulders damaged) on 16-06-2022 at Chapaguri, Damage details -
		Length: 8km, breadth: 3 m, Depth: 1 m, (Long - 90.554028, Lat - 26.503397),
		3. NH 31C Dhopguri to Pachim Jaoliabari Road Dhopguri As reported by PWD (R&B) NH 31C
		Dhopguri to Pachim jaoliabari road (Road Embankment eroded), on 16-06-2022 at Dhopguri,
		Damage details - Length :45m, breadth : 3 m, Depth : 3 m, (Long - 90.421670, Lat - 26.551174)
		Mangaldoi - MB road to Chamuapara via Bahjani At village Bahjani under Mangaldai Rev. Circle
Darrang	7	The road was breached in the first wave and temporary restoration was going on. The same breach
		portion is affected again as reported by PWRD. Dated 16-06-2022 (Long - 91.900000, Lat -
]	26.530000),

			Mahaliajhar to Bhakatpara Road Under Mangaldai Revenue Circle The road have been submerged at various places at different chainage as reported by PWRD. These submergence report were already reflected in the first wave of flood. Dated 16-05-2022 (Long - 92.030000, Lat - 26.520000), Abhaypukhuri to Chapai Dalgaon road Under Mangaldai Revenue Circle The road is submerged due to flood water and length of submergence is 100m Approx. as of now as reported by PWRD. These submergence report were already reflected in the first wave of flood. Dated 16-05-2022 (Long - 92.030000, Lat - 26.550000), Borjhar bagisa to Bhakatpara Under Mangaldai Revenue Circle The road is submerged due to flood water and length of submergence is 350m Approx. as of now as reported by PWRD. These submergence report were already reflected in the first wave of flood. Dated 16-05-2022. (Long - 92.030000, Lat - 26.560000), Patharighat - Bhakatpara Pandaghat Road Pandaghat Bhakatpara Pandaghat Road submerged at length L= 1.00 km Ch 600 mt to 1600 mt as reported by PWD on 16.5.2022 (Long - 91.812122, Lat - 26.480424), Rajghat Bheruadol Road Bheruadol Road erosion at Ch 200 mt as reported by PWD on 16.5.2022 (Long - 91.831600, Lat - 26.490978), MPK Road to Hussain chubri Hussainchubri Submerged at length L= 1200 m Ch 600 mt to 1000 mt depth 0.60 m on 16.5.2022 (Long - 91.827920, Lat - 91.827920) Jonai - PWD territorial road Bridge approaches (both sides) partially damaged at Mohmora to Rigbi, 50.00 meter (left) & 50.00 meter (right) side berm got eroded on 16/06/2022 due to heavy rain. From Ch. 540.00M to Ch.630.00M & Ch.730.00M to Ch. 780.00M As per report received from PWRD, Jonai Territorial road Sub-Division-II, Jonai a PWD territorial road Bridge approaches (both sides) partially damaged at Mohmora to Rigbi, 50.00 meter (left) & 50.00 meter (right) side berm got eroded on 16/06/2022 due to heavy rain. For Immediate restoration contractor Rikey Taye have been engaged. (Long - 0.000000, Lat - 0.000000),
D	Phemaji	3	PWD territorial road partially damaged (two places) at Bahir Jonai to Berachapori via Bolaipam, 20.00 meter Bridge approach & 30.00 meter road got eroded on 16/06/2022 due to heavy rain. From Ch.4420.00M to Ch.4440.00M & Ch.4510.00M to Ch.4540.00M As per report received from PWRD, Jonai Territorial Road Sub-Division-II, Jonai a PWD territorial road partially damaged (two places) at Bahir Jonai to Berachapori via Bolaipam, 20.00 meter Bridge approach & 30.00 meter road got eroded on 16/06/2022 due to heavy rain. For Immediate restoration contractor Shyamal Sarkar have been engaged. (Long - 0.000000, Lat - 0.000000), PWD territorial road partially damaged at Oiramghat to Jampani road, 100.00 meter road got eroded on 16/06/2022 due to Jampani Nallah. From Ch. 120.00M to Ch.220.00M As per report received from PWRD, Jonai Territorial Road Sub-Division-II, Jonai a PWD territorial road partially damaged at Oiramghat to Jampani road, 100.00 meter road got eroded on 16/06/2022 due to Jampani Nallah.For Immediate restoration contractor Rikey Taye have been engaged. (Long - 95.348044, Lat - 27.851655)
D)hubri	10	Golakganj - POKALAGI TO FAILAGURI PMGSY ROAD TO ANANDAPUR BAZAR (BOX CULVERT NO 1/1) APP. DAMAGED AND SIDE SHOULDER DAMAGED FROM CH. 300.00 M TO 900.00 M (DATED 15/06/2022) POKALAGI TO FAILAGURI PMGSY ROAD TO ANANDAPUR BAZAR (Long - 0.000000, Lat - 0.000000), POKALAGI KUKILADANGA PMGSY ROAD TO JIADANGA ROAD DAMAGED ROAD SURFACE AND SIDE SHOULDERS AT 1ST, 2ND AND 3RD KM (DATED 15/06/2022) POKALAGI KUKILADANGA PMGSY ROAD TO JIADANGA ROAD (Long - 0.000000, Lat - 0.000000), POKALAGI KUKILADANGA PMGSY ROAD TO JIADANGA ROAD (Long - 0.000000, Lat - 0.000000), POKALAGI KUKILADANGA ROAD TO KACHARIGAON ROAD SURFACE SIDE SHOULDERS DAMAGED AT CH. 1ST AND 2ND KM (DATED 15/06/2022) POKALAGI KUKILADANGA ROAD TO KACHARIGAON ROAD (Long - 0.000000, Lat - 0.000000), KAMANDANGA TO RAMNATHPARA ROAD DAMGES OF SURFACE, SIDE SHOULDER BOX CULVERT AT 1ST AND 2ND KM (DATED 15/06/2022) KAMANDANGA TO RAMNATHPARA ROAD (Long - 0.000000), TALOWA CHARIALI TO KAMANDANGA ROAD DAMAGED AT 2ND KM (DATED 15/06/2022) TALOWA CHARIALI TO KAMANDANGA ROAD DAMAGED AT 2ND KM (DATED 15/06/2022) TALOWA CHARIALI TO KAMANDANGA (Long - 0.000000, Lat - 0.000000), TAMARHAT TO TAMACHABAGAN ROAD DAMED OF SIDE SHOULDERS, SURFACE AT CH. 2ND AND 3RD KM AND BRIDGES APPROACHES DAMAGED AT BR. NO. 2/1 (DATED 15/06/2022) TAMARHAT TO TAMACHABAGAN ROAD DAMAGED SIDE BERM OF 1ST AND 2ND KM (DATED 15/06/2022) G.K ROAD AT SONAHAT TO DAFARPUR ROAD DAMAGED SIDE BERM OF 1ST AND 2ND KM (DATED 15/06/2022) G.K ROAD AT SONAHAT TO DAFARPUR ROAD DAMAGED OF SIDE SHOULDER ROAD SURFACES & HPC CH. 1ST & 2ND KM (DATED 15/06/2022) TAMACHABAGAN TO KALACHANPARA ROAD DAMAGED OF SIDE SHOULDER ROAD SURFACES & HPC CH. 1ST & 2ND KM (DATED 15/06/2022) TAMACHABAGAN TO KALACHANPARA ROAD DAMAGED OF SIDE SHOULDER ROAD SURFACES & HPC CH. 1ST & 2ND KM (DATED 15/06/2022) TAMACHABAGAN TO KALACHANPARA ROAD (Long - 0.000000), Lat - 0.000000),
G	Goalpara	10	Side berm and surfaced road damaged on Khuniarvita Ranpagli Road from1st KM TO 3rd KM. Dt. 04/06/2022-15/06/2022 Khuniarvita Ranpagli Road from1st KM TO 3rd KM. (Long - 0.000000, Lat - 0.000000) Lakhipur - Lakhipur Khalisabhita Road (At 16th KM and 18th KM) Near Khalisabhita As per

		
		report of PWD roads Departments, The approach road Lakhipur Khalisabhita Road (At 16th KM and 18th KM) has been affected length 0.29 Km and the average depth of submergence 0.35 meter due to overflowing water on 14.06.2022 to till date i.e 16.06.2022 (Long - 90.176852, Lat - 25.987013), Dhumerghat Garojan Road Near Garojan As per report of PWD roads Departments, The approach road Dhumerghat Garojan Road has been affected length 0.30 Km and the average depth of submergence 0.40 meter due to overflowing water on 14.06.2022 to till date i.e 16.06.2022 (Long - 90.176190, Lat - 25.970074), Gossaidubi Sialkanda Road Near Sialkanda Bridge As per report of PWD roads Departments, The approach road Gossaidubi Sialkanda Road has been affected length 0.30 Km and the average depth of submergence 0.45 meter due to overflowing water on 14.06.2022 to till date i.e 16.06.2022 (Long - 90.194923, Lat - 26.014536), Lakhipur Khalisabhita Road (RCC Br. No. 15/1) Near Khalisabhita As per report of PWD roads Departments, The approach road Lakhipur Khalisabhita Road (RCC Br. No. 15/1) has been affected length 0.40 Km and erosion due to overflowing water on 14.06.2022 to till date i.e 16.06.2022 (Long - 90.181780, Lat - 25.989407), Dhumerghat Tarangapur Road Near Dharai As per report of PWD roads Departments, The approach road Dhumerghat Tarangapur Road has been affected length 0.15 Km and eroded due to overflowing water on 14.06.2022 to till date i.e 16.06.2022 (Long - 90.182979, Lat - 25.998573), Satsiakhamar tiniali to Mathakata Banchapara via kandapara Road Near Satsiakhamar As per report of PWD roads Departments, The approach road Satsiakhamar tiniali to Mathakata Banchapara via kandapara Road Near Satsiakhamar Road (SPT Br. No. 2/2) Near Satsiakhamar As per report of PWD roads Departments, The approach road Satsiakhamar Road (SPT Br. No. 2/2) has been affected length 0.60 Km due to overflowing water on 14.06.2022 to till date i.e 16.06.2022 (Long - 90.175458, Lat - 25.992117), Khalisabhita to
Kamrup	3	meter due to overflowing water on 14.06.2022 to till date i.e 16.06.2022 (Long - 90.150013, Lat - 25.980133) Kamalpur - Jalimura Sangsari road Vill-Jalimura Total Length 100 M Submergence for a depth of about 45 to 50 CM on 15.06.2022 as per as per report of the Executive Engineer PWD North KMP Territorial Road Sub-Division Rangia (Long - 26.357698, Lat - 91.726525), Madanpur to Katnipara Road Vill-Madanpur Total length about 250 M Submergence for a depth of about 35 to 45 CM on 15.06.2022 as per report of the Executive Engineer PWD North KMP Territorial Road Sub-Division Rangia (Long - 26.318327, Lat - 91.739796), Goroimari - Hatisolapam to Dakshin Laruajan Goroimari Submerge Length 800 m, Breadth 6 m.
Kokrajhar	11	Reported by PWRD Chhaygaon. Date: 16/06/2022. (Long - 91.206634, Lat - 26.066046) Bagribari - Kazigaon to Bashbari Road Kazigaon Kazigaon – Bashbari Road has been submerged (Long - 0.000000, Lat - 0.000000), Tipkai to Khangkhraibari Road Tipkai Tipkai to Khangkhraibari Road has been Submerged (Long - 0.000000, Lat - 0.000000), Khoraghat to Jalabila Road Khoraghat to Jalabila Road berm has been damaged Khoraghat to Jalabila Road berm has been damaged (Long - 0.000000, Lat - 0.000000), Tipkai to Gossaigaon Road Tipkai Tipkai to Gossaigaon Road surface has been damaged (Long - 0.000000, Lat - 0.000000), Tipkai to Tulshijhora Road Tipkai Tipkai Tulshijhora Road has been damaged. (Long - 0.000000, Lat - 0.000000), Borshijhora to Kazigaon Bazar Road Borshijhora Borshijhora to Kazigaon Bazar Road has been submerged (Long - 0.000000, Lat - 0.000000), Santipur to Kazigaon Road Santipur Santipur to Kazigaon Road has been submerged. (Long - 0.000000, Lat - 0.000000), Debitola Bazar to Borvita road Debitola Bazar Debitola Bazar to Borvita road has been submerged (Long - 0.000000, Lat - 0.000000), Debottor Khopati Modati to Kazigaon Road Modati Eroded in some stretches near Bridge No.4/2, at Ch.1000M, at Ch.30M and at Ch.4th KM (Long - 0.000000, Lat - 0.000000), Chilkikhta to Goraimari Road Chilkikhata Pt-I Road has been closed for all kinds of vehicular traffic for Bridge No.1/1, 1/2, & 2/1 (Long - 0.0000000, Lat - 0.000000)
Lakhimpur	1	Nowboicha - Pahumora to Pakania Road Bamungaya Pahumora to Pakania Road. Flood water overtopped from CH:10000m to CH: 11900m. Road surface and hard crust damaged. Erosion occurred in embankment and shoulders in the above stretches on 16/06/2022. Report received from

			PWRD, Nowboicha Territorial Road Sob-Division. (Long - 0.000000, Lat - 0.000000)
	Nagaon	2	Kampur - Changchaki to Bakulaguri Road at Shaibuk Shaibuk Road at 12 Km Changchaki to Bakulaguri Road breached at 12 km in Shaibuk around 12 m on dated 16.06.2022. The road belongs to PWRD Batadrava, Dhing and Raha Territorial Road Division. (Long - 0.000000, Lat - 0.000000), Raha - Raha kampur road Bagalajan date of occurance-15-6-2022 Department -PWD, Raha Raha Kampur road was eroded at Bagalajan area approx-1.5m (Long - 0.000000, Lat - 0.000000)
	Nalbari	14	Banekuchi - BDT road to majgaon Bangnabari As reported by Gaon Pradhan on 15/6/2022 BDT road to majgaon submerged apro.800 mtr. (Long - 91.497014, Lat - 26.388436), PWD road Banekuchi Mohan Bozar to janopar suburi Barnagar Banekuchi As reported by Gaon Pradhan on 16/6/2022, PWD road Banekuchi Mohan Bozar to Janopar Suburi Submerged (Long - 91.378344, Lat - 26.459608), Barkhetri Banekuchi Donguapara Road Danguapara As reported by PWD Department on date 16/06/2022. (Long - 91.392650, Lat - 26.481228), Haripur Seplekuchi Road Seplekuchi as reported by PWD Department on 16.06.2022 haripur Seplekuchi Submerged . (Long - 91.403324, Lat - 26.463371), Chancharghat Nadipar Supa to NH31 Road Nadipar supa as per report by PWD Department on 16/06/2022. (Long - 91.391440, Lat - 26.468939), Banekuchi Circle office road Banekuchi Revue Circle Office (Barkhetri Banekuchi) As reported by PWD Department on 16.06.2022 . Banekuchi Circle office road Submerged (Long - 91.387187, Lat - 26.458418), Nalbari - Gosala to Bherbheri road Sariahtali As per report of PWRD, Nalbari Gosala to Bherbheri road submerged due to flood on 16/06/2022 (Long - 0.000000, Lat - 0.000000), Namati to Hahdoli road Namati As per report of PWRD, Nalbari Namati to Hahdoli road submerged due to flood on 16/06/2022 (Long - 0.000000, Lat - 0.000000), NH 31 to Charminar chowk Barsarkuchi, Barkura As per report of PWRD, Nalbari NH 31 to Charminar chowk road submerged due to flood on 16/06/2022 (Long - 0.000000, Lat - 0.000000), Ralbari to Bahjani road Bahjani As per report of PWRD, Nalbari this road was submerged due to flood on 16/06/2022 (Long - 0.000000, Lat - 0.000000), Nalbari to Bahjani road Kazipara As per report of PWRD, Nalbari this road was submerged due to rain on 16/06/2022 (Long - 0.000000, Lat - 0.000000), Kazipara to Ratanpur road Kazipara As per report of PWRD, Nalbari this road was submerged due to rain on 16/06/2022 (Long - 0.000000, Lat - 0.000000), Chowkbazar to Nalbari Sa
	Sonitpur	1	Chariduar - NH 15 BALIPARA TO LAKHIMPUR ROAD CGARIDUAR REVENUE CIRCLE DTD 16/06/2022 CHARIDUAR REVENUE CIRCLE CHARIDUAR (Long - 26.828512, Lat - 92.780113)
	Tamulpur	1	Tamulpur - Khairani Road Vill - Khairani Due in incessant rainfall 3 M road eroded on 16/06/2022 (Long - 91.470000, Lat - 26.730000)
	Udalguri	4	Khairabari - Paschim Jhargaon to Athiabari Village Road At Pachim Jhargaon (Near Pabitra Das house) The village road was eroded by river Kalpani on 15.06.2022. Length: 200M (approx.) Breadth: 14 M (approx.) (Long - 91.853945, Lat - 26.562286), Bahmolla to Kuhiarkuchi Village Road At Bahmolla One HPC of length 5M (approx.) was damaged at Bahmolla on 15.06.2022 due to heavy rainfall & flood. Length: 5M (approx.) (Long - 91.818578, Lat - 26.526188), Udalguri - Khawrang to Jalpaiguri road Khawrang Road breaches at khaorang to ongoing bridge via jalpaiguri chowk around 17m on 16.06.2022. (Long - 92.072906, Lat - 26.792373), Kalaigaon - MB road at village Bholabari near Bholabari Tea estate Bholabari The road has severely damaged due to incessant rainfall on 16/06/2022 covering a length of around 500 meters and breadth 12 meters. (Long - 91.965206, Lat - 26.581104)
	Total	99 Numbe	
	District	r	Details
Infrastructur e Damaged - Bridge	Barpeta	4	Kalgachia - RCC Br. No.6/1, Khudrakuchi to Bankabhanga road, As per report received from PWD department on 16/06/22, due to continuous heavy rainfall from last several days RCC Br. No.6/1 approach damaged at Khudrakuchi to Bankabhanga road (PMGSY Pkg. No. AS-01-89)(Length=30.00 m, width=2.00m, height=4.00 m) location coordinates- 26.308095, 90.835141. (Long - 0.000000, Lat - 0.000000), RCC Br. No.2/1 & RCC Br. No.6/1 Gunialguri to Digjani road As per report received from PWD department on 16/06/22, due to continuous heavy rainfall from last several days RCC Br. No.2/1 and RCC Br. No.6/1 approach damaged at Gunialguri to Digjani road (PMGSY Pkg. No. AS-01-58)(Length=100.00 m, width=2.50m, height=4.00 m) location coordinates- 26.310524, 90.829237. (Long - 0.000000, Lat - 0.000000), Chenga - RCC Bridge No. 1/1 on Khongra Roumari Pathar Road to Balartari Road bridge Balartari RCC Bridge No. 1/1 on Khongra Roumari Pathar Road to Balartari Road bridge approach damaged. reported by PWD deptt on 16/6/22 (Long - 91.204088, Lat - 26.264059)

	D	Patharighat - Hatimara RCC bridge hatimara Bridge approch affected as reported by JE PWD on 16.5.2022 (Long - 91.861967, Lat - 26.484384),						
	Darrang	Khatara Kaikapara PWD Bridge Khatara Kaikapara Khatara Kaikapara bridge approach damaged as reported by JE PWD on 16.5.2022 (Long - 91.871046, Lat - 26.466121)						
	Dhemaji	Dhemaji - Jiadhal Railway Station to Dighalgarah Connecting bridge (Ch. 1700.00m to ch.1730.00m) Jiadhal Railway Station to Dighalgarah Connecting bridge Today on 16/06/2022, The Bamboo footbridge was damaged and the subway was submerged at the road connecting Jiadhal Railway Station to Dighalgarah road at Ch.1700.00m to ch.1730.00m. (Long - 94.504747, Lat - 27.454250)						
	Nalbari	Nalbari - SPT Wooden Bridge, Sariahtali Sariahtali As per report of PWRD, Nalbari this bridg is washed away due to flood on 15/06/2022 (Long - 0.000000, Lat - 0.000000)						
	Tamulpur	Goreswar - Tengajhar wooden Bridge Tengajhar Dated 16/06/2022 the repaired wooden Bridge got washed away for the third time. (Long - 91.691087, Lat - 26.606480)						
	Udalguri	Udalguri - Brigde at UT Road Ambagaon Slab of Brigde at UT Road Ambagaon village damaged around 15m on 16.06.2022 (Long - 92.016947, Lat - 26.741726), Kalaigaon - RCC slab culvert Kalaigaon Harishinga Road at Majarchuba Majarchuba The damaged slab culvert has totally collapsed due to flood water from river Noa 0n 16/06/2022 covering a length of around 40 meters and breadth of 12 meters. (Long - 91.986173, Lat - 26.608598)						
	Total	11						
Infrastructur	District	Wildlife affected under protected areas description						
e Damaged - Wildlife	Darrang	Dalgaon - as per report received from divisional forest officer, mangaldai wildlife division, orang national park, silbori, flood water level is rising trend. no of total camp -40, no of inundated camps- 12, animal death and rescue - nil, Report recieved date 16-06-2022						
	District	Other Details						
	Baksa	Barama - Culvert Approach Road Damaged Culvert approch completely damaged on both side at Paschim Gelpejar Boro Supa. Date of occurrence: 15/06/22 (Lat: 26.547194 Lon: 91.435235)						
	Barpeta	Gelpejar Boro Supa. Date of occurrence: 15/06/22 (Lat: 26.547194 Lon: 91.435235) Barnagar - Bridge Approach Road Damaged As per WT message received from The Ex. Engineer, Sorbhog & Jania Territorial Road Divn, Barpeta Road vide Memo No. BR/SJTRD/W.T. MESSAGE/2019-20/245 on 15/06/2022 Sorbhog Culvert No. 2/1 on Dakhin Ganakgari to Sontorabari Road has damaged due to heavy rainfall. Long- 90.893671, Lat- 26.471306, Sericulture Deptt. Damaged As per report received fro Asst. Manager, Sericulture Govt,. VGR, Noontola 9.5 Hectare of Som plants including matured and nurtured plants are damaged due to heavy rainfall.						
	Bongaigao n	Dangtol - Culvert Approach Road Damaged Rachigaon to Chengmari road, Damage-HP Culvert damaged at Ch.1890.00m Latitude:26.37872 & Longtitude 90.486003 reported by PWRD Bongaigaon, date of incident 15.06.2022						
Infrastructur e Damaged - Others	Chirang	Bengtal - Damaged SPT Bridge As reported by PWD (R&B) Bengtal Division, SPT bridge over Sampur River severely damaged at village Bhurbasti on 16-06-2022. Lat-26.684004 Long-90.369706, L-20m, B-7m, D-2.7m, Culvert Approach Road Damaged As reported by Forest Department, Culvert approach road damaged on 16-06-2022 at village Aminpara FV, L-10m B-3m D-3m, Lat-26.75 Long-90.44, Handloom & Textile Deptr As reported by Handloom & Textile Department, Handloom materials of two beneficiaries damaged at village Birinchiguri FV on 16-06-2022, Bamboo Foot Bridge Approach road of bamboo footbridge of village Marupara (Ashrabari VCDC) damaged on 16-06-2022, L-4m B-3m D-6m, Lat-26.633943 Long-90.394073, Agri Bundh Damaged Aimai Mathaori Bundh damaged on 16-06-2022 under Thaikajora vcdc, L-4m B-3m D-2.5m, Lat-26.658763 Long-90.405811, Agri Bundh Damaged No.2 Tukrajhar - Deosri mathaori bundh damaged at No.2 Tukrajhar on 16-06-2022, L-4m B-2.5m D-2m, Lat-26.680172 Long-90.467775, Agri Bundh Damaged Bikrampur agriculture canal damaged at Bikrampur on 16-06-2022, L-5m B-2.5m D-2m, Lat-26.633638 Long-90.50083, Sidli - Washed away Culverts As reported by PWD (R&B) Chirang, Bhutiapara village main road (HP Culvert) washed out on 16-06-2022 at Bhutiapara, Damage details - Length :8m, breadth : 7 m, Depth : 2.2 m, Long-90.407738, Lat-26.453193, Damaged SPT Bridge As reported by PWD (R&B) Chirang, Athiabari to Dhopguri Village road on 16-06-2022 at Dhopguri Long- 90.423011, Lat-26.556611 Damage Details: Length:25M, Breadth: 4M, Power Dept. Conductors As reported by SDE, BESD-II, APDCL, 1.3 Km Conductors is damaged on 16-06-2022., Power Dept. Poles As reported by SDE, BESD-II, APDCL, 3 nos. of LT pole washed away and 1 no. of SP 66 Pole got tilted on 16-06-2022.						
	Darrang	Mangaldoi - Power Dept. Conductors As reported by APDCL SDE Mangaldai Approximately 5 nos of poles are damaged as of now under Mangaldai Rev. Circle. Dated 16-06-2022., Culvert Approach Road Damaged Culvert Damaged at BorjharBagisa to Bhakatpara road at Ch. 2200m as reported by PWRD.Dated 16-06-2022., Culvert Approach Road Damaged Culvert damaged at Mangaldai Majikuchi road as reported by PWRD.Dated 16-06-2022., Dalgaon - Irrigation Canal/Scheme Damaged breach occured at different chainage of the canals at sukhjani FIS under dalgaon revenue circle as on 16-06-2022., Power Dept. Conductors due to overflow of river and road side erosion, conductor snapped at different places under kalaigaon ESD. date of occurance 14/06/2022 and 15/06/2022,						

	Power Dept. Poles due to overflow of river and road side erosion, LT & HT poles at different places under kalaigaon ESD. date of occurance 14/06/2022 and 15/06/2022,
	Fisheries/Pond as per report received from fishery development officer, 45 nos of pond and 7 Ha water area
	affected due to flood as on 16/06/2022 under dalgaon revenue circle,
	Patharighat - Power Dept. Conductors poles and conductor snapped as reported by SDE, APDCL on 16.5.2022
Dhubri	Agamoni - Bridge Approach Road Damaged Bridge approaches damaged of RCC Br no. 2/1 on Belguri Satrasal Road via Futaniganj. Dt. 04/06/2022-15/06/2022
	Chabua - Health Sub-Centre DODHIA KULIGAON HEALTH SUB-CENTRE SUBMERGED AS PER
	INFORMATION RECEIVED FROM HEALTH DEPT. ON 16/6/2022 Coordinates-N27 35.835 E95 13.266,
	Elementary Schools Damaged DODHIA ME SCHOOL SUBMERGED AS PER INFORMATION RECEIVED
	FROM EDUCATION DEPT. ON 16/6/2022 Coordinates:- N27 36.390 E95 13.651, Elementary Schools Damaged DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION
	RECEIVED FROM EDUCATION DEPT. ON 16/6/2022 Coordinates:-N27 35.845 E95 13.227,
	Elementary Schools Damaged DODHIA KARMI LPS SUBMERGED AS PER INFORMATION RECEIVED
	FROM EDUCATION DEPT. ON 16/6/2022 Coordinates:- N 27 36.032 E95 14.787, Elementary Schools Damaged DODHIA TENGABARI LPS SUBMERGED AS PER INFORMATION
Dibrugarh	RECEIVED FROM EDUCATION DEPT. ON 16/6/2022 Coordinates:- N27 36.652 E95 14.237,
	Elementary Schools Damaged DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION
	RECEIVED FROM EDUCATION DEPT ON 16/6/2022 Coordinates:- N27 36.462 E95 14.673, Anganwadi Centres Affected DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT. ON 16/6/2022 Coordinates:- N27 35.845 E 95 13.227,
	Anganwadi Centres Affected DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 16/6/2022 Coordinates:-N27 36.652 E95 14.237,
	Anganwadi Centres Affected DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 16/6/2022 Coordinates:- N27 36.390 E95 13.651
	Haflong - Road Breaches Hume Pipe Blocked leading to overflow of water over Road surface. The dia. of
	existing hume pipe is insufficient to pass such voluminous discharge and gets continuously blocked by trees and
	large boulders as per info received from NHAI dated 16 June 2022,
	Road Breaches Due to blockage of hume pipe at ch. 162+040 entire discharge coming to the Hume pipe from the river starts flowing over the road surface towards the Scurve and consequent to this voluminous discharge:-?
	Road at S-curve has become extremely narrow and unsafe for even light vehicles to pass through the section. ?
	Approximately 3m of road has washed out and only 2.5m is left. ? Massive erosion has occurred to the road and
	drain has widened and deepened & road starting to cave in from drain side as huge water current is continuously eroding the side of road. ? Due to erosion soil at the base of Gabion the gabion structure overhangs and thus
	boulders falls over road surface. as per information received from NHAI dated 16 June 2022.,
Dima-	Road Breaches Damage due to landslide in Jatinga to Harangajao section at different intervals 1.) 25.12 245 N,
Hasao	93.0245 05E 2.)25.12 196N,93.0307 83E 3.)25.11 4313N,93.0068 62E 4.)25.10 6542N,92.9877 77E 5.)25.10
	5395N,92.9709 77E 6.)25.11 256N,92.954087E 7.)25.10 9927N,92.936072E 8.)25.10 8985N,92.924705E 9.)25.10 983N,92.898893E 10.)25.10 6208N,92.8682 63E,
	Power Dept. Transformers Damage of 11 KV Sangbar Feeder at Boro Langlai under Umrangso ESD as per
	information received from APDCL dated 16/06/2022,
	Road Breaches Road blockade due to landslide in between Choto Wapu – Haflong tiniali as per information received from EE, PWRD dated 16/06/2022,
	Road Breaches Landslide at Haflong Mission Road, Haflong as per information received from EE, PWRD dated
	16/06/2022,
	Road Breaches Landslide at Haflong-Jatinga Road as per information received from EE, PWRD dated 16/06/2022
	Rongjuli - Irrigation Canal/Scheme Damaged AS PER OFFICIAL LETTER RECEIVED FROM EXECUTIVE
Goalpara	ENGINEER, DUDHNOI GOALPARA EAST DIVISION, IRRIGATION DUDHNOI RANGRANGA FIS 15M
	BRICKLINED CANAL DAMAGED ON 14/06/2022 . INFORMATION RECEIVED DATE: 15/06/2022 AFTER 12:00 PM LATITUDE 25.965876 LONGITUDE: 90.881963
	Rangia - Power Dept. Poles 3 LT poles damaged in village 3 No. Hassang and Khopnikuchi as per report of
	SDE, APDCL, Sub Div-II on 15.6.22,
V	Fisheries/Pond Total 212 nos. of ponds are affected amounting to water area 23.32 Ha as per report of FDO,
Kamrup	Rangia on 15.6.22, Kamalpur - Fisheries/Pond Water logged 20 Ha (Approx) due to Rain water at Vill-
	Majgaon, Kendua, Singarpara, Barkharikota, Baredola, Bangalgaon, Loch, Sahan, Muktapur, Dhulara, Dhuliara on
	15.06.2022 as per report of Fishery Development Officer Bihdia Jajikona Block under Kamalpur Revenue Circle
Kamrup	Guwahati - Power Dept. Poles Mon Akashi Path, Jyoti Nagar, Nizarapar near Bhupen Hazarika Residence,
(M)	Mahesh Deka Road, Kharghuli Hill, Near Raj Bhawan, Due to havy railfall on 16/06/2022 Bagribari - Damaged SPT Bridge As per report received from A.EE, PWD R. R. Sub Div. Gossaigaon, SPT
	Foot Bridge on Kutkujhora to Mantapara Road has been damaged have been damaged due to incessant rainfall
	from 11/06/2022,
Kokraihar	Bamboo Foot Bridge As per report received from A.EE, PWD R. R. Sub Div. Gossaigaon, Bamboo foot
Kokrajhar	bridge and road washout at Khopati PWD Road to Kutkujhora road due to incessant rainfall from 11/06/2022, Bridge Approach Road Damaged As per report received from A.EE, PWD R. R. Sub Div. Gossaigaon, Both
	side approaches have been damaged on Bashbari to Paglijhora Pt-I road of Bridge No.3/2 due to incessant
	rainfall from 11/06/2022,
	Culvert Approach Road Damaged As per report received from A.EE, PWD R. R. Sub Div. Gossaigaon,

		C. L. (M. 2/1 CT) 1 .T. 11.11 D. 11 1 1 1 1 1 1 1 1 1 1 1 1 1
		Culvert No.3/1 of Tipkai Tulshijhora Road has been damaged. due to incessant rainfall from 11/06/2022, Bhawraguri - Elementary Schools Damaged Due to Heavy Rain on 15-06-2022 a school namely Asharikandi Kartimari LPS partially damaged as per information received from School Teacher, Asharikandi Kartimari LPS Lat-26.34678333 Long- 90.10782222,
		Agri Bundh Damaged Due to Heavy Rain on 15-06-2022 a agri bundh damaged because of erosion at Sekadani FV under Sanfan Range as per information received from Range Officer, Sanfan Range Lat-26.535780 Long-90.084538
	Lakhimpur	Nowboicha - Fisheries/Pond Flood affected pond at Mahghuli and Pandhowa village reported by Fishery Dept, Nowboicha (Total Area 72 Hact) on 16/06/2022, Bihpuria - Protection Bundh Damaged About 20 meters of the protection bundh at Garmur has been affected
	Nalbari	on 16/06/2022 under Karunabari Development Block, Lat-27.138207, Long-93.945573 Banekuchi - Road Breaches As reported by Gaon Pradhan on 15/6/2022 at 8 PM ,Madhupur to Bihampur PWD road at Barakhat suburi damaged , Anganwadi Centres Affected As reported by Gaon Pradhan on 15/6/2022 .23 No Gorber AWC submerged , Culvert Approach Road Damaged Banekuchi Chowk to Mohon bazar Road Submerged and Damaged as per Reported PWD Roads on 16.06.2022
	Sonitpur	Chariduar - Health Sub-Centre BALIPARA BPHC SUBMERGED IN WATER DUE TO FLOOD 26.828512 92.780113 DTD 16/06/2022
	South	South Salmara - Power Dept. Poles As per information received from SDE Apdcl 7 nos poles has been damage due to flood/erosion at Khopati Pt-I on 16/6/22. Area Aprox 2 km. Lat-25.82 long-89.93,
	Salmara	Power Dept. Conductors As per information received from SDE Apdcl 2 km conductor has been damage due to flood/erosion at Khopati Pt-I on 16/6/22. Area Aprox 2 km. Lat-25.82 long 89.93
	Tamulpur	Tamulpur - Public Health Centre (PHC) Boundary wall erosion due to incessant rain fall dated - 16/06/2022, vill- Khairani, Lat - 91.47 & Long - 26.73, Health Sub-Centre Boundary wall erosion due to incessant rain fall dated - 16/06/2022 Vill - Khairani, Lat -
		Whairabari - Culvert Approach Road Damaged The RCC Slab culvert of Village: Hatibandha (Lotakhat) got submerged and the approach was damages/eroded on 15.06.2022. Length: 05M (approx.). GPS-Co-ordinated: Lat: 26.634983 Long: 91.882928, Power Dept. Poles Due to heavy rain along with wind occurred on 14.06.2022, at around 5.25 pm, 02 nos. of LT poles were damaged at villages namely Bagaribari & Darogachuba. As a result the power supply have been hampered., Power Dept. Conductors Due to heavy rain along with wind occurred on 14.06.2022,, at around 5.25 am, HT &
	Udalguri	LT conductors were snapped at various places, namely, Bagaribari, Darogachuba & Nalbari. As a result the power supply to various locations have been hampered., Bridge Approach Road Damaged Bridge approach was damaged at Chinakona on Chinakona to Bagaribari road on 15.06.2022. GPS Coordinates: Lat: 26.559327 Long: 91.809134 Length: 12 M (approx.), Udalguri - Bridge Approach Road Damaged Approach road of Slab Culvert at Goraimari Chutiabasti PMGSY road eroded around 15m on 16.06.2022. GPS - Lat - 26.77228 Long - 96.279594, Kalaigaon - Bamboo Foot Bridge The bamboo foot bridge has washed away at village Bheguri connecting Makenji Road to Rupatal on 16/06/2022 covering a length of around 70 meters. Longitude: 91.976151, Latitude: 26.621021
	District	Details
Erosion	Bongaigao n	Srijangram - 1. Boraichala 2. Tinkonia Part-III Erosion has occurred on 16.06.2022 at Boroichala near river of Manas in a length of 300m. As a results 4nos. of families got affected .Due to ongoing erosion at Tinkonia part III 10 nos. of families got affected at Tinkonia Part III.(90.652966 26.239304) 96
	Dibrugarh	Dibrugarh West - Bordoibam Gaon. As per report received from Executive Engineer, WR Division on 15.06.2022 that damage has been observed around 120 m at Bordoibam Area under Dibrugarh West Revenue Circle pertaining to Dibrugarh W.R. Division. Chainage: 4780 m to 4900 m. Long:-271847.45, Lat:-271845.71 0
	Goalpara	Balijana - Kalpani (Bolbola) marginal Bund L/B of Jinari River Bank erosion of river Jinari at Bolbola Kalpani area observed Erosion reach length- 10 m Width- 1 m Date of occurrence- 16.06.2022 Information received from Water Resource Department, Goalpara. 1523
	Kamrup	Kayan - Baralia L/B embankment, Dhuhi No 1, Lormagurhati, Gopalpur Water resource dept. rangia reported erosion at various places of L/B embankment of Baralia river under Kayan Revenue Circle. dated: 15-06-2022 0
	Kokrajhar	Gossaigaon - BAMUNIGAON, MOKRAMBIL, JAKATI, POKALAGI, DEMDEMA NABROPARA, RANIPUR, GARDENPUR, AMGURI, THAIGIGURI, NOBINAGAR, RIMIZIMI, KACHUKATA AS REPORTED BY GOSSAIGAON WR SUB-DIVN, DUE TO CONTINUOUS RAINING FROM 12-06-2022 TO 15-06-2022 1. SEVERE BANK EROSION OBSERVED AT VILLAGE BAMUNIGAON OF RIVER GONGIA ON R/B LENGTH 1000M 2. SEVERE BANK EROSION OBSERVED AT VILLAGE MOKRAMBILOF RIVER JOYMA ON R/B LENGTH 200M 3. SEVERE BANK EROSION OBSERVED AT VILLAGE JAKATI OF RIVER JAKATI ON R/B LENGTH 200M 4. SEVERE BANK EROSION OBSERVED AT VILLAGE POKALAGI OF RIVER JAKATI ON R/B LENGTH 200M 5. SEVERE BANK EROSION OBSERVED AT VILLAGE DEMDEMA NABROPARA OF RIVER GONGIA ON L/B LENGTH 300M 6. SEVERE BANK EROSION OBSERVED AT VILLAGE RANIPUR OF RIVER PEKUYA ON L/B LENGTH 350M 7. SEVERE BANK EROSION OBSERVED AT VILLAGE GARDENPUR OF RIVER GURUPHELLA ON L/B LENGTH 150M 8. SEVERE BANK EROSION OBSERVED AT VILLAGE GARDENPUR OF RIVER GURUPHELLA ON L/B LENGTH

	Morigaon	250M 9. SEVERE BANK EROSION OBSERVED AT VILLAGE THAIGIGURI OF RIVER GURUPHELLA ON L/B LENGTH 300M 10. SEVERE BANK EROSION OBSERVED AT VILLAGE NOBINNAGAR OF RIVER GONGIA ON L/B LENGTH 300M 11. SEVERE BANK EROSION OBSERVED AT VILLAGE RIMIZIMI OF RIVER GONGIA ON R/B LENGTH 550M 12. SEVERE BANK EROSION OBSERVED AT VILLAGE KACHUKATA OF RIVER GONGIA ON R/B LENGTH 600M 0 Laharighat - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori As per report received from the Water Resources Dept on 16-06-22, erosion is observed in areas like Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori, with maximum erosion of 1 m in Leruamukh, 0 m in Goroimari , 3 m in Bhajaikhati gaon & 2 m in
	Nalbari	Barchapori 0 Banekuchi - Kaithalkuchi Laurapara As reported by WRD on 16/6/2022, Nadala Channel near Lourapara suburi (Kaithalkuchi), erosion had occurred 200, Ghograpar - Borajol As per report of WR department erosion has seen at Borajal (paLengdi) of R/B of river Noona length 45 mtr. On 15/06/2022 0
	Sonitpur	Thelamara - Village-Meghaijaroni, Nabeel and Borbeel Bank erosion is observed at Meghaijarani, Borbeel and Nabeel area on R/Bank of river Gabharu as reported by Water Resource Department, Tezpur on 16/05/2022. Erosion Length at Meghaijarani = 50 m Latitude: 26.720523N, Longitude:92.622171E, Erosion Length at Nabeel = 100 m Latitude: 26.648978 N, Longitude:92'624336 E, Erosion Length at Borbeel = 70 m Latitude: 26.648978N, Longitude:92.61804E 0
	South Salmara	Mankachar - Dorua As per report submitted water resourc department, Dorua river site area Erosion due to kaloo river on 16/06/22. Appx- length-40.00M, Breadth-5.00M. 0, South Salmara - Patakata As per information received from SDMO of South Salmara BPHC on 15/6/2022 Patakata Sub-Centre has been eroded due to erosion by river Brahmaputra at village Patakata PO-Patakata PS-South Salmara. Area-0B-4K-0L. 0
	District	Details
	Dima- Hasao	Haflong - 1. Landslide near Ruina Gas Service, Haflong 2. Landslide at multiple points in between Mahur-Laisong Road 3. Gunjung High School Road being steadily washed away from the side due to fast flowing water 1. Landslide near Ruina Gas Service, Haflong 2. Landslide at multiple points in between Mahur-Laisong Road 3. Gunjung High School Road being steadily washed away from the side due to fast flowing water as per information received from PWRD, Haflng on 16/06/2022 0
	Goalpara	Balijana - Ward no. 19, Azad Nagar, Moilapathar Due to incessant rainfall landslide occurred and and road side concrete wall fell down. Due to the landslide 2 (two) nos. of children are death. The date of occurrence 16.06.2022 at around 6.00 am. 2
	Hojai	Lanka - Lumding, Lanka Rev. Circle Landslide Occurred on 16/06/2022 NH54 to Lumding road near Lumding town. Area approx. 100ft x100ft as per reported by Gaon Pradhan, Lumding 0
Landslide	Kamrup	North Ghy - North Guwahati Town, Krishna nagar During field visit by Field Officer it is found that One guard wall near Aswaklanta Temple damaged on 15/6/2022 due to incessant rain in the last few days. However there is no casualty. Notice has been issued to the land slide prone families to move to a safer place. 39
	Kamrup (M)	Sonapur - 12th mile, Ambher An incident of a minor landslide occurred on 16/06/2022 at 12th mile, Ambher village under Sonapur RC where a house was partially damaged. Affected family shifted to a safer place and relief materials was distributed. 5, Guwahati - Kailashpur Kharghuli, Nursery Kamakhya, Kamakhya Gate, Salbari Noonmati, Pub Jyoti Nagar, Purbhachal Path Hill Side near Red Cross Hospital Landslide incident occurred on 16/06/2022 Major: Kailashpur(26.193583, 91.770221), Kharghuli , Salbari(26.19154, 91.803638), Nursery Kamakhya(26.161834, 91.713693) Minor: Pubjyotinagar, Kamakhya Gate (26.9448, 91.41467) 62, Dispur - Hengrabari, Kailashpur, Amgaon-Bonda, Nur Nagar Noonmati, Landslide incident occurred on 16/02/2022 at Hengrabari, Kailashpur, Amgaon-Bonda, Nur Nagar Noonmati. Partial Damage, No Casualty 27
	District	Details
	Bajali	Bajali - Pathsala Town 12000
	Darrang	Mangaldoi - Mangaldoi town Ward No 6 Due to incessant rain and rising of river water Bega water logging problem is seen at low lying areas under Mangaldoi Town as on 16-06-2022 160, Dalgaon - kharupetia Town flood situation due to waterlogging at Kharupetia Town ward no. 2 and 4 under dalgaon revenue circle on 16-06-2022 2000
	Goalpara	Balijana - Goalpara Town Ward no. 04, 07, 14, 15 & 17 Due to urban flood in Goalpara Town Ward no. 04, 07, 14, 15 & 17 got affected. The date of occurrence of Urban flood on 16.06.2022. 1823
Urban Flood	Kamrup (M)	Guwahati - Bhootnath, Maligaon, Bamunimaidan, Boragaon, Gotanagar Partial water logging aetificial flood 0, Dispur - Jyotikuchi, Beharbari, Satgaon, Janasimolu, Anil Nagar, Nabin Nagar, Tarun Nagar, Hatigaon, Sijubari, Rukminigaon, Zoo Road, Odalbakra, Keraikuchi Due to heavy rainfall waterlogging took place on 16/02/2022. 0
	Kokrajhar	Kokrajhar - WARD NO. 1(BANDARPAR MOTHAURI), WARD NO.2(SANTINAGAR PATHSALA, MONORAMA SCHOOL, BABYLAND SCHOOL), WARD NO. 3(SCIENCE COLLEGE KOKRAJHAR), WARD NO.4(BHATARMARI LPS), WARD NO.5(BEd COLLEGE/FLYOVER), WARD NO. 6(KOKRAJHAR COLLEGE), WARD NO. 8(SWRANG COMMUNITY HALL), WARD NO.9(BACKSIDE OF TAXI STAND KOKRAJHAR), WARD NO.10(DWIMALU CLUB) 8466
	Morigaon	Laharighat - Moirabari Railway colony (Moirabari Town) Due to continuous rainfall from the last 2 days (from 14/06/2022) till date, a situation of artificial flood (urban flood) is observed. 188
	Nalbari	Nalbari - Palla road, Hazo road, Bidyapur, Gopalbazar, Barama road, College road, Nagira Chowk and Sarathi road This places are affected due to urban flood on 15/06/2022 5000

Udalguri	Udalguri - Udalguri Town Overtopping of drain water to nearby houses in Udalguri Town area on 16.06.2022 303