

## **FRIMS Assam**



## Flood Reporting And Information Management System

D					ort as on 24-07	'-2022 a	t 4:00 PM				
Particulars	Situation as	on 24-07-2	2022 (in las	st 24 hours)							
Rivers flowing above Danger	Rivers flow	ing above d	langer	Nil							
Level (as per CWC bulletin issued at 8 AM)	Rivers flow flood level	ing above h	ighest	Nil							
District Affected	No. of Districts Affected Name of Flood Affe			Sected Districts Nam			Name of Urban Flood Districts				
	4	Cachar, 1	Morigaon,	Tamulpur	amulpur Kam			rup (M)			
No. Of Revenue Circles Affected	4										
	District	Total	Revenu								
Name Of	Cachar	1	Katigorah								
Revenue Circles Affected	Kamrup (M)	1	Dispur								
	Morigaon	1	Morigaon								
	Tamulpur	1	Goreswar								
	Total	4	Revenue Circle								
	<b>District</b> Cachar	Total 4									
Villages	Morigaon	30		( Katigorah   4 ) ( Morigaon   30 )							
Affected	Tamulpur	1		( Morigaon   30 )							
	Total	35	( Gores	, tar   1 )							
	District	Male	Femal e	Childre n	Total Populatio n	Popul Detail		Crop Area ( in Hect.	Crop Area	n Details	
Population And Crop	Cachar	1109	650	408	2167	(Katigorah   2167)		0.00	( Katigoral	n   0.00 )	
Area Affected	Morigaon	1100	800	210	2110	( Morigaon   2110 )		196.00	( Morigaon   196.00 )		
	Tamulpur	457	345	90	892	( Goreswar   892 )		0.00	( Goreswar   0.00 )		
	Total	2666	1795	708	5169		196.00				
Relief Camps / Centres Opened	District	Total		elief Camp			Relief Distribution Centres				
	Morigaon	6	6(Morig	aon   6)		0(Morigaon   0)					
	Total	6	6				0				
Inmates In Relief Camps	District	Total		e Circlewis	e	Mal e	Femal e	Childre n	Pregnan t / Lactatin g Mother	Person with Disabilit y	
	Morigaon	542	(Moriga	on   542)		210	245	85	2	0	
	Total	542				210	245	85	2	0	
Human Lives Lost -	Nil										

Distribute   Dis	Confirmed						
Lives Lost Confirmed Peath Type  Human  Lives Lost Missing    Nil							
Continued - Double Type - Human   Fives Lost - Nil   Missing -   Nil   Nil   Missing -   Nil   Nil   N							
Death Type Human Lives Lost Missing Type Animals Affected Animals Washed Nil Damaged Nil District  Nil District  District  District  District  District  District  District  District  Dibrugarh Nil Dibrugarh Nil Dibrugarh Nil Dibrugarh D		Nil					
Human Lives Lots Missing Hyman Lives Lots Missing Flore Animals Affected Animals Washed Away Houses Damaged Reseace Operation Relief Distributed Distr							
Lives Lost Missing Human Lives Lost Missing Type Animals Affected Animals Washed Away Houses Damaged Operation Opera		1					
Missing		Nil					
Human Lives Lots Missing - Type Animals Affected Animals Washed Animals Washed Animals Washed Animals Washed Animals Washed Houses Damaged Floor Distributed Others Infrastructure Damaged- Embankmen Breached    District   Number   Dibrugarh   Dib		1311					
Lives Lost   Nil   Strict   Nil							
Missing Type Animals Affected Animals Washed Away Houses Damaged Rescue Operation Relief Distributed Relief Distributed Relief Distributed Third Street							
Type Animals Affected Animals Affected Animals Affected Animals Affected Animals Anima		Nil					
Afficeted Animals Washed Afficeted Animals Washed Afficeted Animals Washed Nil Amay Houses Damaged Rescue Operation Officers Infrastructure Damaged Embankmen (Breached Part of Part o	_						
Affected Animals Washed Away Washed Away Nil Houses Damaged Rescue Operation Relief Distributed Others Relief Others Relief Distributed Others Relief Distributed Others Relief Others Relief Distributed Others Relief Others Relief Distributed Others Rel							
Animals   Washed   Asway		Nil					
Washed Away  Nil Nouses Damaged Rescue Operation Relief Distributed Relief Roll Relief Distributed Relief Relief Distributed Relief Relief Distributed Relief Relief Distributed Relief Relief Relief Distributed Relief Relief Relief Distributed Relief Relief Relief Distributed Relief Relief Relief Relief Distributed Relief Relief Relief Relief Distributed Relief							
Mary		Nii					
House   Damaged   Rescue   Operation   Relief   Distributed   Relief   Distributed   Others		INII					
Nil							
Rescue Operation   Relief Distributed   Relief Distributed   Nil   Section		Nil					
Operation   Relief   Nil							
Relief Distributed Others   Nil		Nil					
Distributed   Relief   Distributed   Distr		1					
Relief   Distributed   Others		Nil					
Distributed Others   District   Political Embankment   Political Emb							
District   Dibrugarh   Dava		NT'I					
Infrastructure Damaged Embankmen t Breached    District   Numbe   Details		Nil					
e Damaged - Embankmen t Breached    District   Numbe   Proper   Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99-72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 \$16'36.41"N 94 \$6'03.88"E   (Long - 27'16'36.41"N 94 \$6'03.88"E   (L							
Embankmen t Breached    District   Numbe report   District   Dibrugarh   District   Dibrugarh   Dibrug							
District   Number	_	Nil					
District   Number   Company   Comp							
District   Parallel	t Breached	<u> </u>					
Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99.72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 ♠16'36.41"N 94♠50'3.88"E   (Long - 27163641.000000, Lat - 9450388.000000)    Total   1	1		NII				
District   Numbe r		District		Details			
Lakhimpur   1   Narayanpur - Athanabari to taranikhat connection Kutcha road.   Athanabari     Lakhimpur   1   Athanabari to taranikhat connection kutcha road breached as per reported by Rangati   Panchayaton 24/07/2022 .   (Long - 0.000000, Lat - 0.000000)   Raha - Khaplangkuchi Tini Ali to Balipara via Baruakhat   Khaplangkuchi   After recedes of flood water erosion observed at road from Khaplangkuchi Tiniali to Balipara   Nagaon   1   Via Baruakhat at Ch. 2200 m and 24000 m submitted by Morigaon District Territorial     Road Division department and date of occurrence- 23/07/2022   (Long - 0.000000, Lat - 0.000000)   Total   2	e Damaged - Embankmen	Dibrugarh	1	Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99.72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 616'36.41"N 94650'3.88"E   (Long -			
Lakhimpur   1	e Damaged - Embankmen	Dibrugarh	1	Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99.72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 6 6 36.41 "N 94 6 6 0 3.88 "E   (Long - 27163641.000000, Lat - 9450388.000000)			
Road  Nagaon  Nagaon  Nagaon  Total  Road	e Damaged - Embankmen	Dibrugarh	1 Numbe	Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99.72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 6 6 36.41 N 94 6 50 3.88 E   (Long - 27163641.000000, Lat - 9450388.000000)			
	e Damaged - Embankmen t Affected	Dibrugarh  Total  District	1 Number	Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99.72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 (6'36.41"N 94 (50'3.88"E   (Long - 27163641.000000, Lat - 9450388.000000)  Details  Narayanpur - Athanabari to taranikhat connection Kutcha road.   Athanabari   Athanabari to taranikhat connection kutcha road breached as per reported by Rangati Panchayaton 24/07/2022.   (Long - 0.000000, Lat - 0.000000)			
Infrastructur Nil	e Damaged - Embankmen t Affected  Infrastructur e Damaged -	Dibrugarh  Total  District  Lakhimpur  Nagaon	1 Numbe r 1	Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99.72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 ♠16'36.41"N 94♠50'3.88"E   (Long - 27163641.000000, Lat - 9450388.000000)  Details  Narayanpur - Athanabari to taranikhat connection Kutcha road.   Athanabari   Athanabari to taranikhat connection kutcha road breached as per reported by Rangati Panchayaton 24/07/2022.   (Long - 0.000000, Lat - 0.000000)  Raha - Khaplangkuchi Tini Ali to Balipara via Baruakhat   Khaplangkuchi   After recedes of flood water erosion observed at road from Khaplangkuchi Tiniali to Balipara via Baruakhat at Ch. 2200 m and 24000 m submitted by Morigaon District Territorial Road Division department and date of occurrence- 23/07/2022   (Long - 0.000000, Lat -			
	e Damaged - Embankmen t Affected  Infrastructur e Damaged -	Dibrugarh  Total  District  Lakhimpur  Nagaon	1 Numbe r 1	Dibrugarh West - DRDA Ring Bund   Bhogamur Block gaon   As per report received from Executive Engineer WRD Dibrugarh on 23-07-2022 that damage has occurred at Bhogamur Block Gaon ring bund which is safeguarding a vast area comprising of agricultural land, and homestead. Almost 30 m of the DRDA ring bund has been damaged on 19-07-2022 when the Water Level of River Burhidehing at the Khowang gauge Site was 99.72 m (rising). The first damage was observed on 8-07-2022 and a Flood report was submitted regarding the same. Moreover, it is to be added that, the bund is on the verge of being breached and this could lead to severe flood inundation in the entire Block gaon area if the water level rises in the prevailing flood season. This is an alarming situation for the residents of Bhogamur Block Gaon, Nadi Kinar Ahom gaon, Ghogamur Tiniali gaon. As such immediate restoration of the DRDA ring bund is utmost essential as it will not be able to withstand any further flooding by the river Burhidehing in the prevailing flood season. Therefore, I would like to solicit your further instructions regarding this matter. Name of Location: DRDA Ring Bund at Bhogamur Block gaon Coordinates: 27 ♠16'36.41"N 94♠50'3.88"E   (Long - 27163641.000000, Lat - 9450388.000000)  Details  Narayanpur - Athanabari to taranikhat connection Kutcha road.   Athanabari   Athanabari to taranikhat connection kutcha road breached as per reported by Rangati Panchayaton 24/07/2022.   (Long - 0.000000, Lat - 0.000000)  Raha - Khaplangkuchi Tini Ali to Balipara via Baruakhat   Khaplangkuchi   After recedes of flood water erosion observed at road from Khaplangkuchi Tiniali to Balipara via Baruakhat at Ch. 2200 m and 24000 m submitted by Morigaon District Territorial Road Division department and date of occurrence- 23/07/2022   (Long - 0.000000, Lat -			

e Damaged -						
Bridge						
Infrastructur e Damaged - Wildlife	Nil					
	District	Other Details				
Infrastructur e Damaged - Others	Lakhimpur	Narayanpur - Agri Bundh Damaged   As per reported from Rangati panchayat on 24/07/2022 one earthen bund dihiri to chariali to majgaon chariali damaged about 20 meteres at pulinaharani village,  Power Dept. Poles   As per reported from JM APDCL on 24/07/2022 two nos. of lt pole damaged due to heavy rain at pulinaharan village				
	District	Details				
Erosion	Bongaigao n	Manikpur - Bashbari part 2   Erosion of around 1300 mtr. had occurred w.ef 17/06/2022 to 30/06/2022.Two (2) Nos of Relief camp opened due to the said erosion (1) Tilpukhuri ME Madrasa ,Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 no. Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 01.07.2022/Total Inmates 718. Nachankuri no 3(Temp.Shelter) Male=41 Female=48 Child=73 Total=162(Latitude=26.458454 Longitude=90.662741)Medical Team- 2 Nos. date-24.07.2022.   880,  Srijangram - Santoshpur part II (26.316175 90.746723) Tinkonia part I (26.240515 90.652965)   Erosion has been going on at Santoshpur part II(700-900 m in length on river bank of Aie) and Tinkonia part I (800 -1000 m in length on river bank of Manas -Brahmaputra)One relief camp is still in operation namely Santoshpur part II MV School (Male -54 Female-50 Children -52) Medical Team-2 , Date-24.07.2022   156				
	Sivasagar	Nazira - Chanbosa under Nazira Revenue Circle   River bank erosion has been observed on 23/07/2022 due to heavy rainfall and seepage from country side to the river side after receding of water level of Dikhow river at L/B near Chanbosa under Nazira Revenue Circle.   0				
Landslide	Nil	Nil				
	District	Details				
Urban Flood	Kamrup (M)	<b>Dispur</b> - Rukminigaon, VIP, Hatigaon, Sijubari, Ghoramara, Keraikuchi, Beharbari   Due to rain waterlogging took place on 23/07/2022   0				