

FRIMS Assam



Flood Reporting And Information Management System

			Assan	Daily Floo	d Report as on	09-06-2022 a	at 4:00 PM				
Particulars	Assam Daily Flood Report as on 09-06-2022 at 4:00 PM Situation as on 09-06-2022 (in last 24 hours)										
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Nil										
District Affected	No. of Districts Affected	Name of Flood Affected Districts Name of Urban Flood Districts									
11110000	4	Dhemaji,	Dima-Has	ao, Morigao	n	Kamrup (M)				
No. Of Revenue Circles Affected	5										
	District	Total	Revenue								
	Dhemaji	2	Gogamu	kh, Sissibor	gaon						
Name Of Revenue	Dima- Hasao	1	Haflong								
Circles Affected	Kamrup (M)	1	Dispur								
	Morigaon	1	Morigao	n							
	Total	5	D	C' 1							
	District	Total	Revenue		C:1	1 \					
Villages	Dhemaji Dima-	7	(Gogam	ukn 6), (S	issiborgaon	1)					
Affected	Hasao	3	(Haflong 3)								
	Morigaon	15	(Morigaon 15)								
	Total	25									
Population And Crop	District	Male	Femal e	Childre n	Total Populatio n	Population Details		Crop Area (in Hect.)	Crop Area Details		
Area Affected	Dhemaji	1019	1149	762	2930	(Gogamukh 1834), (Sissiborgaon 1096)		95.90	(Gogamukh 35.00), (Sissiborgaon 60.90)		
Affected	Morigaon	0	0	0	0	(Morigaon 0)		1000.00	(Morigaon 1000.00)		
	Total	1019	1149	762	2930			1095.90			
Relief	District	Total	Relief CampRelief Distribution Centres0(Gogamukh 0)4(Gogamukh 4)				es				
Camps /	Dhemaji Dima-	4	0(Gogan	nukh 0)			4(Gogamukh 4)				
Centres Opened	Hasao	3	0(Haflor	ıg 0)			3(Haflong 3)				
•	Total	7	0 7								
Inmates In Relief Camps	Nil										
Human Lives Lost - Confirmed	Nil										
Human Lives Lost Confirmed - Death Type	Nil										
Human Lives Lost - Missing	Nil										
Human Lives Lost Missing - Type	Nil										

	District	Total	Big	Small	Poultry						
Animals Affected	Dhemaji	700	360	340	0						
	Total	700	360	340	0						
Animals Washed	Nil										
Away											
Houses Damaged	Nil										
Rescue Operation	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter	Medical Team Deploye d	
	Dima- Hasao	Civil Defence/Trained Volunteers			0	0	0	0	0	15	
	Total	Voluncers			0	0	0	0	0	15	
Relief	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)			
Distributed	Dhemaji	30.06	5.50	1.65	165.00	0.00	0.00	0.00			
	Dima- Hasao	18.06	1.72	0.60	86.00	0.00	0.00	0.00			
	Total	48.12	7.22	2.25	251.00	0.00	0.00	0.00			
	District	Baby Foo Liquid	od .	Baby Foo	od Solid	Others					
Relief	Dhemaji	0.00-Q		0.00-Q	William of the Milliam of the Property of the Milliam of the Milli				0.60.00 1/ 0	•	
Distributed Others	Dima- Hasao	0.00-Q		43.00-Pkt	Haldi-86.00-Pkt; Milk-86.00-L; Potato-968.00-Kg; Onion- 258.00-Kg; Biscuit-602.00-Pkt; Candle-258.00-Pkt; Match Bo 86.00-Pkt; Mosquito Repellent-172.00-Pkt; Napkin-172.00-Pk Mosquito Net-86.00-Pieces; Battery-172.00-Pieces; Torch-86 Pieces					atch Box- 2.00-Pkt;	
Infrastructur e Damaged - Embankment Breached Infrastructur e Damaged - Embankment s Affected	Nil Nil										
	District	Numbe	Details								
Infrastructur e Damaged - Road	Chirang	2 2	Sidli - Jaoliabari LP School to Amtola Balapara LP School Jaoliabari As per Report Received from PWD Department, Road Embankment & Hard crust damages, Length :10m, Breadth:3m and Depth:1.5m Date of Occurrence:09-06-2022, Bengtal - Bengtol Bazar to Oxiguri Road Bengtol Bus Stand As per received from the PWD Department road embankment occurred on 09/06/2022 due to heavy rain, Length:8M, Breadth:3M, Depth:2M								
	Dhemaji	2	Gogamukh - Gogamukh to Ghilamara Road (SH-22) Gogamukh Road Submerge from Ch.0.00 m to Ch.400.00 m (Length 400m) as a result large potholes as well as depression of road surface occurred on 09/06/2022., Sissiborgaon - PWD Road from Bhairabpur to Kulibazar Bhairabpur to Kulibazar Road submerged from ch 3100.00M to ch 3200.00 M (around 100 meters) as on 09-06-2022								
	Goalpara	1	Lakhipur - Khalisabhita Hindupara to Khalisabhita Muslimpara Near Khalisabhita Bazar The approach road of PWD department Khalisabhita Hindupara to Khalisabhita Muslimpara road have been eroded approx Reach length 50 meter and the width of erosion 1 meter by the overflowing wat of river Jinjiram on 06.06.2022 to 08.06.2022						nd have wing water		
	Kamrup	1	Rangia - Approach road to Kanikuchi Nadipar Suba SPT Bridge 2/1 on Bagals Road Vill - Niz Borigog (Kanikuchi) The approach road to Kanikuchi Nadipar Suba SPT bridge was partly eroded on 8.6.2022 due to incessant rain as per report of AEE,PWD NKT Roads, Rangia								
	Nalbari	1	Nalbari - Sonamati Road submerged At Nankarbhoira and Barpipalia As per the report received from PWRD, Nalbari Territorial road Division, Nalbari via Whatsapp group, Sonamati road is submerged at Nankarbhoira and Babpipalia due to rain water dated 09.08.2022							l is	
	South Salmara	4	Mankachar - 1. Shialtari NEC road to Border link road at Thakuranbari 2.Swaponpara to Ampathi Road at Chamaibeel 3.Notun Gaon Bridge to Border Road Thakuranbari 4.Jiarul house to Idrish Ali House Thakuranbari. 1. Thakuranbari GP As per report submitted GP Secretary ,Thakuranbari road								

		damaged due to heavy rain fall on 09/06/22,under Thakuranbari GP, there are 1. Shialtari NEC road to								
		Border link road at Thakuranbari 2.Swaponpara to Ampathi Road at Chamaibeel 3.Notun Gaon								
		Bridge to Border Road Thakuranbari 4. Jiarul house to Idrish Ali House Thakuranbari.								
	Total	11								
Infrastructur										
e Damaged -	Nil									
Bridge Infrastructur										
e Damaged -	Nil									
Wildlife										
	District	Other Details								
	Cachar	Sonai - Handloom & Textile Deptt Handloom & Textiles Department submitted final damage assessment report of 89 nos beneficiary list under Sonai Revenue Circle, as on dated 4.6.2022								
		Bijni - Bamboo Foot Bridge On 09-06-2022 due to rise in the water level of Jiling river(tributary of Air river) a								
	Chirang	bamboo foot bridge was washed away at No 2 Shishubari. Length=15 meter(approx). Breadth=1.82								
		meter(approx). Lattitude=26.517667 Longitude=90.639675,								
		Bengtal - Bamboo Foot Bridge Bamboo foot bridge washed away at village Khoirabari due to rise in water level of Nangalbhanga River on 09/06/2022 Length:30M, Breadth: 2M Long:90.537505, Lat:26.591797								
		Haflong - Irrigation Canal/Scheme Damaged Head Work & Canal structures affected at Maharajpur, Chandpur								
		Nagar FIS, Manigipur FIS, Dilim FIS Purana Dihajeng FIS, Natun Motibra FIS, Dijambra FIS, Khailimdisa FIS,								
		Kolabari FIS, Watiling FIS, Diboula FIS, Diduki FIS, Yeabra FIS, Longsef, Didambra FIS, Jagaidiwari FIS,								
		Mousuhaja FIS, Digerkro FIS, Semkhor FIS, Dakhin Haplai FIS, Lumvumbra FIS, Wajao Langaobra FIS, Wajao								
		FIS, Aivaphai FIS, Kaotaibari FIS, Tongi FIS, Pidik FIS, Nivang FIS, Mailu Hajong LIS, Gereso FIS,								
		Sengyungpur FIS, Maugusahaja FIS, Augmenting-II I.S, Augmenting III F.I.S, Doirangikro I.S, New								
		Simplangdisa I.S, Bonkai I.S, Khepre I.S, Path L/B I.S, Langaokro, Phaipak I/s, Thingvum I.S., Dilimpur I.S.,								
	Dima-	Boothsap I.S., Daoblivdisa I.S., Dima Dergong I.S., Hogllu Nalla I.S., Retzol Ph-I Irri Scheme, Moti Lampu Irri								
	Hasao	Scheme, P. Sangkai I.S., Lower Retzol I.S., Gunjung I.S., Longmailai I.S., Hadima Galao I.S., Chotoluka								
		Irrigation Scheme, Kokdalangso Irri Scheme, Washubil Irrigation Scheme, Rangapur Irri Scheme, Arlongpla Irrigation Scheme, Daodung Irrigation Scheme, as per information received from Irrigation Department on								
		8/06/2022,								
		Irrigation Canal/Scheme Damaged Head Work, Canal Regulator, Canal Main canal affected at Thaisling Hawar								
		Irri Scheme as per information received from Irrigation Department on 8/06/2022,								
Infrastructur		Irrigation Canal/Scheme Damaged Pump & Canal structures affected at Langaobra LIS and Natun Haja LIS as								
e Damaged - Others		per information received from Irrigation Department on 8/06/2022								
Others	Goalpara	Lakhipur - Power Dept. Conductors As per report of APDCL Lakhipur ESD, LT conductor 0.2 KM at								
		Haldibari, 0.3 KM at Fesarjhar 0.5 KM at Kurung has been damaged on 06.06.2022 and information received on								
		07.06.2022,								
		Power Dept. Poles As per report of APDCL Lakhipur ESD, 2 nos HT Pole at Haldibari, 6 nos LT Pole at Fesarjhar and 2 nos HT Pole at Kurung has been damaged on 06.06.2022 and information received on								
		07.06.2022,								
		Power Dept. Transformers As per report of APDCL Lakhipur ESD, DTR 1×16KVA at Chataimari and DTR								
		1×100KVA at Chataimari Cow Market has been damaged on 06.06.2022 and information received on								
		07.06.2022,								
		Balijana - Power Dept. Poles 3 nos. of LT Poles damaged in village Silsak Damal, Date of occurrence-								
		06.06.2022, information received from APDCL Department Lakhipur Electrical Sun- Division, Goalpara.,								
		Power Dept. Conductors 0.5 KM conductor damaged in village Silsak Damal, Date of occurrence- 06.06.2022,								
		information received from APDCL Department Lakhipur Electrical Sun- Division, Goalpara. Nilambazar - Fisheries/Pond As per report received on 1st june-2022 from District Fishery office, Karimganj,								
	Karimgan	due to incessant of rain fall damages of pond were reported 160 nos of Farmers affected, Total W/A-35 Ha								
	j	approx., Total Loss-Rs. 7,14,000/- approx., nature of Damages-pond damaged and embankments are inundated								
		Nalbari - Culvert Approach Road Damaged As per the W.T msg No-1818-21 dated 07.06.2022 from E.E,								
	Nalbari	PWRD, Nalbari Dist Territorial Road Division received on 08.06.2022, a Culvert Damage in NH-31 to								
		Charminar Chowk Road								
	South	Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department Irrigation Cana								
	Salmara	damage due to heavy rain fall on 09/06/22, as follows Right Main canal of length 42 M as well Left Main canal								
	District	of lenght 27M of Chandamari F.I.S of village chandamari GP- Bhagapara. under Mankachar Dev. Block Details								
Erosion	Biswanat	Halem - Paken Mild erosion observed at Paken area on R/B of river Brahmaputra since 06/06/22 to today 09-								
	h	06-2022. Length 1400m 0								
	Dhubri	Agamoni - Village Borobalarchar under Uttar Maragadadhar GP. • Name of the village: Borobalarchar under								
		Uttar Maragadadhar GP. • Name of River: Gangadhar. • Date of Incident: 6th June'2022 to 9th June'2022. •								
		Time: 1.00 PM. • GPS Co-ordinates: Lat: 26.237469, Long: 89.838106 • Land: 1B-4K-10L (Agricultural Land)								
		(approx.). • Population and household damage: No damage till date. 0								
	Dibrugar h	Dibrugarh West - Thangaon As per report received from Executive Engineer, WR Division on 08.06.2022 that								
		damage has been observed at Thangaon area Right Bank of River Burhidehing under Dibrugarh West Revenue								
		Circle pertaining to Dibrugarh W.R. Division. Name of Dyke: Extension of Tengakhat Bund R/B from								
	V-	Bhogamur to Sessamukh. Location Chainage: 13400 m, Lat:-944456.99 Long:-271457.61 0								
	Kamrup	Hajo - Vill- Sarubakra (Kahibari) As per report of SDO WR, Hajo, yesterday i.e 08/06/2022 erosion occurred at								

		Hajo Suti R/B embankment near Ch. 2900m. Visited with WR Hajo staff and Gaonpradhan . Approximately eroded 120 m 0					
South Salmara Tinsukia		Tezpur - Tinikhoria Chapori Dated: 09/06/2022. As reported by Water Resource Department, Active Bank Erosion is observed at Tinikhoria Chapori under Bihaguri mouza on the R/B of the Brahmaputra river. Length 600 m. (erosion is within the same stretch as reported earlier on 01/06/2022, 02/06/2022, 03/06/2022 & 04/06/2022). 0					
		Mankachar - Berabhanga Pt-I As per report submitted Water Rescues Department Berabhanga Pt-I river side area erosion due to Brahmaputra on 09/06/22. Appx- Length- 1500M, Berath-15 M. 0					
		Doomdooma - 1. Village: No. 1 Kordoiguri(Darjijan), 2. Village: No. 2 Kordoiguri (Simoluguri Satra). 1. River Bank erosion is being observed at No. 1 Kordoiguri (Darjijan)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 09/06/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 400 m in length.(Long: 95.450531, Lati: 27.651217), population affected 37. 2. River Bank erosion is being observed at No.2 Kordoiguri (Simoluguri Satra)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 09/06/2022. As per information received from concerned Lot Mandal and WR department officials, the affected stretch is about 460 m in length.(Long: 95.4505, Lati: 27.65196) 0					
	Udalguri	Kalaigaon - Dolagrant Erosion continues and further deteriorated from last year at Village Dalagrant on 09/06/2022 in the R/B of river Nanoi covering a length of around 620 meters. 60					
Landslide	Nil						
Urban Flood	District	Details					
	Kamrup (M)	Dispur - Keraikuchi, Wireless, Hatigaon, Lokhra, Beharbari, Kahilipara-Jatiya, Rukminigaon, PIBCO, Borbari, Hengrabari, Anil Nagar, Nabin Nagar, Bhangagarh, Juripar Due to heavy rainfall waterlogging took place on 09/06/2022 0					