

## **FRIMS Assam**



## Flood Reporting And Information Management System

	Assam Daily Flood Report as on 04-08-2022 at 4:00 PM											
Particulars	Situation as on 04-08-2022 (in last 24 hours)											
Rivers												
flowing	Rivers flowing above danger level				Nil							
above												
Danger												
Level (as per												
CWC												
bulletin	Rivers flowing	ng above hig	ghest flood	level	Nil							
issued at 8 AM)												
AIVI)	No. of											
District Affected	Districts	Nome of	Flood Affe	octod Diet	riote		N	ame of Urban	Flood Distri	ots		
	Affected	Name of	rioou Aire	cticu Dist	ricts		170	anie or Orban	rioou Distri	Cis		
Affected	6	Rajali Ch	irang Dar	rang Dhe	maji Tamulnur l	Udalouri						
No. Of	0	Dajan, Ci	ijali, Chirang, Darrang, Dhemaji, Tamulpur, Udalguri									
Revenue												
Circles	7											
Affected												
	District Total Revenue Circle											
	Bajali	1	Sarupeta									
Name Of	Chirang	1	Bijni									
Revenue	Darrang	1	Ü	Mangaldoi								
Circles	Dhemaji	1	Dhemaji									
Affected	Tamulpur	1	Goreswa									
	Udalguri	2	Khairaba	ari, Harisi	nga							
	Total	7			<u> </u>							
	District	Total	Revenue	e Circle								
	Bajali	1	( Sarupe									
	Chirang	1	(Bijni									
Villages	Darrang	4	(Mangaldoi   4)									
Affected	Dhemaji	2	( Mangardor   4 ) ( Dhemaji   2 )									
	Tamulpur	2		(Goreswar   2)								
	Udalguri	6		( Khairabari   3 ), ( Harisinga   3 )								
	Total	16	( Khairabarr   5 ), ( Transhiga   5 )									
			F 1 C111		Total			Crop				
	District	Male	Femal Children		Populatio	Population	Details	Area (in	Crop Area	Details		
					n			Hect.)				
D. L.:	Bajali	130	185	67	382	( Sarupeta   382 )		0.00	( Sarupeta   0.00 )			
Population And Crop	Chirang	92	81	50	223	(Bijni   223)		0.00	( Bijni   0.00 )			
And Crop Area	Darrang	0	0	0	0	( Mangaldoi   0 )		256.00	( Mangaldo			
Affected	Dhemaji	0	0	0	0	(Dhemaji   0)		10.00	( Dhemaji			
	Tamulpur	204	160	61	425	( Goreswar		0.00	( Goreswar			
	Udalguri	549	471	143	1163	( Khairabari		54.00	( Khairabar			
						Harisinga   3	Harisinga   381 )		Harisinga   54.0			
	Total	975	897 321 2193				D H OF		320.00			
Relief Camps /	District	Total	Relief C			Relief Distribution Centr			entres			
	Bajali	1	0(Sarupe			1(Sarupeta   1)						
Centres	Chirang	1	1(Bijni				0(Bijni					
Opened	Udalguri	6 <b>8</b>	<u> </u>	abari   3, E	[arisinga   3)	0(Khairabari   0, Harisinga   0)						
	Total	7	7				1					
	District	Total	Revenue Circlew			Male	Female		Pregnant	Person		
					ise			Childre	T 4 - 1	with		
Inmates In								n	Lactatin	Disabilit		
Relief	Chi	222	(D:::::1.0	223			01	50	g Mother	<b>y</b> 0		
Camps	Chirang	223	(Bijni   2		(Harisin as 1	92	81	30	0	U		
	Udalguri	1076	(Khairabari   727), (Harisinga 349)		(riansinga	480	490	106	0	0		
	Total	1299	349)			572	571	156	0	0		
Human	Nil	1477				314	5/1	130	U	U		
Human	1411											

Lives Lost -										
Confirmed										
Human										
Lives Lost										
Confirmed -	Nil									
Death Type										
Human										
Lives Lost -	Nil									
Missing										
Human										
Lives Lost	Nil									
Missing -	1411									
Type										
Animals	District Total Big Small Poultry									
Affected	Bajali	42	25	17	0					
	Total	42	25	17	0					
Animals										
Washed	Nil									
Away			•		•		•	•		
		Fully	Fully	Fully	Partially	Partially	Partiall	Others	Others	Others
Houses	District	Kuccha	Pukka	Total	Kuccha	Pukka	y Total	Huts	Cattle	Total
Damaged		0	0	0	_	2	-	0	Shed	
	Dhemaji	0	0	0	5	0	5	0	0	0
	Total	0	0	0	5	0	5	0	0	0
Rescue	Nil									
Operation							G 1/2			
						Cattle	Cattle			
	District	Rice (in	Dal (in	Salt (in	M. Oil (in	Feed - Green	Feed - Wheat	Cottle For	ad Dias Du	on (in O)
D 1: C	District	<b>Q</b> )	<b>Q</b> )	<b>Q</b> )	L)	Fooder (in	Bran (in	Cattle red	ed - Rice Br	an (m Q)
Relief						Q)	`			
Distributed	Bajali	6.50	1.15	0.47	36.50	0.00	<b>Q</b> )	0.00		
		8.79	1.13	0.47	46.37	0.00	0.00			
	Udalguri Total							0.00		
			1 2 70	1 0 02	92 97	1 0 00	0.00	0.00		
		15.29	2.70	0.93	82.87	0.00	0.00	0.00		
Daliaf	District	Baby Foo		Baby Food		0.00 Others	0.00	0.00		
Relief	<b>District</b> Bajali	Baby Foo		Baby Food		Others		0.00		
Distributed	District	Baby Foo		Baby Food		Others  Tarpaulin-63	3.00-Pieces		oil 14 00 Pk	t: Candla
	<b>District</b> Bajali	Baby Foo	d Liquid	Baby Food		Others  Tarpaulin-63 Sanitary Pad	3.00-Pieces -361.00-Pkt;	Mosquito c	oil-14.00-Pk	tt; Candle-
Distributed Others	District Bajali Chirang	0.00-Q 0.00-Q	d Liquid	Baby Food 0.00-Q 0.00-Q		Others  Tarpaulin-63	3.00-Pieces -361.00-Pkt;	Mosquito c	oil-14.00-Pk	t; Candle-
Distributed Others	District Bajali Chirang Udalguri	0.00-Q 0.00-Q	d Liquid	Baby Food 0.00-Q 0.00-Q		Others  Tarpaulin-63 Sanitary Pad	3.00-Pieces -361.00-Pkt;	Mosquito c	oil-14.00-Pk	t; Candle-
Distributed Others  Infrastructur e Damaged -	District Bajali Chirang	0.00-Q 0.00-Q	d Liquid	Baby Food 0.00-Q 0.00-Q		Others  Tarpaulin-63 Sanitary Pad	3.00-Pieces -361.00-Pkt;	Mosquito c	oil-14.00-Pk	t; Candle-
Distributed Others	District Bajali Chirang Udalguri	0.00-Q 0.00-Q	d Liquid	Baby Food 0.00-Q 0.00-Q		Others  Tarpaulin-63 Sanitary Pad	3.00-Pieces -361.00-Pkt;	Mosquito c	oil-14.00-Pk	t; Candle-
Distributed Others Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil	0.00-Q 0.00-Q	d Liquid	Baby Food 0.00-Q 0.00-Q		Others  Tarpaulin-63 Sanitary Pad	3.00-Pieces -361.00-Pkt;	Mosquito c	oil-14.00-Pk	t; Candle-
Distributed Others Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri	Baby Foo 0.00-Q 0.00-Q 43.00-Pkt	d Liquid	Baby Food 0.00-Q 0.00-Q		Others  Tarpaulin-63 Sanitary Pad	3.00-Pieces -361.00-Pkt;	Mosquito c	oil-14.00-Pk	t; Candle-
Distributed Others Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil	Baby Foo 0.00-Q 0.00-Q 43.00-Pkt	d Liquid  Details	Baby Food 0.00-Q 0.00-Q 0.00-Q	d Solid	Others  Tarpaulin-63 Sanitary Pad	3.00-Pieces -361.00-Pkt: Iatches-17.0	: Mosquito c 0-Pkt		
Distributed Others  Infrastructur e Damaged - Embankment Breached	District Bajali Chirang Udalguri Nil	Baby Foo 0.00-Q 0.00-Q 43.00-Pkt	d Liquid  Details  Bajali - 1	Baby Food 0.00-Q 0.00-Q 0.00-Q	of river Rupal	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M	3.00-Pieces -361.00-Pkt; Iatches-17.0	Mosquito c 0-Pkt	a   Bank Mig	ration at
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur	District Bajali Chirang Udalguri Nil	Baby Foo 0.00-Q 0.00-Q 43.00-Pkt	Details  Bajali - 1 Panpara	Baby Food 0.00-Q 0.00-Q 0.00-Q Panpara area area of river	of river Rupal Rupahi at Rigl	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M	8.00-Pieces -361.00-Pkt: Iatches-17.0	Mosquito c 0-Pkt ent   Panpara 2nd KM) fo	a   Bank Mig or a reach len	ration at 1gth of 250
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged -	District Bajali Chirang Udalguri Nil District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt   Number	Details  Bajali - J  Panpara a M. This i	Baby Food 0.00-Q 0.00-Q 0.00-Q Panpara area area of river	of river Rupal Rupahi at Rigi	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M	8.00-Pieces -361.00-Pkt: Iatches-17.0	Mosquito c 0-Pkt ent   Panpara 2nd KM) fo	a   Bank Mig or a reach len	ration at 1gth of 250
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil	Baby Foo 0.00-Q 0.00-Q 43.00-Pkt	Details  Bajali - Panpara : M. This : 91.11775 Chengeli	Panpara area area of river report is rece 54, Lat - 26.6 mari area of	of river Rupal Rupahi at Rigi ived from AEI 61950), river Rupahi a	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di	8.00-Pieces -361.00-Pkt; Iatches-17.0  k Embankmakment ( Ch. vision,Paths	ent   Panpara 2nd KM) fo ala on 3rd A	a   Bank Mig or a reach len august,2022   nari   Bank M	ration at 19th of 250 (Long -
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged -	District Bajali Chirang Udalguri Nil District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt   Number	Details  Bajali - 1 Panpara : M. This i 91.11775 Chengeli Chengeli	Panpara area area of river report is rece 54, Lat - 26.6 mari area of mari area of	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  at Right Ban t Bank Embar E,Bajali WR di at Right Bank E	8.00-Pieces -361.00-Pkt; Iatches-17.0  k Embankmakment ( Ch. vision,Paths Embankment	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac	ration at gth of 250 (Long -  ligration at th length of
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt   Number	Details  Bajali - 1 Panpara : M. This : 91.11775 Chengeli Chengeli 150 M. T	Panpara area area of river report is rece 64, Lat - 26.6 mari area of Chis report is	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di	8.00-Pieces -361.00-Pkt; Iatches-17.0  k Embankmakment ( Ch. vision,Paths Embankment	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac	ration at gth of 250 (Long -  ligration at th length of
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Number   2	Details  Bajali - 1 Panpara : M. This : 91.11775 Chengeli Chengeli 150 M. T	Panpara area area of river report is rece 54, Lat - 26.6 mari area of mari area of	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  at Right Ban t Bank Embar E,Bajali WR di at Right Bank E	8.00-Pieces -361.00-Pkt; Iatches-17.0  k Embankmakment ( Ch. vision,Paths Embankment	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac	ration at gth of 250 (Long -  ligration at th length of
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Number   2   2	Details  Bajali - 1 Panpara : M. This : 91.11775 Chengeli Chengeli 150 M. T	Panpara area area of river report is rece 64, Lat - 26.6 mari area of Chis report is	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  at Right Ban t Bank Embar E,Bajali WR di at Right Bank E	8.00-Pieces -361.00-Pkt; Iatches-17.0  k Embankmakment ( Ch. vision,Paths Embankment	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac	ration at gth of 250 (Long -  ligration at th length of
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Number   2	Details  Bajali - I Panpara : M. This : 91.11775 Chengeli Chengeli 150 M. T 91.13030	Panpara area area of river report is rece 64, Lat - 26.6 mari area of Chis report is	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  at Right Ban t Bank Embar E,Bajali WR di at Right Bank E	8.00-Pieces -361.00-Pkt; Iatches-17.0  k Embankmakment ( Ch. vision,Paths Embankment	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac	ration at gth of 250 (Long -  ligration at th length of
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Number   2   2	Details  Bajali - 1 Panpara M. This is 91.11775 Chengeli 150 M. T 91.13030  Details	Panpara area area of river report is rece 54, Lat - 26.6 mari area of This report is 77, Lat - 26.6	of river Rupal Rupahi at Rigl ived from AEI 61950), river Rupahi a river Rupahi a received from 647172)	Others  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  Tarpaulin-63 Sanitary Pad Sanitary	k Embankmakment ( Ch. vision,Paths Embankment ( R division,F	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K athsala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ord August,20	ration at egth of 250 (Long - ligration at the length of 222   (Long - ligration at 222   (Long - ligr
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2	Details  Bajali - 1 Panpara M. This is 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba	Panpara area area of river report is reces 4, Lat - 26.6 mari area of Chis report is 77, Lat - 26.6 mari - Naligao	of river Rupal Rupahi at Rig ived from AEI 61950), river Rupahi a river Rupahi a received from 47172)	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban nt Bank Embar E,Bajali WR di at Right Bank E at Right Bank E AEE,Bajali W	k Embankmakment ( Ch. vision,Paths Embankment R division,F	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th Kathsala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ird August,20	ration at 1250 (Long - 425) (225) (Long - 425)
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2	Details  Bajali - Panpara M. This is 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete	Panpara area area of river report is rece 54, Lat - 26.6 mari area of Chis report is 07, Lat - 26.6 ari - Naligao ely submerge	of river Rupal Rupahi at Rigleived from AEI 661950), river Rupahi a river Rupahi a received from 647172)	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di at Right Bank E AEE,Bajali W	k Embankmakment ( Ch. vision, Paths Embankment (R division, Faths and the control of the control	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th Ka Pathsala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ird August,20 Naligaon   R	ration at 19th of 250 (Long - 250) ligration at 15th length of 2022   (Long - 250) load Reported by
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2	Details  Bajali - I Panpara : M. This i 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW	Panpara area area of river report is rece 54, Lat - 26.6 mari area of Chis report is 77, Lat - 26.6 ari - Naligao ely submerge (RD on 30.07)	of river Rupal Rupahi at Rigleived from AEI 661950), river Rupahi a river Rupahi a received from 647172)	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban nt Bank Embar E,Bajali WR di at Right Bank E at Right Bank E AEE,Bajali W	k Embankmakment ( Ch. vision, Paths Embankment (R division, Faths and a damaged. S	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th Ka Pathsala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ird August,20 Naligaon   R	ration at 19th of 250 (Long - 250) ligration at 15th length of 2022   (Long - 250) load Reported by
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2	Details  Bajali - I Panpara : M. This : 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW 26.38348	Panpara area area of river report is rece 54, Lat - 26.6 mari area of Chis report is 77, Lat - 26.6 ari - Naligao ely submerge (RD on 30.07 35),	of river Rupal Rupahi at Rigl ived from AEI i61950), river Rupahi a river Rupahi a received from i47172)	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di at Right Bank E AEE,Bajali W	k Embankmankment (Ch. vision, Paths Embankment (R division, Faths and a damaged. S. 17.06.2022	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K Pathsala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ord August,20 Naligaon   R I damaged, F 1.135210, La	ration at gth of 250 (Long - figration at th length of 222   (Long - coad Reported by at -
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected  Infrastructur e Damaged -	District Bajali Chirang Udalguri Nil District  Bajali  Total District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2     2     Numbe   r	Details  Bajali - I Panpara : M. This : 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW 26.38348 Bagana S	Panpara area area of river report is rece 54, Lat - 26.6 mari area of Chis report is 07, Lat - 26.6 ari - Naligao ely submerge (RD on 30.07 35), Saldah Galiba	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from 647172)  on Pithadi Roac d. Road suface 7.2022(Damag andha Road SE	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di at Right Bank E AEE,Bajali W  ((Bhaktardoba e and formation ed occurred on	k Embankmankment (Ch. vision, Paths Embankment (R division, Faths and adamaged. S. 17.06.2022, ith approach	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th Kantala on 3   Chengelin ( Ch. 4th Kantala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac rd August,20  Naligaon   R I damaged, F 1.135210, La	ration at gth of 250 (Long - figration at th length of O22   (Long - coad Reported by at -
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected	District Bajali Chirang Udalguri Nil District Bajali	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2	Details  Bajali - 1 Panpara : M. This is 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW 26.38348 Bagana S completes	Panpara area area of river report is rece 54, Lat - 26.6 mari area of Chis report is 07, Lat - 26.6 ari - Naligao ely submerge (RD on 30.07, Saldah Galiba ely submerge (St.)	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from 647172)  In Pithadi Road d. Road suface 7.2022(Damag andha Road SF d. Road surface	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di ht Right Bank E ht Right Bank E AEE,Bajali W  d(Bhaktardoba e and formation ed occurred on  PT Br no 1/1 w e and formatio	k Embankmankment (Ch. vision, Paths Embankment (R division, Faths and adamaged. S 17.06.2022) ith approach n damaged.	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K 2athsala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ord August,20 Naligaon   R I damaged, F 1.135210, La .   Bagana   F /1 with appro	ration at agth of 250 (Long - digration at the length of 222   (Long - digration at the length of 222   (Long - digration at the length of 223   (Long - digration at the length of 224   (Long - digration at the length of 224   (Long - digration at the length of 244   (Long - digrati
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected  Infrastructur e Damaged -	District Bajali Chirang Udalguri Nil District  Bajali  Total District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2     2     Numbe   r	Details  Bajali - 1 Panpara : M. This is 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW 26.38348 Bagana S complete damaged	Panpara area area of river report is reces 64, Lat - 26.6 mari area of This report is 77, Lat - 26.6 ari - Naligao ely submerge (RD on 30.07, Saldah Galibaely submerge Reported by Report	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from 647172)  on Pithadi Road d. Road suface 7.2022(Damag andha Road SI d. Road surface y AEE,PWRD	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di at Right Bank E AEE,Bajali W  ((Bhaktardoba e and formation ed occurred on	k Embankmankment (Ch. vision, Paths Embankment (R division, Faths and adamaged. S 17.06.2022) ith approach n damaged.	ent   Panpara 2nd KM) fo ala on 3rd A   Chengelin ( Ch. 4th K 2athsala on 3	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ord August,20 Naligaon   R I damaged, F 1.135210, La .   Bagana   F /1 with appro	ration at agth of 250 (Long - digration at the length of 222   (Long - digration at the length of 222   (Long - digration at the length of 223   (Long - digration at the length of 224   (Long - digration at the length of 224   (Long - digration at the length of 244   (Long - digrati
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected  Infrastructur e Damaged -	District Bajali Chirang Udalguri Nil District  Bajali  Total District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2     2     Numbe   r	Details  Bajali - 1 Panpara : 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW 26.38348 Bagana S complete damaged 91.17002	Panpara area area of river report is reces 64, Lat - 26.6 mari area of This report is 77, Lat - 26.6 ari - Naligao ely submerge (RD on 30.07, Saldah Galibaely submerge 1, Reported be 21, Lat - 26.4	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from 647172)  on Pithadi Road d. Road suface 7.2022(Damag andha Road SI d. Road surfac y AEE,PWRD 148891),	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di ht Right Bank E ht Right Bank E AEE,Bajali W  d(Bhaktardoba e and formation ed occurred on PT Br no 1/1 w e and formatio on 30.07.2022	k Embankment (Ch. vision, Paths Embankment (R division, Faths a damaged. S. 17.06.2022) ith approach n damaged of the company	ent   Panpara 2nd KM) for ala on 3rd A   Chengelin ( Ch. 4th Kathsala on 3   PT Br no 2/2   Long - 9   Long -	a   Bank Mig or a reach len august,2022   nari   Bank M M) for a reac ord August,20 Naligaon   R I damaged, F I.135210, La .   Bagana   F /1 with appr 17.06.2022)	ration at agth of 250 (Long - digration at the length of 2022   (Long - digration at the length of 2022   (Long - digration at the length of 2024   (Long -
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected  Infrastructur e Damaged -	District Bajali Chirang Udalguri Nil District  Bajali  Total District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2     2     Numbe   r	Details  Bajali - I Panpara I M. This I 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW 26.38348 Bagana S complete damaged 91.17002 Rangia N	Panpara area area of river report is reces 64, Lat - 26.6 mari area of This report is 77, Lat - 26.6 ari - Naligao ely submerge (RD on 30.07, Saldah Galibaely submerge, Reported be 21, Lat - 26.4 Vadir Pam M	of river Rupal Rupahi at Rigl ived from AEI 661950), river Rupahi a river Rupahi a received from 647172)  on Pithadi Road d. Road suface 7.2022(Damag andha Road SF d. Road surfac y AEE,PWRD 148891), EM to Besima	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban at Bank Embar E,Bajali WR di at Right Bank E AEE,Bajali W  d(Bhaktardoba e and formation ed occurred on PT Br no 1/1 w e and formatio on 30.07.2022	k Embankmankment (Ch. vision, Paths Embankment (R division, Faths 17.06.2022) ith approach n damaged. Clamaged CVillage Road	ent   Panpara 2nd KM) for ala on 3rd A   Chengelin ( Ch. 4th Kathsala on 3   C	a   Bank Mig or a reach len tugust,2022   nari   Bank M M) for a reach rd August,20 Naligaon   R I damaged, F 1.135210, La .   Bagana   F /1 with appr 17.06.2022)	ration at agth of 250 (Long - digration at the length of 2022   (Long - digration at the length of 2022   (Long - digration at the length of 2024   (Long -
Distributed Others  Infrastructur e Damaged - Embankment Breached  Infrastructur e Damaged - Embankment Affected  Infrastructur e Damaged -	District Bajali Chirang Udalguri Nil District  Bajali  Total District	Baby Foo   0.00-Q   0.00-Q   43.00-Pkt     Numbe   r     2     2     Numbe   r	Details  Bajali - 1 Panpara M. This is 91.11775 Chengeli 150 M. T 91.13030  Details  Sartheba complete AEE,PW 26.38348 Bagana S complete damaged 91.17002 Rangia N Nadir Pa	Panpara area area of river report is reces 4, Lat - 26.6 mari area of This report is 77, Lat - 26.6 mari area of Saldah Galibasely submerge RD on 30.07 Saldah Galibasely submerge I, Lat - 26.4 Nadir Pam M m   Road submerge RO on Submerge II, Lat - 26.4 Nadir Pam M m   Road submerge II Road subm	of river Rupal Rupahi at Rigleived from AEI 661950), river Rupahi a river Rupahi a received from 647172)  on Pithadi Road d. Road suface 7.2022(Damag andha Road SF d. Road surface y AEE,PWRD 148891), EM to Besima benerged comp	Tarpaulin-63 Sanitary Pad 56.00-Pkt; M  ni at Right Ban ht Bank Embar E,Bajali WR di ht Right Bank E ht Right Bank E AEE,Bajali W  d(Bhaktardoba e and formation ed occurred on PT Br no 1/1 w e and formatio on 30.07.2022	k Embankmakment ( Ch. vision,Paths Embankment ( Ch. vision,Paths Embankment ( Ch. vision,Faths Embankment ( Ch. vision,Faths) Embankment ( Ch. vision,	ent   Panpara 2nd KM) for ala on 3rd A   Chengelin ( Ch. 4th K. athsala on 3   Chengelin ( Ch. 4th K. athsala on 3   Chengelin ( Ch. 4th K. athsala on 3	Naligaon   R I damaged, F I with approach	ration at agth of 250 (Long - ligration at the length of 222   (Long - load Reported by at - Road coach badly   (Long - load   Rangia es damaged,

Lat - 26.350793), Barpeta Doulasal Road to amrikhowa Mazdia Road . SPT Br no 2/1 & road surface badly damaged. amrikhowa Mazdia | Road submerged completely .Road surface & SPT Br no 2/1 with approaches damaged, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long-91.443210, Lat - 26.301134), Chengdi Doulasal Road .SPT Br no 1/1 badly damaged with approaches. | Chengdi | Road submerged completely .Road surface & SPT Br no 1/1 with approaches damaged, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long - 91.224650, Lat -26.292225), Rangia Nadir Pam Chariali to Bagudi Village. SPT Br no 1/1 badly damaged with approaches. Rangia Nadir Pam | Road submerged completely .Road surface & SPT Br no 1/1 with approaches damaged, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long -91.133673, Lat - 26.344734), Bagchara Bazar to Kaljahi Joshodarpam Road. Br no 2/1 | Bagchara | Road submerged completely .Road surface & SPT Br no 2/1 with approaches damaged, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long - 91.150801, Lat - 26.350523), Tihu Lochima Road to Tamuli Supa via Jagda Supa Br no 2/1 | Lochima | Road submerged completely .Road surface & SPT Br no 2/1 with approaches damaged, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long - 91.216713, Lat - 26.365047), Amrikhowa Majdia Road (PMGSY-3). Road shoulder badly damaged. | Amrikhowa | Road completely submerged .Road surface and shoulders damaged from 1st to 13th Km, Reported by AEE, PWRD on 30.07.2022 (Damaged occurred on 17.06.2022) | (Long - 91.251438, Lat -26.353334). Chenga Belbari Road (PMGSY-3).Road shoulder badly damaged. | Belbari | Road completely submerged .Road surface and shoulders damaged from 1st to 8th Km, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long - 91.202456, Lat - 26.342183), Kayakuchi Neularbhitha Road. Subway SPT Br.No.4/1 & 6/1 with approaches submerged and huge water hyacinth obstruct the flow of flood water. | Kayakuchi | Subway SPT Br.No.4/1 & 6/1 with approaches submerged and huge water hyacinth obstruct the flow of flood water. SPT Bridge partially damaged with approached, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long - 91.094648, Lat - 26.393230), Nagaon Sarthebari Road. Approaches of RCC Bridge at Singra damaged and road shoulder damaged in stretches from 4th to 15th Km. | Singra | Road submerged in stretches. Approaches of RCC Bridge at Singra damaged and road shoulder damaged in stretches from 4th to 15th Km, Reported by AEE, PWRD on 30.07.2022 (Damaged occurred on 17.06.2022) | (Long - 91.170512, Lat - 26.336164), Sarthebari Bamundi Road. Approaches of RCC Br.No.2/1 badly damaged and road submerged completely | Bamundi | Approaches of RCC Br.No.2/1 badly damaged and road submerged completely, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long -91.205099, Lat - 26.371562), Neularbhitha to Satra Paka via Jabrikuchi Road submerged at 1st to 3rd Km. Approaches of RCC bridge no. 1/1 and shoulder damaged from 1st to 3 rd Km. | Neularbhitha Satra Paka | Road submerged at 1st to 3rd Km. Approaches of RCC Br.No.1/1 and shoulder damaged from 1st to 3rd Km, Reported by AEE, PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long-91.187401, Lat - 26.383853). Dr Jinaram Road(Sarthebari Pathsala Road) breached at 3rd Km and submerged at 1st & 2nd Km. Approaches of RCC Br.No.3/1 damaged. | Sarthebari | Road breached at 3rd Km and submerged at 1st to 3rd Km. Approaches of RCC Br.No.3/1 damaged. Brached at 3rd & 6th km, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long - 91.185556, Lat -26.392557), Galibanda to Mariyam Chupa Chawk Tiniali .Road completely submerged. | Galibanda | Road completely submerged and damaged ICBP surface and shoulders, Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022) | (Long - 91.148595, Lat - 26.431428), Byashkuchi Chengdi PMGSY Road surface and shoulder damaged at 3rd and 4th Km in stretches. Byashkuchi | Road submerged . Road surface and shoulder damaged at 3rd and 4th Km in stretches Reported by AEE,PWRD on 30.07.2022(Damaged occurred on 17.06.2022). | (Long - 0.000000, Lat - 0.000000) Sipajhar - Solap to Bhuktabari Sonapur Road | Solpam | Submerged from 1st Aug, 2022 as Darrang 1 reported by PWRD on 03/08/2022 at 3.45 pm | (Long - 91.845016, Lat - 26.382588) Nalbari - Hajo Nalbari road at Alenghdol | Nalbari | Due to incessant rain and rain water Hajo Nalbari Nalbari Road at Alenghdol have been Damaged as reported from EE PWRD Nalbari on 01/08/2022 1 (Long - 0.000000, Lat - 0.000000) Total 19 Infrastructur Nil e Damaged -Bridge Infrastructur e Damaged -Nil Wildlife

	District	Other Details
		Barpeta - PWSS Damaged   Joypur PWSS, estimated amount=9.577 Lakhs, PHED, Barpeta, date of occurence
	Barpeta	25.06.2022, PWSS Damaged   Phulkipara PWSS, estimated amount=8.943 Lakhs, PHED, Barpeta, date of occurence
		25.06.2022, PWSS Damaged   Joshihatipara PWSS, estimated amount=8.498 Lakhs, PHED, Barpeta, date of occurence
		25.06.2022, PWSS Damaged   Jaharpam PWSS, estimated amount=9.431 lakhs, PHED, Barpeta, date of occurence
		25.06.2022, PWSS Damaged   Bantipur, estimated amount=6.985 Lakhs, PHED, Barpeta, date of occurence 25.06.2022, PWSS Damaged   Banbahar PWSS, estimated amount=7.08 Lakhs, PHED, Barpeta, date of occurence 25.06.2022,
		PWSS Damaged   Kahibari PWSS, estimated amount=3.46 Lakhs, PHED, Barpeta, date of occurence 25.06.2022,
		Sarthebari - PWSS Damaged   Khudra Gomura PWSS , Reported By EE, PHE on 02.08.2022( Damaged occurred on 22.06.2022) )
	Dhemaji	<b>Dhemaji</b> - Power Dept. Poles   On 31/07/2022, PSC Poles and LT lines damaged at samarajan, Nepalikhuti,Ratua,Garubandha,Naruathan, Gohainchapori, Dihiri chapori, Panitula.
		Khairabari - Road Breaches   The overflowing flood water crated breach of about 15.00M on the Batabari
	Udalguri	Jalthangpara road on 02.08.2022. GPS Coordinates: Lat- 26.703616 Long- 91.772578,
		Fisheries/Pond   As per reported by the department on 04.08.2022, approximately 73 farmers were affected in some villages namely: Dhupguri, Batabari, Nalbari & parts of Patala and approximately 9 Ha. of land is affected.,
		<b>Udalguri</b> - Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Embankment cum road of public dong damaged at village Raidanguri around 15m on 16.07.2022. GPS - Lat-26.730886 Long-92.115524,
Infrastructur		Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Breach Of Canal Embankment in B3M canal from Ch 5200m to 5210m at village Harpur around 10m on 17.07.2022. GPS - Lat-26.719237 Long - 92.076785,
e Damaged - Others		Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, CC lining damage in B2M canal from Ch 2800m to 2809 m at village Monpur around 10m on 14.07.2022. GPS - Lat-26.788334 Long - 92.091545,
		Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Erosion Of Canal Embankment in B2M canal from Ch 2850 m to 2860m at village Monpur around 10m on 14.07.2022. GPS -
		Lat-26.787949 Long -92.091802, Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Erosion Of Canal Embankment in B2M canal from Ch 10900 m to 10915m at village No. 02 Sapkhaity around 15m on
		14.07.2022. GPS - Lat- 26.727292 Long-92.085959, Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Damage of HPCD by flood at ch 4800m of B3M canal at village Harpur & Bogapuri around 15m on 17.07.2022. GPS - Lat- 26.719237 Long -92.076785,
		Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Breach Of Canal Embankment in B1M canal at Ch 12000m at village Bandarguri around 12m on 18.07.2022. GPS - Lat-26.670141, Long-92.193869,
		Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Breach Of Canal Embankment in S1K1M canal at Ch 21000m at village Botabari around 13m on 17.07.2022. GPS - Lat-
		26.791326, Long-92.143672, Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Breach Of Canal Embankment in D1B1M canal at Ch 2000m at village Rowta around 14m on 16.07.2022. GPS - Lat-26.701474,
		Long-92.213901, Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Breach Of Canal Embankment in K1B1M canal at Ch 2000m at village Rowta around 14.5m on 18.07.2022. GPS - Lat-
		26.687539 Long-92.19534, Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Breach Of Canal Embankment in D(I)B1M canal at Ch 1125m at village 1 No. Jhargaon around 13.5m on 17.07.2022. GPS -
		Lat-26.668199 Long-92.151645, Irrigation Canal/Scheme Damaged   As reported by Irrigation Department on 04.08.2022, Breach Of Canal Embankment in D(I)B1M canal at Ch 2000m at village 1 No. Jhargaon around 14.5m on 17.07.2022. GPS -
	District	Lat-26.668254 Long-92.151645  Details
	Bajali	<b>Bajali</b> - Chaibari   River: Kaldia Left Bank Issue: Bank Migration and change in course of river. Locations 2 nos. Reach Length= 500 500 = 1000 M This report is received from AEE,Bajali WR Division, Pathsala on 3rd August,2022   0
Erosion	Baksa	Jalah - Khagrabari   On 04 August 2022, approximately 250 meter left bank of river beki is under heavy erosion as per report received from concerned LM and FO,Jalah   11
	Barpeta	Kalgachia - Khudrakhuwa vill   As per concerned LM report received on 04/08/22, total 6 nos of kutcha houses are fully eroded in khudrakhuwa vill on 02/08/22, land eroded 6B-0K- 0L   32,  Baghbar - Village- Sonapur   Erosion is going on at village Sonapur under Jania Mouza by the river Beki. 26
		nos. of houses are washed away .Date-4/8/2022   91

	Bongaigao n	Manikpur - Bashbari Part 2   Erosion of around 1300 mtr. had occurred w.ef 17/06/2022 to 30/06/2022.Two (2) Nos of Relief camp opened due to the said erosion (1) Tilpukhuri ME Madrasa ,Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 no. Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 01.07.2022/Bashbari no 2 Temp.Shelter, Male=55, Femele=45, Child=25,(Toatl=125,Latitude-26.4709483 Longitude-90.748884)Total Inmates 843. Medical Team- 2 Nos. date- 04.08.2022, Total Population-843. GR distribution:-Rice=23.16 qtl. M.Dal=4.215 Qtl. M.Oil=126.45 Ltr. Salt=1.2645 Qtl. Egg-1274 Nos, Amul Taza(200ML)- 1911 Nos, Sanitary Pad- 156 Pkt., Chira- 25.20 Kg, Gur-4.2 Kg on 04.08.2022 erosion continues to Bashbari part II. 6Nos house damage fully kuccha on 04.08.2022   0, Bongaigaon - Popragaon   Bank shifted due to erosion at Popragaon.as per report received from Executive Engineer, W.R. date- 04.08.2022   0, Srijangram - Santoshpur Part III (90.736656 26.30166), Madhufal (90.67939 26.265136), Kushbari Part II (90.710378 26.273191) and Barjana Part I (90.677331 26.246314)   Santoshpur part III : Due to erosion on the river bank of Manas in a length of 300 m approx where 15 no. of families got affected . Madhufal: Due to erosion on river bank of Manas in a length of 1km approx 3 nos. of families got affected and Barjana Part I: Due to erosion on river bank of Manas in a length of 1km approx 3 nos. of families got affected and Barjana Part I: Due to erosion on river bank of Manas in a length of 1km approx 6 nos. of families got affected. Erosion w.e.f 02.08.2022.Total Population-86 nos.   0
	Chirang	<b>Bijni</b> - Bhabanipur   Erosion occured at Bhabanipur on 03-08-2022 due to river Khanamakra. Length=200 mtr(approx) Breadth=30 mtr(approx) Depth=4 mtr(approx)   0
	Dhubri	Agamoni - VILLAGE UTTAR MARAGADADHAR UNDER UTTAR MARAGADADHAR GP   Riverine area of River GANGADHAR UTTAR MARAGADADHAR UNDER UTTAR MARAGADADHAR GP is getting eroded. Village: UTTAR MARAGADADHAR River: Gangadhar GP: UTTAR MARAGADADHAR Incident date: 01/08/2022 to 04/08/2022 Time: 3.00 pm Land: 0 bigha 2 khata 10 Lessa Household affected: 4 Population affected: 27 The affected families has shifted their houses by themselves to another place. GPS Coordinate: Lat. 26.25369 Long. 89.81073   27
	Kokrajhar	<b>Dotma</b> - Dangarkuti   As reported by Executive Engineer W. R. Division, Kokrajhar on 03.08.2022, bank erosion observed at village West Dangarkuti of River Longa.   0
	Morigaon	<b>Laharighat</b> - Borchapori   As per report of the Water Resources Deptt. on dtd-04/08/2022, erosion is observed in Borchapori area with maximum erosion of 2 m.   0
	Nagaon	Dhing - 1. BIRINGABARI RETIREMENT EMBANKMENT AT GATIKORA AREA Long 92.432482, Lati: 26.488263, 2. Severe erosion adjoining to butting point of Brahmaputra dyke at Muwamari Long 925.431328, Lati: 26.487896   1. As per the report received from Section Officer Dhing - II Section, Nagaon W.R. Division, Nagaon on 04.08.2022, Brahmaputra River Bank erosion continued at Muwamari and Gatikara area near Biringabari Retirement embankment. Restoration work is going on to protect the embankment. 2. As per the report received from Executive Engineer, MorigaonW.R. Division, Morigaon on 03.08.2022 Severe erosion has been taking place at Muwamari Butting point of B/dyke under Nagaon W.R. Division and Morigaon W.R. Division. The River Brahmaputra in this reach is flowing in almost perpendicular direction towards the bank and taking U turn and severely eroded and the Land mass. Maximum width of erosion is 231m at the butting point till 09.07.2022 and when riverbank has been submerged state in most of the time. Present available minimum offset of the embankment from riverbank is only 14m as on today 09.07.2022. all efforts are being made to prevent breach of the embankment by dumping mostly Type B geo-bags along with type A geo-bags and also lunching PSC porcupine at upstream and also in downstream to minimize the embayment formation and to mitigate the erosion.   0
	Tinsukia	<b>Sadiya</b> - lakhimpuria   river bank erosion is reported from lakhimpuria village by the Gaonpradhan. stretch area 50m. date from 30/07/2022 to 4/08/2022.   4
	Udalguri	<b>Harisinga</b> - Jalah   Erosion occurred due to overflow of river Kulshi on 31/07/2022 around 90m damaged near House of the Hemchandra Deka.   3
Landslide	Nil	
Urban Flood	Nil	