

## **FRIMS Assam**



## Flood Reporting And Information Management System

			Assam Dail	y Flood Repo	ort as on 12-10-2	2022 at 4:00 P	'M				
Particulars	Situation as	on 12-10-2022 (in last 24 hours)									
Rivers flowing above Danger	Rivers flowing	ng above da	inger level	Brahmaputra (Neamatighat)							
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing flood level	ng above highest Nil									
District	No. of Districts Affected	Name of	Flood Affeo	ted Districts Name o			Urban Flood Districts				
Affected	5	Dhemaji, Nagaon	Dibrugarh,	Golaghat, La	khimpur,						
No. Of		Ivagaon									
Revenue Circles Affected	11										
Affected	District	Total	Revenue	Circle							
Name Of Revenue Circles Affected	Dhemaji	4		Revenue Circle  Dhemaji, Jonai, Sissiborgaon, Gogamukh							
	Dibrugarh	1	Chabua								
	Golaghat	1 Bokakhat									
	Lakhimpur	4									
	Nagaon	1	Kampur								
	Total	11									
Villages Affected	District	Total	Revenue	Circle							
	Dhemaji	76	( Dhemaj	i   10 ), ( Jona	ai   26 ), ( Sissib	orgaon   25 ),	( Gogamukh	1   15 )			
	Dibrugarh	1	( Chabua	1)				. ,			
	Golaghat	4	(Bokakhat   4)								
	Lakhimpur	26	(North Lakhimpur   5), (Bihpuria   8), (Subansiri   1), (Nowboicha   12)								
	Nagaon	3	(Kampur   3)								
	Total	110									
Population And Crop Area Affected	District	Male	Female	Children	Total Population	Population	Details	Crop Area (in Hect.)	Crop Area Details		
	Dhemaji	16199	14690	7885	38774	( Dhemaji   7167 ), ( Jonai   11687 ), ( Sissiborgaon   12905 ), ( Gogamukh   7015 )		2838.40	( Dhemaji   120.00 ), ( Jonai   1085.40 ), ( Sissiborgaon   1433.00 ), ( Gogamukh   200.00 )		
	Dibrugarh	1567	1240	1050	3857	( Chabua   3857 )		0.00	( Chabua   0.00 )		
	Golaghat	0	0	0	0	( Bokakhat   0 )		15.00	( Bokakhat   15.00 )		
	Lakhimpur	11348	9124	6647	27119	( North Lakhimpur   7439 ), ( Nowboicha   16914 ), ( Bihpuria   2615 ), ( Subansiri   151 )		63.00	( North Lakhimpur   40.00 ), ( Nowboicha   0.00 ), ( Bihpuria   0.00 ), ( Subansiri   23.00 )		
	Nagaon	0	0	0	0	( Kampur   0 )		105.00	( Kampur   105.00 )		
	Total	29114	25054	15582	69750			3021.40			
	District	Total	Relief Ca		0 0: "	1.0		ribution Ce			
Relief Camps / Centres Opened	Dhemaji	14	Gogamuk	ch   0)	0, Sissiborgaon	Gogamukh   6)					
	Dibrugarh	1	0(Chabua			1(Chabua   1)					
	Lakhimpur	7		Lakhimpur   C	), Nowboicha   (	7(North Lakhimpur   2, Nowboicha   5)					
	Total	22	0 22								
Inmates In Relief Camps	Nil										
Human Lives											

Nil									
Nil									
TVII									
Nil									
	I			l					
	_								
Total	34827	20310	8493	6024					
Nil									
Nil									
2717									
Nil									
					Cattle	Cattle			
	Dice (in	Dol (in	Solt (in	M Oil (in	Feed -	Feed -	Cattle Feed - Rice Bran (in		
District	`			`	Green	Wheat	Q)		
	(2)	(2)	(4)	<i>L</i> )			(4)		
D1 "	241.40	10.15	10.70	1100.05			0.00		
							0.00		
							0.00		
							0.00		
						0.00	0.00		
		ս ւոգաս	•	1 Soliu		243 00-Pieces	s: Tarnaulin-261 00-Pieces		
	· ·				Tarpounn-	243.00-1 1000	5, 1arpaum-201.00-1 leces		
	`								
Nil									
District	Number Details								
Biswanath	1	Halem - Mild Erosion occured in Paken Area   R/Bank of River Brahmaputra on 12-10-2022.							
	(Long - 93.3/3098, Lat - 26.480320)								
Karbi	Donkamokam - Baliguchi to Pudomoni Embankment   Baliguchi to Pudomoni   Due to incessant Rain damage caused by Kopili River on its L/B from Baliguchi to Pudomoni  Embankment was affected/damaged on 21/05/2022 at the length of 1050 M as reported by Executive Engineer, West Karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022.   (Long - 92.754524, Lat - 26.059822)								
0 0									
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,									
Total	2		1						
Nil									
Nil									
Nil									
District									
Donkamokam - Protection Bundh Damaged   Due to incessant rain damaged caused by Kopili River to Ringbundh from taradubi Weekly market to goroimari area on its L/B in West karbi Anglong at the length of 1825 M affected/damaged on 20/05/2022 at the geographical coordinates of Latitude:26.036568,longitude:92.748124 as reported by Executive Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022.,  Protection Bundh Damaged   Due to incessant rain damaged caused by Kopili River from Tumpreng market area on its L/B in West karbi Anglong at the length of 1025 M affected/damaged on 23/07/2022 at the geographical coordinates of Latitude:26.00687,longitude:92.760351 as reported by Executive Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022.,  Protection Bundh Damaged   Due to incessant rain damaged caused by Kopili River from Tumpreng bridge area to downstream on its L/B in West karbi Anglong at the length of 800 M affected/damaged on									
	Nil  Nil  District  Dhemaji  Dibrugarh  Lakhimpur  Total  Nil  Nil  District  Dhemaji  Dibrugarh  Lakhimpur  Total  Dibrugarh  Lakhimpur  Total  District  Dhemaji  Dibrugarh  Lakhimpur  Total  Total  Nil  District  Biswanath  Karbi  Anglong  West  Total  Nil  Nil  Nil  Nil  Nil  Nil  Karbi  Anglong  Karbi  Anglong  Karbi  Anglong  Karbi  Nil  Nil  Nil  Nil  Nil	Nil    Nil   District   Total   Dhemaji   22541   Dibrugarh   723   Lakhimpur   11563   Total   34827   Nil   Nil   Nil   District   Rice (in Q)   Dhemaji   241.48   Dibrugarh   63.13   Lakhimpur   150.68   Total   455.29   District   Baby Foo   Dhemaji   0.00-Q   Dibrugarh   0.00-Q   Lakhimpur   0.00-Q   Nil   District   Number   Biswanath   1   Karbi   Anglong   West   Total   2   Nil   Nil	Nil	Nil	Nil	Nil	Nil     District   Total   Big   Small   Poultry     Dhemaji   22541   11855   5367   5319     Dibrugarh   723   621   102   0		

		23/07/2022 at the geographical coordinates of Latitude:26.00728,longitude:92.760916 as reported by Executive Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022., Protection Bundh Damaged   Due to incessant rain damaged caused by Kopili River to Hanse Japan on its L/B in West karbi Anglong at the length of 400 M was affected/damaged on 22/07/2022 at the geographical coordinates of Latitude:25.9185,longitude:92.79508 as reported by Executive Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022., Protection Bundh Damaged   Due to incessant rain damaged caused by Kopili River to Sing Ronghang Memorial Park area on its L/B in West Karbi Anglong at the length of 530 M was affected/damaged on 23/07/2022 at the geographical coordinates of Latitude:26.005141,longitude:92.757891 as reported by Executive Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022., Protection Bundh Damaged   Due to incessant rain damaged caused by Kopili River to Goroimari area on its L/B in West Karbi Anglong at the length of 530 M was affected/damaged on 21/05/2022 at the geographical coordinates of Latitude:26.050418,longitude:92.744729 as reported by Executive Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022., Protection Bundh Damaged   Due to incessant rain damaged caused by River Karbi langpi to Kharopindha area on its L/B in West Karbi Anglong at the length of 500 M was affected/damaged on 23/07/2022 at the
		geographical coordinates of Latitude:25.978392,longitude:92.597967 as reported by Executive
		Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022.,
		Protection Bundh Damaged   Due to incessant rain damaged caused by River Kopili to Baligaon area on its L/B in West Karbi Anglong at the length of 500 M was affected/damaged on 20/05/2022 at the geographical coordinates of Latitude:26.005197,longitude:92. 758039 as reported by Executive Engineer, West karbi Anglong, Water Resource Division, Donkamokam on 12/10/2022.
	District	Details
Erosion	Biswanath  Dhemaji  Dibrugarh	Biswanath - Kumolia forseati   Bank erosion continues at Kumolia forseati area on the R/B of river Brahmaputra on 12-10-2022.   0,  Gohpur - R/Bank of River Solengi at Nalbari Area   Erosion has been observed in the R/Bank of River Solengi at Nalbari Area on 12-10-2022.   0,  Halem - Upsteam of Kalyani Than (Dipara Dani Village)   Erosion observed at upstream of Kalyani Than on R/Bank of River Brahmaputra on 12-10-2022.   0,  Naduar RC part - No-4 Bhojmari   Dated: 12/10/2022, Heavy erosion is observed at No-4 Bhojmari by the river Brahmaputra. Due to this erosion some portion of one school namely Bhojmari Govt. Junior Basic have been washed away. The school is situated outside the embankment.   0  Jonai - At Tol Kabu(ward 3 &4) on 11/10/2022 approx. 6.69 hectare of land got eroded by Siang River affecting approx. 35 nos, of families.   As per report received from Gaon Pradhan and LM at Tol Kabu(ward 3 &4) on 11/10/2022 approx. 6.69 hectare of land got eroded by Siang River.   180  Chabua - Gereki Nepali Village   Gereki Nepali AWC eroded as per information received from Social Welfare Deptt. on 12/10/2022 Coordinates-N27 34'09.50" E95 14'37.09"   0,  Dibrugarh East - Nagaghoolie (Kachari Line) also known as (Philonuguri Grant 8/152 No ORR Grant)    Erosion continuously taking place on the bank of the area as per report received from Water Resource Division, Dibrugarh since from 08/10/2022. Since erosion is taking place rapidly Water Resource has built the bund with the help of Mega Bag and Geo Sheets and shifted the dyke to prevent it from breaching. GPS Co-Ordinates are 27.31'32.63" N to 94.59'22.16" E   223  North Lakhimpur - Na Ali Telia pathar Ghancharai right bank.   Continuous erosion observed at Na Ali
	Lakhimpur Morigaon	area about 50 MTR as reported by WR dept, NLP on 12-10-2022.   0  Laharighat - Leruamukh   As per report of the Water Resources Dept on 12-10-2022, erosion is observed in
	3	Leruamukh with max erosion of 3 m.   0
	Sonitpur	<b>Dhekiajuli</b> - Dheraimajuli   As reported by Water Resource dept bank erosion observed at Dheraimajuli area along R/B of river Belsiri at Ch. 3600.00 to 3700.00 m. length 100m. dated 11.10.22   0
	Tinsukia	Sadiya - 1. Lachon gaon( Amarpur)   Bank erosion by Datung river reported by Gaonpradhan. Stretched area 200m. From date 11/10/2022 to 12/10/2022.   5,  Tinsukia - 1. Khamtiguwali TE (KoilaPather) Mouza: Rangagora   Active river bank erosion is going on at
Landslide	Nil	Dibru River since 11/10/2022 till 12/10/2022. As per report by Gaonpradhan, the stretch area is 25 m.   30